

Joy

TAT HENG MOTOR WORKS PTE LTD

BLK 10, ANG MO KIO IND PK 2A

02-09 AMK AUTOPOINT

SINGAPORE 568047

TEL : 6483 7103 FAX : 6481 7732

James

11/4/2019

Steve (LKK) 8322 8813

with Prejudice 3 days

9/4/19 11.30am

THIRD PARTY CLAIM

VEHICLE NO : GBD2531E

MODEL : TOYOTA DYNA YR 2018

CHASSIS : JTFAT35Y60K210058

L/5

Ry AL spray

No	Description	Qty	Unit	Amount
	Tailgate X R	1	repair	0.00 X
	Tailgate hinge / DD	2/1	192.00	384.00 192 ✓
	Rear floor end Panel x R	1	1,001.00	1001.00 X
	Rear side bracket ~ BT	2/1	116.00	232.00 116 ✓
	Taillamp (LH) (RH) / RH X	2/1	317.00	634.00 317 ✓
	Taillamp bracket x	2	132.00	264.00 X
	Rear number plate bracket X	1	102.00	102.00 X
				2,617.00 625
	Less 20%			-523.40 -25%
				2,093.60 468-75 ✓
	Nett Items			
	Tailgate 'TOYOTA' label / ALK	1	89.00	89.00 ✓
	Rear rubber stopper x	2	22.00	44.00 X
	Tailgate '70km/h' label / ALK	1	15.00	15.00 ✓
	Tailgate '13 pax' label / ALK	1	15.00	15.00 ✓
	Reverse sensor / DR	1	250.00	250.00 200 ✓
	Rear number plate x	1	35.00	35.00 X
				319 ✓
	Labour and Miscellaneous			
	To check wiring for proper function.			30.00 ✓
	To remove and replace reverse sensor.			50.00 20
	Cavity preservation on all effected areas.			80.00 20
	To replace repair, straighten & re-align all damaged parts			600.00 350
	To spray paint on all affected areas.			500.00 400
				3,801.60 820 ✓

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before and after repairs.
- To replace repair, straighten & re-align all damaged parts
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification (if any) allowed
- Supplementary item(s) must be resurveyed and is subject to that approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 468-75

AI- 319

L- 820

1607.75

L/5 - 1286.2 = 1300 ✓