

JIN AUTO SERVICES PTE LTD

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62894656 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

not Authorized
Lark
2/5 5200
3/4/19

gdy.
The Able Attorney

4/4/2019

M/S EQ

DEAR SIR

ESTIMATE REPAIR COST FOR SGU1107B (TOYOTA VIOS)

TO SUPPLY :

List Items

- | | | |
|-----|------|------------------------------------|
| 01) | 1 PC | Boot lid |
| 02) | 2 PC | Boot lid Hinge |
| 03) | 1 PC | Boot lid rubber |
| 04) | 1 PC | Boot lid lock |
| 05) | 1 PC | Boot lid lock Cover 3210 |
| 06) | 1 PC | Boot lid lock Lower Catch |
| 07) | 1 PC | Boot lid logo |
| 08) | 1 PC | Boot lid "VIOS " emblem |
| 09) | 1 PC | Boot lid "J" emblem |
| 10) | 1 PC | Boot lid Chrome |
| 11) | 1 PC | number plate lamp |
| 12) | 1 PC | Rear bumper |
| 13) | 1 PC | Rear bumper side retainers 115 |
| 14) | 1 PC | Rear bumper side Reflector 115 |
| 15) | 2 PC | Rear taillamps |
| 16) | 1 PC | Rear LH mudguard Air seat |
| 17) | 1 PC | Rear LH mudguard Inner Carpet trim |
| 18) | 1 PC | Rear LH mudguard |
| 19) | 1 PC | Rear end panel |
| 20) | 1 PC | Rear end panel inner garnish |
| 21) | 1 PC | Spare tyre Panel Sponge 115 |
| 22) | 1 PC | rear windscreen moulding |
| 23) | 1 PC | Spare tyre Panel |
| 24) | 1 PC | rear floor panel top boot |

11/200	\$	627.00	—
3rd/100	\$	114.20	—
100	\$	45.00	—
100	\$	99.21	—
100	\$	144.76	—
100	\$	36.70	x
100	\$	50.80	—
100	\$	47.50	—
100	\$	32.80	—
100	\$	185.60	x
100	\$	48.90	x
100	\$	470.10	—
100	\$	65.10	✓
100	\$	90.20	—
100/100	\$	512.40	✓
100	\$	55.60	—
100	\$	230.80	—
100/100	\$	977.70	—
100	\$	517.10	—
100	\$	211.20	—
100	\$	134.20	—
100	\$	45.80	—
100	\$	655.40	x
100	\$	45.20	—
	\$	5,443.27	—
less 25%	\$	(1,360.82)	—
	\$	4,082.45	—

4404.01
3303.00

Special Nett Items

- | | | |
|----|-------|-----------------------------|
| 25 | 1 PC | No .plate |
| 26 | 1 set | Rear bumper clip (1 set) |
| 27 | 1 set | Rear reverse sensor (1 set) |

100	\$	40.00	✓
100	\$	70.00	40
100	\$	280.00	200

28	1 set	Windscreen Sealant	her	\$	40.00	✓
29	1 set	End panel Sealant	her	\$	60.00	50
		<u>Labour Costs</u>				
30		To remove and refit Rear Windscreen		\$	120.00	✓
31		To remove and refit wiring		\$	30.00	✓
32		To remove and refit inner garnishes		\$	120.00	80
33		To remove and refit rear reverse sensor		\$	80.00	50
34		Panel beating		\$	1,580.00	1400
35		To spray painting		\$	1,350.00	1100
36		To apply undercoating		\$	120.00	100
				\$	<u>7,972.45</u>	

6557

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: