

BW WORKSHOP SERVICES PTE. LTD.

30 UBI ROAD 4 SINGAPORE 408615

TEL: 6289 8800 FAX: 6858 2120

GST REG NO : 201504834E

Estimate

To	:	AXA Insurance Pte Ltd	DATE	:	2/4/2019
Attn	:	Claims Officer		:	
CC	:	1299	VEHICLE NO	:	SMH 220 K
YEAR	:	2018	CHASSIS NO	:	GK31337888
MODEL	:	HONDA FIT 1.3GF CVT	PAGE	:	1 OF 3

Please quote the following items listed.

Third Party Claims

S/NO	ITEMS	Qty	Price
1	Front bumper	1	\$540.00
2	Front bumper towing cap	1	\$23.00
3	Front bumper side retainer - LH & RH @ \$20.00	2	\$40.00
4	Front bumper lower grille	1	\$230.00
5	Front bumper duct - LH & RH @ \$35.00	2	\$70.00
6	Front grille	1	\$460.00
7	Front grille chrome - upper	1	\$250.00
8	Front grille chrome - lower	1	\$190.00
9	Front bumper reinforcement	1	\$290.00
10	Front headlamp - RH & LH @ \$810.00	2	\$1,620.00
11	Front headlamp bracket - RH & LH @ \$35.00	2	\$70.00
12	Front support panel garnish - center	1	\$35.00
13	Rear tailgate	1	\$860.00
14	Rear tailgate center trim	1	\$280.00
15	Rear tailgate handle holder - inner	1	\$45.00
16	Rear tailgate lock	1	\$260.00
17	Rear tailgate garnish center - inner	1	\$140.00
18	Rear bumper	1	\$520.00
19	Rear bumper trim - center	1	\$130.00
20	Rear bumper trim - RH & LH @ \$25.00	2	\$50.00
21	Rear bumper side retainer - RH & LH @ \$20.00	2	\$40.00
22	Rear end panel	1	\$420.00
23	Rear end panel garnish - center	1	\$65.00
24	Rear spare tyre tray - center	1	\$240.00
25	Rear fender garnish - inner - RH	1	\$230.00
26	Rear fender lamp - RH	1	\$430.00
			\$7,528.00

BW WORKSHOP SERVICES PTE. LTD.

30 UBI ROAD 4 SINGAPORE 408615

TEL: 6289 8800 FAX: 6858 2120

GST REG NO : 201504834E

Estimate

To	:	AXA Insurance Pte Ltd	DATE	:	2/4/2019
Attn	:	Claims Officer		:	
CC	:	1299	VEHICLE NO	:	SMH 220 K
YEAR	:	2018	CHASSIS NO	:	GK31337888
MODEL	:	HONDA FIT 1.3GF CVT	PAGE	:	2 OF 3

Please quote the following items listed.

Third Party Claims

S/NO	ITEMS	Qty	Price
27	Rear bumper sensor antenna	1	\$110.00
28	Rear exhaust silencer plate (Repair)	1	-
29	Rear bumper sensor warning buzzer	1	\$120.00
30	Rear spare tyre panel (Repair)	1	-
			\$230.00
		TOTAL :	\$7,758.00
		Discount 20%	\$1,551.60
		TOTAL :	\$6,206.40
S/NO	SPECIAL ITEMS	Qty	Price
1	Front bumper clips @ \$4.00	10	\$40.00
2	Front grille logo "Honda"	1	\$25.00
3	Front number plate c/w casing	1	\$85.00
4	Rear tailgate center trim logo " Honda "	1	\$20.00
5	Rear tailgate emblem " FIT "	1	\$35.00
6	Rear windscreen moulding	1	\$95.00
7	Rear bumper clips @ \$4.00	10	\$40.00
8	Rear bumper reverser sensor	1set	\$150.00
			\$490.00
		Parts Total :	\$6,206.40
		S/P Item :	\$490.00
		TOTAL :	\$6,696.40

BW WORKSHOP SERVICES PTE. LTD.

30 UBI ROAD 4 SINGAPORE 408615

TEL: 6289 8800 FAX: 6858 2120

GST REG NO : 201504834E

Estimate

To	: AXA Insurance Pte Ltd	DATE	: 2/4/2019
Attn	: Claims Officer		
CC	: 1299	VEHICLE NO	: SMH 220 K
YEAR	: 2018	CHASSIS NO	: GK31337888
MODEL	: HONDA FIT 1.3GF CVT	PAGE	: 3 OF 3

Please quote the following items listed.

Third Party Claims

S/NO	LABOURS	AMOUNT
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS. \$280/ Per Days	\$ 1,680.00
2	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS. \$250/ Per Panel	\$ 1,250.00
3	DISCONNECT AND CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS,ETC. REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	\$ 120.00
4	TO REMOVE AND REFIT REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	\$ 100.00
5	TO REMOVE AND REPAIR REAR EXHAUST SILENCER PLATE.	\$ 100.00
6	TO TRANSFER TAILGATE'S FITTINGS.	\$ 100.00
7	TO APPLY UNDERSEALING.	\$ 80.00
8	TO REMOVE AND REFIT REAR EXHAUST.	\$ 100.00

Working Days : 10 Days.

NOTE: ALL QUOTED PRICE IS SUBJECT TO 7% GST

TOTAL	:	\$3,530.00
PARTS TOTAL	:	\$6,696.40
GRAND TOTAL	:	\$10,226.40