

BW WORKSHOP SERVICES PTE. LTD.

30 UBI ROAD 4 SINGAPORE 408615

TEL: 6289 8800 FAX: 6858 2120

GST REG NO : 201504834E

Estimate

To : AXA Insurance Pte Ltd DATE : 2/4/2019
 Attn : Claims Officer
 CC : 1299 VEHICLE NO : SMH 220 K
 YEAR : 2018 CHASSIS NO : GK31337888
 MODEL : HONDA FIT 1.3GF CVT PAGE : 1 OF 3

Poh Kin.

Please quote the following items listed.

Third Party Claims

S/NO	ITEMS	Qty	Price
1	Front bumper <i>Debond</i>	1	\$540.00 ✓
2	Front bumper towing cap <i>new</i>	1	\$23.00
3	Front bumper side retainer - LH & RH @ \$20.00 <i>new</i>	2	\$40.00
4	Front bumper lower grille <i>Not Nec</i>	1	\$230.00
5	Front bumper duct - LH & RH @ \$35.00 <i>new</i>	2	\$70.00
6	Front grille <i>Cracked</i>	1	\$460.00 <i>382</i>
7	Front grille chrome - upper <i>lt</i>	1	\$250.00
8	Front grille chrome - lower <i>lt</i>	1	\$190.00
9	Front bumper reinforcement <i>Bent</i>	1	\$290.00
10	Front headlamp - RH & LH @ \$810.00 <i>Cracked</i>	2	\$1,620.00
11	Front headlamp bracket - RH & LH @ \$35.00 <i>Cracked</i>	2	\$70.00
12	Front support panel garnish - center <i>Not Nec</i>	1	\$35.00
13	Rear tailgate <i>Bent</i>	1	\$860.00
14	Rear tailgate center trim <i>new</i>	1	\$280.00
15	Rear tailgate handle holder - inner <i>new</i>	1	\$45.00
16	Rear tailgate lock <i>new</i>	1	\$260.00
17	Rear tailgate garnish center - inner <i>Cracked</i>	1	\$140.00
18	Rear bumper <i>Distorted</i>	1	\$520.00
19	Rear bumper trim - center <i>Debond</i>	1	\$130.00
20	Rear bumper trim - RH & LH @ \$25.00 <i>new</i>	2	\$50.00
21	Rear bumper side retainer - RH & LH @ \$20.00 <i>new</i>	2	\$40.00
22	Rear end panel <i>Distorted</i>	1	\$420.00
23	Rear end panel garnish - center <i>Debond</i>	1	\$65.00
24	Rear spare tyre tray - center <i>Cracked</i>	1	\$240.00
25	Rear fender garnish - inner - RH <i>Debond</i>	1	\$230.00
26	Rear fender lamp - RH <i>Cracked</i>	1	\$430.00 <i>382</i>
			\$7,528.00

GST REG NO : 201504834E

To	AXA Insurance Pte Ltd	DATE	2/4/2019
Attn	Claims Officer		
CC	1299	VEHICLE NO	SMH 220 K
YEAR	2018	CHASSIS NO	GK31337888
MODEL	HONDA FIT 1.3GF CVT	PAGE	2 OF 3

Third Party Claims

S/NO	ITEMS	Qty	Price
27	Rear bumper sensor antenna <i>New</i>	1	\$110.00
28	Rear exhaust silencer plate (Repair) <i>new</i>	1	-
29	Rear bumper sensor warning buzzer <i>New new</i>	1	\$120.00
30	Rear spare tyre panel (Repair) <i>Repair</i>	1	-
	<i>6642</i> <i>5313.60</i>		\$230.00
		TOTAL :	\$7,758.00
		Discount 20%	\$1,551.60
		TOTAL :	\$6,206.40
S/NO	SPECIAL ITEMS	Qty	Price
1	Front bumper clips @ \$4.00 <i>ne</i>	10	\$40.00 <i>30</i>
2	Front grille logo "Honda" <i>m</i>	1	\$25.00 ✓
3	Front number plate c/w casing <i>Cashed</i>	1	\$85.00 <i>60</i>
4	Rear tailgate center trim logo " Honda " <i>ne ne</i>	1	\$20.00 ✓
5	Rear tailgate emblem " FIT " <i>ne</i>	1	\$35.00 ✓
6	Rear windscreen moulding <i>ne</i>	1	\$95.00 ✓
7	Rear bumper clips @ \$4.00 <i>m</i>	10	\$40.00 <i>30</i>
8	Rear bumper reverser sensor <i>Damaged</i>	1set	\$150.00 ✓
	<i>HHS</i>		\$490.00
		Parts Total :	\$6,206.40
		S/P Item :	\$490.00
		TOTAL :	\$6,696.40

BW WORKSHOP SERVICES PTE. LTD.

30 UBI ROAD 4 SINGAPORE 408615

TEL: 6289 8800 FAX: 6858 2120

GST REG NO : 201504834E

Estimate

To : AXA Insurance Pte Ltd DATE : 2/4/2019
Attn : Claims Officer
CC : 1299 VEHICLE NO : SMH 220 K
YEAR : 2018 CHASSIS NO : GK31337888
MODEL : HONDA FIT 1.3GF CVT PAGE : 3 OF 3

Please quote the following items listed.

Third Party Claims

S/NO	LABOURS	AMOUNT
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS. \$280/ Per Days	\$ 1,680.00
2	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS. \$250/ Per Panel	\$ 1,250.00
3	DISCONNECT AND CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC. REMOVE AND REINSTALL DAMAGED PARTS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	\$ 120.00
4	TO REMOVE AND REFIT REAR WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	\$ 100.00
5	TO REMOVE AND REPAIR REAR EXHAUST SILENCER PLATE.	\$ 100.00
6	TO TRANSFER TAILGATE'S FITTINGS.	\$ 100.00
7	TO APPLY UNDERSEALING.	\$ 80.00
8	TO REMOVE AND REFIT REAR EXHAUST.	\$ 100.00

Working Days : 10 Days.

2700

NOTE: ALL QUOTED PRICE IS SUBJECT TO 7% GST

TOTAL : \$3,530.00
PARTS TOTAL : \$6,696.40
GRAND TOTAL : \$10,226.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Ling
P/P 03/04/19.

11 Days.

Total: 8458.60.