

SK Automobile Pte. Ltd.
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel: 6789 5155 Fax : 6783 5155

TO : AXA	DATE : 28-Mar-19
ATTENTION : MOTOR CLAIMS DEPARTMENT	JOB TYPE : T/P CLAIMS
ESTIMATE REPORT :	
OWNER PARTICULAR	
NAME :	VEHICLE DETAILS
ADDRESS :	VEHICLE NO. : SLW2868L
TEL. NO. :	MODEL / MAKE : TOYOTA WISH
	CHASSIS NO. : JTDGG20W50J009247
OWNER INSUANCE : AXA	
POLICY NO. : VPA/P2081434	ACCIDENT DETAIL
	DATE : 23-Mar-19
	TIME : 00:00hrs
PERSON INCHARGE :	

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	RAER DOOR RH	1	\$ 1,035.70	\$ 1,035.70
2	REAR DOOR BLACK FRAME STICKER HORIZONTAL RH	1	\$ 55.90	\$ 55.90
3	REAR DOOR BLACK FRAME STICKER VERTICAL RH	2	\$ 48.20	\$ 96.40
4	REAR DOOR BLACK FRAME STICKER INNER RH	1	\$ 45.30	\$ 45.30
5	REAR DOOR GLASS OUTER MOULDING RH	1	\$ 95.60	\$ 95.60
6	REAR DOOR LOWER CHROME MOULDING RH	1	\$ 180.60	\$ 180.60
7	REAR DOOR INNER TRIM BOARD RH	1	\$ 713.20	\$ 713.20
8	REAR DOOR WEATHER STRIP RH	1	\$ 152.90	\$ 152.90
9	REAR FENDER RH	1	\$ 1,032.70	\$ 1,032.70
10	REAR FENDER QUARTER GLASS WITH MOULDING RH	1	\$ 402.80	\$ 402.80
11	ROCKER SIDE SKIRTING RH	1	\$ 1,123.90	\$ 1,123.90
12	REAR BUMPER	1	\$ 839.20	\$ 839.20
13	REAR BUMPER SIDE RETAINER LH/RH <i>LH x RH - 102</i>	2	\$ 89.60	\$ 179.20
14	REAR BUMPER INNER SIDE SHIELD RH	1	\$ 156.40	\$ 156.40
15	REAR SUSPENSION SHOCK ABSORBER RH	1	\$ 312.50	\$ 312.50
16	REAR SUSPENSION WHEEL HUB BEARING RH	1	\$ 692.30	\$ 692.30

TOTAL PRICE \$ 7,114.60

LESS -25% \$ (1,778.65)

SUB TOTAL PRICE \$ 5,335.95

3521.25

2640.94

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR DOOR INNER TRIM BOARD CLIPS SET RH	1	\$ 50.00	\$ 20 50.00
2	REAR FENDER SEALANT RH	1	\$ 120.00	\$ 44 X 120.00
3	REAR FENDER QUARTER GLASS SEALANT WITH PRIMER RH	1	\$ 80.00	\$ 44 X 80.00
4	REAR FENDER INNER TRIM BOARD CLIPS SET RH	1	\$ 50.00	\$ 44 X 50.00
5	ROCKER SIDE SKIRTING CLIPS SET RH	1	\$ 60.00	\$ 30 60.00
6	REAR BUMPER CLIPS SET	1	\$ 60.00	\$ 30 60.00
7	REAR 18" SPORT RIM RH	1	\$ 1,080.00	\$ 500 1,080.00

TOTAL

\$ 1,500.00

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,600.00	700	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,200.00	700	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 100.00	30	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30	
TO DISMANTLE & REINSTALL REAR DOOR INNER COMPONENT MECHANISM RH TO FACILITATE REPAIR WITH CHECKING	\$ 250.00	60	
TO DISMANTLE & REINSTALL REAR FENDER RH QUARTER GLASS PERFORM WITH WATER LEAK TEST	\$ 150.00	60	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 80.00	30	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 180.00	X 44	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00	20	

TOTAL

\$ 3,720.00

wheel alignment \$ 60

1690

QUOTATION SUMMARY

PAGE 03

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	6,835.95
TOTAL LABOUR COST	:	\$	3,720.00
TOTAL REPAIR COST	:	\$	<u>10,555.95</u>

APPROVED DETAILS

EXCESS :
NO. OF REPAIR DAYS :
RE-SURVEY :
P / P OR L / S :

DATE / TIME OF SURVEY :
SURVEYED BY / FROM :
CONTACT NUMBER :
FAX NUMBER :
EMAIL ADDRESS :

Tanjin 97445711/67418434
5/4/19 5pm 'WP'
surellkauto.com
Resurvey after repair
6 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: