

# RALLY PITSTOP

176 Sin Ming Drive  
#04-17 Sin Ming Autocare  
Singapore 575721  
Tel: 64516985  
Email: tar6985@hotmail.com

Date: 04-04-2019

To: Motor Claims Department

RE: Estimate repair cost of GBB2080X

Your Insured: SCA61H

Dear Sir/Madam,  
Vehicle No: GBB2080X  
Make Model: Nissan Cabstar  
Date of accident: 27-03-2019

We are pleased to quote you the repair cost for the above-mentioned vehicle:

Qty	Description	Unit Price	TOTAL	
2	Side gate hinge left	78.30	234.90	✓
1	Side gate left		1,275.30	✓
1	Hua Heng Electrical Service' sticker		300.00	✓
1	Rear left tyre front panel		148.30	✓
1	Rear left tyre rear panel		148.30	✓
1	Rear tail gate		987.40	✓
1	Rear tail lamp left		185.40	✓
1	Rear reinforcement		557.80	✓
1	Rear left tyre		180.90	✓
1	Rear left tail gate lock hinge		130.90	✓
1	Rear left rim		240.10	✓
	<b>Sub-total before discount</b>		<b>4,389.30</b>	
	<b>Parts percentage discount 25%</b>		<b>1,097.33</b>	
	<b>PARTS TOTAL</b>		<b>3,291.98</b>	
	<b>LABOUR CHARGES &amp; MISC</b>			
1	Labour to dismantle, panel beat, repair & replace rear panel, rear reinforcement and all necessary parts		1,000.00	550
2	To putty and spray paint the accident damaged parts		800.00	500
3	To check wiring		50.00	200
	<b>LABOUR TOTAL</b>		<b>1,850.00</b>	
	<b>LABOUR &amp; PARTS TOTAL</b>		<b>5,141.98</b>	

Regards,  
Terrence Lim

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: