

**CAS GARAGE PTE LTD**

(Reg No: 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Insurance Company: AIG ASIA PACIFIC INSURANCE PTE LTD

Address: 78, SHENTON WAY, #07-16

S(079120)

Telephone: 64193000

Fax: 68357416

Email shengyang.lim@aig.comnoormarriesa.abukassim@aig.com

Make/ Model : LEXUS RX350

Date: 02.04.2019

Chassis No : JTJBK11A802423555

Vehicle No: SBN1222Y

Date/Time of Accide 30.03.2019/1145

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	PARTS DISCOU	FINAL PRICE \$
1	FRONT BUMPER <i>Repair</i>	1	\$ 985.60	10%	\$ 887.04
2	FRONT BUMPER RETAINER <i>new</i>	1	\$ 138.20	10%	\$ 124.38
3	FRONT BUMPER LOWER SPOILER <i>new</i>	1	\$ 285.40	10%	\$ 256.86
4	FRONT FENDER RH <i>Painted</i>	1	\$ 1,123.70	10%	\$ 1,011.33
5	FRONT FENDER INNER COWLING RH <i>new</i>	1	\$ 426.30	10%	\$ 383.67
6	FRONT FENDER LOWER GARNISH RH <i>new</i>	1	\$ 325.60	10%	\$ 293.04
	FRONT HEADLAMP RH <i>cut</i>	1	\$ 1,654.90	10%	\$ 1,489.41
	HEADLAMP LOWER BRACKET RH <i>new</i>	1	\$ 130.80	10%	\$ 117.72
	FRONT DOOR RH <i>Painted</i>	1	\$ 1,345.80	10%	\$ 1,211.22
	FRONT DOOR OUTER HANDLE RH <i>new</i>	1	\$ 425.90	10%	\$ 383.31
	FRONT DOOR OUTER GARNISH RH <i>new</i>	1	\$ 345.90	10%	\$ 311.31
	FRONT SIDE ROCKER PANEL RH <i>new</i>	1	\$ 723.30	10%	\$ 650.97
7	FRONT SIDE MIRROR ASSY RH <i>Repair</i>	1	\$ 1,005.95	10%	\$ 905.36
8	FRONT WHEEL HUB BEARING RH <i>new</i>	1	\$ 290.50	10%	\$ 261.45
9	FRONT ABSORBER RH <i>Best</i>	1	\$ 697.10	10%	\$ 627.39
10	FRONT ABSORBER MOUNTING RH <i>new</i>	1	\$ 135.90	10%	\$ 122.31
11	FRONT LOWER ARM RH <i>Best</i>	1	\$ 697.60	10%	\$ 627.84
12	FRONT KNUCKLE ARM RH <i>Best</i>	1	\$ 685.90	10%	\$ 617.31
13	TIE ROD END RH <i>new Best</i>	1	\$ 145.60	10%	\$ 131.04
14	FRONT STEERING RACK <i>new Best</i>	1	\$ 6,033.10	10%	\$ 5,429.79
15	CROSS MEMBER CHASSIS <i>new</i>	1	\$ 2,017.50	10%	\$ 1,815.75
16	STABILIZER LINK <i>new</i>	1	\$ 325.60	10%	\$ 293.04
Total List Price Cost					\$ 17,951.54

1140678.

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$		FINAL PRICE \$
1	FRONT BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00		\$ 30.00
2	FRONT FENDER INNER COWLING CLIPS <i>new</i>	1 SET	\$ 30.00		\$ 30.00
Total Special Nett Items					\$ 60.00

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE,BEAT ,WELD , REALIGN AND ALIGNE ALL PARTS	\$ 1,600.00
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,200.00
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 200.00
TO REMOVE/ REFIT WIRING CHECKS	\$ 150.00
TO REMOVE/ REFIT FRONT HEADLAMP AND RESET HEADLAMP FOCUSING	\$ 80.00
Total Others Cost	\$ 430.00
GRAND TOTAL	
	\$ 21,241.54

To Perform computerize wheel alignment

\$180.00

80.

1410.

CAS GARAGE PTE LTD

UEN 201828067M

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY,
SINGAPORE 417883

CAS GARAGE PTE LTD

Person Incharge: Allan
Direct Contact: +65 8782 7171
Email: allangoh.cas@gmail.com
Fax : 6509 9501
TEL: 64842220

Adrian Ling
4/s 03/04/15

06 Days.

total: 12816.78.

4/s : 10.2K.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: