



Section A - Accident Details



Registration Number	SHC4926S
Case Reference Number	TAX/03/19/2147
Registration Date	1/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	SAPARI BIN SARTHY
Type of Accident	Head To Side
Accident Date and Time	30/3/2019 8:10 PM
Accident Reported Date and Time	1/4/2019 8:39 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24100847
Special Instruction to ARC, if any	TP
Prepared Date and Time	1/4/2019 4:00 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	



Left / Rear View Side

Right Side

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$845.00	\$500.00
Total Spray Cost	\$1,674.00	\$600.00
Total Spare Part Cost	\$5,216.41	\$99.68
Total Other Cost	\$480.00	\$50.00
TOTAL COST	\$8,215.41	\$1,249.68 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	4.0
Prepared / Adjusted By	Tuck Foo Kok	Hwee Jie (LKK) / AIG
ARC / Surveyor Sign Off Date	01/04/2019 4:49 PM	02/04/2019 4:21 PM
Signature	 	
Remarks		
		P/P REPAIR, PHOTO BEFORE PAINT.

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1904-0285	Invoice Number	
Quotation Date	22.04.2019	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$845.00	\$500.00
Total Labour	\$845.00	\$500.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$50.00
TO RESPRAY FRONT DOOR RH	\$378.00	\$200.00
TO RESPRAY VIEW MIRROR	\$180.00	\$50.00
TO RESPRAY ROCKER PANEL MOULDING	\$180.00	\$100.00
Total Spray Painting & Panel Beating	\$1,674.00	\$600.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$30.00
TO WASH AND VACUUM	\$60.00	\$0.00
Total Other Costs	\$480.00	\$50.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119479 62	COVER, FR BUMPER	0.00	\$495.50	0.00	\$0.00	Replace	Not Given
		52115470 50	SUPPORT, FR BUMPER RH	0.00	\$76.90	0.00	\$0.00	Replace	Not Given
		53801470 80	FENDER SUB-ASSY, FR, RH	1.00	\$933.10	100.00	\$0.00	Replace	Repair
		53875470 70	LINER, FR FENDER, RH	0.00	\$198.40	0.00	\$0.00	Replace	Not Given
		75374471 40	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace
		42611-47450	WHEEL, DISC FRONT	1.00	\$1,555.10	100.00	\$0.00	Replace	Repair
		75850479 10	MOULDING ASSY, BODY ROCKER PANEL, RH	1.00	\$576.00	100.00	\$0.00	Replace	Repair
		67001471 52	PANEL SUB-ASSY, FRONT DOOR RH	1.00	\$1,249.60	100.00	\$0.00	Replace	Repair
			STICKER DECAL SMRT (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		87910474 50	MIRROR ASSY, OUTER REAR VIEW, RH	0.00	\$1,373.50	0.00	\$0.00	Replace	Not Given
		87940474 40	COVER, OUTER MIRROR, RH	1.00	\$89.50	100.00	\$0.00	Replace	Repair
Total					\$6,660.50		\$99.68		

99.68
+ 500.00
+ 650.00
1249.68