



WTS Engineering Pte Ltd

8 Gul Circle, Singapore 629564 Tel: 65598984 Fax: 68622163
Company Registration Number: 200505706E

Quotation

DATE: 03/04/19
VEHICLE NO: XD7925E
DRIVER: SAMBANTHAM DHATCHINAMOORTHY
ATTENTION TO:
PREPARED BY: Chan Soo Lye

LOCATION: Gul Workshop
Q REF No: Q19/04/1005
DEPARTMENT: WTS Log Prime Mover
ACCIDENT DATE: 02/04/19
REF No: JW-0419-271

- Leas Auto Consultants
the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

S/N	Description	Qty	Cost per Unit	Amount S\$
Spare Parts				
1	FRONT WINDSCREEN GLASS	1	637.15	637.15
2	RETAINING SECTION	1	19.5	19.50
3	RUBBER STRIP	1	54.45	54.45
4	MIRROR TRIM GREY COVER	1	104.25	104.25
5	TRIM RIGHT OUTER	1	31.8	31.80
6	COVERING HINGE RIGHT	1	11.7	11.70
7	FRONT BUMPER	1	2243.1	2,243.10
Labour Costs				
1	TO DISMANTLE AND REFIT FRONT WINDSCREEN (CRACKED)	1	300	300.00
2	TO REMOVE AND REFIT FRONT BUMPER, HEAD LAMP AND RHS MIRROR COVER,	1	450	450.00
Spray Paint				
1	Spray Painting TO SPRAY PAINTING FRONT BUMPER. <i>1st panel.</i>	1	350	350.00
TOTAL:				4,201.95
Total Amount				SGD 4,201.95

Remarks:

Signature of Workshop Dpt

Signature of Department Head

Signature of Claim Department

Surveyor Sign:	<i>Taufik</i>
Surveyor Name:	Taufik
Date:	5/4/19