



WTS Engineering Pte Ltd

From : Workshop Department

M/S : WTS Logistics & Trading Pte Ltd

Date : 16-May-19

No: 0519/1022

No 8 Gul Circle

Singapore 629564

S/n	Description	Unit	Amount
	Repair cost of XD7925E Accident Date: 02/04/2019 Repair works took 5 days Lumpsum repair inclusive of labour charges and spray painting		\$ 3,850.00
	Add 7% GST		\$ 269.50
	SGD: Four Thousand One Hundred Nineteen & Cents Fifty Only		
	Total		\$ 4,119.50

Authorized Signature

WTS Engineering Pte Ltd

8, Gul Circle, Singapore 629564 Tel: 6 559 8988 Fax: 6 898 2394

URL: www.woodlandstransport.com.sg

Company Registration Number : 200505706E

