

VOLKSWAGEN CENTRE SINGAPORE

Tuas Avenue
639176 Singapore
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/2

Company
Lonpac Insurance BHD
101 Thomson Road
307591 Singapore

Customer data:
Mr
NG
YEW CHOON MARVIN
13 DOVER CLOSE EAST
130013 Singapore

Document no.
Document date 03-04-2019
Customer no. 5211043801
Customer GST-ID
Dealer 39999
Job order number 2019000074/ 1
Job order date 03-04-2019
Service Advisor MEI KWAN KONG

License plate	Model code	First registration	VIN	Model	Mileage
SX9999H	1622G5		WWWZZZ16ZEM027470	Jetta TSI Trend 90 D7F	47,982

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
5C6807217 GRU	Cover	1	pcs.	510.40	#1	510.40	546.13
	BUMPER COVER FRT						
5C6807665	Plastic Foam	1	pcs.	19.71	#1	19.71	21.09
5C6805706D	Guide	1	pcs.	101.32	#1	101.32	108.41
	BUMPER CENTRE GUIDE						
5C6807109C	Bumper Bracket	1	pcs.	634.44	#1	634.44	678.85
	BUMPER FRT REINFORCEMENT						
5C6807248A	Foam Insert	1	pcs.	99.69	#1	99.69	106.67
	BUMPER FOAM INSERT LH						
5C6807248B	Foam Insert	1	pcs.	99.69	#1	99.69	106.67
	BUMPER FOAM INSERT RH						
5C6823031C	Hood	1	pcs.	592.00	#1	592.00	633.44
5C8823509C	Latch	1	pcs.	78.40	#1	78.40	83.89
5C6823301	Flap Hinge	1	pcs.	115.54	#1	115.54	123.63
	BONNET HINGE LH						
5C6823302	Hinge	1	pcs.	52.80	#1	52.80	56.50
	BONNET HINGE RH						
5C6853651 QWA	Radiator Grille Satin Bla	1	pcs.	449.90	#1	449.90	481.39
5C6805931	Cross Support	1	pcs.	37.32	#1	37.32	39.93
	HEADLAMP BRACE LH						
5C6805932	Cross Support	1	pcs.	37.32	#1	37.32	39.93
	HEADLAMP BRACE RH						
5C6805588D	Carrier	1	pcs.	440.00	#1	440.00	470.80
	LOCK CARRIER						
5C8941005	Twin Halogen Headlamps	1	pcs.	652.57	#1	652.57	698.25
	HEADLAMP LH						
5C8941006	Twin Halogen Headlamps	1	pcs.	652.57	#1	652.57	698.25
	HEADLAMP RH						
	FRONT NUMBER PLATE	1	pcs.	80.00	#1	80.00	85.60
	Supply of Registration Plate						
	LABOUR	6	pcs.	840.00	#1	5,040.00	5,392.80
	SPRAY PAINTING	4	pcs.	800.00	#1	3,200.00	3,424.00
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
	For Diagnostic and Programming						
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
	Harness Repair and Short Circuit Check						

Quotation valid till 2019-04-10

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1		13,653.67	7%	955.76	13,653.67	14,609.43
Total		13,653.67		955.76	13,653.67	14,609.43

VOLKSWAGEN CENTRE SINGAPORE

Tuas Avenue
639176 Singapore
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page	2/2
Document no.	
Document date	03-04-2019
Customer no.	5211043801
Customer GST-ID	
Dealer	39999
Job order number	2019000074/ 1
Job order date	03-04-2019
Service Advisor	MEI KWAN KONG

Company
Lonpac Insurance BHD
101 Thomson Road
307591 Singapore

Customer data:
Mr
NG
YEW CHOON MARVIN
13 DOVER CLOSE EAST
130013 Singapore

License plate	Model code	First registration	VIN	Model	Mileage
SX9999H	1622G5		WWWZZZ16ZEM027470	Jetta TSI Trend 90 D7F	47,982

Customer

Service Advisor

-----VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).-----

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resurvey
Hp 90010068
8 days
12/04/19 @ 1050
Resurvey before paint