

GOLD AUTOWORKS PTE LTD

48 Toh Guan Road East Enterprise Hub #01-119 Singapore 608586

Email : claims@goldautoworks.com.sg Company Reg no. 201716329M

CAR MODEL : YAMAHA YZF-R25

VEH NO: JSQ8225

CHASSIS NO: PMYRG1510J0013060

HP:8199-9149

Estimate Bill

	List Item	Qty	Unit Price	Amount
1	fender, front 1WD-XF151-30-P1 X	1	\$ 245.00	\$ 245.00
2	yamaha logo 1WD-F153-00 X	1	\$ 30.00	\$ 30.00
3	windshield 1WD-F8381-00 X	1	\$ 186.00	\$ 186.00
4	cover, meter 1WD-H3559-00 X	1	\$ 106.30	\$ 106.30
5	body, front upper 1 1WD-F835G-00 ?	1	\$ 215.90	\$ 215.90
6	body cowling sub assy 1WD-XF83F-20-P1 SCA	1	\$ 296.50	\$ 296.50
7	panel, inner 5 RH 1WD-836N-00 ?	1	\$ 141.69	\$ 141.69
8	body front. Under 2 sub assy 1WD-XF83M-20-P1 SCA	1	\$ 376.20	\$ 376.20
9	panel 2 RH 1WD-F835V-00-P0 ?	1	\$ 185.60	\$ 185.60
10	front flasher light assy RH 1WD-H3320-10 X	1	\$ 100.00	\$ 100.00
11	headlight assy 1WD-H4300-00 ?	1	\$ 496.30	\$ 496.30
12	lever RH 1WD-H3922-00 SCA	1	\$ 60.00	\$ 60.00
13	front footrest assy RH 1WD-F7430-00 Bro	1	\$ 110.00	\$ 110.00
14	front crown, handle 1WD-F3435-00 X	1	\$ 600.00	\$ 600.00
15	front fork assy RH 1WD-F3100-00 X	1	\$ 850.00	\$ 850.00
				-10% \$ 3,599.54
	SPECIAL NETT ITEM			
16	rear muffler P9 full system PA	1	\$ 2,000.00	\$ 2,000.00
17	rear view mirror RH X	1	\$ 300.00	\$ 300.00
18	sticker SCA	1	\$ 90.00	\$ 90.00
19	front side stand set SCA (slide)	1	\$ 100.00	\$ 100.00
20	rear side stand set X	1	\$ 100.00	\$ 100.00
21	helmet CRK	2	\$ 100.00	\$ 200.00
22	rear storage box SCA	1	\$ 300.00	\$ 300.00
23	storage box bracket X	1	\$ 200.00	\$ 200.00
				\$ 3,290.00
	Labour			
A	to renew, remove, and refit accident damaged parts	-	\$ 600.00	\$ 600.00
B	to spray painting ? X	-	\$ 600.00	\$ 600.00
C	to check wiring X	-	\$ 80.00	\$ 80.00
D	to remove & repair fork assy X	-	\$ 400.00	\$ 400.00
E	towing charge X	1	\$ 60.00	\$ 60.00
				\$ 1,740.00
	LUMP-SUM			-20%

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068

3 days

4/5

03/04/19 @ 1720

Ready after repair