

Trans-cab Auto Services Pte Ltd

AAD1904-019

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9798G*Not Authored
L15m @ 1550h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 9798G

VF1ABL15AUC277292

RENAULT

LATITUDE

29.3.2019

CHINA TAIPING

14/4/2014

PART		LIST	
1	DOOR PANEL FRT LH	\$	<i>N</i> 2,844.66
1	DOOR HINGE UPPER LH	\$	<i>N</i> 261.28
1	DOOR HINGE LOWER LH	\$	<i>N</i> 300.55
1	DOOR CHECK FRT LH	\$	<i>SL</i> 194.77
1	DOOR LOCK FRT LH	\$	<i>N</i> 908.75
1	DOOR CATCH FRT LH	\$	<i>SL</i> 131.23
1	DOOR HANDLE OUTER FRT LH	\$	<i>SL</i> 477.76
1	DOOR HANDLE COVER FRT LH	\$	<i>SL</i> 13.22
1	DOOR HANDLE MODULE FRT LH	\$	<i>SL</i> 133.60
1	DOOR REGULATOR FRT LH	\$	<i>SL</i> 505.19
1	DOOR REGULATOR MOTOR FRT LH	\$	<i>SL</i> 796.46
1	DOOR REGULATOR GUIDE FRT LH	\$	<i>SL</i> 120.97
1	DOOR PANEL REAR LH	\$	<i>N</i> 2,844.66
1	DOOR GUIDE REAR LH	\$	<i>SL</i> 176.82
1	DOOR HINGE UPPER LH	\$	<i>N</i> 274.50
1	DOOR HINGE LOWER LH	\$	<i>N</i> 300.55
1	DOOR CHECK REAR LH	\$	<i>SL</i> 203.06
1	DOOR LOCK REAR LH	\$	<i>N</i> 908.75
1	DOOR HANDLE OUTER REAR LH	\$	<i>SL</i> 126.49
1	DOOR HANDLE CAP REAR LH	\$	<i>SL</i> 35.52
1	DOOR HANDLE SEAL REAR LH	\$	<i>SL</i> 7.89
1	DOOR HANDLE COVER REAR LH	\$	<i>SL</i> 13.22
1	DOOR HANDLE MODULE REAR LH	\$	<i>SL</i> 133.60
1	DOOR REGULATOR REAR LH	\$	<i>SL</i> 1,135.10
1	DOOR REGULATOR MOTOR REAR LH	\$	<i>SL</i> 893.75
1	DOOR REGULATOR NUT REAR LH	\$	<i>SL</i> 12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>SL</i> 6.31
1	DOOR FINISHER REAR LH	\$	<i>SL</i> 423.10
1	DOOR MOULDING REAR LH	\$	<i>SL</i> 176.82
1	DOOR MOULDING CLIP L70Y	\$	<i>SL</i> 5.92

Trans-cab Auto Services Pte Ltd**AAD1904-019**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9798G

1	DOOR MOULDING SCREW L70Y	\$	Sn 6.91	}	X
1	DOOR CASING REAR LH	\$	Sn 1,509.06		
1	DOOR WATER SHIELD REAR LH	\$	Sn 30.39		
1	DOOR CASING CLIP	\$	nn 12.63		
1	DOOR CASING LIGHT L70Y	\$	Sn 48.74		
1	DOOR FINISHER INNER REAR LH	\$	Sn 323.44		
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n 46.97		
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n 20.33		
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n 20.33		
1	DOOR FINISHER BRACKET INNER REAR LH	\$	n 20.33		
1	DOOR GRAB HANDLE REAR LH	\$	Sn 210.96		
1	DOOR BLIND REAR LH	\$	Sn 741.80		
1	DOOR WHEATHESTRIIP REAR LH	\$	Sn 410.66		
1	DOOR SEAL REAR LH	\$	Sn 162.02		
1	DOOR GLASS RUNNER SEAL REAR LH	\$	Sn 229.31		
1	DOOR WAIST SEAL OUTER REAR LH	\$	Sn 334.69		
1	DOOR WAIST SEAL INNER REAR LH	\$	Sn 115.64		
1	FENDER PANEL REAR LH	\$	n 3,299.13		
1	FENDER PANEL INNER TRIM REAR	\$	Sn 671.45		
1	WHEELARCH REAR LH	\$	Sn 543.47		
1	DOOR MIRROR ASSY LH	\$	CNA 1,483.40		

\$	24,608.59
----	------------------

10% \$	2,460.86
--------	-----------------

\$	22,147.73
----	------------------

Special Nett

1SET	WHEELARCH CLIP FRT LH	\$	nn	30.50	X
1	FRONT DOOR STICKER 'Trans-cab'	\$	nn	80.00	60sn
1	FRONT DOOR STICKER 'Chassis'	\$	nn	50.00	155sn
1	REAR DOOR STICKER '6555 3333'	\$	nn	80.00	X
1	DOOR CHECK BOLT	\$	nn	22.69	} X
1	DOOR GUIDE SCREW	\$	nn	10.85	
1	DOOR HINGE BOLT	\$	nn	10.85	
1	DOOR HINGE NUT RH	\$	sn	14.60	
1	DOOR CHECK BOLT	\$	sn	22.69	
1	DOOR CHECK NUT	\$	sn	3.75	
1	DOOR LOCK SCREW L70Y	\$	sn	6.12	
1	DOOR CATCH SCREW L70Y	\$	sn	10.06	

Trans-cab Auto Services Pte Ltd

AAD1904-019

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9798G

TOTAL	\$	342.13
TOTAL PARTS	\$	22,489.86

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00	2001
To apply paint protection system (PPS) maintain and enhancement	\$	380.00	nn X
Putty and spray painting of the affected portion.	\$	3,000.00	2801
To rust-proofing of the affected areas.	\$	170.00	nn X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	nn X
To check steering geometry and computer wheel alignment	\$	220.00	nn X
To transfer of tire, rim and on wheel balancing.	\$	170.00	nn X
To Check Electrical Lighting Concerned.	\$	170.00	201
To Transfer Of Door Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	nn X

TOTAL \$ 7,660.00**Over All Total \$ 30,149.86****LUMP SUM(REPAIR DAY)****10 DAYS****2 days**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: