

Survivor: Marcus

ASSIGNMENT (Office)

CWS

From (Person): Eileen Lee

of

FC1

Date/Time: 4.4.19 3.07 p.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLV 2911E

Insured:

SHD 6838 U

at Workshop m/s Trans Eurokars

Tel:

91277928

of 5 Ubi Close

Policy No:

Claim No: D19002295 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 3.4.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time: 4.4.19 3.05pm

Person Contacted:

Jecs

Vehicle IN/OUT

Date/Time Action/Instruction (✓) Estimate.

SLV 2911E - x

SHD 6838 U - x

12.4.2019 - Vn1 - Ronald

24/4@10.55am - revised preli advise via email.

Surveyor

ASSIGNMENT

From: Date: 22/4/19

Estimated Cost:

OD (TP/WS/TP RES/OD RES/EVA/INV/MV)

To inspect Vehicle No: SLU 2911E
at Workshop m/s: Trans Burkers
of: 5 ubi close

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

3pm
Donald

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

up

LA 5-4094

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SLU 2911E Yr Regn: 11.17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA/

Make: mazda 5

C.C.

1998

Colour: white

A/C: Insured / Std / NI / NA

Sp. Reading: 37634

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Rear

R/Bal.

L/Bal.

D.O.I.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
7/6/19	confirmed final by #5612-88 with Catherine. (Red. 9430.61, 62%)
RECEIVED 10 JUN 2019	

Date/Time, File Pass to?

1/16 Typst

Date/Time, File Return to?

2)

Report Format:

Lump Sum / (B): (\$ 5612.86)

Days Of Repair: 7

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

5x15: 75

170 + 75

50

50

48

393



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D19002295MFSH

Date: 24/4/2019

Our Ref: CS/FCI19005984/Utd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLU 2911E

Please be informed that we had conducted the inspection of the abovementioned vehicle 22/4/2019 at the premises of M/s Trans Eurokars have the following to report: -

Workshop Estimate Amount	: S\$ 15,043.47
Revised Estimate Amount	: S\$ 5,473.00
"Check" Items Amount	: S\$ 152.19
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the
Rear portion.



Comments/ Present Status:
Damages Consistent.

Yours faithfully
Marcus
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	04-04-2019	Our Ref No. D19002295MFSH
Accident Date	03-04-2019	Claim Type. Third Party
Insured Vehicle	SHD6838U	Third Party Vehicle. SLU2911E
Survey Location	5 UBI CLOSE	
Contact Person.	RONALD YAP	
Contact No.	63958899/ 91277928	Fax No. 0
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS EUROKARS PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 24 April 2019 10:55 AM
To: Admin-D (LKKAUTO); 'CWS Motor Claims'; assignments
Cc: 'Eileen Lee'; SUR
Subject: RE: SURVEY ASSESSMENT - D19002295MFSH/1
Attachments: PRELI ADVISED SLU 2911E.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SLU 2911E**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 4 April 2019 3:15 PM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Eileen Lee' <EileenLee@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D19002295MFSH/1

Dear Sir / Mdm,

Thank you for the assignment.

Please be informed vehicle not in the workshop, repairer will arrange.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Thursday, 4 April, 2019 3:07 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Eileen Lee <EileenLee@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D19002295MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

F



ANNOUNCING Speedo Motoring

as sgCarMart Premium Dealer for the 8th Consecutive Year

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

MINI Cooper S 1.6 AT With Very Low Mileage.



Immaculate Condition, Car Is
Rarely Used. Original Mini
Accessories.
Direct Owner StarAd



Browse by Category ▾

Sort by Date Posted

10 vehicles

Mazda 5

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	V
Search Selection	Mazda	5	Any	Any	2017	Any	Any	
	Mazda	5 2.0A Sunroof	\$85,800	\$9,730 /yr	16-Feb-2017	1,998 cc	-	
Low Interest Rate From 1.99% For Limited Period Only! In House Loan Available, 1 Owner Only! Maintain By Mazda With Warranty Till f It From Us With A Peace Of Mind, A Company Accredited Wi...								
Dickson Automobile								
Posted: 22-Apr-2019 Tags: 2017 Mazda 5, 2017 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda								
	Mazda	5 2.0A Sunroof	\$88,000	\$9,150 /yr	29-Dec-2017	1,998 cc	29,800 km	
Enjoy Loan Interest Rate At 2.28% Financing Possible. Trade In Welcome. 100% Accident-Free. Well Maintained, View To Believe. Don't White Beauty, Call/SMS To Arrange A Viewing Now Viewing St...								
Posted: 21-Apr-2019 Tags: 2017 Mazda 5, 2017 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda								
	Mazda	5 2.0A Sunroof	\$88,800	\$9,540 /yr	12-Sep-2017	1,998 cc	-	
1 Owner, Well Maintained, Accident Free, Full Mazda Service, Attractive Interest Rate Of 2.28% Available, Trade In Welcome, Strictly By Only								
Posted: 10-Apr-2019 Tags: 2017 Mazda 5, 2017 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda								
	Mazda	5 2.0A Sunroof	\$91,800	\$10,100 /yr	01-Jun-2017	1,998 cc	34,591 km	
\$2,000 Republic Auto Warranty Workshop Credits, 7 Seaters MPV, Vehicle Warranty By Eurokars, Maintained And Service By Agent! Low Usage, Well Kept By Owner, Good Valve, Call For Viewing Or Wha...								
Republic Auto								
Posted: 02-Apr-2019 Tags: 2017 Mazda 5, 2017 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda								
	Exterior Premium Package (Small Vehicle)							
Premium package polishing and coat sealant. Call us to find out more on our different packages.								
Find out more!								
	Mazda	5 2.0A Sunroof	\$93,800	\$10,150 /yr	08-Sep-2017	1,998 cc	18,000 km	
Nice Number 1151. Well Maintain Seldom Drive With Low Mileage. Accident Free Car. Second Family Car For Sales. Under Warranty By f MPV. Original Condition With Well Maintained Ex...								
ed: 02-Apr-2019 Tags: 2017 Mazda 5, 2017 mazda 5, Mazda 5, mazda 5, Mazda, 5, Used Mazda								

Compare

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9296D
Vehicle Details	
Vehicle No.:	SLU2911E
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Apr 2019
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA5 WAGON 2.0 AT EU6
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	PE10527459
Chassis No.:	JM6CW1071H0126708
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$17,116.00
Original Registration Date:	28 Nov 2017
First Registration Date:	28 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$17,116.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Nov 2027
PARF Rebate Amount:	\$12,837.00
Intended COE Rebate Details	
COE Expiry Date:	27 Nov 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$48,005.00
COE Rebate Amount:	\$41,257.00
Total Rebate Amount:	\$54,094.00

The information contained herein is correct as at 23 Apr 2019

OK



TRANS EUROKARS PTE LTD

EUROKARS GROUP

ESTIMATE COST OF REPAIRS

FIRST CAPITAL INSURANCE LTD		NAME : Mr Lee Yew Weng		WIP : 48216	
36 ROBINSON ROAD		ADDRESS : Blk 23 Pasir Ris Grove		EXCESS :	
#16-01 CITY HOUSE		#12-42		DATE : 3-Apr-19	
SINGAPORE 068877		Singapore 518071			
ATTN. : MOTOR CLAIMS		TEL : 91763472			
FAX :					
VEH NO :	SLU2911E	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6CW1071H0126708	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDAS	DATE REG.:	28-Nov-17	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY		REVISED	PRICES	
1	1	MC513-50-221EBB	20/02	\$ - 961.20	
2	1	MC235-56-B9XC	Ref	\$ - 155.40	
3	4	MBHN1-50-021A	Ref	\$ - 10.80	
4	2	MC235-50-ES1	Ref	\$ - 9.40	
5	2	MGD7A-50-EA1	Ref	\$ - 6.40	
6	4	MBN8F-50-355	Ref	\$ - 22.80	
7	2	MG043-62-864A	Ref	\$ - 7.00	
8	1	MCG15-70-750B	Ref	\$ 515.70	
9	1	MC513-68-89XD	Ref	\$ 80.40	
10	1	MC513-68-894A	Ref	\$ 13.70	
11	8	MGJ21-68-885B02	Ref	\$ 24.00	
12	1	MCGY3-62-02XF	Ref	\$ 1,637.00	
13	2	MTK48-62-864	Ref	\$ 14.80	
14	5	MGJ21-68-885B02	Ref	\$ 15.00	
15	1	MC513-62-310A	Ref	\$ 256.20	
16	1	MD652-62-361	Ref	\$ 57.90	
17	1	MCGY0-51-711	Ref	\$ 45.30	
18	1	MCGY0-51-721	Ref	\$ 36.30	
19	1	MC597-51-771	Ref	\$ 80.00	
20	1	MC513-50-611	Ref	\$ 60.50	
21	1	MDJ01-50-897	Ref	\$ 7.20	
22	2	MC273-50-896	Ref	\$ 16.40	
23	4	MGJ6A-50-897	Ref	\$ 51.20	
24	1	MG21E-63-938B	Ref	\$ 11.10	
25	6	MD204-50-896A	Ref	\$ 16.80	
26	2	MC514-51-979B	Ref	\$ 11.00	
27	2	MC514-51-982B	Ref	\$ 24.00	
28	2	MC514-51-972B	Ref	\$ 28.20	
29	3	MC514-51-958A	Ref	\$ 23.10	
30	1	MC525-51-958A	Ref	\$ 8.70	

31	GASKET LHS, TAILGATE LAMP	1	MC513-51-3J8	net	\$ 95.40
32	GASKET RHS, TAILGATE LAMP	1	MC513-51-3H8	net	\$ 95.40
TOTAL PARTS					\$ 4,398.30
LESS 10%					\$ 439.83
TOTAL PARTS COST					\$ 3,958.47

Labour Description

1	MZ-BR-REAR06	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL AND TAILGATE. TO REPAIR REAR FLOOR PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.	660	1650	\$ 3,960.00
2	MZ-SP-SREAR6	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, REAR FLOOR PANEL AND TAILGATE.	630	1890	\$ 2,835.00
3	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	11X	NETT	\$ 560.00
4	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	MX	NETT	\$ 120.00
5	MZ-BR-TAILME	TO TRANSFER TAILGATE MECHANISM.	11X	NETT	\$ 330.00
6	MZ-BR-REVSEN	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)	200	NETT	\$ 660.00
7	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.	11X	NETT	\$ 330.00
8	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.		200	\$ 990.00
9	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING	11	X	\$ 350.00
10	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.	11	X	\$ 250.00
11	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		120	\$ 250.00
12	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		150	\$ 350.00
13	MZ-BR-SUNDRI	SUNDRIES.	net 30	NETT	\$ 100.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

REMARKS:

TOTAL LABOUR	\$ -	\$ 11,085.00
TOTAL PARTS	\$ -	\$ 3,958.47
TOTAL	\$ -	\$ 15,043.47
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

TRANS EUROKARS PTE LTD



TRANS EUROKARS PTE LTD



FINALISED COST OF REPAIRS

FIRST CAPITAL INSURANCE LTD		NAME : Mr Lee Yew Weng		WIP : 48216	
36 ROBINSON ROAD		ADDRESS : Blk 23 Pasir Ris Grove		EXCESS :	
#16-01 CITY HOUSE		#12-42		DATE: 3-Apr-19	
SINGAPORE 068877		Singapore 518071			
ATTN. : MOTOR CLAIMS		TEL : 91763472			
FAX :					
VEH NO :	SLU2911E	DATE IN :		CONTACT PERSON :	Ronald 63957875
CHASSIS NO :	JM6CW1071H0126708	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY CLAIM
MODEL :	MAZDA5	DATE REG.:	28-Nov-17	POLICY NO. :	
NATURE OF WORKS					
Parts Description					
NO	QTY			REVISED	PRICES
1	REAR BUMPER	1	MC513-50-221EBB	\$ 961.20	\$ 961.20
2	REAR REINFORCEMENT	1	MC235-56-B9XC	\$ 155.40	\$ 155.40
3	GROMMET, REAR BUMPER	4	MBHN1-50-0Z1A	\$ 10.80	\$ 10.80
4	GROMMET, REAR BUMPER	2	MC235-50-ES1	\$ 9.40	\$ 9.40
5	FASTENER, REAR BUMPER	2	MGD7A-50-EA1	\$ 6.40	\$ 6.40
6	RIVET, REAR BUMPER	4	MBN8F-50-355	\$ 22.80	\$ 22.80
7	TAPE PROTECTOR, REAR BUMPER	2	MG043-62-864A	\$ 7.00	\$ 7.00
8	REAR END PANEL	1	MCG15-70-750B		\$ 515.70
9	TRIM, END PANEL	1	MC513-68-89XD		\$ 80.40
10	BEZEL, LOCK	1	MC513-68-894A		\$ 13.70
11	FASTENER, TRIM	8	MGJ21-68-885B02		\$ 24.00
12	TAILGATE	1	MCGY3-62-02XF		\$ 1,637.00
13	TAPE PROTECTOR, TAILGATE	2	MTK48-62-864		\$ 14.80
14	FASTENER, TAILGATE	5	MGJ21-68-885B02		\$ 15.00
15	LOCK, TAILGATE	1	MC513-62-310A		\$ 256.20
16	STRIKER, LOCK	1	MD652-62-361		\$ 57.90
17	ORNAMENT, MAZDA	1	MCGY0-51-711	\$ 45.30	\$ 45.30
18	ORNAMENT, S	1	MCGY0-51-721	\$ 36.30	\$ 36.30
19	ORNAMENT, SKYACTIVE	1	MC597-51-771	\$ 80.00	\$ 80.00
20	REAR WINDSCREEN MOULDING	1	MC513-50-611		\$ 60.50
21	SPACER, REAR WINDSCREEN	1	MDJ01-50-897		\$ 7.20
22	FASTENER, REAR WINDSCREEN	2	MC273-50-896		\$ 16.40
23	SPACER, REAR WINDSCREEN	4	MGJ6A-50-897		\$ 51.20
24	PIN STUD, REAR WINDSCREEN	1	MG21E-63-938B		\$ 11.10
25	FASTENER, REAR WINDSCREEN	6	MD204-50-896A		\$ 16.80
26	PROTECTOR, SPOILER	2	MC514-51-979B		\$ 11.00
27	PROTECTOR, SPOILER	2	MC514-51-982B		\$ 24.00
28	PROTECTOR, SPOILER	2	MC514-51-972B		\$ 28.20
29	CLIP, SPOILER	3	MC514-51-958A		\$ 23.10
30	CLIP, SPOILER	1	MC525-51-958A		\$ 8.70
31	GASKET LHS, TAILGATE LAMP	1	MC513-51-3J8	\$ 95.40	\$ 95.40

32	GASKET RHS, TAILGATE LAMP	1	MC513-51-3H8	\$ 95.40	\$ 95.40
			TOTAL PARTS	\$ 1,525.40	\$ 4,398.30
			LESS 10%	\$ 152.54	\$ 439.83
			TOTAL PARTS COST	\$ 1,372.86	\$ 3,958.47
Labour Description					
1	MZ-BR-REAR06	TO REPLACE REAR BUMPER, REAR REINFORCEMENT, TO REPAIR REAR FLOOR PANEL , REAR END PANEL, TAILGATE AND ALL AREAS AFFECTED BY THE ACCIDENT.		\$ 1,650.00	\$ 3,960.00
2	MZ-SP-SREAR6	TO RESPRAY REAR BUMPER, REAR REINFORCEMENT, REAR END PANEL, REAR FLOOR PANEL AND TAILGATE.		\$ 1,890.00	\$ 2,835.00
3	MZ-BR-GLASS1	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.			\$ 560.00
4	MZ-BR-GLASS2	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.			\$ 120.00
5	MZ-BR-TAILME	TO TRANSFER TAILGATE MECHANISM.			\$ 330.00
6	MZ-BR-REVSER	TO TRANSFER REVERSE SENSORS. (WITH REVERSE SENSOR)		\$ 200.00	\$ 660.00
7	MZ-BR-CAMERA	TO TRANSFER REVERSE CAMERA.			\$ 330.00
8	MZ-BR-TRIMS2	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.		\$ 200.00	\$ 990.00
9	MZ-BR-SEALER	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING			\$ 350.00
10	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.			\$ 250.00
11	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 120.00	\$ 250.00
12	MZ-BR-REPROG	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		\$ 150.00	\$ 350.00
13	MZ-BR-SUNDRI	SUNDRIES.		\$ 30.00	\$ 100.00
			TOTAL LABOUR	\$ 4,240.00	\$ 11,085.00
			TOTAL PARTS	\$ 1,372.86	\$ 3,958.47
			TOTAL	\$ 5,612.86	\$ 15,043.47
			LESS EXCESS	\$ -	\$ -
			TOTAL AFTER EXCESS	\$ 5,612.86	
			GST 7%	\$ 392.90	\$ -
			GRAND TOTAL	\$ 6,005.76	\$ -

REMARKS:

7 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI19005984/Utd3n2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 11-06-2019		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 6838U	Veh. Inspected	SLU 2911E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002295MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	04/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 5 (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6CW1071H0126708	Colour	WHITE	
Odometer	37634	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	TOYO	6 mm	
L/H Front Tyre	205/55 R16	TOYO	6 mm	
R/H Rear Tyre	205/55 R16	TOYO	6 mm	
L/H Rear Tyre	205/55 R16	TOYO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	03/04/2019	Inspection Date	22/04/2019	
Survey held at	TRANS EUROKARS PTE LTD NO 5 UBI CLOSE SINGAPORE 408605			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 2911E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED / DEFORMED	961.20	961.20
1	REAR REINFORCEMENT	BENT	155.40	155.40
4	GROMMET, REAR BUMPER	NECESSARY	10.80	10.80
2	GROMMET, REAR BUMPER	NECESSARY	9.40	9.40
2	FASTENER, REAR BUMPER	NECESSARY	6.40	6.40
4	RIVET, REAR BUMPER	NECESSARY	22.80	22.80
2	TAPE PROTECTOR, REAR BUMPER	NECESSARY	7.00	7.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	515.70	-
1	TRIM, END PANEL	NOT NECESSARY	80.40	-
1	BEZEL, LOCK	NOT NECESSARY	13.70	-
8	FASTENER, TRIM	NOT NECESSARY	24.00	-
1	TAILGATE	TO REPAIR SEE LABOUR	1,637.00	-
2	TAPE PROTECTOR, TAILGATE	NOT NECESSARY	14.80	-
5	FASTENER, TAILGATE	NOT NECESSARY	15.00	-
1	LOCK, TAILGATE	NOT NECESSARY	256.20	-
1	STRIKER, LOCK	NOT NECESSARY	57.90	-
1	ORNAMENT, MAZDA	NECESSARY	45.30	45.30
1	ORNAMENT, 5	NECESSARY	36.30	36.30
1	ORNAMENT, SKYACTIVE	NECESSARY	80.00	80.00
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	60.50	-
1	SPACER, REAR WINDSCREEN	NOT NECESSARY	7.20	-
2	FASTENER, REAR WINDSCREEN	NOT NECESSARY	16.40	-
4	SPACER, REAR WINDSCREEN	NOT NECESSARY	51.20	-
1	PIN STUD, REAR WINDSCREEN	NOT NECESSARY	11.10	-
6	FASTENER, REAR WINDSCREEN	NOT NECESSARY	16.80	-
2	PROTECTOR, SPOILER	NOT NECESSARY	11.00	-
2	PROTECTOR, SPOILER	NOT NECESSARY	24.00	-
2	PROTECTOR, SPOILER	NOT NECESSARY	28.20	-
3	CLIP, SPOILER	NOT NECESSARY	23.10	-

Report Ref No. CS/FCI19005984/Utd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	CLIP,SPOILER	NOT NECESSARY	8.70	-
1	GASKET LHS,TAILGATE LAMP	NECESSARY	95.40	95.40
1	GASKET RHS,TAILGATE LAMP	NECESSARY	95.40	95.40
	LESS 10% DISCOUNT		-439.83	-152.54
			3,958.47	1,372.86
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
			100.00	30.00
	<u>LABOUR</u>			
	TO REPLACE REAR BUMPER,REAR REINFORCEMENT,REAR END PANEL AND TAILGATE.TO REPAIR REAR FLOOR PANEL AND ALL AREAS AFFECTED BY THE ACCIDENT.		3,960.00	1,650.00
	TO RESPRAY REAR BUMPER,REAR REINFORCEMENT,REAR END PANEL,REAR FLOOR PANEL AND TAILGATE.		2,835.00	1,890.00
	TO REMOVE & REFIT THE WINDSCREEN GLASS AND CONDUCT WATER LEAK TEST.	NOT NECESSARY	560.00	-
	TO SUPPLY SEALER ON THE WINDSCREEN GLASS.	NOT NECESSARY	120.00	-
	TO TRANSFER TAILGATE MECHANISM.	NOT NECESSARY	330.00	-
	TO TRANSFER REVERSE SENSORS (WITH REVERSE SENSOR).		660.00	200.00
	TO TRANSFER REVERSE CAMERA.	NOT NECESSARY	330.00	-
	TO REMOVE & REFIT CARPET & TRIMS ON THE REAR SECTION TO GIVE WAY TO THE REPAIR ON THE REAR SECTION.		990.00	200.00
	TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CUTTING.	NOT NECESSARY	350.00	-
	TO CARRY-OUT BODY CAVITY PRESERVATION.	NOT NECESSARY	250.00	-
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	120.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	150.00
			10,985.00	4,210.00
	GRAND TOTAL		15,043.47	5,612.86

Report Ref No. CS/FCI19005984/Utd3n2



RECOMMENDED COST OF REPAIRS			5,612.86
-----------------------------	--	--	----------

Report Ref No. CS/FCI19005984/Utd3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.