

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: AXA INSURANCE S'PORE PTE LTD 8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811	Document No.	: SQT19001502	Page	1
Registration No	: SDJ5354X	Date	: 3. Apr 2019		
Chassis No	: JHMGK5850HX200412	Customer No.	: WZA006		
Model	: JAZZ 1.5VTIR CVT 17YM	Svc Advisor	: ANIKKA LAI SWEE KAM		
Owner's Name	: TAY NOOI CHENG	Engine No	: L15B31190259		
Ins Policy No.	:	Date Time	: 3. Apr 2019 4:51:24 PM		
Date of Accident	: 1/4/2019	Surveyor Name	:		
		Survey Date	:		
		Authorisation Date	:		

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: TAY NOOI CHENG OWNER INSURER: LIBERTY ACC DATE: 01/04/2019 SURVEYED BY: DATE: REF NO: TP INSURER: AXA TP VEH: SKK3818A						
04636-TAS-300ZZ	PANEL SET,R.RR.OUTSIDE	1	548.30	25	411.22	28.79	440.01
67510-T5A-N10ZZ	PANEL COMPR.RR.DOOR	1	717.50	25	538.12	37.67	575.79
67825-T5A-003	TAPER.RR.DOOR SASH	1	15.40	25	11.55	0.81	12.36
72910-T5A-003	MOLDING ASSYR.RR.DOOR	1	33.60	25	25.20	1.76	26.96
71800-T5B-J11ZV	GARNISH ASSY,R.SIDE	1	370.80	25	278.10	19.47	297.57
04715-T5B-J50ZZ	FACE,RR.BUMPER	1	502.50	25	376.87	26.38	403.25
71593-T5A-J50	SPACER,R.RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
71598-T5A-J50	SPACER,L.RR.BUMPER SIDE	1	16.90	25	12.67	0.89	13.56
91505-TM8-003	CLIP,BUMPER	1	2.30	25	1.72	0.12	1.84
42700-TAR-E91	DISK ALUMINIUM WHEEL,16X6	1	772.30	25	579.22	40.55	619.77
				Sum Item	2247.34	157.33	2,404.67
BOSUN	SUNDRIES	1	100.00		100.00	7.00	107.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	100.00		100.00	7.00	107.00
BG52D	REMOVE & INSTALL RR. R QTR GLASS.(N)	1	280.00		280.00	19.60	299.60
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	560.00		560.00	39.20	599.20
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	120.00		120.00	8.40	128.40
BKDR22R	REMOVE & TRANSFER ITEMS TO NEW RR R DR. ADJUST	1	560.00		560.00	39.20	599.20
GSG96R	REPLACE RIMS WITH TYRES	1	100.00		100.00	7.00	107.00

Printed on 3/4/2019 5:10:37 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SDJ5354X
Chassis No : JHMGK5850HX200412
Model : JAZZ 1.5VTIR CVT 17YM
Owner's Name : TAY NOOI CHENG
Ins Policy No. :
Date of Accident : 1/4/2019

Document No. : SQT19001502 **Page** 2
Date : 3. Apr 2019
Customer No. : WZA006
Svc Advisor : ANIKKA LAI SWEE KAM
Engine No : L15B31190259
Date | Time : 3. Apr 2019 4:51:24 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BKFE22R	CUT & RENEW RR R FENDER. STRAIGHTEN INNER PANEL	1	3000.00		3000.00	210.00	3210.00
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P)	1	3000.00		3000.00	210.00	3210.00
Sum Labor					7820.00	547.40	8,367.40

Survey By

Date & Time

Excess

Status

Signature

Total Amount 10,067.34 704.73 10,772.07

Total (Inclusive of GST) **10,772.07**

Printed on 3/4/2019 5:10:37 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.