



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI19005993/Jsd3s2	
			Date: 20/06/2019	
			Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 7393J	Veh. Inspected	PC 3425H	
Policy No.		Coverage (\$)	0.00	
Claim No.	D19002196MFSH	Excess (\$)	0.00	
Assign From	SITHARA	Assign Date	04/04/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MITSUBISHI ROSA	c.c	2998	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	BE641JK30017	Colour	WHITE	
Odometer	377505 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/75 R17.5	LANDY TIRE	7 mm	
L/H Front Tyre	215/75 R17.5	LANDY TIRE	7 mm	
R/H Rear Tyre	215/75 R17.5 (D)	LANDY TIRE	7/7 mm	
L/H Rear Tyre	215/75 R17.5 (D)	LANDY TIRE	7/7 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	29/03/2019	Inspection Date	08/04/2019	
Survey held at	CROWN ASIA BUS BUILDER PTE LTD NO. 44 SUNGEI KADUT STREET 1 SINGAPORE 729349			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>5 Working Days</b>	