



CROWN ASIA BUS BUILDER PTE LTD

44 SUNGEI KADUT AVE, SINGAPORE 729667
Tel : +65 6467 0956 (112) Fax : +65 6469 4319
Email : claims@crownasia.com.sg
Company Reg No: 201023449R

2 April 2019

To: MS First Capital Insurance Limited

BY EMAIL ONLY

(motor_claims@msfirstcapital.com.sg)

Attn: Motor Claims Dept.

Dear Sirs,

We are instructed by M/s RUI FENG CHARTERED PTE LTD to notify you of a road traffic accident on 29/03/2019 at about 0805 hours along Ewe Boon Road involving our customer's bus, PC3425H and your insured's taxi SHC7393J. A copy of the Singapore Accident Statement report is enclosed.

As a result of the accident, our customer's vehicle has been damaged. Before we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, we shall proceed to repair the vehicle without further reference to you.

Please contact our PIC Mr. Jayden at 87511688 for the survey.

Kindly provide to us your list of 10 surveyors for us to choose as SJE.

Yours faithfully

Encl.



Hwee Jie - LKK

8/4/19

hweejie@lkkauto.com

**CROWN ASIA BUS BUILDER PTE. LTD.** (UEN:201023449R)

44 Sungei Kadut Avenue Singapore 729667
Tel: (65) 6469 3319, Fax: (65) 6902 6758
GST ID No : 201023449R

Repair Estimate**No. : QT-000036**

MS FIRST CAPITAL INSURANCE LIMITED

6 Raffles Quay,
Singapore 048580

Your Ref. :

Our D/O No. :

Terms : C.O.D.

Date : 10-04-2019

Page : 1 of 2

TEL :

FAX :

Item	Tax Code	Description	Qty	UOM	U/ Price S\$	Disc. S\$	Total S\$
ZR		Traffic accident on 29/03/2019 involving PC3425H and SHC7393J along Ewe Boon Road.					
<u>Parts Required:</u>							
1.	ZR	SIDE SIGNAL LAMP <i>CRA ✓</i>	3.00		80.00		240.00
	SR	SubTotal					240.00
2.	ZR	LESS 10% TRADE DISCOUNT	1.00		-24.00		-24.00
<u>Net Item:</u>							
3.	ZR	STICKER EXCURSION <i>rel ✓</i>	1.00		20.00		20.00
<u>Labour Charges:</u>							
4.	ZR	LABOUR CHARGES 1. TO CHECK ALL THE WIRING OF SIGNAL LAMP, DOOR AND OTHER AFFECTED AREA	1.00		200.00		<i>50</i> 200.00
5.	ZR	LABOUR CHARGES 2. TO KNOCK AND REPAIR, PUTTY AND SPRAY ON LEFT HAND SIDE REAR, CENTER, DOOR AREA AND ALL AFFECTED ACCIDENT PARTS (TWO COLOUR PAINT)	1.00		2,850.00		<i>1600</i> 2,850.00

NOTE: THIS ESTIMATE IS BASED ON VISIBLE DAMAGE ONLY. SHOULD ANY HIDDEN PARTS AND/OR LABOUR CHARGES REQUIRED DURING WORKS IN PROGRESS, IT WILL BE NOTIFIED ACCORDINGLY.

PRICE QUOTED IS SUBJECTED TO 7% GST

**CROWN ASIA BUS BUILDER PTE. LTD.** (UEN:201023449R)

44 Sungei Kadut Avenue Singapore 729667

Tel: (65) 6469 3319, Fax: (65) 6902 6758

GST ID No : 201023449R

Repair Estimate

No. : QT-000036

MS FIRST CAPITAL INSURANCE LIMITED

6 Raffles Quay,
Singapore 048580

Your Ref. :

Our D/O No. :

Terms : C.O.D.

Date : 10-04-2019

Page : 2 of 2

TEL :

FAX :

Item	Tax Code	Description	Qty	UOM	U/ Price Disc. S\$	Total S\$
------	-------------	-------------	-----	-----	--------------------------	--------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE DOLLAR THREE THOUSAND TWO HUNDRED EIGHTY SIX ONLY

Sub Total (Excluding GST) **3,286.00**GST payable @ 7% on 0.00 **0.00**Total (Inclusive of GST) **3,286.00**

Notes :

1. All cheques should be crossed and made payable to CROWN ASIA BUS BUILDER PTE. LTD.
2. Goods sold are neither returnable nor refundable. Otherwise a cancellation fee of 20% on purchase price will be imposed.

GST Summary

Amount(S\$)

Tax(S\$)

Authorised Signature

18/4/19
Three Re-LKK
15/4/19
L/S Sdaps.