

ASS. INC. BY:

REF:

CC3/ ALG19005990/Atd3nz

Adrian Munnen

ASSIGNMENT

Front: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 1800088209

Claims No. _____

Sum Insured: _____ Excess: \$1600

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 170K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 06/8/19 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMC9171K Yr Regn: 2018, July

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A5 Sportback c.c. 1984

Colour: Black A/C: Insured / Std / Nil / NA

Sp. Reading: 14998 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: WAU222F50JA104599

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F: 245/40 R18

R: 245/40 R18

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 06 mm R/Bal: 06 mm

L/Bal: 06 mm L/Bal: 06 mm

D.O.A. D.O.I. 04/04/19

Survey held at Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front N/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

DD AIG.

SMC9171K - X

5/4 Revert via Munnen

12/4 @ 11:49am - mandate approval by Victor Koh

mv: 12/4 @ 12:30pm - Inform premium Anthrose repair excess \$1600.

PV:

Nett:

RECEIVED 19 JUN 2019

Part by part \$13,188 (Red: 85%, 39%)

Attached DV & Final bill

Date/Time, File Pass to?

Date/Time, File Return to?

1)

2)

3)

4)

5)

6)

Prel. Report:

Final Report:

Part Prices Check:

IN

OUT

Survey Fee:

Date:

Basic & Add.

S + RS, \$

Photos

Others

TOTAL

200

11

5/1

View Received Message

This mail is associated with :

***SMC9171K (0575847244SG)**

OD

Mar 15 2019 11:00AM

[CHOCKALINGAM RAMASAMY]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on 12/04/2019 11:49 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$14585.00) - SMC9171K - Claim Handler: Gan, Hunchung

Approved:14585.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Loh, Chee-Heng

Date: 05 Apr 2019

Preliminary Advice

Vehicle No	: SMC9171K	Accident Date	: 15/03/2019
Make	: AUDI A5	Policy No.	: 888888888
Assignment Date	: 04/04/2019	Excess	: S\$0.00
Date of Inspection	: 04/04/2019	Est. Duration of Repair	: 5.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	21,763.00
Revised Amount	:S\$	14,585.00
Check Items (Estimated)	:S\$	1,165.00
Total	:S\$	15,750.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	170,000.00
COE / PARF Rebate	:S\$	65,833.00
Salvage Value	:S\$	
Margin for Repair	:S\$	104,167.00

Remarks

- (x) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 12 April 2019 12:13 PM
To: Claims; SUR
Subject: RE: OD CLAIM FOR SMC 9171 K

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle SMC 9171K (**Excess \$1,600/-**).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Friday, 5 April 2019 11:19 AM
To: Denise Tay (LKKAuto) <denisetay@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Claims' <claims@premiumauto.com.sg>
Subject: RE: OD CLAIM FOR SMC 9171 K

Hi Denise ,

Noted of details needed.

I have attached the insurance cert for your kind reference.

Best Regards,
Sheila M Ismail
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	7542E
Vehicle Details	
Vehicle No.:	SMC9171K
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Apr 2019
Vehicle Make:	AUDI
Vehicle Model:	A5 SB 2.0 TFSI S TRONIC (DESIGN)
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	CVK062620
Chassis No.:	WAUZZZF50JA104999
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$39,562.00
Original Registration Date:	27 Jul 2018
First Registration Date:	27 Jul 2018
Transfer Count:	0
Actual ARF Paid:	\$47,387.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jul 2028
PARF Rebate Amount:	\$35,540.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jul 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,551.00
COE Rebate Amount:	\$30,293.00
Total Rebate Amount:	\$65,833.00

The information contained herein is correct as at 05 Apr 2019

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	30/03/2019 12:00
Date Of Accident	15/03/2019 11:00
Exact Location Of Accident	SIM LIM TONER
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMC9171K
Insured/Policyholder	
Name Of Registered Owner	CHOCKALINGAM RAMASAMY
NRIC No	S7077542E
Email Address	CHOCKAN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-97967966
Alternative Phone No	OFFICE-97967966

Vehicle Particulars

Manufacturer	AUDI
Model	A5 SB 2.0 TFSI S TRONIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	CHOCKALINGAM RAMASAMY
NRIC No	S7077542E
Date Of Birth	22/09/1970
Occupation	INDOOR
Date Of Driving Pass	15/04/2004
Driving Experience	14 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97967966
Fax Number	
Contact Number	OFFICE-97967966
Email Address	CHOCKAN@GMAIL.COM

Address	APT BLK 372 PASIR PANJANG ROAD #05-16
Postcode	118709
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

WHILE DRIVING UP IN THE SPIRAL CAR PARK BECAUSE OF NARROW LANE, I WAS DRIVING CLOSE TO LEFT SIDE AND KNOCK ON THE PILLAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

Sketch Plan


SKETCH PLAN

IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name: 
NRIC/FIN No.: 



Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While driving up in the spiral carpark because of narrow lane, I was driving close to left side and knock on the pillar.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

C. Panadur

Policyholder's Signature
Date & Time:

C. Panadur

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]



Reporting Centre Personnel's Signature
Name: *Wendy Ewing Standridge*
NRIC/FIN No.: *G1723432*

Accident Photo



REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **S7077542E**

CHOCKALINGAM RAMASAMY

Birth Date: 22 Sep 1970
Issue Date: 17 May 2016

002560076H

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. **S7077542E**

CHOCKALINGAM RAMASAMY

சென இராமசாமி

Race: **INDIAN**
Date of Birth: **22-09-1970** Sex: **M**
Country of birth: **INDIA**

S7077542E

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor cars with unladen weight $\leq 3000\text{kg}$ with ≤ 7 passengers, exclusive of driver; and other motor vehicles with unladen weight $\leq 2500\text{kg}$ **15 Apr 2004**

NP 428A



4804470

NRIC No: S7077542E

Date of Issue: **22-12-2011**

APT BLK 372 PASIR PANJANG ROAD #05-18
SINGAPORE 118709
NRIC No: **S7077542E** Date: **23/03/2016**

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0428/2019/DY
Date	:	4-Apr-19

Vehicle NOT IN workshop.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Chockalingam Ramasamy
Address	:	372 Pasir Panjang Road #05-16 Singapore 118709
Telephone	:	97967966
Type of Claim	:	Own Damage Claims
Policy No.	:	1800088209
Vehicle No	:	SMC 9171 K
Model Code	:	A5 Sportback 2.0 TFSI
Model / Year	:	27/7/2018
Engine No	:	CVK 062620
Chassis No	:	WAUZZZF50JA104999
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	15-Mar-19
Place of Accident	:	Sim Lim Tower

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMC 9171 K

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	s/n \$ 480.00 ✓	✓
2	To dismanttle lhs front door panel trim. To remove and reinstall lhs wing mirror assy.	s/n \$ 300.00 ✗ ✓	✓
3	To dimantle and renew front bumper, lhs front fender and lhs headlight. Re-organize crash management components. Reinstall all pars removed.	\$ 2,100.00 1250 ✓	✓
4	To respray front bumper, lhs front fender and lhs front door. ✗	\$ 2,500.00 1650 ✓	✓
5	To renew lhs front rim and carry out wheel alignment.	s/n \$280.00 ✓	✓
6	To carry out diagnostic check.	s/n \$ 192.00 ✓	✓
TOTAL LABOUR CHARGES		: \$ <u>5,852.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SMC 9171 K**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Rehd</i>	\$ 2,073.00 ✓	1657.40
2	FRONT BUMPER FIXING PARTS <i>Net new</i>	\$ 368.00 + X	80
3	FRONT BUMPER SECURING STRIP <i>Net</i>	\$ 64.00 ✓	50.89
4	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE <i>net 2</i>	\$ 207.00 +	
5	FRONT BUMPER SPOILER <i>Net new</i>	\$ 489.00 +	
6	FRONT AIR GUIDE-LH	\$ 56.00 +	
7	FRONT BUMPER AIR GUIDE GRILLE-LH	\$ 431.00 +	
8	FRONT BUMPER FOAM FILLER PIECE <i>Net new</i>	\$ 113.00 +	
9	FRONT BUMPER CARRIER	\$ 733.00 +	
10	FRONT BUMPER GUIDE SECTION-LH <i>Net</i>	\$ 33.00 ?	26.08
11	FRONT BUMPER SUPPORT-LH/RH <i>Net</i>	2 \$ 52.00 + X	
12	FRONT SENSOR OUTER <i>3 new</i>	\$ 231.00 + X	
13	FRONT SENSOR SEAL RING	4 \$ 12.00 + X	
14	FRONT FENDER-LH <i>Dented</i>	\$ 968.00 ✓	714.40
15	FRONT FENDER ATTACHMENT PARTS-LH <i>Net new</i>	\$ 48.00 ?	
16	FRONT FENDER CLOSING ELEMENT -LH <i>Dmgd</i>	\$ 68.00 ?	53.76
17	FORNT FENDER BRACKET-LH <i>Dmgd</i>	\$ 32.00 —	25.20
18	FRONT FENDER BRACE-LH <i>Best</i>	\$ 107.00 ? ✓	85.60
19	FRONT FENDER DEFORMATION BRACKET-LH <i>Net new</i>	\$ 45.00 ? X	
20	FRONT FENDER UPPER BRACKET-LH <i>Net new</i>	\$ 32.00 ? X	
SUB TOTAL SPARE PARTS		\$ 6,162.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SMC 9171 K**

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remark
21	FRONT FENDER REAR BRACKET-LH <i>new</i>	\$ 53.00	+ X
22	FRONT WHEEL HOUSING LINER-LH <i>new behind</i>	\$ 256.00	+ 204.80
23	FRONT WHEEL SPOILER-LH <i>new cranked</i>	\$ 66.00	+ 52.32
24	FRONT FENDER END PLATE-LH <i>Bent</i>	\$ 32.00	? 25.04
25	FRONT STONE CHIP GUARD-LH <i>new</i>	\$ 48.00	✓ 36.64
26	FRONT FENDER LEDGE COVER-LH <i>3 new</i>	\$ 32.00	- 25.44
27	FRONT FENDER LEDGE TOP COVER-LH <i>new</i>	\$ 14.00	- 11.04
28	FRONT FENDER TRIM-LH <i>new</i>	\$ 145.00	+ 115.60
29	FRONT DOOR TRIM-LH <i>int.</i>	\$ 145.00	+ 115.60
30	LED HEADLIGHT-LH <i>int</i>	\$ 7,204.00	✓ 5763.20
31	FRONT ALUMINIUM RIM-LH <i>new</i>	\$ 943.00	+
32	RUBBER VALVE <i>new</i>	4 \$ 13.00	+
33	SUNDRIES <i>new</i>	\$ 800.00	? 12
TOTAL SPARE PARTS		\$ 15,911.00	
TOTAL LABOUR CHARGES		\$ 5,852.00	
GRAND TOTAL		\$ 21,763.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

old image ←

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adnan King
Surveyed Date : 04/04/19
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 05 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khal@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0428/2019/DY
Date	:	4-Apr-19

Vehicle NOT IN workshop.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

6 days - ok - jb - 18 May 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr. Chockalingam Ramasamy
Address	:	372 Pasir Panjang Road #05-16 Singapore 118709
Telephone	:	97967966
Type of Claim	:	Own Damage Claims
Policy No.	:	1800088209
Vehicle No	:	SMC 9171 K
Model Code	:	A5 Sportback 2.0 TFSI
Model / Year	:	27/7/2018
Engine No	:	CVK 062620
Chassis No	:	WAUZZZF50JA104999
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	15-Mar-19
Place of Accident	:	Sim Lim Tower

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMC 9171 K

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	s/n \$	480.00	\$ 480.00
2	To dismanttle lhs front door panel trim. To remove and reinstall lhs wing mirror assy.	s/n \$	300.00	\$ 300.00
3	To dimantle and renew front bumper, lhs front fender and lhs headlight. Re-organize crash management components. Reinstall all pars removed.	\$	2,100.00	\$ 1,250.00
4	To respray front bumper, lhs front fender and lhs front door.	\$	2,500.00	\$ 1,650.00
5	To renew lhs front rim and carry out wheel alignment.	s/n	\$280.00	\$ 280.00
6	To carry out diagnostic check.	s/n \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	<u>\$ 5,852.00</u>	<u>\$ 4,152.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SMC 9171 K**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER	\$ 2,073.00	\$ 1,658.40
2	FRONT BUMPER FIXING PARTS	\$ 368.00	
3	FRONT BUMPER SECURING STRIP 2	\$ 64.00	\$ 50.88
4	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	\$ 207.00	
5	FRONT BUMPER SPOILER	\$ 489.00	
6	FRONT AIR GUIDE-LH	\$ 56.00	
7	FRONT BUMPER AIR GUIDE GRILLE-LH	\$ 431.00	
8	FRONT BUMPER FOAM FILLER PIECE	\$ 113.00	
9	FRONT BUMPER CARRIER	\$ 733.00	
10	FRONT BUMPER GUIDE SECTION-LH	\$ 33.00	\$ 26.08
11	FRONT BUMPER SUPPORT-LH/RH 2	\$ 52.00	
12	FRONT SENSOR OUTER	\$ 231.00	
13	FRONT SENSOR SEAL RING 4	\$ 12.00	
14	FRONT FENDER-LH	\$ 968.00	\$ 774.40
15	FRONT FENDER ATTACHMENT PARTS-LH	\$ 48.00	
16	FRONT FENDER CLOSING ELEMENT -LH	\$ 68.00	\$ 53.76
17	FORNT FENDER BRACKET-LH	\$ 32.00	\$ 25.20
18	FRONT FENDER BRACE-LH	\$ 107.00	\$ 85.60
19	FRONT FENDER DEFORMATION BRACKET-LH	\$ 45.00	
20	FRONT FENDER UPPER BRACKET-LH	\$ 32.00	
SUB TOTAL SPARE PARTS		\$ 6,162.00	\$ 2,674.32

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SMC 9171 K**

S/N	Parts Description	c/f	Damaged Parts & Prices	
			S/Nett	Remark
				\$ 2,674.32
21	FRONT FENDER REAR BRACKET-LH		\$ 53.00	
22	FRONT WHEEL HOUSING LINER-LH		\$ 256.00	\$ 204.80
23	FRONT WHEEL SPOILER-LH		\$ 66.00	\$ 52.32
24	FRONT FENDER END PLATE-LH		\$ 32.00	\$ 25.04
25	FRONT STONE CHIP GUARD-LH		\$ 46.00	\$ 36.64
26	FRONT FENDER LEDGE COVER-LH		\$ 32.00	\$ 25.44
27	FORNT FENDER LEDGE TOP COVER-LH		\$ 14.00	\$ 11.04
28	FRONT FENDER TRIM-LH		\$ 145.00	\$ 115.60
29	FRONT DOOR TRIM-LH		\$ 145.00	\$ 115.60
30	LED HEADLIGHT-LH		\$ 7,204.00	\$ 5,763.20
31	FRONT ALUMINIUM RIM-LH		\$ 943.00	
32	RUBBER VALVE	4	\$ 13.00	
33	SUNDRIES		\$ 800.00	\$ 12.00
TOTAL SPARE PARTS			\$ 15,911.00	\$ 9,036.00
TOTAL LABOUR CHARGES			\$ 5,852.00	\$ 4,152.00
GRAND TOTAL			\$ 21,763.00	\$ 13,188.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SMC 9171 K

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0428/2019/NK

14 June 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Dear Sir,

RE: INSURANCE CLAIM FOR SMC 9171 K, Audi Q5 SB 2.0 TFSI.

With reference to the above-mentioned vehicle, no. **SMC 9171 K** claimant, **Mr. Chockalingam Ramasamy**, please find the related document per attached.

1. A copy of the Original invoice no. 85013896 – S\$12,399.16.
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encl
AIG – SMC 9171 K

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9628 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 13:52

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Customer

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice: B5013896	Account: A0006 (T 0)
		Date : 13/06/2019	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
		Order : SMC9171K	
		Term : 30	
Regn No: SMC9171K (V 38750)		Regn Date: 27/07/2018	Mileage: 16413 WIP No.: 48663
Model: A5 SPORTBACK 2.0 TFSI S tronic		Chassis: WAUZZZF50JA104999	Engine: CVK 062620 Dept: U
You have been assisted by :- UB-Siti Marsilla (137)			

		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-1600.00	1.00	-1,600.00
S	BODYWORK	M: TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNES FOR HEADLIGHT,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY	300.00	1.00	300.00
S	BODYWORK	M: TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER AND LHS HEADLIGHT.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	1250.00	1.00	1,250.00
S	BODYWORK	M: TO RESPRAY FRONT BUMPER,LHS FRONT FENDER AND LHS FRONT DOOR	1650.00	1.00	1,650.00
S	BODYWORK	M: TO CARRY OUT WHEEL ALIGNMENT	280.00	1.00	280.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
X	A8W6941773E	(A) (SK) HEADLIGHT 16/	Less 020%	1.00	7204.00
X	A8W6821105B	FENDER	Less 020%	1.00	968.00
X	A8W6853887	SPOILER	Less 020%	1.00	65.40
X	A8W6821171C	WHEEL HOUS(LAST)	Less 020%	1.00	256.00
X	A8W6807065D GRD	(A) (SK) COVER 16/4/19	Less 020%	1.00	2073.00
X	A8W6821467	BRACKET	Less 020%	1.00	31.50
X	A8W6853603A PUZ	TRIM(LAST)	Less 020%	1.00	144.50
X	A8W6807283	GUIDE	Less 020%	1.00	32.60
X	A8W6821131B	(V) (SK) SUPPORT 3/5/1	Less 020%	1.00	107.00
X	A8W6821091	007218/(V) (SK) PLATE	Less 020%	1.00	67.20
X	A8W6820581E	COVER(LAST)	Less 020%	1.00	31.80

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6541 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 13:52

Company Reg. No. 199902271W
GST Reg. No. 199902271W

Customer

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice: 85013896 Date : 13/06/2019 Order : SMC9171K Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
Regn No: SMC9171K (V 38750) Model: A5 SPORTBACK 2.0 TFSI S tronic You have been assisted by :- UB-Siti Marsilla (137)	Regn Date: 27/07/2018 Chassis: WAUZZZ2F50JA104999	Mileage: 16413 Engine: CVK 062620	WIP No.: 48663 Dept: U

		Details		Qty	Unit Price	Amount
X	A8W0807277	STRIP	Less 020%	2.00	31.80	50.88
X	A8W6823745	COVER	Less 020%	1.00	13.80	11.04
X	A8W6853823B 9B9	STONEGUARD	Less 020%	1.00	45.80	36.64
X	A8W6853601A PUZ	(A) (GER) TRIM 16/4/19	Less 020%	1.00	144.50	115.60
X	A8W0853833	SPOILER	Less 020%	1.00	31.30	25.04
X	AN 0161857	POP-RIVET	Less 020%	5.00	3.00	12.00

Parts 9,036.00
Labour 0.00
Sublet 4,152.00
Menus 0.00
Lubricant 0.00



Sub-Total	11,588.00
7% GST	811.16
Grand Total	12,399.16

Received by

For & on behalf of
Premium Automobiles Pte Ltd

Premium Automobiles

Telefax

to **AIG Asia Pacific Insurance Pte Ltd**
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Motor Claims Dept
Yr Ref: SMC 9171 K

Norah Khai
6768 9828
6841 1183

Body Repair

PA/OD/0428/2019/SM
9TH MAY 2019

from
Telephone +65-
Telefax +65-
Mobile +65-
Our department
Your Claim Ref
Our Ref
Date

RE: CLAIM – OWNER'S SATISFACTION/DISCHARGE VOUCHER

1

total pages

Make & Model : Audi A5 SPORTBACK 2.0 TSFSI S TRONIC
Vehicle Chassis No. : WAUZZZF50JA104999
Vehicle Regn No. : **SMC 9171 K**
Vehicle Mileage : 16409 KM
Vehicle Owner : Mr. Chockalingam Ramasamy
Certificate No : 1800088209
Own Damage Excess : \$1712.00 (Inclusive 7% GST)
Accident Date : 15th MARCH 2019
Place : SIM LIM TONER
Repair Cost : \$2,399.16
WIP No. : 48663
Repairer's Name : Premium Automobiles Pte Ltd

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Road 1
Singapore 408699
Telephone (65) 6366 2323
Telefax (65) 6841 1183

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature :

C. Ramasamy

Time :

9/5/19 6pm

Date :

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Apr 2019		04 Apr 2019 16:20 Edit Adj Rpt	S\$13,188.00 Edit Estimates	S\$13,188.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	CHOCKALINGAM RAMASAMY , ID: S7077542E, Tel: +6597967966, Email: CHOCKAN@GMAIL.COM								
Vehicle Reg. No.:	SMC9171K	Date of Loss:	15/03/2019 11:00 - :59 [7 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 0575847244SG	Policy/Cover Note No.:	888888888 (Comprehensive)						
		Excess:	S\$1,600.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Gan, Hunchung] Hunchung.Gan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 15/04/2019]								
Driver/Custodian:	CHOCKALINGAM RAMASAMY (48 / Male), NRIC: S7077542E, Tel: +6597967966 Email: CHOCKAN@GMAIL.COM								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (12/04/2019): Alert - Adj Mandate Approved (S\$14585.00) - SMC9171K - Claim Handler: Gan, Hunchung... - AIG_SG (12/04/2019): SMC9171K / OD / 15/03/2019 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMC9171K (0575847244SG)

OD

Mar 15 2019 11:00AM

[CHOCKALINGAM RAMASAMY]

Premium Automobiles Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	Use Viewer
Assessment Reports						1 per page	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	05/04/19 08:54	Adjuster Immediate Advice				Load HTM	
Photos/Images						3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	05/04/19 08:40	General View				Load JPG	
2	05/04/19 08:40	General View				Load JPG	
3	05/04/19 08:40	General View				Load JPG	
4	05/04/19 08:40	General View				Load JPG	
5	05/04/19 08:40	General View				Load JPG	
6	05/04/19 08:40	General View				Load JPG	
7	05/04/19 08:40	General View				Load JPG	
8	05/04/19 08:40	General View				Load JPG	
9	05/04/19 08:40	General View				Load JPG	
10	05/04/19 08:40	General View				Load JPG	
11	05/04/19 08:40	General View				Load JPG	
12	05/04/19 08:40	General View				Load JPG	
13	05/04/19 08:40	General View				Load JPG	
14	05/04/19 08:40	General View				Load JPG	
15	05/04/19 08:40	General View				Load JPG	
16	05/04/19 08:40	General View				Load JPG	
17	05/04/19 08:40	General View				Load JPG	
18	05/04/19 08:40	General View				Load JPG	
19	05/04/19 08:40	General View				Load JPG	
20	05/04/19 08:40	General View				Load JPG	
21	05/04/19 08:40	General View				Load JPG	
22	05/04/19 08:40	General View				Load JPG	
23	05/04/19 08:40	General View				Load JPG	
24	23/05/19 19:22	Reinspection Photo				Load JPG	
25	23/05/19 19:22	Reinspection Photo				Load JPG	
26	23/05/19 19:22	Reinspection Photo				Load JPG	
27	23/05/19 19:22	Reinspection Photo				Load JPG	
28	23/05/19 19:22	Reinspection Photo				Load JPG	
29	23/05/19 19:22	Reinspection Photo				Load JPG	
30	23/05/19 19:22	Reinspection Photo				Load JPG	
31	23/05/19 19:22	Reinspection Photo				Load JPG	
32	23/05/19 19:22	Reinspection Photo				Load JPG	
33	23/05/19 19:22	Reinspection Photo				Load JPG	
34	23/05/19 19:22	Reinspection Photo				Load JPG	
Documentation						1 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)				Thumbnail	Print
1	04/04/19 17:42	ESTIMATE				Load PDF	
2	04/04/19 17:42	Driver's Driving License and NIRC				Load PDF	
3	04/04/19 17:42	Singapore Accident Statement				Load PDF	
4	05/04/19 11:21	Certificate of Insurance				Load PDF	

5	12/04/19 08:53	UNDER TAKING AND INTERVIEW	1	Load PDF	
6	24/06/19 09:31	WORKSHOP INVOICE	1	Load PDF	
7	24/06/19 09:31	DISCHARGE VOUCHER	1	Load PDF	

Linked Accident Report Documents

					View	Use Viewer	
Assessment Reports					1 per page		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print		
1	30/03/19 14:49	Accident Statement	1	Load HTM			
Photos/Images					3 per page		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print		
1	30/03/19 14:48	Accident Photo	1	Load JPG			
2	30/03/19 14:48	Accident Photo	1	Load JPG			
3	30/03/19 14:48	Accident Photo	1	Load JPG			
4	30/03/19 14:48	Accident Photo	1	Load JPG			
5	30/03/19 14:48	Accident Photo	1	Load JPG			
6	30/03/19 14:48	Accident Photo	1	Load JPG			
7	30/03/19 14:48	Accident Photo	1	Load JPG			
8	30/03/19 14:48	Accident Photo	1	Load JPG			
Documentation					1 per page		
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print		
1	30/03/19 14:47	Sketch Plan	1	Load JPG			
2	30/03/19 14:47	Sketch Plan #2	1	Load JPG			

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #08-16
Singapore 079120

Our File No: CC3/AIG19005998/ATD3N2

Date: 24/06/2019

REFERENCE

Insured/Claimant: CHOCKALINGAM RAMASAMY
Date of Loss: 15/03/2019Policy No: 888888888
Nature of Claim: OD

Claim No: 0575847244SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC9171K	Engine No:	CVK062620
Make & Model:	AUDI A5, 2.0 SPORTBACK (A)	Chassis No:	WAUZZZF50JA104999
Reg. Date:	27/07/2018 (Man. Year: 2018)	Odometer:	14998 km
Colour:	Black		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$170,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40R18	Rear Tyre Size:	245/40R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	15,911.00	9,036.00	6,875.00	43.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,852.00	4,152.00	1,700.00	29.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,763.00	13,188.00	8,575.00	39.40
- Excess (S\$)	1,600.00	1,600.00	0.00	0.00
(S\$)	20,163.00	11,588.00	8,575.00	42.53
+ GST 7.00/7.00% (S\$)	1,411.41	811.16	600.25	42.53
Nett Amount (S\$)	21,574.41	12,399.16	9,175.25	42.53

INSPECTION

Date of Assignment: 04/04/2019

Date Inspected: 04/04/2019 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,073.00 FS	*1,658.40 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	368.00 FS	*- FS
3	2		*FRONT BUMPER SECURING STRIP	Necessary	64.00 FS	*50.88 FS
4	1		*FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	Not Necessary	207.00 FS	*- FS
5	1		*FRONT BUMPER SPOILER	Not Necessary	489.00 FS	*- FS
6	1		*FRONT AIR GUIDE-LH	Not Necessary	56.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE-LH	Not Necessary	431.00 FS	*- FS
8	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	113.00 FS	*- FS
9	1		*FRONT BUMPER CARRIER	Not Necessary	733.00 FS	*- FS
10	1		*FRONT BUMPER GUIDE SECTION-LH	Necessary	33.00 FS	*26.08 FS
11	2		*FRONT BUMPER SUPPORT-LH/RH	Not Necessary	52.00 FS	*- FS
12	1		*FRONT SENSOR OUTER	Not Necessary	231.00 FS	*- FS
13	4		*FRONT SENSOR SEAL RING	Not Necessary	12.00 FS	*- FS
14	1		*FRONT FENDER-LH	Dented	968.00 FS	*774.40 FS
15	1		*FRONT FENDER ATTACHMENT PARTS-LH	Not Necessary	48.00 FS	*- FS
16	1		*FRONT FENDER CLOSING ELEMENT-LH	Damaged	68.00 FS	*53.76 FS
17	1		*FRONT FENDER BRACKET-LH	Damaged	32.00 FS	*25.20 FS
18	1		*FRONT FENDER BRACE-LH	Bent	107.00 FS	*85.60 FS
19	1		*FRONT FENDER DEFORMATION BRACKET-LH	Not Necessary	45.00 FS	*- FS
20	1		*FRONT FENDER UPPER BRACKET-LH	Not Necessary	32.00 FS	*- FS
21	1		*FRONT FENDER REAR BRACKET-LH	Not Necessary	53.00 FS	*- FS
22	1		*FRONT WHEEL HOUSING LINER-LH	Deformed	256.00 FS	*204.80 FS
23	1		*FRONT WHEEL SPOILER-LH	Cracked	66.00 FS	*52.32 FS
24	1		*FRONT FENDER END PLATE-LH	Bent	32.00 FS	*25.04 FS
25	1		*FRONT STONE CHIP GUARD-LH	Necessary	46.00 FS	*36.64 FS
26	1		*FRONT FENDER LEDGE COVER-LH	Necessary	32.00 FS	*25.44 FS
27	1		*FRONT FENDER LEDGE TOP COVER-LH	Necessary	14.00 FS	*11.04 FS
28	1		*FRONT FENDER TRIM-LH	Necessary	145.00 FS	*115.60 FS
29	1		*FRONT DOOR TRIM-LH	Cut	145.00 FS	*115.60 FS
30	1		*LED HEADLIGHT-LH	Cut	7,204.00 FS	*5,763.20 FS
31	1		*FRONT ALUMINIUM RIM-LH (Not Necessary)	Old Damaged	943.00 FS	*- FS
32	4		*RUBBER VALVE	Not Necessary	13.00 FS	*- FS
33	1		*SUNDRIES	Necessary	800.00 FS	*12.00 FS
F=Franchise part. S=SpcNetl.						
Total Parts (\$\$)					15,911.00	9,036.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE LHS FRONT DOOR PANEL TRIM.TO RMEOVE AND REINSTALL LHS WING MIRROR ASSY	New	300.00	300.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER AND LHS HEADLIGHT.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	1,250.00
4	TO RESPRAY FRONT BUMPER,LHS FRONT FENDER AND LHS FRONT DOOR	New	2,500.00	1,650.00
5	TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			5,852.00	4,152.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >