

Su Brothers' Motor Workshop

Blk 5034 Ang Mo Kio Industrial Park 2

#01-341/343

Singapore 569537

Tel : 64824355 Fax : 64824788 Email : su_bros@singnet.com.sg

Co. Reg. No : 26584500M GST Reg No : M9-0008282-A

Date : 03/04/2019

Pg 1/2

Our Ref : SB/MC/0131/04/19 TD

Lonpac Insurance Bhd

300 Beach Road

#17-04/07 The Concourse

Singapore 199555

Attention : Motor Claims Department

Vehicle No : SKT 2924 K

Make/Model : Subaru XV

DOA : 02/04/2019

Your insured Vehicle reg no: GBB 1600 C

List Items:-

1 pc	Rear bumper / DR	\$	894.00
1 pc	Rear bumper side retainer / DR	\$	16.00
10 pcs	Rear bumper clip @ \$3.50 / DR	\$	35.00
1 pc	Rear bumper n/s side reflector / DR	\$	24.00
1 pc	Rear bumper reinforcement / DR	\$	187.24
1 pc	Rear bumper n/s bracket / DR	\$	28.80
1 pc	Rear bumper centre reflector / DR	\$	102.00
1 pc	n/s tail lamp assy / DR	\$	377.40
1 pc	Rear end panel / DR	\$	388.00
1 pc	Rear end panel upper garnish / DR	\$	100.00
1 pc	Rear end panel upper garnish chrome plate / DR	\$	210.00
1 pc	Boot gate / DR	\$	910.80
1 pc	Boot gate rubber / DR	\$	119.00
1 pc	Boot gate emblem "Subaru" / DR	\$	68.00
1 pc	Boot gate emblem "XV" / DR	\$	40.80
1 pc	Boot gate emblem "Symmetrical AWD" / DR	\$	69.00
1 pc	Rear w/s moulding / DR	\$	98.00
1 pc	Rear camera head / DR	\$	560.00
1 pc	Rear n/s fender inner shield / DR	\$	64.80
1 pc	Rear n/s fender curve outer garnish / DR	\$	180.50
1 pc	Rear n/s fender lower air vent garnish / DR	\$	64.00
1 pc	Rear boot inner trim / DR	\$	252.00
		\$	4,789.34
Less 10%		\$	478.93
Bal c/d		\$	4,310.41
1 pc	Rear bumper tow garnish / DR	\$	38.50
1 pc	Rear left taillamp lower bracket / DR	\$	22.50

Our Ref : SB/MC/0131/04/19 TD
 Vehicle No : SKT 2924 K

Bal b/f \$ 4,310.41

Special Nett Item:-

1 pc Rear w/s gum \$ 50.00 X

Labour Charges:-

Towing	\$ 120.00 ✓
To check & reconnect harness wiring.	\$ 35.00 ✓
To spray on anti rust proofing.	\$ 100.00 20
To putty & spray painting.	\$ 880.00 500 600
To remove/refit rear w/s glass.	\$ 120.00 X
To transfer rear wiper motor, blade, 3rd brake light, rear spoiler etc to new boot gate.	\$ 80.00 X
To cut/weld rear end panel, knock & reshape rear spare tyre panel, n/s tail lamp panel, rear n/s fender, to renew above parts etc.	\$ 860.00 480 450
	\$ 6,435.41



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TZONE

TOWING & RECOVERY SERVICES

TEL: 97297337

T ZONE TOWING & RECOVERY SERVICES

8 Kaki Bukit Ave 4 #06-32 Premier@Kaki Bukit

Singapore 415875

Email: t-zonetowing@live.com.sg

Reg No. 53125821A

No. T 53222

CASH SALE / WORK ORDER

Svc Date

2/4/19

Member's Name

Cash

M'ship / NRIC No.

Member's Contact No.

Car Regr. No.

SKP 2924 K

Car Make / Model

Subaru

Remarks (if any)

Time Received

Time Arrived

Time Completed

From

TPE - Changi Rd

To

Amie Incl Pk 2

Tow Truck No.

YP 6723C


Amount

120/-

ADDITIONAL CHARGES

- ☒ Dolly Wheels / Flat bed
- ☐ Basement / Multi-storey
- ☐ Crane up / Bogged
- ☐ Causeway / 2nd Link
- ☐ Low Bodykit
- ☐ Collection of Key
- ☐ ERP / Carpark

BODY & PAINT CONDITION RECORD



*please remove any valuables or personal belongings in the car

Tow Driver's Name & Signature

Member's Signature

Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

bizSAFE₃