

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Apr 2019 Edit Reg		04 Apr 2019 00:00 Edit Adj Rpt	S\$902.80 Edit Estimates	S\$902.80 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS			[Created by adjuster]						
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: -								
Main Claimant:	ER GUO YAO ALDRED, ID: S8406991D								
Vehicle Reg. No.:	SLJ2025X	Date of Loss:	26/03/2019 08:00 - :59 [85 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT19030812	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHA3463C	Policy No. (Claimant):	DMPCSN3121871902						
		Excess:							
Repairer:	Car City Auto Centre Pte Ltd (HQ) Blk 9006 #01-198, Tampines Street 93, 528840 Tampines - Tel: 6781 0300								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sundari Nagarajan - 6347 6071]								
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 15/04/2019]								
ASSOCIATED MAIL RECEIVED			View All Compose Case Mail						
<ul style="list-style-type: none"> III_SG (24/05/2019): Alert - Adj Mandate Approved (S\$0.00) - SLJ2025X - Claim Handler: Sundari Nagara... 									
ALL ASSOCIATED TASKS			View All Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLJ2025X (MCT19030812)**
[SHA3463C]
TP
ER GUO YAO ALDRED
Mar 26 2019 8:00AM
[COMFORT TRANSPORTATION PTE LTD]
Car City Auto Centre Pte Ltd

View

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/05/20 14:20	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
2	04/05/20 14:20	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
3	04/05/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>
4	04/05/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>
5	04/05/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>
6	04/05/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>
7	04/05/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>
8	04/05/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>
9	04/05/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>
10	04/05/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>
11	04/05/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>
12	04/05/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>
13	04/05/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>
14	04/05/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>
15	04/05/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>
16	04/05/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>
17	04/05/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>
18	04/05/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>
19	04/05/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>
20	04/05/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>
21	04/05/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>
22	04/05/20 14:20	General View	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/04/19 16:41	EMAIL FROM III DD 04042019	Load PDF	<input type="checkbox"/>
2	04/04/19 16:41	TP GIA REPORT	Load PDF	<input type="checkbox"/>
3	04/04/19 16:41	TP POLICE REPORT	Load PDF	<input type="checkbox"/>
4	04/04/19 16:41	NOTE FOUND	Load PDF	<input type="checkbox"/>
5	10/04/19 08:54	TP ESTIMATE- MARKED	Load PDF	<input type="checkbox"/>
6	04/05/20 14:18	EMAIL TO III DD 040520	Load PDF	<input type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	05/04/19 09:21	Singapore Accident Statement	Load PDF	<input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	<input type="button" value="Reset"/>	<input type="button" value="Save"/>	<input type="button" value="Print"/>
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III19006003/UEA3S2**Date:** 08/05/2020REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015	
Claimant Vehicle No :	SLJ2025X	Insured Vehicle No :	SHA3463C	
Date of Loss:	26/03/2019	Nature of Claim:	TP	Claim No: MCT19030812

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ2025X		Engine No:	G4FGCU462019
Make & Model:	HYUNDAI ELANTRA, 1.6 (A)		Chassis No:	KMHDH41CMCU417810
Reg. Date:	17/02/2012 (Man. Year: 2012)		Odometer:	106269 km
Colour:	Red			
Engine Capacity:	1591 cc			
Market Value/New Car Price:	N/A			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,012.48	372.80	1,639.68	81.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,790.00	530.00	1,260.00	70.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,802.48	902.80	2,899.68	76.26
+ GST 7.00/7.00% (S\$)	266.17	63.20	202.97	76.26
Nett Amount (S\$)	4,068.65	966.00	3,102.65	76.26

INSPECTION

Date of Assignment:	04/04/2019		
Date Inspected:	08/04/2019	Inspected At:	Car City Auto Centre Pte Ltd (HQ) Blk 9006 #01-198, Tampines Street 93 Singapore 528840
Estimated Period of Repair:	2.0 days		

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 08 May 2020)**Parts:** 143 HYUNDAI ELANTRA 1.6 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SLJ2025X)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	433.40 FL	*- FL
2	1		*FRONT BUMPER RETAINER LH	Not Necessary	21.50 FL	*- FL
3	1		*FRONT FENDER LH	Dented	466.00 FL	*466.00 FL
4	1		*FRONT FENDER COWLING LH	Not Necessary	97.20 FL	*- FL
5	12		*FRONT FENDER COWLING CLIPS	Not Necessary	30.00 FL	*- FL
6	1		*FRONT WING MIRROR ASSY LH (W/SIGNAL)	Repair	555.00 FL	*- FL
7	1		*FRONT SPORT RIM LH	Serviceable	730.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	2,333.10	466.00
- List Item Discount on L Items 20.00/20.00% (S\$)	320.62	93.20
Total Parts (S\$)	2,012.48	372.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT AFFECTED PARTS; PANEL BEATING ON DAMAGED AREAS, CUT, WELD, KNOCK STRAIGHTEN, REALIGN & RESHAPE. FRONT BUMPER, FRONT SUPPORT PANEL, FRONT HEADLAMP LH, FRONT FENDER LH & OTHER.	New	800.00	200.00
2	TO CHECK & REPAIR WIRING SYSTEM, REMOVE & REPLACE DAMAGED WIRE. SIGNAL LIGHT WIRE, ALL LAMP WIRE, SENSOR WIRE & OTHER WIRING.	New	50.00	20.00
3	TO APPLY ANTI-RUST UNDERCOAT ON REPLACE & REPAIRED PANELS.	New	60.00	30.00
4	TO PUTTY, CLEANING, SANDING, POLISHING, WAXING & SPRAY PAINT ON ALL NECESSARY PARTS AND AREAS. FRONT BUMPER, FRONT SUPPORT PANEL, FRONT FENDER LH, FRONT DOOR LH, WING MIRROR LH ETC.	New	800.00	280.00
5	WHEEL ALIGNMENT.	New	80.00	0.00
			Gross Labour Cost (\$\$)	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >