

Ryder

Auto Pte Ltd

2 Kaki Bukit Ave 2, #02-19 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TP LON PAC

Xiao Tony

ESTIMATE OF REPAIR

SJS4504T Pg 1/1

Veh # : SJS4504T Model : VOLKSWAGEN NEW GOLF 1.4 (18/8/2009)

Date Of Accident: 2/4/2019 3P : SJR8698X (LONPAC)

WVV 2221K2 4W015052

Location : BOON LAY MARKET (NEAR BY)

S/Nos.	Qty	Description	Surveyor Remarks	Surveyor Adj	Amount \$	
		List Items				
1	1 pc	Rear n/s door <i>Revised</i>			1,560.00	1380
2	1 pc	Rear n/s door weatherstrip <i>re</i>			422.00	255
3	1 pc	Rear n/s fender <i>By 5</i>			1,760.00	1
4	1 pc	Rear n/s wheel rim <i>cut</i>			800.00	580
		Sub-Total			4,542.00	
		After -10%			4,087.80	
		Labour				
1		To dismantle rear n/s portion, straighten and welding.			1,000.00	500
2		To spray painting.			1,000.00	500
3		To remove and refit door <i>Fittings</i>			280.00	80
4		To remove and refit rear seat, roof lining and floor carpet.			380.00	80
5		To check wiring			50.00	30
6		To re-seal anti-rust			50.00	1
		Sub-Total			2,660.00	
		Total			6,747.80	
		After -20%			5,398.24	

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)

 **BOK SENG**
(heavy vehicles, marine vessels)

 **iiv**
International Insurance

Authorised Workshop
Authorised Reporting Centre

 **8778 1999**
24 hr accident call

 **Mobil 1**

Adrian Ling total: 3241.5
c/s 08/04/19 4/s: 2.6K
0.5 p/s. (2.6K)