CHEW MOTOR PTE. LTD.

1 Kaki Bukit Avenue 6, Blk C #01-41 Autobay@Kaki Bukit Singapore 417883

Tel: 6509 5545

Fax: 6509 5567

Website: www.chewmotor.com

Registration No.: 201718369R

09/04/2019

EZ SWIFT CAR RENTAL & LEASING PTE LTD

01-43

Singapore 417883

Blk 1 Kaki Bukit Ave 6

TPA16

Soy

Accident date: 28/03/2018

Estimated repair cost for vehicle no: SJS3641L HYUNDAI AVANTE 1.6 A '09

S/n	Qty	Items	U/price	Amount
1	1	Rear R/H Tail Lamp	\$321.80	\$321.80
2	2	Rear R/H Tail Lamp Clip New	\$8.00	\$16.00
3	1	Rear R/H Tail Lamp Panel 3 H	\$158.00	\$158.00
4	1	Rear R/H Boot Lid Side Reflector		\$188.00
5	1	Rear Bumper Deband		\$487.00
	10	Rear Bumper Clip	\$6.50	\$65.003
6 7	2	Rear Bumper Side Retainer Z	\$35.50	\$71.00
7/1	1	Rear Bumper Reinforcement	3 V MARCON C MINO	\$286.80
8	2	Rear Bumper Reinforcement Bracket 2	\$66.80	\$133.60
9		Rear Bumper Top & Lower Bracket	\$38.50	\$192.50
10	5	7 7		\$130.00×
11	1		~	\$350.00
12	1	A	***	\$530.00
13	1	Rear End Panel Top Garnish Nem		\$158.00
14	1	Medi Elia i dilet rep es		\$795.00
15	1	Rear Spare Tyre Panel		\$178.00
16	1	Rear Spare Tyre Panel Top Cover		\$450.00
17	1	Rear Spare Tyre Panel & End Panel Sealant		
18	1	Rear Exhaust		\$585.00
19	2	Rear Exhaust Mounting	\$38.20	\$76.40

Subtotal :- \$5,172.10

8548

Labour charges

To remove & refit cushion

\$280.00

To remove & refit rear exhaust

\$280.00 ×

To remove & refit reverse sensor

\$100.0050

To check wiring

\$100,00 30

Tuff kote

180 ·

\$150.00 *

Panel Beating

\$150.00

Spray painting

\$800.00 250

Subtotal :-

\$2,710.00

Total:-

\$7,882.10

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: