

HWA SENG SPRAY PAINTING COMPANY

1 of 1

160 Sin Ming Drive, #05-11,
Sin Ming AutoCity
Singapore 575722
(Registration no :095744/00B)
Tel : 64533100, Fax 62669932

Date of accident : 28/03/2019
Your Insured
Vehicle no: SDP 6039T

Estimate repair cost to MAZDA 6 reg no : SLG 713 Y

1pc front bumper	S\$	1096.40	✓
1pc front bumper o/s retainer		16.20	✓
1pc o/s headlamp		917.60	✓
1pc o/s headlamp bracket		28.00	✓
1pc front bumper reinforcement		552.00	✓
1pc front bumper o/s fog lamp cover		62.50	✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Less : 20%

Labour & misc charges

Panel knocking	400.00	300
Spray painting	500.00	400
Wire checking	80.00	20

3118.16

HWA SENG SPRAY PAINTING COMPANY



Not Authorised
Resurvey By paint
3 days