

INSURANCE

INS. CASE OWNER

CC3 / AIG1900 6013

E 813/19

LKK IDAC

Surveyor:

CTY

DOI:

ASSIGNMENT

24/7/19

Date / Time:

4/4/19

Registered in Merimen:

16/4/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SFT 31279

Name of Insured:

YAP KIAM WU

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

21/7/19

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

597726456554

Policy No.:

170008844-01

Make / Model:

AM01

Place of Accident:

TPE

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final? Yes / No

SDJ 5005D



INSRS:
WSP:
Tel:
Liability:
RMKS:

Performance



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
	Non-Reporting Itr (1st)	
	Non-Reporting Itr (2nd)	
	Non-Reporting Itr (Final)	
	Notification Itr (if non-pickup)	
	Call OI	
	After call Itr to OI	email only 6/7/19
22/7/19	Documentation Check List:	Handler Typist
	Notification Itr (if non-pickup)	
	After call Itr to OI	
	Authorisation To Act	
	Release Voucher	
	Final Repair Bill	
	Car Rental Invoice	
	Towing Invoice	
	LTA / GIA	
	Medical Bill	
	PIR	
	Mandate/Reject Instruction	
	LOD	
	Payment Breakdown Form	
	Post-Repair Photos	
	Others	

PRELIMINARY ADVICE Date/Time: Sent By:

FINALIZATION Date/Time: Confirm with: Confirm by: CTY

Repair Cost: PIP \$510,671.75 (5 days) Reduction: 6% Email Call

FINAL SETTLEMENT Date/Time: 30/7/19 Confirm with: (signature) Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27 If NO or B 28, Ass. Lia

Repair Cost: (with GST) \$5 10,776.77 O/D REAR END TD

Loss of Rental (LOR): \$5 (- days)

Loss of Use (LOU): \$5 (5 - 5 - days)

Loss of Income (LOI): \$5 (5 - 5 - days)

LOR only LOU only LOR + LOI LOR + LO [Tick only one]

GIA/LTA Search \$5 2.00

Medical: \$5 -

Disbursement: \$5 - (e.g. Tow/ Independent)

Legal Cost: \$5 -

Total: \$5 10,778.77 Global Sum SS:

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: \$5 10,778.77 Name 1: PERFORMANCE MOTOR LIMITED

Payee 2: (Strike if N.A.) \$5 Name 2:

Payee 3: (Strike if N.A.) \$5 Name 3:

COPI SENT

1) Claim status: (Normal) / Reject / Private Settle
2) Report format: TP
3) Survey fee: \$320

22.04 @ loan
 333 Survey before 1 pm

arrange rental car from BKW

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
 Toll-Free Number (1800-2255269)



193, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax: 64747770

280, Tampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax: 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax: 64796601 (AfterSales)
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

04 APR 2019

Estimate No. : b1 50732	Page No. : 1 of 5
Date Estimated : 04/04/2019	
Prepared By : Inthiran A/L Thurasamy	

- ESTIMATE REPAIR FOR - Eng Li Yan Amy 28 Flora Drive #03-54 Singapore 506951	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDJ5005D	V259747	29/12/2015	216d CAT	0

DESCRIPTION	VALUE
To replace rear bumper, tailgate and attachments. <i>850</i>	<i>2550</i> / <i>1700</i> 2,550.00
<i>974</i> / <i>791</i> Painting rear bumper and tailgate.	<i>2399</i> / <i>1730</i> 1,923.00
To check electrical wiring systems and lightings at the rear section for proper function.	<i>150</i> ✓ 177.00
To remove and install rear windscreen glass to facilitate the repair job.	// 574.00
To conduct water leak tests.	/ ✓ 75.00
To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.	<i>478</i> / <i>451</i> 531.00
To carry out body cavity preservation. (Per panel).	<i>100</i> ✓ 118.00
Sundries. <i>Nil</i>	? ✓ 150.00
Total Labour 1: 6,098.00	

DESCRIPTION	QTY	PRIC	VALUE
TRUNK LID / <i>00</i>	1	1,204.35	1,204.35 ✓
REAR BUMPER PANEL PRIMED (PDC) / <i>00</i>	1	1,029.50	1,029.50 ✓
RR BUMPER LH SIDE GUIDE	1	49.05	49.05 ✓
REAR BUMPER CARRIER <i>Subs</i>	1	458.10	458.10 ✓
SUPPORT <i>2 EA</i>	1	45.30	45.30 ✓
RR BUMPER LH INNER SIDE GUIDE <i>2 EA</i>	1	60.05	60.05 ✓
RR BUMPER RH INNER SIDE GUIDE <i>2 EA</i>	1	60.05	60.05 ✓
SET MOUNTS PDC SENSOR REAR <i>2 units</i>	1	62.95	62.95 ✓
GROMMET / <i>NEC</i>	2	0.75	1.50 ✓
PLAQUE 74MM / <i>NEC</i>	1	71.25	71.25 ✓
BUMP STOP / <i>NEC 10x</i>	10	3.50	35.00 ✓

303, Alexandra Road
Sime Darby Performance Centre
Singapore 119941
Fax: 64747770280, Kampong Arang Road
East Coast Centre
Singapore 436180
Fax: 63443772315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 50732
Date Estimated : 04/04/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDJ5005D	V259747	29/12/2015	216d CAT	0

DESCRIPTION	QTY	PRIC	VALUE
RR LH LIGHT IN THE SIDE PANEL <i>BR</i>	1	365.20	365.20
(DG) CLEANER R1 (100ML) <i>ABC</i>	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) <i>ABC</i>	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206) <i>ABC</i>	1	27.85	27.85
Total Parts :			3,759.40

Steve
83228813wHL *Primer*
22/4/19 10.45am
Ry *bf spy*
PIP
5 *days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	6,098.00
Parts	:	3,759.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	690.02
Grand Total	:	10,547.42

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020061-X



SUPPLEMENTARY

Estimate No. : b1 50961
Date Estimated : 24/04/2019
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -
Eng Li Yan Amy
28 Flora Drive
#03-54

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 506951

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE		
SDJ5005D	V259747	29/12/2015	216d CAT	0		
DESCRIPTION			ORIGINAL PRICE	DISC. %	NETT	
# To remove and install boot compartment carpet and garnish to facilitate repairs			231.00		231.00	✓
# To replace antenna comfort access include conducting sensitivity tests and checks for proper function			100.00		100.00	✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6 * ✓ H&L	2.55	3.00		7.65
# EXPANDING NUT * ✓ H&L	1.00	2.00		2.00
# OUTSIDE ANTENNA COMFORT ACCESS * ✓ BE	96.35	1.00		96.35

Total Labour : 331.00
Total Parts : 106.00

Total Labour & Parts : 437.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401599W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : **b1 50961**
Date Estimated : **24/04/2019**
Prepared By : **Inthiran A/L Thurasamy**

Page No. :

REPAIR FOR -
Eng Li Yan Amy
28 Flora Drive
#03-54

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 506951

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDJ5005D	V259747	29/12/2015	216d CAT	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
* To replace rear bumper and attachments, trunk lid, rear LH light in trunk lid include making good the tail end panel and knocking out dents caused by the accident	2550.00		2,550.00	
* To spray paint rear bumper, trunk lid and tail end panel	2399.00		2,399.00	
# To remove and install boot compartment carpet and garnish to facilitate repairs	231.00		231.00	
To carry out body cavity preservation (Per panel)	100.00		100.00	
To transfer lock mechanism from old to new trunk lid include conducting checks on new trunk lid power window system for proper function	451.00		451.00	
To check electrical wiring system and lighting at the rear section for proper function	150.00		150.00	
# To replace antenna comfort access include conducting sensitivity tests and checks for proper function	100.00		100.00	
Sundries	150.00		150.00	
To remove and install rear windscreen glass to facilitate the repair job	574.00		574.00	
To conduct water leak test	75.00		75.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6 *	2.55	3.00		7.65
TRUNK LID *	1,204.35	1.00		1,204.35
REAR BUMPER PANEL PRIMED (PDC) *	1,029.50	1.00		1,029.50
# EXPANDING NUT *	1.00	2.00		2.00
REAR BUMPER CARRIER *	458.10	1.00		458.10
SUPPORT *	45.30	1.00		45.30
RR BUMPER LH INNER SIDE GUIDE *	60.05	1.00		60.05
RR BUMPER RH INNER SIDE GUIDE *	60.05	1.00		60.05

Performance Motors Limited

A member of the Sims Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

GROMMET *	0.75	2.00	1.50
PLAQUE 74MM *	71.25	1.00	71.25
RR LH LIGHT IN THE TRUNK LID	255.65	1.00	255.65
# OUTSIDE ANTENNA COMFORT ACCESS *	96.35	1.00	96.35

SUPPLEMENTARY ITEMS

Total Labour :	6,780.00
Total Parts :	3,291.75
Total Labour & Parts :	10,071.75
Deduction for Excess :	
Total Repair Costs less Excess:	10,071.75
GST @7%:	705.02
Grand Total :	10,776.77

ANNOUNCING Speedo Motoring
as sgCarMart Premium Dealer for the 8th Consecutive Year

Post an Advertisement
Sell it yourself! Advertise it at just **\$58** until it's **SOLD!**

New 5 Series Car Released Monthly Starting 1.88



Free 3000 evaluation
Free planning and 3 months maintenance
Free finance consulting service during period
Extension of 30/36 and 36/36 purchase agreement
100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Post an Ad Advertiser Login Ways of Selling

Filter by Category

Sort by Date Posted 20 results/page

12 vehicles

BMW 2

Advanced Search

Image	Model	Price	Depreciation	Reg. Year	Reg. Cap.	Mileage	Veh. Type	Status
	BMW 2 Series 220i Coupe M-Sport	\$112,800	\$15,776 /yr	18-Feb-2013	1,967 cc	-	Sports	Available
<p>The BMW 228i M-sport Coupe Offers One Of The Best Driving Experiences With A Very Reasonable Price Tag! Outstanding Road Holding Capabilities With Dynamic Engine Performance On-Demand! High Trade-In...</p> <p>Feng's Motor Trading Pte Ltd</p> <p>Posted: 22-Apr-2019 Tag: 2013 BMW 228i, 2015 BMW 228i, BMW 228i, BMW 228i, BMW 228i, Used BMW</p>								
	BMW 2 Series 218i Active Tourer	\$79,800	\$11,960 /yr	27-Feb-2013	1,499 cc	80,000 km	Hatchback	Available
<p>Best Condition! One Owner Low Mileage, Low/Trade In Available! Call For Test Drive!</p> <p>Posted: 22-Apr-2019 Tag: 2013 BMW 218i, 2015 BMW 218i, BMW 218i, BMW 218i, BMW 218i, Used BMW</p>								
	BMW 2 Series 218i Active Tourer	\$88,800	\$11,658 /yr	29-Oct-2013	1,499 cc	29,000 km	Hatchback	Available
<p>1 Owner Sporty Pearl White With Low Mileage 26,000 KM Only As Owner Stationed Overseas, Brand New 20" Sport Rims, Full Service History By BMW PHL, Accident Free, Loan Available, Trade In Welcome...</p> <p>Posted: 22-Apr-2019 Tag: 2013 BMW 218i, 2015 BMW 218i, BMW 218i, BMW 218i, BMW 218i, Used BMW</p>								
	BMW 2 Series 218i Active Tourer	\$75,800	\$11,310 /yr	27-Feb-2013	1,499 cc	50,000 km	Hatchback	Available
<p>1.99% Interest Rate! Cheapest In Town! High Loan Available! In Excellent Condition, Agent Serviced And Maintained, Original Paintwork Shook Day 1, Accident-Free, Immaculate Condition, In House Loan An...</p> <p>Heritage Auto Enterprise Pte Ltd</p> <p>Posted: 22-Apr-2019 Tag: 2013 BMW 218i, 2015 BMW 218i, BMW 218i, BMW 218i, BMW 218i, Used BMW</p>								
	BMW 2 Series 218i Active Tourer	\$76,800	\$11,390 /yr	27-Feb-2013	1,499 cc	-	Hatchback	Available
<p>\$1,174/month x 69 Months With Only 10% Down Payment! In House Loan Available! Over-Trade In Accepted! 1 Owner Well Maintained Unit! Welcome Workshop Inspection Or STA Evaluation! Call To Arrange View...</p> <p>Den Motors</p> <p>Posted: 19-Apr-2019 Tag: 2013 BMW 218i, 2015 BMW 218i, BMW 218i, BMW 218i, BMW 218i, Used BMW</p>								
	BMW 2 Series 218d Gran Tourer Luxury	\$111,000	\$14,890 /yr	30-Nov-2013	1,496 cc	84,500 km	MPV	Available
<p>Fuel Type: Diesel (Euro 5 Engine and Above)</p> <p>7 Seater! Full PHL Maintained, Only One Owner, Owner Extended Servicing And Warranty, BMW PHL 5yr/121,000km Free Servicing And 5yr/200,000km Warranty, Interior And Exterior All Well Maintained And 1...</p> <p>Performance Cars Pte Ltd</p> <p>Posted: 18-Apr-2019 Tag: 2013 BMW 218d, 2015 BMW 218d, BMW 218d, BMW 218d, BMW 218d, Used BMW</p>								
	BMW 2 Series 218d Active Tourer	\$79,800	\$10,430 /yr	28-Dec-2013	1,496 cc	53,718 km	Hatchback	Available
<p>Fuel Type: Diesel (Euro 5 Engine and Above)</p> <p>Low Interest Rate, Maintained By Performance Motors, 1 Year Warranty, Balloon Scheme, In-House Financing Options Available, Buy With A Peace Of Mind, 1 Owner, Low Mileage, 100% Genuine Mileage, No Cha...</p> <p>GDHaven Pte Ltd</p> <p>Posted: 19-Apr-2019 Tag: 2013 BMW 218d, 2015 BMW 218d, BMW 218d, BMW 218d, BMW 218d, Used BMW</p>								
	BMW 2 Series 218i Active Tourer	\$95,800	\$11,570 /yr	29-Sep-2013	1,499 cc	30,000 km	Hatchback	Available
<p>3 Years Warranty And Servicing Done With Performance Motor Limited, Hardly Used, Pristine Conditions, Viewing Strictly By Appointment Only As Vehicle Is Not At Office Premises, Please Call To Schedule...</p> <p>Prime Motor & Leasing</p> <p>Posted: 18-Apr-2019 Tag: 2013 BMW 218i, 2015 BMW 218i, BMW 218i, BMW 218i, BMW 218i, Used BMW</p>								
	BMW 2 Series 218d Gran Tourer Luxury	\$95,800	\$11,850 /yr	27-Nov-2013	1,496 cc	52,500 km	MPV	Available
<p>Fuel Type: Diesel (Euro 5 Engine and Above)</p> <p>1 Owner, Come With 5 Years 200K Km Warranty, Fully PHL Service And Maintained, Original Paint Work, BMW In Car Front And Back Recorder, Well kept, Pristine Condition, 7-Seater MPV Equipped With 4 L.S...</p> <p>Posted: 22-Apr-2019 Tag: 2013 BMW 218d, 2015 BMW 218d, BMW 218d, BMW 218d, BMW 218d, Used BMW</p>								
	BMW 2 Series 218i Active Tourer	\$81,800	\$10,810 /yr	28-Aug-2013	1,499 cc	53,000 km	Hatchback	Available
<p>1 Owner White Accident Free Agent Unit, Fully Maintained By PHL, All Wear And Tear Parts Replaced When About To Due By PHL, Very Well Maintained Dealer Out, Trade In And Loan Available, Viewing By App...</p> <p>Posted: 22-Apr-2019 Tag: 2013 BMW 218i, 2015 BMW 218i, BMW 218i, BMW 218i, BMW 218i, Used BMW</p>								

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Monday, 29 July 2019 4:06 PM
To: Chee-Heng.Loh@aig.com
Cc: Admin A
Subject: SEEK MANDATE - AIG Ref: TP / 5977269565SG [ACCIDENT INVOLVING SFT 3127Y (OI) & SDJ 5005D (TP) ON 29/03/2019]

Tracking:	Recipient	Delivery
	Chee-Heng.Loh@aig.com	
	Admin A	
	Meikwan@lkkauto.com	Delivered: 29/7/2019 4:07 PM
	olivialau@lkkauto.com	Delivered: 29/7/2019 4:06 PM
	shupeir@lkkauto.com	Delivered: 29/7/2019 4:06 PM

AIG Ref: TP / 5977269565SG
LKK Ref: CC3/AIG19006013/Ekb3

Dear Sirs/Madam,

ACCIDENT INVOLVING SFT 3127Y (OI) & SDJ 5005D (TP) ON 29/03/2019

We refer to the above matter.

This is a head to rear collision. We are of the opinion that liability is down against Insured and BOLA 27 is applicable. We did clarify with insured the nature of the accident and he is aware of NCD (if any) will be affected.

We seek your approval to offer to Third Party repairer, "**PERFORMANCE MOTORS LTD**" as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 11,524.33	\$ 10,776.77
2. LTA/ GIA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 11,526.33	\$ 10,778.77

**5 days recommendation for repair

All the relevant documents had been uploaded in Merimen.

Kindly let us have your mandate in Merimen.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	SDJ5005D	Model:	
Date of Accident:	29.03.2019		

Global Sum Settlement:	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	: \$	10,547.42	
Final Repair Cost	: \$	10,776.77	
Loss of Use	: \$	--	days at \$ per day
Rental (if any)	: \$	--	days
LTA / GIA Search Fee	: \$	2.00	
Others	: \$	--	
	: \$	--	
Final Settlement Sum	: \$	10,778.77	

Is Third Party Workshop GIA Registered? YES NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Application: Yes / No
BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks


Payment Instruction: Payee's Breakdown

1)	Performance Motor Limited	: \$	10,776.77
2)	Performance Motor Limited	: \$	2.00
3)		: \$	

Signed by appointed surveyor

Date

**Please attach all the supporting documents to the form.
Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;
Survey Report; Medical Report / Bill (if any)**

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #15-01186 Singapore Land Tower, Singapore 048621
Tel: 6461 6555 | Fax: 6221 3302 | Website: www.sompo.com.sg
Co. Reg. No.: 198905490E | GST Reg. No.: M200001194

Certificate of Insurance

**MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)**

Cert No./Policy No. : D18MTPV01020399
Insured : ENG LI YAN AMY
Motor Car (Registration No.) : SDJ5005D
Cover : Comprehensive - ExcelDrive PRESTIGE
Policy Commencement Date : 29 DECEMBER 2018 00:00
Policy Expiry Date : 28 DECEMBER 2019 23:59
Maximum Liability (Section I) : Market value at time of loss
Excess* : NIL
(Waived up to S\$1,000 if accident repair is done at ExcelDrive Workshops for the first claim per policy year)
Voluntary Excess* : N/A
Windscreen Excess* : S\$100.00 - Waived if Repair at ExcelDrive Workshop
Loss of Use : Per Policy Schedule

* Subject to GST wherever applicable

Persons or Classes of Persons entitled to drive*

1. The Insured.
2. Any other person who is driving on the Insured's order or with his permission.
3. In the event of the death of the insured,
 - a. any member of the insured's family, or a paid driver who has been driving the Motor Car during the life of the insured and permission to drive had not been withdrawn prior to the death of the insured; and
 - b. any other person who has been given permission to drive the Motor Car prior to the death and such permission had not been withdrawn by the insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Car. And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

ExcelDrive Workshops and Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Car within 24 hours of the accident or by the next working day thereof.

All accident repairs to the Motor Car must be carried out at ExcelDrive Workshops, otherwise the claim is not payable under the Policy. For ExcelDrive Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExcelDrive Workshops.

For the list of Accident Reporting Centres and ExcelDrive Workshops, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6226 3323.

I/We HEREBY CERTIFY that the policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act 1987 (Malaysia); and (2) the Policy terms, conditions and exceptions of the Private Car Policy ref MTP 27.

Sompo Insurance Singapore Pte. Ltd.

Authorised Signatory

Date/Time of Issue : 19 DECEMBER 2018 14:22

IMPORTANT NOTICE

- Keep the Certificate in your Motor Car;
- Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act;
- On the sale of the Motor Car or if for any reason the Insurance is terminated during its currency, the Insured must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189);
- This Policy will cease to be valid once the Motor Car has been sold to another person. The Policy is not transferable to the new owner of the Motor Car.

Intermediary Code & Name : 11001104 & DIRECT-CLIENT (CASH TERM) | CI Code : 22A_D_KD2212JTYN1V4A

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S73771091



Name
ENG LI YAN AMY

伍 丽 燕

Race
CHINESE

Date of birth 23-06-1973 Sex F

Country of birth
MALAYSIA

S73771091

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: **S73771091**

Name
ENG LI YAN

Birth Date: 23 Jun 1973

Issue Date: 05 Dec 2003



001037780K



3304539



NRIC No: **S73771091**

Date of issue
03-04-2004

28 FLORA DRIVE #03-54
SINGAPORE 506951

NRIC No: S73771091

Date: 31/07/2010

No: 6598897

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIE

Class	Description	PASS DATE
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	36 Nov 1998

PASS DATE

36 Nov 1998



Licence No: S73771091

NP 428A

Print Received Message

This mail is associated with :

***SDJ5005D (5977269565SG)**
[SFT3127Y]
TP
ENG LI YAN AMY
Mar 29 2019 6:00PM
[YAP KIAM WU]
Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 30/07/2019 08:24 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10778.77) - SDJ5005D - Claim Handler: Loh, Chee-Heng

Approved:10778.77.

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Thursday, 4 July 2019 2:42 PM
To: KIAMWU@GMAIL.COM
Cc: Admin A
Subject: ACCIDENT INVOLVING SFT3127Y & SDJ5005D ALONG TPE TO PASIR RIS ON 29/03/2019

Tracking:	Recipient	Delivery
	KIAMWU@GMAIL.COM	
	Admin A	
	olivialau@lkkauto.com	Delivered: 4/7/2019 2:42 PM
	shupei@lkkauto.com	Delivered: 4/7/2019 2:42 PM
	Meikwan@lkkauto.com	Delivered: 4/7/2019 2:42 PM

OUR REF: CC3/AIG19006013/Ekb3
YOUR REF: SFT3127Y

Dear Mr. Yap Kiam Wu,

ACCIDENT INVOLVING SFT3127Y [AIG] & SDJ5005D ALONG TPE TO PASIR RIS ON 29/03/2019

We refer to the above subject matter.

We write to inform you that we are the loss adjuster appointed by your motor insurer, **AIG Asia Pacific Insurance Pte Ltd** to deal with the third party claim against your policy.

We have received a claim from SDJ5005D against your motor insurance policy.

Based on the accident report and accident scenario, we are of the view that liability is not in your favour. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,
Khanchna | Case Handler
LKK Auto Consultants Pte Ltd
DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, Eng Li Yan Amy ("the third party claimant")
of 28 Flora Drive #03-54 S(506951) (address),
owner of SDJ 5005 D (vehicle no.) hereby authorize
Performance Motors Ltd

("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SDJ 5005 D that was
damaged pursuant to the accident which occurred on 29/3/19 (date) along
Along TPE Slip Road toward Pasir Ris Drive 8 (location)
involving vehicle no/s S173127Y ✓ ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.


I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 29 day of 04 (month) 2019 (year)

Signed by "the third party claimant"

Signed by "the workshop"

303 Aljunied Road
Sims Drive Performance Centre
Singapore 120311



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

380, Kempung Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/330 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1355539	Page No. : 1 of 2
Date IN : 22/04/2019	Invoice Number : 2102611 / WSB
Motor Claim Advisor: Inthiran A/L Thurasamy	Invoice Date : 23/05/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Toh Jing Xuan

- CUSTOMER INFORMATION -

Ms Eng Li Yan Amy
28 Flora Drive
#03-54

Singapore 506951

- INVOICE TO - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO. / SDJ5005D	CHASSIS NO. / V259747	REGN. DATE / 29/12/2015	MODEL / 216D CAT	MILEAGE / 99521
----------------------	-----------------------	-------------------------	------------------	-----------------

- - - - LABOUR 1 - - - -

	NETT
To replace rear bumper and attachments, trunk lid, rear left light in trunk lid including make good the tail end panel and knock out dented area caused by the accident.	2,550.00
To respray rear bumper, trunk lid and tail end panel.	2,399.00
To remove and install boot compartment carpet and garnish to facilitate repairs.	231.00
To carry out body cavity preservation.	100.00
To transfer lock mechanism from old to new trunk lid including conduct checks on new trunk lid central locking system for proper function.	451.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00
To replace antenna comfort access including conduct sensitivity tests and checks for proper function.	100.00
Sundries.	150.00
To remove and install rear windscreen glass to facilitate the repair job.	574.00
To conduct water leak tests.	75.00
INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.	0.00
DATE OF ACCIDENT : 29.03.2019. 3RD PARTY CAR : SFT3127Y.	
YOUR REF NO : NIL.	
VEHICLE WAS SURVEYED BY MR STEVE CHEN FROM LKK AUTO ON 22.04.2019 AT 10:45AM. AUTHORISED REPAIR BY MS ASHER SNG FROM LKK AUTO ON 10.04.2019 VIA EMAIL.	
GIA SEARCH FEE = \$2.00.	0.00
COURTESY CAR PROVIDED BY BKW DURING REPAIR.	0.00
Total Labour 1:	6,780.00

- - - - PARTS - - - -

	Qty	Retail Price	NETT
REAR BUMPER PANEL PRIMED (PDC)	1	1,029.50	1,029.50
GROMMET	2	0.75	1.50
PLAQUE 74MM	1	71.25	71.25
TRUNK LID	1	1,204.35	1,204.35
REAR BUMPER CARRIER	1	458.10	458.10

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020082-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

390, Sempang Arang Road
East Coast Centre
Singapore 438160
Tel: 63190888 (AfterSales)
Fax: 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel: 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1355539	Page No. : 2 of 2
Date IN : 22/04/2019	Invoice Number : 2102611 / WSB
Motor Claim Advisor: Inthiran A/L Thurasamy	Invoice Date : 23/05/2019
	Payment Terms : 30 Days From Invoice
	Invoice By : Toh Jing Xuan

SUPPORT	1	45.30	45.30
RR BUMPER LH INNER SIDE GUIDE	1	60.05	60.05
BLIND RIVET NUT M6	3	2.55	7.65
RR BUMPER RH INNER SIDE GUIDE	1	60.05	60.05
RR LH LIGHT IN THE TRUNK LID	1	255.65	255.65
EXPANDING NUT	2	1.00	2.00
OUTSIDE ANTENNA COMFORT ACCESS	1	96.35	96.35
	Total Parts :		3,291.75

Labour Charges :	6,630.00	Total Labour & Parts Charges :	S\$ 10,071.75
Parts Charges :	3,291.75	Less Insurance Excess :	S\$ 0.00
Lubricant/Misc :	150.00	Invoice Total Amount Exclude GST :	S\$ 10,071.75
		GST @ 7% :	S\$ 705.02
		Invoice Total Amount Include GST :	S\$ 10,776.77

Computer generated invoice. No signature is required.

Amount Payable Include GST : **S\$ 10,776.77**

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
 Phone: +65 6224 0010 Fax: +65 6224 0030
 Operating Hours: Monday to Friday 9am to 5pm
 GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-19-052566

Date of Request: 04/04/2019

Your Ref No:

Online Purchase

Performance Motors Limited
 303 Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941

Dear Sir/Madam,

Enquiry Date 04/04/2019
 Enquiry By Melanie Setiawati
 TP Vehicle No. SFT3127Y
 Accident Date 29/03/2019

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SFT3127Y	AIG Asia Pacific Insurance Pte. Ltd.	29/12/2018-28/12/2019	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
 Phone: +65 6224 0010 Fax: +65 6224 0030
 Operating Hours: Monday to Friday 9am to 5pm
 GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-19-052566

Date of Request: 04/04/2019

Your Ref No:

Online Purchase

Performance Motors Limited
 303 Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941

Dear Sir/Madam,

Enquiry Date 04/04/2019
 Enquiry By Melanie Setiawati
 TP Vehicle No. SFT3127Y
 Accident Date 29/03/2019

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

 GIRO Cash Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Apr 2019 Edit Reg		22 Apr 2019 00:00 Edit Adj Rpt	S\$10,071.75 Edit Estimates	S\$10,071.75 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	YAP KIAM WU , ID: S7271753H								
Main Claimant:	ENG LI YAN AMY , ID: S73771091								
Vehicle Reg. No.:	SDJ5005D	Date of Loss:	29/03/2019 18:00 - :59 [39 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 5977269565SG	Policy/Cover Note No.:	1700088444 (Comprehensive)						
Vehicle Reg. No. (Insured):	SFT3127Y	Policy No. (Claimant):	D18MTPV01020399						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com								
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 15/04/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (30/07/2019): Alert - Adj Mandate Approved (S\$10778.77) - SDJ5005D - Claim Handler: Loh, Chee-...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SDJ5005D (5977269565SG)
[SFT3127Y]
TP
ENG LI YAN AMY
Mar 29 2019 6:00PM
[YAP KIAM WU]
Performance Motors Limited

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View View in Browser	
Letters/Correspondences										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit		
Assessment Reports										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)						Thumbnail	Print		
1	05/04/19 15:25	Accident Statement <small>Prem:00 - Reg. No: SFT3127Y, Claimant: YAP KIAM WU</small>							Load HTM		
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	23/04/19 08:25	General View							Load JPG	<input checked="" type="checkbox"/>	
2	23/04/19 08:25	General View							Load JPG	<input checked="" type="checkbox"/>	
3	23/04/19 08:25	General View							Load JPG	<input checked="" type="checkbox"/>	
4	23/04/19 08:25	General View							Load JPG	<input checked="" type="checkbox"/>	
5	23/04/19 08:25	General View							Load JPG	<input checked="" type="checkbox"/>	
6	23/04/19 08:25	General View							Load JPG	<input checked="" type="checkbox"/>	
7	23/04/19 08:25	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>	
8	23/04/19 08:25	Chassis Number							Load JPG	<input checked="" type="checkbox"/>	
9	23/04/19 08:25	General View							Load JPG	<input checked="" type="checkbox"/>	
10	23/04/19 08:25	General View							Load JPG	<input checked="" type="checkbox"/>	
11	23/04/19 08:25	General View							Load JPG	<input checked="" type="checkbox"/>	
12	23/04/19 08:25	General View							Load JPG	<input checked="" type="checkbox"/>	
13	23/04/19 08:25	General View							Load JPG	<input checked="" type="checkbox"/>	
14	23/04/19 08:25	General View							Load JPG	<input checked="" type="checkbox"/>	
15	23/04/19 08:25	General View							Load JPG	<input checked="" type="checkbox"/>	
16	23/04/19 08:25	General View							Load JPG	<input checked="" type="checkbox"/>	
17	23/04/19 08:25	General View							Load JPG	<input checked="" type="checkbox"/>	
18	23/04/19 08:25	General View							Load JPG	<input checked="" type="checkbox"/>	
19	23/04/19 08:25	General View							Load JPG	<input checked="" type="checkbox"/>	
20	23/04/19 08:25	General View							Load JPG	<input checked="" type="checkbox"/>	
21	23/04/19 19:25	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
22	23/04/19 19:25	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
23	23/04/19 19:25	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
24	23/04/19 19:25	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
25	23/04/19 19:25	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
26	23/04/19 19:25	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
27	23/04/19 19:25	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
28	23/04/19 19:25	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
29	23/04/19 19:25	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	
30	23/04/19 19:25	Photographs of Damaged Parts							Load JPG	<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	23/04/19 19:25	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
32	23/04/19 19:25	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
33	23/04/19 19:25	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
34	23/04/19 19:25	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
35	23/04/19 19:25	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
36	23/04/19 19:25	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
37	23/04/19 19:25	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
38	24/04/19 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	24/04/19 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	24/04/19 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	24/04/19 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	24/04/19 09:28	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	25/04/19 16:57	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
44	25/04/19 16:57	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/04/19 17:11	TP EST &GIA REPORT	Load PDF	
2	23/04/19 19:18	TP ESTIMATE- MARKED	Load PDF	
3	13/05/19 09:51	RENTAL RECEIPT	Load PDF	
4	04/07/19 14:42	EMAIL TO OI	Load PDF	
5	26/07/19 12:36	GIA SEARCH	Load PDF	
6	05/08/19 09:24	AUTHORISATION TO ACT FORM	Load PDF	
7	05/08/19 09:24	WORKSHOP INVOICE	Load PDF	
8	05/08/19 09:24	Release Voucher	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SFT3127Y (Insd veh)	Model:	BMW 216D 1.5 D ACTIVE TOURER (F45) D/AB LED (A)
	SDJ5005D (TP veh)		
Date of Accident:	29/03/2019		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	: \$		11,524.33
Final Repair Cost	: \$		10,776.77
Loss of Use	: \$		days at \$0.00 per day
Rental (if any)	: \$		0.00 days
LTA / GIA Search Fee	: \$		2.00
Others:	: \$		0.00
	: \$		
Final Settlement Sum	: \$		10,778.77

Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____
 BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ (%)
 * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown		
1)	Performance Motors Limited	: \$ 10,778.77
2)		: \$

JOANNE LEE KHANG MIN

05 Aug
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19006013/EKB3Q2
Date: 05/08/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1700088444
Claimant Vehicle No : SDJ5005D	Insured Vehicle No :	SFT3127Y
Date of Loss: 29/03/2019	Nature of Claim: TP	Claim No: 5977269565SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDJ5005D	
Make & Model:	BMW 216D, 1.5 D Active Tourer (F45) D/AB LED (A)	Engine No: 35329363B37C15A
Reg. Date:	29/12/2015 (Man. Year: 2015)	Chassis No: WBA2B32070V259747
Colour:	Brown	Odometer: 99521 km
Engine Capacity:	1496 cc	
Market Value/New Car Price:	N/A	
Sum Insured (S\$):	Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,015.40	3,441.75	573.65	14.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,755.00	6,630.00	125.00	1.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	10,770.40	10,071.75	698.65	6.49
+ GST 7.00/7.00% (S\$)	753.93	705.02	48.91	6.49
Nett Amount (S\$)	11,524.33	10,776.77	747.56	6.49
	+ Doc/Search Fee (S\$)	2.00		
	Nett Liability (S\$)	10,778.77		

INSPECTION

Date of Assignment:	22/04/2019	
Date Inspected:	22/04/2019 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	5.0 days	

Adjuster: CHEN TSUE YEE

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS	
2	1		*TRUNK LID	Dented	1,204.35 FS	*1,204.35 FS	
3	1		*REAR BUMPER PANEL PRIMED (PDC)	Dented	1,029.50 FS	*1,029.50 FS	
4	1		*RR BUMPER LH SIDE GUIDE	Not Necessary	49.05 FS	*- FS	
5	1		*REAR BUMPER CARRIER	Dented	458.10 FS	*458.10 FS	
6	1		*SUPPORT	Broken	45.30 FS	*45.30 FS	
7	1		*RR BUMPER LH INNER SIDE GUIDE	Broken	60.05 FS	*60.05 FS	
8	1		*RR BUMPER RH INNER SIDE GUIDE	Broken	60.05 FS	*60.05 FS	
9	1		*SET MOUNTS PDC SENSOR REAR	Not Necessary	62.95 FS	*- FS	
10	2		*GROMMET	Necessary	1.50 FS	*1.50 FS	
11	1		*PLAQUE 74MM	Necessary	71.25 FS	*71.25 FS	
12	10		*BUMP STOP	Not Necessary	35.00 FS	*- FS	
13	1		*RR LH LIGHT IN THE TRUNK LIP	Broken	365.20 FS	*255.65 FS	
14	1		*(DG) CLEANER R1 (100ML)	Not Necessary	26.15 FS	*- FS	
15	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Not Necessary	263.10 FS	*- FS	
16	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Not Necessary	27.85 FS	*- FS	
17	3		*BLIND RIVET NUT N6	Necessary	7.65 FS	*7.65 FS	
18	2		*EXPANDING NUT	Necessary	2.00 FS	*2.00 FS	
19	1		*OUTSIDE ANTENNA COMFORT ACCESS	Broken	96.35 FS	*96.35 FS	
					Total Parts (\$\$)	4,015.40	3,441.75

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	231.00	231.00
2	TO REPLACE ANTENNA COMFORT ACCESS INCLUDE CONDUCTING SENSITIVITY TESTD AND CHECK FOR PROPER FUNCTION	New	100.00	100.00
3	TO REPLACE REAR BUMPER ,TAILGATE AND ATTACHMENTS	New	2,550.00	2,550.00
4	PAINTING REAR BUMPER AND TAILGATE	New	2,399.00	2,399.00
5	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
6	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO FACILITATE THE REPAIR JOB	New	574.00	574.00
7	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
8	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	451.00
9	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
Gross Labour Cost (S\$)			6,755.00	6,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >