

\* arrange rental car from BKW

22.04 @ 10am  
 \*\*\* Survey before 12pm

BMW Dealer

# Performance Motors Limited

A Sime Darby Motors Company  
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
 Toll-Free Number (1800-2255269)



303, Alexandra Road  
 Sime Darby Performance Centre  
 Singapore 159941  
 Fax. 64747770

280, Kampong Arang Road  
 East Coast Centre  
 Singapore 438180  
 Fax. 63449773

315, Alexandra Road  
 Sime Darby Business Centre  
 Singapore 159944  
 Fax. 64796601 (AfterSales)  
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

04 APR 2019

## ESTIMATE

Estimate No. : b1 50732	Page No. : 1 of 5
Date Estimated : 04/04/2019	
Prepared By : Inthiran A/L Thurasamy	

<b>- ESTIMATE REPAIR FOR -</b> <b>Eng Li Yan Amy</b> <b>28 Flora Drive</b> <b>#03-54</b>  <b>Singapore 506951</b>	<b>- ACCOUNT - 40000</b> <b>Cash Sales - Service</b> <b>Singapore</b>
--	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDJ5005D	V259747	29/12/2015	216d CAT	0

DESCRIPTION	VALUE
To replace rear bumper, tailgate and attachments. 850	1700 2,550.00
Painting rear bumper and tailgate. 934 / 796	1730 1,923.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
To remove and install rear windscreen glass to facilitate the repair job.	/ 574.00
To conduct water leak tests.	/ 75.00
To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.	478 531.00
To carry out body cavity preservation. (Per panel).	100 118.00
Sundries.	? 150.00
<b>Total Labour 1: 6,098.00</b>	

DESCRIPTION	QTY	PRIC	VALUE
TRUNK LID / 00	1	1,204.35	1,204.35
REAR BUMPER PANEL PRIMED (PDC) / 00	1	1,029.50	1,029.50
RR BUMPER LH SIDE GUIDE	1	49.05	49.05
REAR BUMPER CARRIER	1	458.10	458.10
SUPPORT	1	45.30	45.30
RR BUMPER LH INNER SIDE GUIDE	1	60.05	60.05
RR BUMPER RH INNER SIDE GUIDE	1	60.05	60.05
SET MOUNTS PDC SENSOR REAR	1	62.95	62.95
GROMMET / NEC	2	0.75	1.50
PLAQUE 74MM / NEC	1	71.25	71.25
BUMP STOP / NEC	10	3.50	35.00

# Performance Motors Limited

A Sime Darby Motors Company  
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
 Toll-Free Number (1800-2255269)



303, Alexandra Road  
 Sime Darby Performance Centre  
 Singapore 159941  
 Fax. 64747770

280, Kampong Arang Road  
 East Coast Centre  
 Singapore 438180  
 Fax. 63449773

315, Alexandra Road  
 Sime Darby Business Centre  
 Singapore 159944  
 Fax. 64796601 (AfterSales)  
 64796624 (Motorrad)

**GST REG. NO : M2 - 0020081 - X**

## E S T I M A T E

Estimate No. : <b>b1 50732</b> Date Estimated : <b>04/04/2019</b> Prepared By : <b>Inthiran A/L Thurasamy</b>	Page No. : <b>2 of 5</b>
---	--------------------------

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDJ5005D	V259747	29/12/2015	216d CAT	0

DESCRIPTION	QTY	PRIC	VALUE
RR LH LIGHT IN THE SIDE PANEL <i>BR</i>	1	365.20	365.20
(DG) CLEANER R1 (100ML) <i>NEC</i>	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) <i>NEC</i>	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206) <i>NEC</i>	1	27.85	27.85
<b>Total Parts :</b>			<b>3,759.40</b>

*Steve  
83228813*

*WHL Arjun  
22/4/19 10.45 am  
Ry bnf spy  
PIP  
5 or days*

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

**Acknowledged by Repairer**  
 Signature:  
 Date:

Labour 1	:	6,098.00	
Parts	:	3,759.40	
Labour 2	:	0.00	
Excess	:	0.00	
Total GST @ 7%	:	690.02	
<b>Grand Total</b>	<b>:</b>	<b>10,547.42</b>	

**\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\***  
**\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\***