

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## FINAL REPORT

Page No. :

Estimate No. : b1 50961  
Date Estimated : 24/04/2019  
Prepared By : Inthiran A/L Thurasamy

REPAIR FOR -  
Eng Li Yan Amy  
28 Flora Drive  
#03-54

- ACCOUNT - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

Singapore 506951

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE	ORIGINAL PRICE	DISC. %	NETT
SDJ5005D	V259747	29/12/2015	216d CAT	0			
DESCRIPTION							
# To replace rear bumper and attachments, trunk lid, rear LH light in trunk lid include making good the tail end panel and knocking out dents caused by the accident					2550.00		2,550.00 /
# To spray paint rear bumper, trunk lid and tail end panel					2399.00		2,399.00 /
To remove and install boot compartment carpet and garnish to facilitate repairs					231.00		231.00 /
# To carry out body cavity preservation (Per panel)					100.00		100.00 /
# To transfer lock mechanism from old to new trunk lid include conducting checks on new trunk lid power window system for proper function					451.00		451.00 /
# To check electrical wiring system and lighting at the rear section for proper function					150.00		150.00 /
# To replace antenna comfort access include conducting sensitivity tests and checks for proper function					100.00		100.00 /
Sundries					80.00		80.00 /

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6 *	2.55	3.00		7.65 /
# TRUNK LID *	1,204.35	1.00		1,204.35 /
# REAR BUMPER PANEL PRIMED (PDC) *	1,029.50	1.00		1,029.50 /
# EXPANDING NUT *	1.00	2.00		2.00 /
# REAR BUMPER CARRIER *	458.10	1.00		458.10 /
# SUPPORT *	45.30	1.00		45.30 /
# RR BUMPER LH INNER SIDE GUIDE *	60.05	1.00		60.05 /
# RR BUMPER RH INNER SIDE GUIDE *	60.05	1.00		60.05 /
# GROMMET *	0.75	2.00		1.50 /
# PLAQUE 74MM *	71.25	1.00		71.25 /
RR LH LIGHT IN THE TRUNK LID / TR	255.65	1.00		255.65 /

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## FINAL REPORT

# OUTSIDE ANTENNA COMFORT ACCESS *	96.35	1.00	96.35 ✓
------------------------------------	-------	------	---------

### # SUPPLEMENTARY ITEMS

Total Labour :	6,061.00 ✓
Total Parts :	3,291.75 ✓
Total Labour & Parts :	9,352.75 ✓
Deduction for Excess :	0.00
Total Repair Costs less Excess:	9,352.75
GST @7%:	654.69
<u>Grand Total :</u>	<u>10,007.44</u>

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## SUPPLEMENTARY

Estimate No. : b1 50961  
Date Estimated : 24/04/2019  
Prepared By : Inthiran A/L Thurasamy

Page No. :

REPAIR FOR -  
Eng Li Yan Amy  
28 Flora Drive  
#03-54

- ACCOUNT - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

Singapore 506951

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDJ5005D	V259747	29/12/2015	216d CAT	0

  

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To replace rear bumper and attachments, trunk lid, rear LH light in trunk lid include making good the tail end panel and knocking out dents caused by the accident	2550.00		2,550.00 ✓
# To spray paint rear bumper, trunk lid and tail end panel	2399.00		2,399.00 ✓
# To carry out body cavity preservation (Per panel)	100.00		100.00 ✓
# To transfer lock mechanism from old to new trunk lid include conducting checks on new trunk lid power window system for proper function	451.00		451.00 ✓
# To check electrical wiring system and lighting at the rear section for proper function	150.00		150.00 ✓
# To replace antenna comfort access include conducting sensitivity tests and checks for proper function	100.00		100.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BLIND RIVET NUT M6 * / ALCC	2.55	3.00		7.65
# TRUNK LID * / DD	1,204.35	1.00		1,204.35
# REAR BUMPER PANEL PRIMED (PDC) * - DD	1,029.50	1.00		1,029.50
# EXPANDING NUT * / ALCC	1.00	2.00		2.00
# REAR BUMPER CARRIER * / DD	458.10	1.00		458.10
# SUPPORT * / RR	45.30	1.00		45.30
# RR BUMPER LH INNER SIDE GUIDE * / DD	60.05	1.00		60.05
# RR BUMPER RH INNER SIDE GUIDE * / DR	60.05	1.00		60.05
# GROMMET * - ALCC	0.75	2.00		1.50
# PLAQUE 74MM * - ALCC	71.25	1.00		71.25
# OUTSIDE ANTENNA COMFORT ACCESS * / DR	96.35	1.00		96.35

Total Labour : 5,750.00  
Total Parts : 3,036.10

# Performance Motors Limited

A member of the Sims Derby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## SUPPLEMENTARY

Total Labour & Parts : 8,786.10



# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax: 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax: 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 50732  
Date Estimated : 04/04/2019  
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SDJ5005D	V259747	29/12/2015	216d CAT	0

DESCRIPTION	QTY	PRIC	VALUE
RR LH LIGHT IN THE SIDE PANEL <i>TRUNK LID</i> <i>BR</i>	1	365.20 <i>255-65</i>	365.20 <i>255-65</i>
(DG) CLEANER R1 (100ML) <i>NEC</i>	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) <i>NEC</i> <i>X N/A</i>	2	131.55	263.10
(DG/SL) GLASS PRIMER 30ML (VP206) <i>NEC</i> <i>X N/A</i>	1	27.85	27.85
Total Parts :			3,759.40

Steve  
83228873

with *Prudin*  
22/4/19 10.45 am  
By *bf spj*  
PIP  
5 *or* days

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	6,098.00
Parts	:	3,759.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	690.02
Grand Total	:	10,547.42

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*