

Taufik

1111 03/40119006015/T1sd302

ASSIGNMENT (Office)

From: Jenny few

401

End Time: 3/4/19 @ 4:47pm

References

Willcox

OD/TP WS/TP RES/OD RES/KVA INV/MP/CS

The Inspect Vehicle File.

Q86 2585F

Discussion

SFQ 4649S

© 2004 Blackwell Publishing Ltd

Bornio Motor

Tel. 92213150

10

2 pondon crescent level 4

Policy Inc

Claim No. M12D1021504

Social Investment

Discussion

Make of Veh.
(Officer's Record)

DECA 19/03/2019

CA / REV / REP. / REV 24 HRS

H.C. Le. Hainbois et al.

Date/Time: 9:16am 4/4/17 Person Contacted:

Raymond

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	GIB02585C-X
	2FG 46495-NA/INCO8021134/151
	2FA 25/7/18

ASSIGNMENT

From: Date: 4/4/19

Estimated Cost:

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV

To Inspect Vehicle No: GBG 2585E

at Workshop n/s

of

Insured

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh: (CIC) Raymond @ 9221 3150

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res:

Yes or No

Lum Sum:

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS Wp

Date:

Person Contacted:

Vehicle: IN / OUT

Raymond

Veh No: GBG 2585E Yr Regn: 2017 / July
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Hiace

cc 2982

Colour:

Silver

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

STF HT02PX00 219558

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: ☒ N / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

195/R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

4/4/19 @ 11am

Survey held at

Borneo Pendar

Des. of Damages: ☒ Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time: 5/4/19 Action / Instruction: E-mail Raymond report until \$32,000

09/07/19 Confirmed L/S \$32,000/- @ 12 days with Taufik
(\$26,970.26 Red - 46%)

Taufik

Re-survey photos cannot see the damaged.

RECEIVED 8 OCT 2019

Date/Time, File Pass to?

09/10/19

1) Typist
Date/Time, File Return to?

☐

: Prel. Report

☒

: Final Report

Days Of Repair:

12

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / L.B.I: (\$ 32,000/- L/S)

Survey Fee:

1200+250

Transportation:

60

3 - RS - 19

80

Phone:

113

Other:

580

05P

9/10/19

1703

Nivitha (LKK Auto)

From: LEW JENNY <jennylew@uoi.com.sg>
Sent: Wednesday, 3 April 2019 4:47 PM
To: Suraidah B Saidi PTCBC; assignments@lkkauto.com; sur@lkkauto.com
Subject: RE: Direct Settlement (RS) - Accident Involving GBG2585E & SFQ4649S DOA 19.03.2019
Attachments: GBG2585E_Est Inv.zip

WITHOUT PREJUDICE

Dear Suraidah,

We will appoint LKK as SJE for this case.

Dear Denise/Catherine,

Please arrange to survey the vehicle at Borneo Motors @ 2 Pandan Crescent.

Warmest Regards

Jenny Lew

Claims Division

United Overseas Insurance Limited

3 Anson Road, #26-01 Springleaf Tower, Singapore 079909
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3869 | Email • jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Suraidah B Saidi PTCBC [mailto:SuraidahB.Saidi@inchcape.com.sg]
Sent: Wednesday, 3 April, 2019 4:43 PM
To: LEW JENNY <jennylew@uoi.com.sg>
Subject: RE: Direct Settlement (RS) - Accident Involving GBG2585E & SFQ4649S DOA 19.03.2019

Hi Jenny,

We have no objection on your proposal to have LKK, please be inform that our client's vehicle is grounded in our premises.

Thank you.

Warmest Regards,
SURAIDAH
TPR TEAM, CLAIMS DEPT
D: 6631 1887 | F: 6872 7260 | E: suraidahb.saidi@inchcape.com.sg
Inchcape Centre
Level 4, Bodycare Centre
2 Pandan Crescent
Singapore 128462

www.borneomotors.com.sg | www.lexus.com.sg | www.toyotasingapore.com.sg | www.hino.com.sg | www.suzukicar.com.sg

From: LEW JENNY <jennylew@uoi.com.sg>
Sent: Wednesday, 3 April 2019 4:36 PM
To: Suraidah B Saidi PTCBC <SuraidahB.Saidi@inchcape.com.sg>
Subject: RE: Direct Settlement (RS) - Accident Involving GBG2585E & SFQ4649S DOA 19.03.2019

CAUTION: This email originated from outside of the organization (Inchcape). Do not click links or open attachments unless you recognise the sender and know the content is safe.

WITHOUT PREJUDICE

Dear Suraidah,

Pursuant to the amended Pre-action Protocol for Non-Injury Motor Accident (NIMA), we enclose a list of our Surveyors, for your attention.

In this case, we propose to appoint M/s LKK Auto Consultants Pte Ltd.

Please revert to the undersigned within **two (2) working days** whether you have any objections to the appointment of any of our Surveyors, failing which we shall proceed to carry out the survey of your client's vehicle by our appointed Surveyors.

Please forward us a copy of the estimated cost of repair.

We reserve all our rights in this matter.

Thank You.

Warmest Regards

Jenny Lew

Claims Division

United Overseas Insurance Limited

3 Anson Road, #25-01 Springleaf Tower, Singapore 079909
Main • (65) 6222 7733 | DID • (65) 6490 9329 | Fax • (65) 6327 3669 | Email • jennylew@uoi.com.sg

UOB EMAIL DISCLAIMER

Any person receiving this email and any attachment(s) contained, shall treat the information as confidential and not misuse, copy, disclose, distribute or retain the information in any way that amounts to a breach of confidentiality. If you are not the intended recipient, please delete all copies of this email from your computer system. As the integrity of this message cannot be guaranteed, neither UOB nor any entity in the UOB Group shall be responsible for the contents. Any opinion in this email may not necessarily represent the opinion of UOB or any entity in the UOB Group.

From: Suraidah B Saidi PTCBC [<mailto:SuraidahB.Saidi@inchcape.com.sg>]
Sent: Wednesday, 3 April, 2019 4:26 PM
To: LEW JENNY <jennylew@uoi.com.sg>
Subject: Direct Settlement (RS) - Accident Involving GBG2585E & SFQ4649S DOA 19.03.2019

Hi,

Reference to the above-mentioned.

Please find attached herein a copy of our client's Accident Report, Damaged Photos (separate email) & Estimate Invoice for your kind perusal.

As our client is claiming against your insured **SFQ4649S** thus would appreciate if you could revert to us on the liability urgently or we could settle the case under Direct Settlement with **Car Rental of @ \$100 per day x no. of days** as recommended by your appointed surveyor.

Kindly have your surveyor to contact our Motor Claim Assessor, **Raymond Seah @ 9221 3150 / 6631 1865** located at **2 Pandan Crescent, Level 4** for an appointment to inspect our client's vehicle soonest as vehicle is in our premises.

As for liability clearance, kindly revert to this email.

Your kind attention into the above is greatly appreciated.

Thank you!

Warmest Regards,

SURAIDAH

TPR TEAM, CLAIMS DEPT

D: 6631 1887 | F: 6872 7260 | E: suraidahb.saidi@inchcape.com.sg

Inchcape Centre

Level 4, Bodycare Centre

2 Pandan Crescent

Singapore 128462

www.borneomotors.com.sg | www.lexus.com.sg | www.toyotasingapore.com.sg | www.hino.com.sg | www.suzukicar.com.sg

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:

Business

Owner ID:

1100B

Vehicle Details

Vehicle No.:

GBG2585E

Vehicle to be Exported:

No

Intended Deregistration Date:

19 Mar 2019

Vehicle Make:

TOYOTA

Vehicle Model:

HIACE VAN TURBO 5DR MT

Primary Colour:

Silver

Manufacturing Year:

2017

Engine No.:

1KD2697878

Chassis No.:

JTFHT02PX00219558

Maximum Power Output:

-

Open Market Value:

\$28,138.00

Original Registration Date:

07 Jul 2017

First Registration Date:

07 Jul 2017

Transfer Count:

0

Actual ARF Paid:

\$1,407.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

06 Jul 2027

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

QP Paid:

\$36,879.00

COE Rebate Amount:

\$30,597.00

Total Rebate Amount:**\$30,597.00**

The information contained herein is correct as at 19 Mar 2019.

OK

MV \$ 63,000.
 SV \$ 30,597

 RC \$ 32,403.
 Repair Unit \$ 32,000



Toyota Hiace \$43,800 \$7,430 /yr 20-Oct-2017 2,982 cc 10,500 km Van Available
Fuel Type: Diesel
 Japan Made Hiace Glaze Van With Rear Cooler, Durable Euro 5 Engine! Full Loan Can Be Arranged, Monthly At \$1234 Only! Welcome To Call Us For Enquiry & Viewing Appointment!
 Think One Automobile & Trading

Posted: 11-Mar-2019 Tags: 2017 Toyota Hiace, 2017 Toyota Hiace, Toyota Hiace, Toyota Hiace, Toyota, Hiace, Hiace, Used Toyota



Toyota Hiace 3.0A Super GL Dark Prime \$84,800 \$10,400 /yr 28-Apr-2017 2,982 cc 55,000 km Bus Available
Fuel Type: Diesel
 Enjoy Low Interest Bank Rate, Highest Specification Toyota Hiace. Comes With 5 Years Engine Warranty, Luxurious 8 Rear Seater Bus With Plenty Of Leg Room For Adult Passenger, Conditions As Good As New...
 Euro Performance Asia Pte Ltd

Posted: 12-Mar-2019 Tags: 2017 Toyota Hiace, 2017 Toyota Hiace, Toyota Hiace, Toyota Hiace, Toyota, Hiace, Hiace, Used Toyota



Toyota Hiace \$68,800 \$8,300 /yr 16-Aug-2017 2,982 cc Van Available
Fuel Type: Diesel
 Deliver Jan'2019! Euro 5 Toyota Hiace Turbo 5DR Manual, Some Unit, Ready Stock, Agent Warranty 3 Years Or 100000Kms! 90% To 100% Loan Available!
 Euro Performance Asia Pte Ltd

Posted: 09-Mar-2019 Tags: 2017 Toyota Hiace, 2017 Toyota Hiace, Toyota Hiace, Toyota Hiace, Toyota, Hiace, Hiace, Used Toyota



Sell with Quotz: Get \$3,000 more than Trade-In
 Trading-in? Owners who sell with sgCarMart Quotz receive up to \$3,000 above market value, getting you the Highest Selling Price in SG. Get your Free Car Valuation Today.
 Find out more!



Toyota Hiace \$60,800 \$7,660 /yr 24-Feb-2017 2,982 cc 55,200 km Van Available
Fuel Type: Diesel
 Agent Unit, 5 Years Or 140,000.00 Free Service And Warranty, Vehicle In Showroom Condition, Loan Available.
 Euro Performance Asia Pte Ltd

Posted: 16-Feb-2019 Tags: 2017 Toyota Hiace, 2017 Toyota Hiace, Toyota Hiace, Toyota Hiace, Toyota, Hiace, Hiace, Used Toyota



Toyota Hiace Commuter \$106,000 \$13,070 /yr 27-Apr-2017 2,982 cc 10,100 km Bus Available
Fuel Type: Diesel
 Look No Further, Superbly Low Mileage, Best Value For Your Money, Beautiful Hiace Commuter GL 3.0 Auto With Brown-Black Leather Upholstery Owned By 1 Private Owner, Selling Due To Upgrading To New Car...
 Euro Performance Asia Pte Ltd

Posted: 07-Feb-2019 Tags: 2017 Toyota Hiace, 2017 Toyota Hiace, Toyota Hiace, Toyota Hiace, Toyota, Hiace, Hiace, Used Toyota



Toyota Hiace \$68,800 \$8,630 /yr 07-Mar-2017 2,982 cc Bus Available
Fuel Type: Diesel
 Well Taken Care By Previous Owner, No Further Offer, Serious Buyers Are Welcome!
 Euro Performance Asia Pte Ltd

Posted: 01-Feb-2019 Tags: 2017 Toyota Hiace, 2017 Toyota Hiace, Toyota Hiace, Toyota Hiace, Toyota, Hiace, Hiace, Used Toyota



Toyota Hiace \$64,800 \$7,960 /yr 15-Jun-2017 2,982 cc 65,000 km Van Available
Fuel Type: Diesel
 Only One Available In The Market! Still Under Warranty Till 3years/80,000 Mileage! Tinted Windows! 2.5" Lowered! Well Maintained By Owner! Flexible Loan Packages Available!
 Euro Performance Asia Pte Ltd

Posted: 30-Jan-2019 Tags: 2017 Toyota Hiace, 2017 Toyota Hiace, Toyota Hiace, Toyota Hiace, Toyota, Hiace, Hiace, Used Toyota



Toyota Hiace \$58,800 \$6,870 /yr 30-Nov-2017 2,982 cc 10,687 km Van Available
Fuel Type: Diesel
 Cheapest In Town, 3 Day Delivery, Price Negotiable, Flexible Loan With Lowest Interest Rate, In House Finance Available, Super High Trade In, Call Now!
 ARWIN Bus Pte Ltd

Posted: 23-Jan-2019 Tags: 2017 Toyota Hiace, 2017 Toyota Hiace, Toyota Hiace, Toyota Hiace, Toyota, Hiace, Hiace, Used Toyota

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Eng Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home New Cars Used Cars Sell My Car Directory Products Insurance Article Forum Resources

sgCarMart is the number one car dealership for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to CSE cars & CPE cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, compare rates & car insurance. Find buy used Toyota Hiace, Toyota Hiace Singapore, used Toyota Hiace Singapore, used vehicles Singapore or even buy used Toyota Hiace Singapore, you have new car dealers comprising parallel importers, authorized car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, motor, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Compare

Cheap Car Insurance Renewal

Is your car insurance expiring soon?

Receive best quotations from multiple insurers in as little as 2 hours.

Post an Advertisement.
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

Up To 100% Loan. Rare Golf Stationwagon R-Line Model



STA Graded A, Very Low Mileage.
Clean, Under Agent Warranty. As
Good As New.
SKL Automobile - StarAd

• Free NCDM evaluation
• Free grooming and 6 months maintenance
• In-house workshop ensures quality service
• Member of SVTA and hire purchase association
• 100% deposit refund for unapproved loan

YONG LEE SENG MOTOR PTE LTD

Browse by Category

Sort by Date Posted 20 results/page

15 vehicles

Toyota Hiace

Advanced Search Submit

	Make	Model	Price	Deprecation	Eng Date	Eng Cap	Mileage	veh Type	Status
Search Selection	Toyota Hiace		Any	Any	2017	Any	Any	Any	Available
	Toyota Hiace		\$65,800	\$7,760 /yr	08-Sep-2017	2,982 cc	29,500 km	Van	Available
	Fuel Type: Diesel Think One Automobile & Trading Posted: 19-Mar-2018 Tags: 2017 Toyota Hiace, 2017 Toyota Hiace, Toyota Hiace, Toyota Hiace, Toyota Hiace, Hiace, Used Toyota								
	Toyota Hiace		\$67,800	\$7,840 /yr	09-Nov-2017	2,982 cc	30,107 km	Van	Available
	Fuel Type: Diesel 1 Owner, Easy And Flexible In-House Financing Available. Pioneer DVD Sound System, Reverse Sensors, Tip Top Condition, Serviced Regularly, No More Repairs Needed, Price Inclusive Of GST. Posted: 19-Mar-2018 Tags: 2017 Toyota Hiace, 2017 Toyota Hiace, Toyota Hiace, Toyota Hiace, Toyota Hiace, Hiace, Used Toyota								
	Toyota Hiace		\$61,800	\$7,070 /yr	13-Dec-2017	2,982 cc	---	Van	Available
	Fuel Type: Diesel Cheapest In Market With COE, Nett Price Inclusive Of GST, ARF, Road Tax And Registration Fees! Cash Buyer Welcome With No Additional Surcharge! Latest Euro 6 Toyota Hiace Model With Borneo Agent Wana... Yes Motoring Posted: 19-Mar-2018 Tags: 2017 Toyota Hiace, 2017 Toyota Hiace, Toyota Hiace, Toyota Hiace, Toyota Hiace, Hiace, Used Toyota								
	Toyota Hiace 3.0A DX		\$63,800	\$7,480 /yr	27-Sep-2017	2,982 cc	45,000 km	Van	Available
	Fuel Type: Diesel Loan Available! 1 Single Owner! Highly Recommended By All Toyota Hiace User With Low Maintenance/Fuel Consumption And Definitely High Productivity! Comes With Rear Aircon To Keep Your Items Or Family ... Car (S) Pte Ltd Posted: 19-Mar-2018 Tags: 2017 Toyota Hiace, 2017 Toyota Hiace, Toyota Hiace, Toyota Hiace, Toyota Hiace, Hiace, Used Toyota								
	DVD Panel	Daihatsu Materia dvd panel / Toyota hi P panel More info about this product							
	Toyota Hiace		\$62,800	\$7,370 /yr	26-Sep-2017	2,982 cc	30,000 km	Van	Available
	Fuel Type: Diesel Still Under Warranty! Superb Cond & Low Mileage, Seldom Use Yet A1 Engine, 100% Loan Can Be Arrange Right Away With High Trade In, Hurry Free DoorStep Viewing With No Obligation Yet Negotiable Victory Automotives Pte Ltd Posted: 19-Mar-2018 Tags: 2017 Toyota Hiace, 2017 Toyota Hiace, Toyota Hiace, Toyota Hiace, Toyota Hiace, Hiace, Used Toyota								
	Toyota Hiace 3.0A Super GL Dark Prime		\$75,000	\$8,900 /yr	11-Aug-2017	2,982 cc	45,000 km	Van	Available
	Fuel Type: Diesel Reliable 3.0L Turbo Diesel, 4 Cylinder Inline, 16 Valve, DOHC, Easy To Maintenance Engine, Reliable 4 Speed Auto Gearbox. Posted: 19-Mar-2018 Tags: 2017 Toyota Hiace, 2017 Toyota Hiace, Toyota Hiace, Toyota Hiace, Toyota Hiace, Hiace, Used Toyota								
	Toyota Hiace 3.0A Super GL Dark Prime		\$89,800	\$10,990 /yr	19-May-2017	2,982 cc	6,000 km	Bus	Available
	Fuel Type: Diesel Think One Automobile & Trading Posted: 13-Apr-2018 Tags: 2017 Toyota Hiace, 2017 Toyota Hiace, Toyota Hiace, Toyota Hiace, Toyota Hiace, Hiace, Used Toyota								

Compare

Shirley Hiew (LKK Auto)

From: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Sent: Friday, 5 April 2019 10:19 AM
To: 'Raymond Seah PTCBC'
Cc: Shirley Hiew (LKK Auto)
Subject: GBG2585E REPAIR LIMIT

Hi Raymond,

Please take note repair limit for this van is \$32,000.

Regards
Taufikh
Lkk Auto



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI17006565/Gvbn2-1

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 12-10-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBA 6573U	Veh. Inspected	GU 5738D
Policy No.	DMCVSN3084761600	Coverage (\$)	0.00
Claim No.	SNM17D01843C02	Excess (\$)	0.00
Assign From	IRENE TAY	Assign Date	11/10/2018

2. Vehicle Particulars & Condition

Make & Model	ISUZU NHR89E	c.c	3059
Engine No.	HIDDEN	Year of Reg.	2001
Chassis No.	JAANHR69EY7100926	Colour	BLUE
Odometer	999999	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15C	MICHELIN	6 mm
L/H Front Tyre	195 R15C	MICHELIN	6 mm
R/H Rear Tyre	165 R13C	YOKOHAMA	6 mm
L/H Rear Tyre	165 R13C	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	27/03/2017	Inspection Date	15/05/2017
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/03/2019 15:57
Date Of Accident	19/03/2019 13:10
Exact Location Of Accident	JUNCTION OF TUAS CRES AND TUAS BAY DR
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBG2585E
Insured/Policyholder	
Name Of Registered Owner	KELANTAN ELECTRIC COMPANY
Co Reg No	07481100B
Email Address	JOSEPH@KELANTANELECTRIC.COM
Mobile Phone No	(LOCAL) +65-83999247
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE-2.0 (M)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5101384708
Cover Note Number	

Driver

Name of Driver	KOH CHEE HOCK
Passport No/FIN	G2170599W
Date Of Birth	08/08/1991
Occupation	OUTDOOR
Date Of Driving Pass	16/12/2014
Driving Experience	4 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83817426
Fax Number	
Contact Number	
Email Address	JOSEPH@KELANTANELECTRIC.COM

Address	3 PENJURU CLOSE SINGAPORE
Postcode	608627
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CROSS JUNCTION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE SIZE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFQ4649S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CUMARAN KUMALACUMAR
NRIC/Passport Number	S9218767E
Contact Number	94553241
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.

6. The report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes (i) of

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims;

(collectively the "Purposes").

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;

(d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;

(e) the information so collected under (d) above may be shared / disclosed

(f) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or

(g) for complying with requirements under any regulations, laws or court orders.

KOH CHEE HOON
20/03/2019 15:33

Policyholder's Signature / Date &
Time


Driver's Signature (if driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

Sketch Plan #2

Sketch Plan

The sketch plan is based on the closest scenario.
Please refer to "Circumstances of the Accident".



Describe Circumstances of the Accident

BLACK CAR : SFO46495

WHITE CAR : GBG2585E

DESCRIPTION :

I was travelling in Tuas crescent before Tuas Bay Dr going straight. SFO46495 was on my right on Tuas Bay Dr when i approaching the junction of Tuas crescent and Tuas Bay Dr SFO46495 dash out from Tuas Bay Dr (which has a stop line to the main road Tuas crescent and we collided

Declaration

I/We declare the foregoing particulars are true in every respect.

KOH CHEE HOCK
20/03/2019 15:33

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

WORK PERMIT
Employment of Foreign Manpower Act (Chapter 91A)
Republic of Singapore

Employer: **KELANTAN ELECTRIC CO**

Factor: **MANUFACTURING**

Name: **KOH CHEE HOCK**
Occupation: **DRIVER**

Work Permit No: **4 04312650**

Date of Application: **24-05-2017**

Date of Issue: **30-05-2017**

Date of Expiry: **28-05-2019**





L7981979

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: **G2170599W**

Name: **KOH CHEE HOCK**

Date of Birth: **08 Aug 1991**

Issue Date: **16 Dec 2014**

Valid Till: **15 Dec 2019**





VISIT PASS
Immigration Regulations

Name: **KOH CHEE HOCK**



Date of Birth: **08-08-1991 M**

Nationality: **MALAYSIAN**

Pin: **G2170599W**

Date of Issue: **30-05-2017**

Date of Expiry: **28-05-2019**

YOU ARE TO SURRENDER THIS CARD WHEN IT IS CANCELLED OR HAS EXPIRED, OR WHEN A NEW CARD IS ISSUED TO YOU.



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

CLASS	VEHICLE CLASS	EFFECTIVE DATE
Class 2B	Motorcycles < 200 CC	16 Dec 2014
Class 2	Motor vehicles < 2000 kg with up to 7 passengers, excluding of the driver and other restrictions < 2000 kg	16 Dec 2014
Class 4A	Car/Jeeps	16 Dec 2014

G2170599W

S / No. 9000213054



NP 428A

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960

ROAD TRANSPORT ACT, 1987 (MALAYSIA)

MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number : 5101384708

Cover : Preferred Workshop Plan

1. Index mark and Registration Number of Vehicle

GBG2585F

Chassis Number

ITFH102P100219558

2. Name of Policyholder

KELANTAN ELECTRIC COMPANY

3. Effective Date of Insurance

07 Jul 2018

4. Expiry Date of Insurance

06 Jul 2019

5. Persons or Classes of Persons entitled to drive

(a) The Policyholder

(b) Any other person who is driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use

(a) Use for social domestic and pleasure purposes and in connection with the Policyholder's business or profession.

(b) Use for the carriage of passengers or goods in connection with the Policyholder's business.

This Policy does not cover

(a) Use for hire or reward.

(b) Use for racing, pace-making, reliability trial or speed-testing.

(c) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle

7. Limitations rendered inoperative by Section E of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings:

EXCESS (SECTION 1) : S\$600

EXCESS (SECTION 2) : N/A

WINDSCREEN EXCESS : S\$100

INSURE WITH COE : YES

HIRE PURCHASE COMPANY : UNITED OVERSEAS BANK LIMITED

SUM INSURED : MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

(We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia))

Agency : XCB AGENCY (00000614904)

Date of Issue : 12 Jun 2018 09:43 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive

Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo





Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sgToyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no: 6631-1108Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000019 / ICU011	M/s Kelantan Electric Co 3 Penjuru Close Singapore 608627 Mobile: 83999247
	Document No	
	0	
	Document Date	
	03/04/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	SBMDY	S5	KDH201R	07/07/2017	GBG2585E	0	42734 69DS/GBG2585E190319
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTFHT02PX00219558	1KD2697878	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP VHSFQ4649S ACC DATE:19/03/2019 TP INS:UOI NO OF REPAIR DAYS: TOW IN:19/03/2019 DATE SURVEY: BY:LKK- AUTHORIZED ON: -TP/DS CLAIM				✓ 30.00
2	S	BP-SUBLET TO SUPPLY AND INSTALL FRONT NO. PLATE				ht ✓ 68.00
3	S	BP-SUBLET TO SUPPLY AND INSTALL BOTH COMPANY REGISTRATION STICKER.				neu ✓ 120.00
4	C	BP-ECU2 TO RESET ECU AND REPROGRAMME				✓ 180.00
5	Z	BP-SLANT SUPPLY SEALANT (NETT) FOR FRONT BONNET AND FRONT RH DOOR.				neu ✓ 120.00
6	C	BP-WS2 R/I FRONT WINDSCREEN TO FACILITATE REPAIRS.				✓ 420.00
7	C	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO FOCUS HEADLAMP AND WATER TEST FOR LEAK.				✓ 122.40
8	C	BP-MECH2 R/I AIRCON CONDENSER, RADIATOR AND INTERCOOLER TO FACILITATE REPAIRS.				✓ 360.00
9	C	BP-MECH2 R/I FRONT DASHBOARD, AIRCON BLOWER AND OTHER ATTACHMENT TO FACILITATE REPAIRS.				✓ 1440.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Charge Summary	Total
	Please acknowledge receipt of vehicle	Parts	Tanaka 97445744/67446
		Labour	- WP 4/4/19 11am
		Materials	Recovery before paint
		Lubrication/Fluid	sure taken to car
		Others	
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey below after spray painting • To dentlaw damaged vehicles during inspection			Amount Due
			* check repair cost x 12 days

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Supplementary demand must be surveyed and is subject to final approval from DATE

03/04/2019

Acknowledged by Repairer

Signature:

Date:

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO

GBG2585E

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

CUSTOMER

**Borneo Motors**

3942046

3942046



Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sgToyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no: 6631-1188Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000019/ICUOI1	M/s Kelantan Electric Co 3 Penjuru Close Singapore 608627 Mobile: 83999247
	Document No	
	Document Date	
	0	
	03/04/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	SBMDY	S5	KDH201R	07/07/2017	GBG2585E	0	42734 69DS/GBG2585E190319
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTFHT02FX00219558	1KD2697878	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	C	BP-MECH2 TO REPLACE BOTH FRONT AIRBAG AND / BOTH FRONT SEAT BELTS.				✓ 720.00
11	C	BP-LAB2 TO TRANSFER FRONT RH DOOR BOARD, GLASS / AND OTHER ATTACHMENT TO NEW PANEL.				✓ 360.00
12	C	BP-LAB2 R/I FRONT CARPET, TRIMMING, SEATS / AND ALL OTHER ATTACHMENT TO FACILITATE REPAIRS.				✓ 360.00
13	C	BP-LAB2 TO REPLACE FRONT ACCIDENT DAMAGE PARTS. / STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.				✓ 4320 5248.00
14	C	BP-RES2 TO SPRAY PAINT ON FRONT ACCIDENT / AFFECTED AREAS.				✓ 3540 4720.00
15	1	T81130-26731 UNIT ASSY, HEADLAMP, /	1.00	731.80	✓	✓ 731.80
16	2	T81170-26731 UNIT ASSY, HEADLAMP, /	1.00	731.80	✓	✓ 731.80
17	3	T89170-26400 SENSOR ASSY, AIR BAG /	1.00	904.70	✓	✓ 904.70
18	4	T89173-59275 SENSOR, AIR BAG, FR /	1.00	319.60	✓	✓ 319.60
19	5	T89173-59275 SENSOR, AIR BAG, FR /	1.00	319.60	✓	✓ 319.60
20	6	T85315-26100 FRONT WASHER JAR, /	1.00	59.10	✓	✓ 59.10
21	7	T86520-20300 LOW-PITCHED HORN ASSY, (MARUKO) /	1.00	114.30	✓	✓ 114.30
22	8	T88450-26120 A/C CONDENSER ASSY, /	1.00	1663.40	✓	✓ 1663.40
23	9	T88711-2F310 HOSE, DISCHARGE /	1.00	482.10	✓	✓ 482.10
24	0	T88712-2F360 HOSE, SUCTION /	1.00	477.90	✓	✓ 477.90

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
✓	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3942047

TO SECURITY GUARD

3942047

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 03/04/2019
TIME 16:46

VEHICLE NO GBG2585E

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**



Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sgToyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000019 / ICUOI1	M/s Kelantan Electric Co 3 Penjuru Close Singapore 608627 Mobile: 83999247
	Document No 0	
	Document Date 03/04/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	SBMDY	S5	KDH201R	07/07/2017	GBG2585E	0	42734 69DS/GBG2585E190319
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTFHT02PX00219558	1KD2697878	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
25	1	T88715-26390 A/C DISCHARGE TUBE,	1.00	225.00	?	225.00
26	2	T88710-2F620 A/C TUBE & ACCESSORY,	1.00	104.20	?	104.20
27	3	T88716-2N121 TUBE, LIQUID, NO.1	1.00	291.60	?	291.60
28	4	T88717-2F680 TUBE SUCTION NO. 1	1.00	528.50	?	528.50
29	5	T88719-33020 SENSOR, AIR	1.00	438.00	?	438.00
30	6	T15710-30020 COOLER ASSY, OIL	1.00	970.10	?	970.10
31	7	T16400-30163 RADIATOR ASSY	1.00	2195.90	?	2195.90
32	8	S08889-80102 COOLANT, SLIC&S	2.00	73.80	15.00	125.46
33	9	T16470-75124 RADIATOR RESERVE TANK,	1.00	529.10	?	529.10
34	0	T16360-30023 FAN ASSY, W/MOTOR	1.00	3499.20	?	3499.20
35	1	T16264-75170 HOSE, WATER BY-PASS,	1.00	20.80	?	20.80
36	2	T16261-75230 HOSE, WATER BY-PASS	1.00	20.80	?	20.80
37	3	T17700-30281 CLEANER ASSY, AIR	1.00	666.60	?	666.60
38	4	T17750-30040 INLET ASSY, AIR	1.00	95.30	?	95.30
39	5	T17311-30050 AIR-INLET DUCT NO 1,	1.00	95.90	?	95.90
40	6	T17940-30051 INTERCOOLER ASSY	1.00	1588.90	?	1588.90
41	7	T17893-30060 RESONATOR, INTAKE	1.00	31.80	?	31.80
42	8	T17945-30040 INTERCOOLER BRACKET,	1.00	59.10	?	59.10
43	9	T22204-30020 METER SUB-ASSY,	1.00	358.30	?	358.30
44	0	T17881-30150 HOSE, AIR CLEANER,	1.00	101.20	?	101.20

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3942048

TO SECURITY GUARD

3942048

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 03/04/2019
TIME 16:46

VEHICLE NO GBG2585E

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

Inchcape



Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sgToyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000019 / ICUOI1	M/s Kelantan Electric Co 3 Penjuru Close Singapore 608627 Mobile: 83999247
	Document No 0	
	Document Date 03/04/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	SBMDY	S5	KDH201R	07/07/2017	GBG2585E	0	42734 69DS/GBG2585E190319
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTFHT02PX00219558	1KD2697878	60	Raymond Seah L M	--/--/----	0.00 --/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
45	1	T17894-30020 RESONATOR, INTAKE	1.00	59.60	?	na x 59.60
46	2	T17360-30050 PIPE ASSY, AIR	1.00	160.20	?	na x 160.20
47	3	T45100-26350 BO WHEEL ASSY, STEERING	1.00	1273.50	na	✓ 1273.50
48	4	T45130-26370 BO PAD ASSY, STEERING	1.00	2445.90	na	✓ 2445.90
49	5	T84258-60020 COVER, STEERING PAD,	1.00	22.70	de	✓ 22.70
50	6	T84259-60020 COVER, STEERING PAD,	1.00	22.70	de	✓ 22.70
51	7	T45186-60040 B1 COVER, STEERING	1.00	11.40	de	✓ 11.40
52	8	T45187-60020 B1 COVER, STEERING	1.00	9.20	de	✓ 9.20
53	9	T45107-22010 WIRE SUB-ASSY, HORN	1.00	7.20	de	✓ 7.20
54	0	T84306-12160 CABLE SUB-ASSY,	1.00	414.20	dis	✓ 414.20
55	1	T52119-26650 COVER, FR BUMPER	1.00	534.30	de	✓ 534.30
56	2	S52161-OK040 PIECE, RR BUMPER	10.00	4.00	na	✓ 40.00
57	3	T52127-26200 BO COVER, FR BUMPER	1.00	13.50	de	✓ 13.50
58	4	T53112-26060 GRILLE, RADIATOR,	1.00	55.60	na	✓ 55.60
59	5	T53113-26060 GRILLE, RADIATOR,	1.00	55.60	na	✓ 55.60
60	6	T53112-26070 GRILLE, RADIATOR,	1.00	175.80	na	✓ 175.80
61	7	T52115-26170 SUPPORT, FR BUMPER	1.00	141.10	de	✓ 141.10
62	8	T52116-26170 R/FRONT BUMPER SUPPORT	1.00	141.10	de	✓ 141.10
63	9	T52131-26021 REINFORCEMENT, FR	1.00	352.90	de	✓ 352.90
64	0	T58127-26050 R/F MEMBER CROSS REINFOR	1.00	53.70	de	✓ 53.70

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3942049

TO SECURITY GUARD

3942049

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 03/04/2019
TIME 16:46

VEHICLE NO GBG2585E

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**



Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sgToyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000019 / ICUOI1	M/s Kelantan Electric Co 3 Penjuru Close Singapore 608627 Mobile: 83999247
	Document No 0	
	Document Date 03/04/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	SBMDY	S5	KDH201R	07/07/2017	GBG2585E	0	42734 69DS/GBG2585E190319
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTFHT02PX00219558	1KD2697878	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
65	1	T53036-26020 L/F MEMBER CROSS REINFOR	1.00	56.00		AM X 56.00
66	2	T57053-26030 REINFORCE SUB-ASSY,	1.00	150.60		bt + 150.60
67	3	T57104-26191 F/LOWER CROSS-MEMBER,	1.00	395.10		✓ 395.10
68	4	T53111-26510 GRILLE, RADIATOR,	1.00	378.10		✓ 378.10
69	5	T53111-26500 GRILLE, RADIATOR,	1.00	218.70		✓ 218.70
70	6	T53112-26090 GRILLE, RADIATOR,	1.00	561.30		✓ 561.30
71	7	T53301-26080 FRONT BONNET ASSY,	1.00	1006.10		✓ 1006.10
72	8	T53801-26011 R/FRONT FENDER PANEL,	1.00	264.90		✓ 264.90
73	9	T53802-26021 L/FRONT FENDER PANEL,	1.00	264.90		X 264.90
74	0	T53803-26011 R/FRT SIDE BRACKET,	1.00	43.40		✓ 43.40
75	1	T90975-02086 TOYOTA SYMBOL EMBLEM,	1.00	72.20		✓ 72.20
76	2	T53510-26060 FRONT BONNET LOCK,	1.00	92.30		✓ 92.30
77	3	T53410-26040 R/FRT BONNET HINGE,	1.00	58.30		✓ 58.30
78	4	T53420-26040 L/FRT BONNET HINGE,	1.00	58.30		AM X 58.30
79	5	T53209-26110 BRACE SUB-ASSY, HOOD	1.00	63.80		✓ 63.80
80	6	T53201-26082 SUPPORT SUB-ASSY,	1.00	371.80		✓ 371.80
81	7	T57109-26021 REINFORCEMENT	1.00	446.30		✓ 446.30
82	8	T55330-26310 FRT INSTRUMENT REINFORCEMENT,	1.00	648.70		bt: 648.70
83	9	T73970-26050 B1 AIR BAG ASSY, INSTR	1.00	3588.50		✓ 3588.50
84	0	T55300-26120 B0 PANEL ASSY,	1.00	815.30		✓ 815.30

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3942050

TO SECURITY GUARD

3942050

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 03/04/2019
TIME 16:46

VEHICLE NO GBG2585E

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**



Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sgToyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 129462
Tel no.: 6631-1188Co Reg No : 196700086Z
GST Reg No : MR-8500000-9**ESTIMATE**

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail	Account No	Customer Detail
United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000019 / ICUOI1	M/s Kelantan Electric Co 3 Penjuru Close Singapore 608627 Mobile: 83999247
	Document No 0	
	Document Date 03/04/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	SAMDY	S5	KDH201R	07/07/2017	GBG2585E	0	42734 69DS/GBG2585E190319
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTFHT02PX00219558	1KD2697878	60	Raymond Seah L M	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
85	1	T56118-26020 DAM, WINDOW GLASS	1.00	18.30	?	18.30
86	2	T56117-26060 FRT W/SCREEN DAM KIT,	1.00	38.90	?	38.90
87	3	T53866-26011 R/FRT FENDER SEAL	1.00	18.30	?	18.30
88	4	T55877-26030 R/FRT VENT COWL COVER	1.00	25.70	?	25.70
89	5	T61123-26020 PANEL, COWL SIDE	1.00	180.40	?	180.40
90	6	T61124-26010 PANEL, COWL SIDE,	1.00	180.40	?	180.40
91	7	T61101-26040 PANEL SUB ASSY, COWL	1.00	151.80	?	151.80
92	8	T61102-26030 PANEL SUB-ASSY, COWL	1.00	151.20	?	151.20
93	9	T55700-26440 PANEL ASSY, COWL FR	1.00	737.90	?	737.90
94	0	T75531-26071 FRONT W/SCREEN MLDG,	1.00	76.80	?	76.80
95	1	T67001-26302 PANEL SUB-ASSY, FR	1.00	1844.10	?	1844.10
96	2	T68610-26041 CHECK ASSY, FR DOOR	1.00	156.60	?	156.60
97	3	T67863-26010 WEATHERSTRIP, FR	1.00	50.00	?	50.00
98	4	T68710-26022 R/FRT DOOR TOP HINGE,	1.00	93.50	?	93.50
99	5	T68730-26012 R/FRT DOOR LOW HINGE,	1.00	93.50	?	93.50
100	6	T73210-26770 CO BELT ASSY, FR SEAT,	1.00	851.00	?	851.00
101	7	T73220-26530 CO BELT ASSY, FR SEAT,	1.00	851.00	?	851.00
102	8	T62413-26210 BO GARNISH, CTR PILLAR,	1.00	201.80	?	201.80
103	9	T62414-26220 BO GARNISH, CTR PILLAR,	1.00	223.80	?	223.80

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	58,930.26 / 53,508.26
	Please acknowledge receipt of vehicle	Parts	39,239.86	
		Labour	14,080.40	GST 7.00%
		Materials	188.00	3,745.58
		Lubrication/Fluid	0.00	Less
		Others	0.00	0.00
			Amount Due	57,253.84

PLEASE TEAR ALONG PERFORATED LINE

3942051

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 03/04/2019
TIME 16:46

58,930.40

3942051

VEHICLE NO GBG2585E

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD**Borneo Motors**

Inchope


CUSTOMER

Model Name HIACE
 Model -----KDH201R-SBMDY
 VIN/VDS (Frame No) --JTFHT02PX00219558
 (1312-)RHD

Catalog Code (711360)
 (KDH201R-SBMDY
 (KDH201-0219558)

Prod. Date (YYYYMM) 201702
 Fig-No. 55-51

KDH212, 229, LH212, 222, TRH213, 229




PNC	Part Name	Part Number	Q'ty	L/P
55330B	REINFORCEMENT ASSY, INSTRUMENT PANEL	55330-26310	01	XXXXXXXXXX
73970A	AIR BAG ASSY, INSTRUMENT PANEL PASSENGER	73970-26050-B1	01	XXXXXXXXXX
55301	PANEL SUB-ASSY, INSTRUMENT	55300-26120-B0	01	XXXXXXXXXX

2960.30

Model Name HIACE
 Model-----KDH201R-SBMDY
 VIN/VDS (Frame No)--JTFHT02PX00219558
 (1312-)

Catalog Code (711360)
 (KDH201R-SBMDY
 (KDH201 -0219558)

Prod. Date (YYYYMM) 201702
 Fig-No. 84-21



PNC	Part Name	Part Number	Q'ty	L/P
89173A	SENSOR, AIR BAG, FRONT RH	89173-59275	01	(XXXXXXXXXX)
89174A	SENSOR, AIR BAG, FRONT LH	89173-59275	01	(XXXXXXXXXX)
89170	SENSOR ASSY, AIR BAG	89170-26400	01	(XXXXXXXXXX)

Model Name HIACE

Model -----KDH201R-SBMDY

VIN/VDS (Frame No)--JTFHT02PX00219558

(1312-)TRH201,22#..4FC,5F ; (1312-

,222,TRH200,203,213..02S,03S,06S,10S,11S,12S,13S,14S,15S,16S

4-SPOKE,W(AIR BAG)


Catalog Code (711360)

(KDH201R-SBMDY

(KDH201 -0219558)

Prod. Date (YYYYMM) 201702

Fig-No. 45-04



456501

PNC	Part Name	Part Number	Q'ty	L/P
45100	WHEEL ASSY, STEERING	45100-26350-B0	01	(XXXXXXXXXX)
45130	BUTTON ASSY, HORN	45130-26370-B0	01	(XXXXXXXXXX)
84258	COVER, STEERING PAD, RH	84258-60020	01	(XXXXXXXXXX)
84259	COVER, STEERING PAD, LH	84259-60020	01	(XXXXXXXXXX)
45186	COVER, STEERING WHEEL, LOWER NO.2	45186-60040-B1	01	(XXXXXXXXXX)
45187	COVER, STEERING WHEEL, LOWER NO.3	45187-60020-B1	01	(XXXXXXXXXX)
45107	WIRE SUB-ASSY, HORN BUTTON	45107-22010	01	(XXXXXXXXXX)



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota M account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no: 6631 1100

ESTIMATE

Account Detail		Account No	Customer Detail	
United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000019/ICU011	M/s Kelantan Electric Co 3 Penjuru Close	
		Document No	Singapore 608627	
		0	Mobile: 83999247	
		Document Date		
		21/05/2019		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	SEMDY	S5	KDH201R 07/07/2017	GBG2585E	0	42734	69DS/GBG2585E190319
Chassis No		Engine No		Terms	Service Engineer	Vehicle In	Collected On
JTFHT02PX00219558		1KD2697878		60	Raymond Seah L M	08/04/2019 8.00	08/04/2019 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	2	BP-SUNDRY SUNDRIES TP VEHSEFQ4649S ACC DATE:19/03/2019 TP INS:UOI NO OF REPAIR DAYS:12 TOW IN:19/03/2019 DATE SURVEY:04/04/2019 BY:LKK-TAUFIKH AUTHORISED ON:12/04/2019 -TP/DS CLAIM				30.00
2	S	BP-SUBLET TO SUPPLY AND INSTALL FRONT NO. PLATE	E33			68.00
3	S	BP-SUBLET TO SUPPLY AND INSTALL BOTH COMPANY REGISTRATION STICKER.	E33			120.00
4	S	BP-SUBLET SUPPLY SEALANT (NETT) FOR FRONT BONNET AND FRONT RH DOOR.	A45			120.00
5	S	BP-SUBLET R/I FRONT WINDSCREEN TO FACILITATE REPAIRS.	A45			420.00
6	S	BP-SUBLET TO CHECK WIRING AND LIGHTING. TO FOCUS HEADLAMP AND WATER TEST FOR LEAK.	A45			122.40
7	S	BP-SUBLET R/I AIRCON CONDENSER, RADIATOR AND INTERCOOLER TO FACILITATE REPAIRS.	A45			360.00
8	S	BP-SUBLET R/I FRONT DASHBOARD, AIRCON BLOWER AND OTHER ATTACHMENT TO FACILITATE REPAIRS.	A45			1440.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	Amount Due
		Others	

PLEASE TEAR ALONG PERFORATED LINE

3968927

3968927

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO GBG2585E

CUSTOMER

DATE 21/05/2019
TIME 12:44

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Lt

Online Service Booking :

Toyota Body Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept.	S1000019 / ICUOI1	M/s Keiantan Electric Co 3 Penjuru Close Singapore 608627 Mobile: 83999247
	Document No 0	
	Document Date 21/05/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	SBMDY S5	KDH201R	07/07/2017	GBG2585E	0	42734	69DS/GBG2585E190319
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTFHT02PX00219558	1KD2697878	60	Raymond Seah L M	08/04/2019	8.00	08/04/2019	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
9	S	BP-SUBLET TO REPLACE BOTH FRONT AIRBAG AND BOTH FRONT SEAT BELTS.	A45			720.00
10	S	BP-SUBLET TO TRANSFER FRONT RH DOOR BOARD, GLASS AND OTHER ATTACHMENT TO NEW PANEL.	A45			360.00
11	S	BP-SUBLET R/L FRONT CARPET, TRIMMING, SEATS AND ALL OTHER ATTACHMENT TO FACILITATE REPAIRS.	A45			360.00
12	S	BP-SUBLET TO REPLACE FRONT ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.	A45			4320.00
13	S	BP-SUBLET TO SPRAY PAINT ON FRONT ACCIDENT AFFECTED AREAS.	A45			3540.00
14	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00
15	1	T81130-26731 UNIT ASSY, HEADLAMP,	1.00	731.80		✓ 731.80
16	2	T81170-26731 UNIT ASSY, HEADLAMP,	1.00	731.80		✓ 731.80
17	3	T89173-59275 SENSOR, AIR BAG, FR	1.00	319.60		✓ 319.60
18	4	T89173-59275 SENSOR, AIR BAG, FR	1.00	319.60		✓ 319.60
19	5	T88450-26120 A/C CONDENSER ASSY	1.00	1663.40		✓ 1663.40
20	6	T16400-30163 RADIATOR ASSY	1.00	2195.90		✓ 2195.90
21	7	S08889-80102 COOLANT, SLIC&&&	2.00	73.80		✓ 147.60
22	8	T17700-30281 AIR CLEANER ASSY,	1.00	666.60		✓ 666.60
23	9	T17750-30040 INLET AIR CLEANER	1.00	95.30		✓ 95.30

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3968928

TO SECURITY GUARD

3968928

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 21/05/2019
TIME 12:44

VEHICLE NO GBG2585E

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail		Account No		Customer Detail	
United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000019 / ICUOI1		M/s Kelantan Electric Co 3 Penjuru Close	
		Document No		Singapore 608627	
		0		Mobile: 83999247	
		Document Date			
		21/05/2019			

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	SBMDY S5	KDH201R	07/07/2017	GBG2585E	0	42734	69DS/GBG2585E190319

Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On
JTFHT02FX00219558	1KD2697878	60	Raymond Seah L M	08/04/2019 8.00	08/04/2019 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
24	0	T52119-26650 COVER, FR BUMPER	1.00	534.30		✓ 534.30
25	1	S52161-OK040 PIECE, RR BUMPER	10.00	4.00		✓ 40.00
26	2	T52127-26200 BO COVER, FR BUMPER	1.00	13.50		✓ 13.50
27	3	T53112-26060 FRT LWR RADIATOR GRILLE,	1.00	55.60		✓ 55.60
28	4	T53113-26060 L/FRT BUMPER GRILLE	1.00	55.60		✓ 55.60
29	5	T53112-26070 GRILLE, RADIATOR,	1.00	175.80		✓ 175.80
30	6	T52115-26170 SUPPORT, FR BUMPER RH	1.00	141.10		✓ 141.10
31	7	T52116-26170 SUPPORT, FR BUMPER LH	1.00	141.10		✓ 141.10
32	8	T52131-26021 REINFORCEMENT, FR	1.00	352.90		✓ 352.90
33	9	T58127-26050 R/F MEMBER CROSS REINFOR	1.00	53.70		✓ 53.70
34	0	T53111-26510 GRILLE, RADIATOR,	1.00	378.10		✓ 378.10
35	1	T53111-26500 GRILLE, RADIATOR,	1.00	218.70		✓ 218.70
36	2	T53112-26090 GRILLE, RADIATOR,	1.00	561.30		✓ 561.30
37	3	T53301-26080 HOOD SUB-ASSY	1.00	1006.10		✓ 1006.10
38	4	T53801-26011 R/F FRONT FENDER SUB-ASSY,	1.00	264.90		✓ 264.90
39	5	T90975-02086 EMBLEM, SYMBOL	1.00	72.20		✓ 72.20
40	6	T53510-26060 FRONT BONNET LOCK ASSY,	1.00	92.30		✓ 92.30
41	7	T53201-26082 SUPPORT SUB-ASSY,	1.00	371.80		✓ 371.80
42	8	T57109-26021 REINFORCEMENT	1.00	446.30		✓ 446.30
43	9	T55330-26310 FRT INSTRUMENT REINFORCEMENT	1.00	648.70		✓ 648.70

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	Amount Due
		Others	

PLEASE TEAR ALONG PERFORATED LINE

3968929

3968929

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 21/05/2019
TIME 12:44

VEHICLE NO GBG2585E

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Inchcape



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 120462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000019 / ICUOI1	M/s Kelantan Electric Co 3 Penjuru Close Singapore 608627 Mobile: 83999247
	Document No	
	Document Date	
	0	
	21/05/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	SBMDY	S5	KDH201R	07/07/2017	GBG2585E	0	42734 69DS/GBG2585E190319
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTFHT02FX00219558	1KD2697878	60	Raymond Seah L M	08/04/2019	8.00	08/04/2019	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
44	0	T55300-26120 BO PANEL ASSY,	1.00	815.30		✓ 815.30
45	1	T89170-26400 SENSOR ASSY, AIR BAG	1.00	904.70		✓ 904.70
46	2	T17311-30050 DUCT, AIR INLET	1.00	95.90		✓ 95.90
47	3	T45100-26350 BO WHEEL ASSY, STEERING	1.00	1273.50		✓ 1273.50
48	4	T45130-26370 BO PAD ASSY, STEERING	1.00	2445.90		✓ 2445.90
49	5	T84258-60020 COVER, STEERING PAD,	1.00	22.70		✓ 22.70
50	6	T84259-60020 COVER, STEERING PAD,	1.00	22.70		✓ 22.70
51	7	T45186-60040 B1 COVER, STEERING	1.00	11.40		✓ 11.40
52	8	T45187-60020 B1 COVER, STEERING	1.00	9.20		✓ 9.20
53	9	T57104-26191 CROSSMEMBER, FR	1.00	395.10		✓ 395.10
54	0	T53803-26011 BRACKET SUB ASSY	1.00	43.40		✓ 43.40
55	1	T53410-26041 HINGE ASSY, HOOD RH	1.00	58.30		✓ 58.30
56	2	T73970-26050 B1 AIR BAG ASSY, INSTR	1.00	3588.50		✓ 3588.50
57	3	T67001-26302 PANEL ASSY, FR DR RH	1.00	1844.10		✓ 1844.10
58	4	T68610-26041 CHECK ASSY, FR DOOR	1.00	156.60		✓ 156.60
59	5	T67863-26010 WEATHERSTRIP, FR	1.00	50.00		✓ 50.00
60	6	T73210-26770 CO BELT ASSY, FR SEAT,	1.00	851.00		✓ 851.00
61	7	T73220-26530 CO BELT ASSY, FR SEAT,	1.00	851.00		✓ 851.00
62	8	T17940-30051 INTERCOOLER ASSY	1.00	1588.90		✓ 1588.90
63	9	T17945-30040 BRACKET, INTERCOOLER	1.00	59.10		✓ 59.10

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

396893C

396893C

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 21/05/2019
TIME 12:44

VEHICLE NO GBG2585E

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Moto

Inchcode



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631-1188

Account Detail	Account No	Customer Detail
United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000019 / ICU011 Document No 0 Document Date 21/05/2019	M/s Kelantan Electric Co 3 Penjuru Close Singapore 608627 Mobile: 83999247

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	SBMDY	S5	KDH201R	07/07/2017	GBG2585E	0	42734 69DS/GBG2585E190319
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTFHT02PX00219558	1KD2697878	60	Raymond Seah L M	08/04/2019	8.00	08/04/2019	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
64	0	T45107-22010 WIRE SUB-ASSY, HORN	1.00	7.20		✓ 7.20
65	1	T84306-12160 CABLE SUB ASSY	1.00	414.20		✓ 414.20
66	2	T57053-26030 REINFORCE SUB-ASSY,	1.00	150.60		✓ 150.60
67	3	T53420-26041 HINGE ASSY, HOOD, LH	1.00	57.90		✓ 57.90
68	4	T68710-26022 HINGE ASSY DOOR	1.00	93.50		✓ 93.50
69	5	T68730-26012 HINGE ASSY DOOR	1.00	93.50		✓ 93.50
70	6	T44610-26820 BOOSTER ASSY, BRAKE	1.00	1517.50		✓ 1517.50
71	7	T82020-26597 HARNESS ASSY, WIRING	1.00	2344.70		✓ 2344.70
72	8	T82151-26571 WIRE, FR DOOR, RH	1.00	529.70		✓ 529.70
73	9	T53245-26040 BRACKET, HEADLAMP	1.00	20.30		✓ 20.30
74	0	T88715-26390 TUBE, DISCHARGE	1.00	225.00		✓ 225.00
75	1	T88710-2F620 TUBE, ACCESSORY	1.00	104.20		✓ 104.20
76	2	T88716-2N121 TUBE, LIQUID, NO.1	1.00	291.60		✓ 291.60
77	3	T88717-2F680 TUBE SUCTION, NO.1	1.00	528.50		✓ 528.50
78	4	T16573-30030 HOSE, RADIATOR, NO.3	1.00	38.60		✓ 38.60
79	5	T55405-26220 B1 INSTRUMENT PANEL CLUSTER	1.00	550.20		✓ 550.20
80	6	T82143-26022 WIRE, INSTRUMENT	1.00	24.40		✓ 24.40
81	7	T53209-26100 BRACE, HOOD LOCK	1.00	35.80		✓ 35.80
82	8	T90075-65002 COVER, SOCKET	1.00	17.10		✓ 17.10
83	9	T90075-60077 PLUG, SOCKET	1.00	16.90		✓ 16.90

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	Less
		Labour	
		Materials	
		Lubrication/Fluid	
		Others	Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3968931

TO SECURITY GUARD

3968931

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 21/05/2019
TIME 12:44

VEHICLE NO GBG2585E

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000019/ICUOI1	M/s Kelantan Electric Co 3 Penjuru Close Singapore 608627 Mobile: 83999247
	Document No 0	
	Document Date 21/05/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	SBMDY	S5	KDH201R	07/07/2017	GBG2585E	0	42734 69DS/GBG2585E190319
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
JTFHT02PX00219558	1KD2697878	60	Raymond Seah L M	08/04/2019	8.00	08/04/2019	18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
84	0	T53245-26040 R/FRT H/LAMP BRACKET,	1.00	20.30		20.30
85	1	T90981-13058 BULB	1.00	78.60		78.60
86	2	T16360-30023 FAN ASSY, W/MOTOR	1.00	3499.20		3499.20
87	3	TBB105-D31R BOSCH BATTERY 105D31R	1.00	210.00		210.00
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 38,452.40	50,612.80
		Labour 210.00	GST 7.00% 3,542.90
		Materials 11,950.40	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 54,155.70

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO GBG2585E

CUSTOMER

DATE 21/05/2019
TIME 12:44

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

inchcape

2021 04

38,662.40
- 15,464.96
= 23,197.44

3968932

3968932

Vehicle Diagnostic Report

1KDFTV
057375 km

GBG2585E

Borneo Motors

Printed By: Default User(1)

22/5/2019 3:38:03 PM

Health Check Results All Systems(1 of 1)

Enhanced

System	DTC Related Information						RoB	Calibration
	FFD	DTC	Curr Conf	Pend	Hist	Test Failed		
Air Conditioner	No	B1412			X		-	-
SRS Airbag	No	B1801			X		-	8917F26070
Engine and ECT							-	326K4100
							-	A2501000
Cruise Control							-	-
Combination Meter							-	8380026E4103

Vehicle Diagnostic Report

1KDFTV
057375 km

GBG2585E

Borneo Motors

Printed By: Default User(1)

22/5/2019 3:39:01 PM

Health Check Results

All Systems(1 of 1)

Enhanced

System	DTC Related Information						RoB	Calibration
	FFD	DTC	Curr Conf	Pend	Hist	Test Failed		
Engine and ECT							-	326K4100
							-	A2501000
Cruise Control							-	-
Air Conditioner							-	-
Combination Meter							-	8380026E4103
SRS Airbag							-	8917F26070



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota M account & more!

Borneo Motors (Singapore) Pte Lt

Online Service Booking:
www.toyota.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

ESTIMATE

Account Detail	Account No	Customer Detail
United Overseas Insurance Ltd 3 Anson Road #28-01 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000019/ICUOI1 Document No 0 Document Date 21/05/2019	M/s Kelantan Electric Co 3 Penjuru Close Singapore 608627 Mobile: 83999247

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	SBMDY	S5	KDH201R	07/07/2017	GBG2585E	0	42734 69DS/GBG2585E190319
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		

JTFHT02PX00219558 1KD2697878 60 Raymond Seah L M 08/04/2019 8.00 08/04/2019 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	M	BP-REC TO CONDUCT ACCIDENT REPAIR AT LIMIT \$32000.00				32000.00
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 0.00 Labour 32,000.00 Materials 0.00 Lubrication/Fluid 0.00 Others 0.00	32,000.00 GST 7.00% 2,240.00 Less 0.00 Amount Due 34,240.00

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 21/05/2019
TIME 14:58

VEHICLE NO GBG2585E

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

incacape



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD		Ref : CS/UOI19006015/T1sd3e2		
3 ANSON ROAD #28-01 SPRINGLEAF TOWER SINGAPORE 079909		Date : 09-10-2019		
		Code : UOI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SFQ 4649S	Veh. Inspected	GBG 2585E	
Policy No.		Coverage (\$)	0.00	
Claim No.	M12D10211904	Excess (\$)	0.00	
Assign From	JENNY LEW	Assign Date	03/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTFHT02PX00219558	Colour	SILVER	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/03/2019	Inspection Date	04/04/2019	
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 2585E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SUNDRIES (SN)	NECESSARY	30.00	30.00
1	FRONT NO. PLATE (SN)	BENT	68.00	68.00
1	COMPANY REGISTRATION STICKER (SN)	NECESSARY	120.00	120.00
1	SEALANT (SN)	NECESSARY	120.00	120.00
1	UNIT ASSY, HEADLAMP, (SN)	CRACKED	731.80	731.80
1	UNIT ASSY, HEADLAMP, (SN)	CRACKED	731.80	731.80
1	SENSOR ASSY, AIR BAG (SN)	ACTIVATED	904.70	904.70
1	SENSOR, AIR BAG, FR (SN)	ACTIVATED	319.60	319.60
1	SENSOR, AIR BAG, FR (SN)	ACTIVATED	319.60	319.60
1	FRONT WASHER JAR (SN)	NOT NECESSARY	59.10	-
1	LOW-PITCHED HORN ASSY, (MARUKO) (SN)	NOT NECESSARY	114.30	-
1	A/C CONDENSER ASSY (SN)	BENT	1,663.40	1,663.40
1	HOSE, DISCHARGE (SN)	NOT NECESSARY	482.10	-
1	HOSE, SUCTION (SN)	NOT NECESSARY	477.90	-
1	A/C DISCHARGE TUBE, (SN)	DEFORMED	225.00	225.00
1	A/C TUBE & ACCESSORY (SN)	DEFORMED	104.20	104.20
1	TUBE, LIQUID, NO.1 (SN)	BENT	291.60	291.60
1	TUBE SUCTION NO.1 (SN)	BENT	528.50	528.50
1	SENSOR, AIR (SN)	NOT NECESSARY	438.00	-
1	COOLER ASSY, OIL (SN)	NOT NECESSARY	970.10	-
1	RADIATOR ASSY (SN)	BENT	2,195.90	2,195.90
2	COOLANT, SLLC&&& (SN)	NECESSARY	147.60	147.60
1	RADIATOR RESERVE TANK (SN)	NOT NECESSARY	529.10	-
1	FAN ASSY, W/MOTOR (SN)	SERVICEABLE	3,499.20	-
1	HOSE, WATER BY-PASS (SN)	NOT NECESSARY	20.80	-
1	HOSE, WATER BY-PASS (SN)	NOT NECESSARY	20.80	-
1	CLEANER ASSY, AIR (SN)	CRACKED	666.60	666.60
1	INLET ASSY, AIR (SN)	DEFORMED	95.30	95.30
1	AIR-INLET DUCT NO 1, (SN)	DEFORMED	95.90	95.90
1	INTERCOOLER ASSY (SN)	SERVICEABLE	1,588.90	-
1	RESONATOR, INTAKE (SN)	NOT NECESSARY	31.80	-
1	INTERCOOLER BRACKET, (SN)	BENT	59.10	59.10
1	METER SUB-ASSY, (SN)	NOT NECESSARY	358.30	-
1	HOSE, AIR CLEANER, (SN)	NOT NECESSARY	101.20	-

Report Ref No. CS/UOI19006015/T1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RESONATOR, INTAKE (SN)	NOT NECESSARY	59.60	-
1	PIPE ASSY, AIR (SN)	NOT NECESSARY	160.20	-
1	WHEEL ASSY, STEERING (SN)	ACTIVATED	1,273.50	1,273.50
1	PAD ASSY, STEERING (SN)	ACTIVATED	2,445.90	2,445.90
1	COVER, STEERING PAD, (SN)	DEFORMED	22.70	22.70
1	COVER, STEERING PAD, (SN)	DEFORMED	22.70	22.70
1	COVER, STEERING (SN)	DEFORMED	11.40	11.40
1	COVER, STEERING (SN)	DEFORMED	9.20	9.20
1	WIRE SUB-ASSY, HORN (SN)	DEFORMED	7.20	7.20
1	CABLE SUB-ASSY, (SN)	DISTORTED	414.20	414.20
1	COVER, FR BUMPER (SN)	DEFORMED	534.30	534.30
10	PIECE, RR BUMPER (SN)	NECESSARY	40.00	40.00
1	COVER, FR BUMPER (SN)	DEFORMED	13.50	13.50
1	GRILLE, RADIATOR (SN)	CRACKED	55.60	55.60
1	GRILLE, RADIATOR (SN)	CRACKED	55.60	55.60
1	GRILLE, RADIATOR (SN)	CRACKED	175.80	175.80
1	SUPPORT, FR BUMPER (SN)	DISTORTED	141.10	141.10
1	R/FRONT BUMPER SUPPORT (SN)	DISTORTED	141.10	141.10
1	REINFORCEMENT, FR (SN)	BENT	352.90	352.90
1	R/F MEMBER CROSS REINFOR (SN)	BENT	53.70	53.70
1	L/F MEMBER CROSS REINFOR (SN)	NOT NECESSARY	56.00	-
1	REINFORCE SUB-ASSY (SN)	BENT	150.60	150.60
1	F/LOWER CROSS-MEMBER (SN)	BENT	395.10	395.10
1	GRILLE, RADIATOR, (SN)	CRACKED	378.10	378.10
1	GRILLE, RADIATOR (SN)	CRACKED	218.70	218.70
1	GRILLE, RADIATOR (SN)	CRACKED	561.30	561.30
1	FRONT BONNET ASSY (SN)	BENT	1,006.10	1,006.10
1	R/FRONT FENDER PANEL (SN)	BENT	264.90	264.90
1	L/FRONT FENDER PANEL (SN)	TO REPAIR SEE LABOUR	264.90	-
1	R/FRT SIDE BRACKET, (SN)	DEFORMED	43.40	43.40
1	TOYOTA SYMBOL EMBLEM, (SN)	NECESSARY	72.20	72.20
1	FRONT BONNET LOCK, (SN)	BENT	92.30	92.30
1	R/FRT BONNET HINGE (SN)	BENT	58.30	58.30
1	L/FRT BONNET HINGE (SN)	NOT NECESSARY	58.30	-
1	BRACE SUB-ASSY, HOOD (SN)	BENT	63.80	63.80

Report Ref No. CS/UOI19006015/T1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607196-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SUPPORT SUB-ASSY (SN)	BENT	371.80	371.80
1	REINFORCEMENT (SN)	BENT	446.30	446.30
1	FRT INSTRUMENT REINFORCEMENT (SN)	BENT	648.70	648.70
1	AIR BAG ASSY, INSTR (SN)	ACTIVATED	3,588.50	3,588.50
1	PANEL ASSY, (SN)	DEFORMED	815.30	815.30
1	DAM, WINDOW GLASS (SN)	NOT NECESSARY	18.30	-
1	FRT W/SCREEN DAM KIT (SN)	NOT NECESSARY	38.90	-
1	R/ FRT FENDER SEAL (SN)	NOT NECESSARY	18.30	-
1	R/FRT VENT COWL COVER (SN)	NOT NECESSARY	25.70	-
1	PANEL, COWL SIDE, (SN)	NOT NECESSARY	180.40	-
1	PANEL, COWL SIDE, (SN)	NOT NECESSARY	180.40	-
1	PANEL SUB ASSY, COWL (SN)	NOT NECESSARY	151.80	-
1	PANEL SUB-ASSY, COWL (SN)	NOT NECESSARY	151.20	-
1	PANEL ASSY, COWL FR (SN)	NOT NECESSARY	737.90	-
1	FRONT W/SCREEN MLDG, (SN)	NOT NECESSARY	76.80	-
1	PANEL SUB-ASSY, FR (SN)	BENT	1,844.10	1,844.10
1	CHECK ASSY, FR DOOR (SN)	BENT	156.60	156.60
1	WEATHERSTRIP, FR (SN)	NECESSARY	50.00	50.00
1	R/FRT DOOR TOP HINGE, (SN)	BENT	93.50	93.50
1	R/FRT DOOR LOW HINGE, (SN)	BENT	93.50	93.50
1	BELT ASSY, FR SEAT, (SN)	ACTIVATED	851.00	851.00
1	BELT ASSY, FR SEAT, (SN)	ACTIVATED	851.00	851.00
1	GARNISH, CTR PILLAR, (SN)	NOT NECESSARY	201.80	-
1	GARNISH, CTR PILLAR, (SN)	NOT NECESSARY	223.80	-
1	HINGE ASSY, HOOD, LH (SN) (ADDITIONAL)	BENT	57.90	57.90
1	BOOSTER ASSY, BRAKE (SN) (ADDITIONAL)	SERVICEABLE	1,517.50	-
1	HARNESS ASSY, WIRING (SN) (ADDITIONAL)	SERVICEABLE	2,344.70	-
1	WIRE, FR DOOR, RH (SN) (ADDITIONAL)	SERVICEABLE	529.70	-
1	BRACKET, HEADLAMP (SN) (ADDITIONAL)	CRACKED	20.30	20.30
1	HOSE, RADIATOR, NO.3 (SN) (ADDITIONAL)	DISTORTED	38.60	38.60
1	INSTRUMENT PANEL CLUSTER (SN) (ADDITIONAL)	DEFORMED	550.20	550.20
1	WIRE, INSTRUMENT (SN) (ADDITIONAL)	DEFORMED	24.40	24.40
1	BRACE, HOOD LOCK (SN) (ADDITIONAL)	DEFORMED	35.80	35.80
1	COVER, SOCKET (SN) (ADDITIONAL)	DISTORTED	17.10	17.10
1	PLUG, SOCKET (SN) (ADDITIONAL)	DISTORTED	16.90	16.90
1	R/FRT H/LAMP BRACKET, (SN) (ADDITIONAL)	CRACKED	20.30	20.30

Report Ref No. CS/UOI19006015/T1sd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	BULB (SN) (ADDITIONAL)	CRACKED	78.60	78.60
1	BOSCH BATTERY 105D31R (SN) (ADDITIONAL)	NOT NECESSARY	210.00	-
			45,062.00	29,164.20
	LABOUR			
	TO RESET ECU AND REPROGRAMME.		180.00	180.00
	R/I FRONT WINDSCREEN TO FACILITATE REPAIRS.		420.00	420.00
	TO CHECK WIRING AND LIGHTING. TO FOCUS HEADLAMP AND WATER TEST FOR LEAK.		122.40	122.40
	R/I AIRCON CONDENSER, RADIATOR AND INTERCOOLER TO FACILITATE REPAIRS.		360.00	360.00
	R/I FRONT DASHBOARD, AIRCON BLOWER AND OTHER ATTACHMENT TO FACILITATE REPAIRS.		1,440.00	1,440.00
	TO REPLACE BOTH FRONT AIRBAG AND BOTH FRONT SEAT BELTS.		720.00	720.00
	TO TRANSFER FRONT RH DOOR BOARD, GLASS AND OTHER ATTACHMENT TO NEW PANEL.		360.00	360.00
	R/I FRONT CARPET, TRIMMING, SEATS AND ALL OTHER ATTACHMENT TO FACILITATE REPAIRS.		360.00	360.00
	TO REPLACE FRONT ACCIDENT DAMAGE PARTS. STRAIGHTEN / REALIGN ALL OTHER AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF L/FRONT FENDER PANEL.		5,248.00	4,320.00
	TO SPRAY PAINT ON FRONT ACCIDENT AFFECTED AREAS.		4,720.00	3,540.00
			13,930.40	11,822.40
	GRAND TOTAL		58,992.40	40,986.60
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			32,000.00

Report Ref No. CS/UOI19006015/T1sd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.