

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SGM4106B/1904047

04th April 2019

The Manager
Motor Claim Department
AIG Asia Pacific Insurance Pte Ltd
CHARTIS Building
78 Shenton Way #07-16
Singapore 079120

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
be subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

no of Authored
L/K
15/4/19
take the Auth rep.
4 days.
2/5 \$2200

Date of Accident : 03rd April 2019

Location : IKEA Tampines Carpark

Third Party Claim Vehicle No : SKK 6915 H

Repair Cost For Vehicle No : SGM 4106 B Toyota Wish 1.8A

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear door assy RH 00/2net	1	1,122.80	\$ 1,122.80 ✓
2	Rear door regulator gear RH 11	1	201.90	\$ 201.90 X
3	Rear door power window motor RH 11	1	646.80	\$ 646.80 X
4	Rear fender RH 11	1	838.60	\$ 838.60 X
5	Rear fender cowling RH 11	1	205.50	\$ 205.50 X
6	Rear fender cowling clips RH 11	1set	38.00	\$ 38.00 X
7	Rear fender glass moulding RH 11	1	429.20	\$ 429.20 X
				\$ 3,482.80
Less 25%				\$ 870.70
				\$ 2,612.10
8	Rear wheel rim RH (s/net) 647	1	568.30	\$ 568.30 400
9	Rear wheel tyre RH (s/net) 526	1	380.00	\$ 380.00 X
10	Rear windscreen sealant (s/net) 11	1	60.00	\$ 60.00 X
				\$ 3,620.40

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SGM4106B/1904047

04th April 2019

Balance b/f \$ 3,620.40

Labour Charges :-

Cut out, renew, knocking & welding rear door assy RH, rear fender RH, remove & install all damage parts, straighten & re-align body

Amounts

\$ 980.00 520

Tuff-kote on damage parts

\$ 80.00 30

Remove & install rear door lock, regulator gear, lock & etc

\$ 120.00 60

Remove & install rear seats, carpets & upholstery

\$ 280.00 80

Remove & install rear fender glass

17 \$ 120.00 2

Computerise wheel alignment

\$ 120.00 60

Spray painting on damage parts

\$ 1,200.00 800

Labour Charge

\$ 2,900.00

Total Amount

\$ 6,520.40

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

22821
2233