

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62894656 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

22/4/2019

M/S EQ INSURANCE

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR GX4798 TOYOTA

CR42-5008963

QTY	List Items : LIST PRICE	AMOUNT
1	1 PC BONNET	509.10 Suc ✓
2	1 PC BONNET HINGE	66.50 r X
3	1 PC BONNET RUBBER	74.50 ru ✓
4	1 PC BONNET LOCK	141.45 ru ✓
5	1 PC GRILLE	381.45 cu ✓
6	1 PC GRILLE BADGE	48.50 ru ✓
7	2 PCS HEADLAMPS @ 305	610.00 Dye ✓
8	2 PCS HEADLAMP RIM 50 148	296.00 cu ✓
9	1 PC FRONT SIDELAMP	161.00 cu ✓
10	2 PCS FRONT FENDER 455.00	910.00 n/s suc 1pc
11	1 PC FRONT BUMPER	374.45 Dis ✓
12	1 PC FRONT BUMPER CLIPS	45.00 ru ✓
13	1 PC FRONT BUMPER CENTER COVER	132.00 ✓
14	2 PCS FRONT BUMPR FOG LAMP COVER 65	130.00 n/s m/s 1pc
15	1 PC FRONT BUMPER REINFORCEMENT	399.10 Suc ✓
17	1 PC FRONT BUMPER BEAM	128.00 Suc ✓
18	1 PC FRONT SUPPORT PANEL	972.10 Suc ✓
19	1 PC FRONT BRACE PANEL	151.00 ru ✓
20	1 PC FRONT HORN	95.00 Dye ✓
21	1 PC AIRCON CONDENSER	971.00 Part ✓
22	1 PC AIRCON DRIER	189.00 11 X
23	2 PCS AIRCON LIQUID PIPE 311	622.00 11 X
24	1 PC RADIATOR	1218.00 Ref/cu ✓
25	1 PC RADIATOR COWLING	166.00 cu ✓
26	1 PC RADIATOR FAN BLADE	105.00 cu ✓
27	1 PC RADIATOR FAN CLUTCH	366.00 ru ✓
28	1 PC RADIATOR TOP HOSE	45.00 11 X
29	1 PC REAR BUMPER	381.00 Dye ✓
30	1 PC REAR BUMPER CLIPS	45.00 ru ✓
31	2 PCS REAR BUMPER RED REFLECTORS 65	130.00 11 X
32	1 PC REAR BUMPER BEAM	320.00 X n/s X

not Authorized
H/W
2/5 # 7500/
5/8/19
thigher than before
10 day!

33	1 PC	TAILGATE
34	1 PC	TAILGATE LITEACE STICKER
35	1 PC	TAILGATE GLASS
36	1 PC	TAILGATE GLASS MOULDING
37	1 PC	TIALGATE NUMBR PLATE GARNISH
38	1 PC	TAILGATE LOCK
39	1 PC	TAILGATE RUBBER
40	1 PC	TAILLAMP
41	1 PC	TAILLAMP PANEL

972.00 Body 00 —
 42.00 nec ✓
 845.00 Shothel —
 171.00 nec —
 166.00 Buffers —
 361.00 D/Jm —
 299.00 12 X
 395.00 12 X
 321.00 2 X

less 25%

42	1 SET	REVERSE SENSOR
43	1 SET	SEALANT Rear windscreen
44	1 PC	70KM/H STICKER
45	1 PC	NO PLATE
46	1 PC	DOOR STICKER

Shokko \$ 250.00 200
 nec \$ 40.00 ✓
 nec \$ 15.00 10
 Bro \$ 40.00 14
 12 \$ 30.00 X

47	LABOUR :	
48	TOWING	\$ 80.00 50
49	SPRAY PAINTING front portion	\$ 1,000.00 600
50	TO TOP UP AIRCON GAS	\$ 150.00 100
51	ADJUST HEADLAMP AIM & CHECK WIRING	\$ 35.00 20

52	TO REMOVE AND REFIX WINDSCREEN	\$ 100.00 ✓
53	TO SPRAY PAINTING Rear portion	\$ 1,000.00 600
54	TO REMOVE AND RENEW REVERSE SENSOR	\$ 80.00 50
55	TO panel beating & replacing parts	\$ 1,200.00 1100
56	REAR WIRING	\$ 35.00 20
57	TUFF KOTE	\$ 120.00 50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- The resurvey is on a "Without Prejudice" basis
- No fee (to be paid) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer: _____
 Signature: _____
 Date: _____

10847.65
 252
 8135.73
 11288.73
 9031