

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLN 28E

at Workshop m/s

Performance

of

Insured:

AKH

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

+ days

Res.: Yes or No

Lump Sum:

- %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLN 28E

Yr Regn:

2015 / NOV

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

B.M.W 740 L3

C.C

2998

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading:

53491

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WPA 7E220504099682

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/40R20

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

02/04/19

D.O.A.

09/04/19

Survey held at

Performance

Des. of Damages:

Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Pip: + 10,532.95 (RED: + 19,132.90) 6.3% EXCHANGE CHECK ITEM + 12,312.90

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

D + RS: 0

Photos:

Others:

TOTAL:

Report Format:

Lump Sum / I.B.I. (\$))

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Car In = 3/2/10

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197802559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159943
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

319, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

04 APR 2019

E S T I M A T E

Estimate No. : b1 50729
Date Estimated : 04/04/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Chua Tiong Boon
87 Hazel Pk Terrace

Singapore 678920

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN28E	GD99682	06/11/2015	740Li	0

DESCRIPTION

VALUE

To replace front bumper, bonnet, air duct, bumper carrier and attachments.

850 ~~5,100.00~~

Painting front bumper and bonnet.

938 ~~2,386.00~~

To check electrical wiring systems at the front section for proper function including adjustments of headlights.

150 ~~177.00~~

To replace right headlight.

408 ~~481.00~~

To replace left headlight.

408? ~~481.00~~

To carry out body cavity preservation.
(Per panel).

100? ~~118.00~~

Sundries.

? ~~150.00~~

- front no. plate \$83 mis ✓

Total Labour 1: 8,843.00

DESCRIPTION

QTY

PRIC

VALUE

ALUMINIUM BONNET	1	3,012.85	3,012.85
SET MOUNTS PDC SENSOR FRT	1	69.00	69.00
IMPACT ABSORBER TOP	1	84.45	84.45
FRT BUMPER CARRIER	1	839.25	839.25
LH PROTECTIVE STRIP BOTTOM	1	53.25	53.25
RH PROTECTIVE STRIP BOTTOM	1	53.25	53.25
LH PROTECTIVE STRIP TOP	1	86.40	86.40
RH PROTECTIVE STRIP TOP	1	86.40	86.40
BUMPER GUARD CENTRE	1	81.05	81.05
FRT BUMPER PANEL PRIMED (PDC/PMA)	1	1,571.70	1,571.70
FRT BUMPER TOWING LUG COVER PRIMED	1	57.10	57.10
LICENCE PLATE BASE	1	70.65	70.65
GRILLE AIR INLET MIDDLE (PURE EXCEL)	1	81.45	81.45
GRILLE AIR INLET LH (PURE EXCELLENC)	1	85.10	85.10
GRILLE AIR INLET RH (PURE EXCELLENC)	1	85.10	85.10

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)



387, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Karpang Arang Road
East Coast Centre
Singapore 438188
Fax: 63469773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 50729
Date Estimated : 04/04/2019
Prepared By : Inthiran A/L Thurasamy

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLN28E	GD99682	06/11/2015	740Li	0

DESCRIPTION	QTY	PRIC	VALUE
TRIM GRILLE I-CAM ?	1	21.70	21.70
FRT LH GRILLE (BASIS) ?	1	193.55	193.55
FRT RH GRILLE (BASIS) ?	1	193.55	193.55
AIR FLAPS TOP ?	1	330.50	330.50
BMW EMBLEM ?	1	71.25	71.25
AIR DUCT BOTTOM ?	1	55.95	55.95
COVERING CROSS MEMBER (ECE) ?	1	33.65	33.65
AIR DUCT RADIATOR TOP ?	1	61.50	61.50
AIR DUCT RADIATOR BOTTOM ?	1	61.50	61.50
LH HEADLIGHT LED AHL HIGH (ICON LIG ?	1	5,847.60	5,847.60
RH HEADLIGHT LED AHL HIGH (ICON LIG ?	1	5,847.60	5,847.60
DECOUPING RING PDC TORQUE CONVERTER ?	4	5.05	20.20
ULTRASONIC SENSOR ARKTIKGRAU (WC27) ?	2	380.65	761.30

Total Parts : 19,816.85

LKK Auto Consultants hence notify
the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / (Ord Party) Uninsured losses / Direct Settlement	
Reg No. _____	Claim No. _____
Date/Time 04/04/19 09:00	Excess \$0
Surveyor's Name Ranaul	Sign _____
Surveyor's Tel 90010068	Authorised Yes / No
Authorised Time _____	Time _____
PHOTO BY SURVEYOR Yes / No PML Yes / No	
Surveyor's Note	
Working Days Recommended 4 days	

Labour 1	:	8,843.00
Parts	:	19,816.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,006.19
Grand Total	:	30,666.04

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Asher Sng (LKKAUTO)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Monday, 15 April 2019 4:38 PM
To: Asher Sng (LKKAUTO)
Subject: Re: CAR IN WORKSHOP. PLEASE ARRANGE SURVEY ASAP. REQUEST FOR DIRECT SETTLEMENT - SLN28E & SMG1057P ON 02/04/2019 *** LKK REF: CC3/AIG19006029/ea3

Follow Up Flag: Follow up
Flag Status: Flagged

Dear Asher,

We have redirected the claim to Direct Asia insured SLW7206P.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Mei Kwan (LKKAUTO) <Meikwan@lkkauto.com>
Sent: Thursday, 4 April 2019 8:36:22 PM
To: PBSP; Asher Sng (LKKAUTO)
Cc: CS A Team; 甯珺 @; assignments
Subject: RE: CAR IN WORKSHOP. PLEASE ARRANGE SURVEY ASAP. REQUEST FOR DIRECT SETTLEMENT - SLN28E & SMG1057P ON 02/04/2019 *** LKK REF: CC3/AIG19006029/ea3

'WITHOUT PREJUDICE'
SAVE AS TO COSTS

Dear Caroline,

We refer to the above matter.

Please be informed that we are currently **pending for our principal to release OI GIA report.**

Kindly note that for liability, claim negotiation and settlement, please contact Asher at 6841 6051.

Our respective case handler will look into the matter and revert to you in due course.

Meanwhile, please arrange appointment for survey.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@sime-darby.com.sg>

Sent: Thursday, 4 April, 2019 10:23 AM

To: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>; assignments <assignments@lkkauto.com>

Subject: CAR IN WORKSHOP. PLEASE ARRANGE SURVEY ASAP. REQUEST FOR DIRECT SETTLEMENT - SLN28E & SMG1057P ON 02/04/2019

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Asher Sng (LKKAUTO)

From: Lee, Ming-Yao <MingYao.Lee@aig.com>
Sent: Monday, 15 April 2019 5:06 PM
To: Asher Sng (LKKAUTO)
Subject: RE: Our Ref : 6252891147SG-003 | Accident Involving SMG1057P (OIV), SLW7206P & SLN28E on 02/04/2019 *** LKK REF: CC3/AIG19006029/ea3

Follow Up Flag: Follow up
Flag Status: Completed

Hi Asher,

Thanks for informing.

Regards,
Lee Ming Yao
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way #08-16 Singapore(079120)
Tel +(65) 6419 1769
MingYao.Lee@AIG.com | www.aig.sg



Follow us:



IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Asher Sng (LKKAUTO) [mailto:AsherSng@lkkauto.com]
Sent: 15 April 2019 16:43
To: Lee, Ming-Yao <MingYao.Lee@aig.com>
Subject: [EXTERNAL] RE: Our Ref : 6252891147SG-003 | Accident Involving SMG1057P (OIV), SLW7206P & SLN28E on 02/04/2019 *** LKK REF: CC3/AIG19006029/ea3

This message is from an external sender; be cautious with links and attachments.

Hi Ming Yao,

We refer to the earlier email.

Third party repairer inform that they have redirect the claim against SLW 7206P.

In view of above we will process to close of the case and submit our w/p report.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Mei Kwan (LKKAuto)

Sent: Wednesday, 10 April 2019 11:58 AM

To: Lee, Ming-Yao <MingYao.Lee@aig.com>; Asher Sng (LKKAuto) <AsherSng@lkkauto.com>

Cc: Admin A <admin-a@lkkauto.com>; CS A Team <cs-a@lkkauto.com>

Subject: RE: Our Ref : 6252891147SG-003 | Accident Involving SMG1057P (OIV), SLW7206P & SLN28E on 02/04/2019 *** LKK REF: CC3/AIG19006029/ea3

'WITHOUT PREJUDICE'

SAVE AS TO COSTS

Dear Sir / Madam,

Thank you for your email.

Please note that: -

LKK ref	Officer in charge
CC3/AIG19006029/ea3	Asher - 6841 6051

Our respective case handler will look into the matter and revert to you in due course.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Lee, Ming-Yao <MingYao.Lee@aig.com>

Sent: Wednesday, 10 April, 2019 11:51 AM

To: Admin A <admin-a@lkkauto.com>

Subject: Our Ref : 6252891147SG-003 | Accident Involving SMG1057P (OIV), SLW7206P & SLN28E on 02/04/2019

Hi,

We refer to above mentioned accident where we understand repairer of SLN28E, m/s Performance Motors Limited had submitted claim notification against us, being the insurer of SMG1057P.

Upon reviewing video footage which we have uploaded in Merimen and police report filed by driver of SLW7206P:

Brief Details.

On 02/04/2019 at about 1400hrs, I was driving V1) SLW7206P entering the open space carpark of Bik 265 Bukit Batok East Avenue 4. While waiting for the barrier of the gantry to be up, V1 moving slowly. V1 suddenly accelerated quite fast and I tried to swerve to the right which have caused me to hit onto V2) SMG1057P and V3) SLN28E. I hit V2 on it's rear right and since I saw there was an empty lot on my right, I decided to move into the lot hoping that V1 would come to a stop. However, V1 did not stop upon hitting the curb and ran over the drain hitting into the wall of the coffeeshop. V1 subsequently stopped but the engine was still on. I switched off the engine and alighted from V1 together with my wife who was in V1. I believed that I have stepped onto the brake but V1 did not stop moving, however I am not sure. Both V1 and V2 drivers approached each other. Police then came to the accident.

We have reasons to believe that there was no contact between our insured's vehicle, SMG1057P & third party vehicle, SLN28E.

As such, kindly assist to inform third party repairer to redirect claim to the owner of SLW7206P and kindly proceed to close the file.

Kindly notify us upon confirmation.

Regards,

Lee Ming Yao

AIG

Complex Claims Examiner

Claims | AIG Asia Pacific Insurance Pte. Ltd

AIG Building, 78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1769

MingYao.Lee@AIG.com | www.aig.sg



Celebrating 100 Years:
Visit 100.aig to learn more.

Follow us:



IMPORTANT NOTICE

* The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Apr 2019 Edit Reg		09 Apr 2019 00:00 Edit Adj Rpt	\$10,526.95 Edit Estimates	\$10,526.95 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LIM CHOON KHEE , ID: S1275751D								
Main Claimant:	CHUA TIONG BOON , ID: S0226338F								
Vehicle Reg. No.:	SLN28E	Date of Loss:	02/04/2019 14:00 - :59 [40 Months and 27 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6252891147SG	Policy/Cover Note No.:	1800153878 (Comprehensive) Coverage: 02/01/2019 - 01/01/2020						
Vehicle Reg. No. (Insured):	SMG1057P	Policy No. (Claimant):	VPA/P2138729						
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 15/04/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLN28E (6252891147SG)
[SMG1057P]
TP
CHUA TIONG BOON
Apr 2 2019 2:00PM
[LIM CHOON KHEE]
Performance Motors Limited

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser	
Video						1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print		
1	10/04/19 11:47	Video - Accident From:OO - Reg. No: SMG1057P, Claimant: LIM CHOON KHEE		Load MP4			
2	10/04/19 11:47	Video - Accident From:OO - Reg. No: SMG1057P, Claimant: LIM CHOON KHEE		Load MP4			
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	16/04/19 15:28	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>		
2	16/04/19 15:28	Chassis Number		Load JPG	<input checked="" type="checkbox"/>		
3	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
4	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
5	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
6	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
7	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
8	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
9	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
10	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
11	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
12	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
13	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
14	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
15	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
16	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
17	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
18	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
19	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
20	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
21	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
22	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
23	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
24	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
25	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
26	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
27	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
28	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
29	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
30	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
31	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		
32	16/04/19 15:28	General View		Load JPG	<input checked="" type="checkbox"/>		

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
33	16/04/19 15:28	General View	Load JPG	<input checked="" type="checkbox"/>
34	16/04/19 15:28	General View	Load JPG	<input checked="" type="checkbox"/>
35	16/04/19 15:28	General View	Load JPG	<input checked="" type="checkbox"/>
36	16/04/19 15:28	General View	Load JPG	<input checked="" type="checkbox"/>
37	16/04/19 15:28	General View	Load JPG	<input checked="" type="checkbox"/>
38	16/04/19 15:28	General View	Load JPG	<input checked="" type="checkbox"/>
39	16/04/19 15:28	General View	Load JPG	<input checked="" type="checkbox"/>
40	16/04/19 15:28	General View	Load JPG	<input checked="" type="checkbox"/>
41	16/04/19 15:28	General View	Load JPG	<input checked="" type="checkbox"/>
42	16/04/19 15:28	General View	Load JPG	<input checked="" type="checkbox"/>
43	16/04/19 15:28	General View	Load JPG	<input checked="" type="checkbox"/>
44	16/04/19 15:28	General View	Load JPG	<input checked="" type="checkbox"/>
45	16/04/19 15:28	General View	Load JPG	<input checked="" type="checkbox"/>
46	16/04/19 15:28	General View	Load JPG	<input checked="" type="checkbox"/>
47	16/04/19 15:28	General View	Load JPG	<input checked="" type="checkbox"/>
48	16/04/19 15:29	General View	Load JPG	<input checked="" type="checkbox"/>
49	16/04/19 15:29	General View	Load JPG	<input checked="" type="checkbox"/>
50	16/04/19 15:29	General View	Load JPG	<input checked="" type="checkbox"/>
51	16/04/19 15:29	General View	Load JPG	<input checked="" type="checkbox"/>
52	16/04/19 15:29	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	04/04/19 20:35	TP ESTIMATE	Load PDF	
2	04/04/19 20:35	TP GIA REPORT	Load PDF	
3	13/04/19 14:24	TP ESTIMATE - MARKED	Load PDF	
4	16/04/19 15:23	EMAIL FROM WSP DD 150419	Load PDF	
5	16/04/19 15:24	EMAIL FROM AIG DD 150419	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	05/04/19 10:41	OI GIA REPORT	Load PDF	
2	15/04/19 16:32	SLW7206P - Singapore Accident Statement	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19006029/R1EA3Q2

Date: 23/04/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800153878
Claimant Vehicle No : SLN28E **Insured Vehicle No :** SMG1057P
 Date of Loss: 02/04/2019 Nature of Claim: TP Claim No: 6252891147SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN28E**
 Make & Model: BMW 740LI, 3.0 SR LED (A) Engine No: 22649341B58B30A
 Reg. Date: 06/11/2015 (Man. Year: 2015) Chassis No: WBA7E22050GD99682
 Colour: Grey Odometer: 53491 km
 Engine Capacity: 2998 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R20 Rear Tyre Size: 245/40 R20
 Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
 Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,049.85	8,184.95	11,864.90	59.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,693.00	2,342.00	6,351.00	73.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	28,742.85	10,526.95	18,215.90	63.38
+ GST 7.00/7.00% (S\$)	2,012.00	736.89	1,275.11	63.38
Nett Amount (S\$)	30,754.85	11,263.84	19,491.01	63.38
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 09/04/2019
 Date Inspected: 09/04/2019 Inspected At: Performance Motors Limited (Alexandra)
 303 Alexandra Road, Sime Darby
 Performance Centre
 Singapore 159941
 Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	*Check	150.00 FS	*- FS
2	1		*FRONT NO PLATE	Missing	83.00 FS	*83.00 FS
3	1		*ALUMINIUM BONNET	*Check	3,012.85 FS	*- FS
4	1		*SET MOUNTS PDC SENSOR FRT	Necessary	69.00 FS	*69.00 FS
5	1		*IMPACT ABSORBER TOP	*Check	84.45 FS	*- FS
6	1		*FRT BUMPER CARRIER	*Check	839.25 FS	*- FS
7	1		*LH PROTECTIVE STRIP BOTTOM	*Check	53.25 FS	*- FS
8	1		*RH PROTECTIVE STRIP BOTTOM	Scratched	53.25 FS	*53.25 FS
9	1		*LH PROTECTIVE STRIP TOP	Missing	86.40 FS	*86.40 FS
10	1		*RH PROTECTIVE STRIP TOP	*Check	86.40 FS	*- FS
11	1		*BUMPER GUARD CENTRE	*Check	81.05 FS	*- FS
12	1		*FRT BUMPER PANEL PRIMED (PDC/PMA)	Scratched	1,571.70 FS	*1,571.70 FS
13	1		*FRT BUMPER TOWING LUG COVER PRIMED	Scratched	57.10 FS	*57.10 FS
14	1		*LICENCE PLATE BASE	Cut	70.65 FS	*70.65 FS
15	1		*GRILLE AIR INLET MIDDLE (PURE EXCEL)	Cracked	81.45 FS	*81.45 FS
16	1		*GRILLE AIR INLET LH (PURE EXCELLENC)	*Check	85.10 FS	*- FS
17	1		*GRILLE AIR INLET RH (PURE EXCELLENC)	*Check	85.10 FS	*- FS
18	1		*TRIM GRILLE I-CAM	*Check	21.70 FS	*- FS
19	1		*FRT LH GRILLE (BASIS)	*Check	193.55 FS	*- FS
20	1		*FRT RH GRILLE (BASIS)	Scratched	193.55 FS	*193.55 FS
21	1		*AIR FLAPS TOP	*Check	330.50 FS	*- FS
22	1		*BME EMBLEM	Necessary	71.25 FS	*71.25 FS
23	1		*AIR DUCT BOTTOM	*Check	55.95 FS	*- FS
24	1		*COVERING CROSS MEMBER (ECE)	*Check	33.65 FS	*- FS
25	1		*AIR DUCT RADIATOR TOP	*Check	61.50 FS	*- FS
26	1		*AIR DUCT RADIATOR BOTTOM	*Check	61.50 FS	*- FS
27	1		*LH HEADLIGHT LED AHL HIGH (ICON LIG)	*Check	5,847.60 FS	*- FS
28	1		*RH HEADLIGHT LED AHL HIGH (ICON LIG)	Scratched	5,847.60 FS	*5,847.60 FS
29	4		*DECOUPING RING PDC TORQUE CONVERTER	*Check	20.20 FS	*- FS
30	2		*ULTRASONIC SENSOR ARKTIKGRAU (WC27)	*Check	761.30 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	20,049.85	8,184.95
-------------------	-----------	----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE FRONT BUMPER ,BONNET ,AIR DUCT ,BUMPER CARRIER AND ATTACHMENTS	New	5,100.00	850.00
2	PAINTING FRONT BUMPER AND BONNET	New	2,336.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
4	TO REPLACE RIGHT HEADLIGHT	New	481.00	408.00
5	TO REPLACE LEFT HEADLIGHT (*Check)	New	481.00	0.00
6	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL) (*Check)	New	118.00	0.00
Gross Labour Cost (\$\$)			8,693.00	2,342.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >