

ASSIGNMENT

DCL



Data / Time

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. : SCN 66 B
 Name of Insured : Giam KIA KIT
 Insured Tel No. : _____ HP: _____
 Excess Sec II :SS _____ D.O.A: 24/2019
 Is driver the owner? (YES / NO) Nature of Accident : _____
 If NO, Driver Name / Age : Lu JIAYAN
 Driver Tel No. : _____ (V/L: YES / NO) _____

Claim No. : _____
 Policy No. : _____
 Make / Model : _____
 Place of Accident : _____
 OJ GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
 Insured Liability : % Final ? Yes / No



INSRS:
WSP: cheng hoo
Tel : _____
Liability : _____
RMKS: _____



INSRS:
WSP: _____
Tel : _____
Liability : _____
RMKS: _____



INSRS:
WSP: _____
Tel : _____
Liability : _____
RMKS: _____



INSRS:
WSP: _____
Tel : _____
Liability : _____
RMKS: _____

Date/ Time

STAGE DATE / PIC

Non-Reporting ltr (1st):
 Non-Reporting ltr (2nd):
 Non-Reporting ltr (Final):
 Notification ltr (if non-pickup):
 Call OI:
 After call ltr to OI: 7 10/11/2019 - khanchua
 Documentation Check List: Handler Typist
 Notification ltr (if non-pickup) ☒ ☐
 After call ltr to OI: ☒ ☐
 Authorisation To Act: ☒ ☐
 Release Voucher: ☒ ☐
 Final Repair Bill: ☒ ☐
 Car Rental Invoice: ☐ ☐
 Towing Invoice: ☐ ☐
 LTA / GIA : ☐ ☐
 Medical Bill: ☐ ☐
 PIR: ☐ ☐
 Mandate/Reject Instruction: ☐ ☐
 LOD: ☒ ☐
 Payment Breakdown Form: ☐ ☐
 Post-Repair Photos: ☐ ☐
 Others: ☐ ☐

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost: 45 SS 6,000 (7 days) Reduction: 28 %

Confirm by:

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No. : 27Email ☒ Call ☐Repair Cost: (41655) SS 6,420

If NO or B 28, Ass. Lia :

Loss of Rental (LOR): \$S (- days)

Loss of Use (LOU): \$S 900 (5100 x 9 days)

Loss of Income (LOI): \$S (\$ - x days)

LOR only ☐ LOU only ☒ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

\$S -

Medical:

\$S -

Disbursement:

\$S -

Legal Cost

\$S -

Total: \$S 7,320

Global Sum \$S:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

JP \$320

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐Payee 1: \$S 7,320

Name 1:

CHENG HOE MOTOR PTELTD

Payee 2 (if N/A)

\$S -

Name 2:

Payee 3 (if N/A)

\$S -

Name 3:

ASS. REC. BY:

REF:

AIG/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PC 70864

Yr Regn:

02, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota

c.c

2882

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading

164218

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFJ 702P600001294

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: N/A / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15 X8

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

2/4/19

D.O.I.

4/4/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

CL/S 6,000 Red \$ 2,353.65 / 38%

7 days + 1 Sunday + 1 PMS = 9 days

Data/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Data/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Fuel

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

PC7096Y
70/An6

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department \ MS KAREN

Estimate No: ES1991359/YISHUN

Date: 04 Apr 2019

Policy No: 5105344004

Veh Reg No: PC7096Y

Make/Model: TOYOTA HIACE
COMMUTER MANUAL

WS Ref: TP/AIG/YS

Claim Type: Third Party

Accident Date: 02/04/2019

TP Veh Reg No: SCN66B

Chassis No: JTFJT02P600001294

Engine No: 1KD1969940

Reg. Date: 23/02/2010

Not Notion

6/12/07

Insurance After Paint

7 days

Estimate Repair Cost to Vehicle No :PC7096Y

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 REAR BUMPER	396.10	1 PC	396.10	✓
2 REAR BUMPER CLIPS	3.50	6 PCS	21.00	✓
3 REAR BUMPER SIDE RETAINERS	49.15	2 PCS	98.30	✓
4 REAR TAILGATE	1,950.90	1 PC	1,950.90	✓
5 TAILGATE LOGO	59.60	1 PC	59.60	✓
6 TAILGATE STICKER (TOYOTA HIACE)	49.90	1 PC	49.90	✓
7 TAILGATE OUTER GARNISH	198.10	1 PC	198.10	✓
8 TAILGATE INNER LOCK	299.80	1 PC	299.80	✓
9 TAILGATE INNER RUBBER	391.20	1 PC	391.20	506.10 AS.60
10 TAILGATE INNER BOARD	240.95	1 PC	240.95	✓
11 TAILGATE DAMPERS	244.36	2 PCS	488.72	7 x 110
12 TAILLAMPS	277.62	2 PCS	555.24	✓
13 REAR END PANEL OUTER	325.50	1 PC	325.50	✓
14 REAR END PANEL INNER	742.85	1 PC	742.85	✓
15 REAR END PANEL INNER TOP BEAM	188.70	1 PC	188.70	✓
16 REAR VIEW MIRROR	473.68	1 PC	473.68	7 x 110
17 REAR SPARE TYRE TRAY HOLDER	264.13	1 PC	264.13	7 x 110
			6,744.67	
	Less 25%		1,686.17	5,058.50
Special Net				
18 REVERSE SENSOR	200.00	1 PC	200.00	✓
19 REAR WINDSCREEN GLASS GUM	40.00	1 ROLL	40.00	✓
20 STICKER - 60 KM/H	10.00	1 PC	10.00	✓
21 STICKER - EMERGENCY	30.00	1 PC	30.00	✓
			280.00	280.00
Labour				
22 TAILLAMP PANEL	290.10	2 PCS	580.20	7 x 110
			580.20	
	Less 25%		145.05	435.15

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST-201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
TEL: 64193000 **FAX:** 64153727
ATTN: Motor Claim Department \ MS KAREN

WS Ref: TP/AIG/YS
Claim Type: Third Party
Accident Date: 02/04/2019
TP Veh Reg No: SCN66B

Estimate No: ES1991359/YISHUN
Date: 04 Apr 2019
Policy No: 5105344004
Veh Reg No: PC7096Y
Make/Model: TOYOTA HIACE
 COMMUTER MANUAL
Chassis No: JTFJT02P600001294
Engine No: 1KD1969940
Reg. Date: 23/02/2010

Estimate Repair Cost to Vehicle No :PC7096Y

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
23 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
24 REMOVE & REFIX REAR BUMPER ASSY, TAIL LAMPS, TAILGATE & ATTACHMENT, LOCK ASSY, TO STRAIGHTEN, KNOCK & REPAIR REAR FLOOR BOARD PANEL, CUT, WELD & RENEW REAR END PANEL & INNER AND REALIGN THE SAME	1,200.00	1 LA	1,200.00	1000
25 REMOVE & REFIX REAR FIX WHEEL CHAIR REAR CARPET, ETC	200.00	1 LA	200.00	150
26 PUTTY & RESPRAY ON REAR FLOOR BOARD PANEL, REAR END PANEL OUTER & INNER, TAILGATE, REAR BUMPER	1,000.00	1 LA	1,000.00	900
27 RUSTPROOFING	60.00	1 LA	60.00	✓
			2,580.00	2,580.00
			Total	SS 8,353.65
			Add GST @ 7%	584.76
			Total Amount Payable	SS 8,938.41

For Cheng Hoe Motor Pte Ltd

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

AUTHORISED SIGNATURE

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Club/Association/Organisation
Owner ID:	0070F
Vehicle Details	
Vehicle No.:	PC7096Y
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE COMMUTER MANUAL
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	1KD1969940
Chassis No.:	JTFJT02P600001294
Maximum Power Output:	-
Open Market Value:	\$44,017.00
Original Registration Date:	23 Feb 2010
First Registration Date:	23 Feb 2010
Transfer Count:	0
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 03 Apr 2019

OK

Khanchna (LKK Auto)

From: Khanchna (LKK Auto)
Sent: Thursday, 7 November 2019 9:32 AM
To: Cheng Hoe Motor Pte Ltd (Yishun-June)
Cc: Admin A
Subject: OFFER - ACCIDENT INVOLVING PC 7096Y & SCN 66B ON 02/04/2019

Tracking:	Recipient	Delivery
	Cheng Hoe Motor Pte Ltd (Yishun-June)	
	Admin A	
	olivialau@lkkauto.com	Delivered: 7/11/2019 9:32 AM
	Meikwan@lkkauto.com	Delivered: 7/11/2019 9:32 AM
	shupeil@lkkauto.com	Delivered: 7/11/2019 9:32 AM

Without Prejudice
(save as to costs)

Dear Sirs/Mdm,

We refer to the above matter.

We confirm settlement as per your LOD for **\$7,320.00(all in)**.

PAYMENT ADVICE

Your Ref: _____
Third party Vehicle No: SCN66B
Claimant Vehicle No: PC7096Y

Accident on: 02/04/2019 involving vehicle no: PC7096Y & SCN66B
Location: JUNCTION OF ANG MO KIO AVE 3 & AVE 8

BREAKDOWN OF PAYMENTS

1) Repair cost	<u>\$5,420.00</u>	Payable to Cheng Hoe Motor Pte Ltd
2) Loss of Use (Repair cost)	<u>\$5,000.00</u>	Payable to Cheng Hoe Motor Pte Ltd
	<u>(2,100.00)</u>	
3) Hire of Vehicle	<u>\$5,000.00</u>	Payable to Cheng Hoe Motor Pte Ltd
4) C.T.A Search	<u>\$5,000.00</u>	Payable to Cheng Hoe Motor Pte Ltd
Total	<u>\$5,320.00</u>	

Service Address: LKK
Contact No: 67540360

We will proceed to do the necessary.

Thank you.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Khanchna | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841 2360 | email: Khanchna@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

PRE-REPAIR INSPECTION REQUEST – PC7096Y vs SCN66B (OI) on D.O.A.: 02/04/2019

From: Hor, Yinnul
To: 'assignments@lkkauto.com', Admin A (admin-a@lkkauto.com)
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur
Sent: 4/4/2019 1:45:19 PM

Hi,

Please refer to the enclosed request from **Cheng Hoe Motor Pte Ltd**.
Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.
*Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.*

Thanks & Regards,

Yin Rul, Hor (Viviane)
AIG
Claim Adjuster II, Singapore ENOL Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

Yinnul.Hor@aig.com | www.aig.sg

From: chmotor@singnet.com.sg [mailto:chmotor@singnet.com.sg]
Sent: Thursday, April 04, 2019 1:40 PM
To: Hor, Yinnul
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; chmotor@singnet.com.sg
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SCN66B AND PC7096Y ON 02/04/2019

Hi,

Our selection as below :-

Kenneth Kong LKK Auto Consultants Pte Ltd

Pls assist to arrange for survey asap..

Thanks

Rgds

June

Cheng Hoe Motor Pte Ltd

Tel : 67556142

Fax : 67557719

Tiw: 2.11pm

Person: Sharon

in ✓

1019 01#1374

Gishun Industri Park A

762761

E : ✓

From: Hor, Yinnul
Sent: Thu, 4 Apr 2019 03:57:39 +0000
To: chmotor@singnet.com.sg
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SCN66B AND PC7096Y ON 02/04/2019

Without Prejudice

Your Reference : PC7096Y
Our Reference : SCN66B

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Yin Rul, Hor (Viviane)

AIG

Claims Adjuster II, Singapore FNCIL, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

Yinrul.Hor@aig.com | www.aig.sg

From: Cheng Hoe Motor Pte Ltd (Yishun-June) [mailto:chmotor@singnet.com.sg]

Sent: Wednesday, April 03, 2019 4:57 PM

To: Md Ishak, Mohd Imran; Chin, Lee-Ying; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Kaur, Baljit; Abu Kassim, Noor Mariesa; Azlan, Syazairdina

Subject: [EXTERNAL] Repair Survey (Single Joint Expert) - PC7096Y

Caution: External Email

Dear Sir,

OUR CLIENT – PC7096Y

DOA – 2/4/19 @1440hrs

YOU

R INSURED : SCN66B

Kindly provide us of your surveyor listing for the selection on the survey.

Thank you.

Regards

June

Cheng Hoe Motor Pte Ltd

Tel : 67556142

Fax : 67557719

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the

recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Apr 2019 Edit Reg		04 Apr 2019 00:00 Edit Adj Rpt	\$S\$6,000.00 Edit Estimates	\$S\$6,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	GIAH KIA KIT, ID: 576130448								
Main Claimant:	LING KWANG HOME FOR SENIOR CITIZENS, Co. Reg. No.: TD8SS0070F								
Vehicle Reg. No.:	PC7096Y	Date of Loss:	02/04/2019 15:00 - :59 [109 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1120169366SG	Policy/Cover Note No.:	1800136465 (Comprehensive)						
Vehicle Reg. No. (Insured):	SCN668	Policy No. (Claimant):	5105344004						
		Excess:							
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 15/04/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (05/04/2019): Request To Upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*PC7096Y (1120169366SG)
[SCN66B]

TP

LING KWANG HOME FOR SENIOR CITIZENS

Apr 2 2019 3:00PM

[GIAM KIA KIT]

Cheng Hoe Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser v	
Letters/Correspondences			1 per page v ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Thumbnail Edit v p
Photos/Images			3 per page v ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		
1	20/11/19 10:27	General View		Load JPG ☒
2	20/11/19 10:27	General View		Load JPG ☒
3	20/11/19 10:27	General View		Load JPG ☒
4	20/11/19 10:27	General View		Load JPG ☒
5	20/11/19 10:27	General View		Load JPG ☒
6	20/11/19 10:27	General View		Load JPG ☒
7	20/11/19 10:27	General View		Load JPG ☒
8	20/11/19 10:27	General View		Load JPG ☒
9	20/11/19 10:27	General View		Load JPG ☒
10	20/11/19 10:27	General View		Load JPG ☒
11	20/11/19 10:27	General View		Load JPG ☒
12	20/11/19 10:27	General View		Load JPG ☒
13	20/11/19 10:27	General View		Load JPG ☒
14	20/11/19 10:27	General View		Load JPG ☒
15	20/11/19 10:27	General View		Load JPG ☒
16	20/11/19 10:27	General View		Load JPG ☒
17	20/11/19 10:27	General View		Load JPG ☒
18	20/11/19 10:27	General View		Load JPG ☒
19	20/11/19 10:27	General View		Load JPG ☒
20	20/11/19 10:27	General View		Load JPG ☒
21	20/11/19 10:27	General View		Load JPG ☒
22	20/11/19 10:27	General View		Load JPG ☒
23	20/11/19 10:27	General View		Load JPG ☒
24	20/11/19 10:27	General View		Load JPG ☒
25	20/11/19 10:27	General View		Load JPG ☒
26	20/11/19 10:27	General View		Load JPG ☒
27	20/11/19 10:27	General View		Load JPG ☒
28	20/11/19 10:27	General View		Load JPG ☒
29	20/11/19 10:27	General View		Load JPG ☒
30	20/11/19 10:27	General View		Load JPG ☒
31	20/11/19 10:27	General View		Load JPG ☒
32	20/11/19 10:27	General View		Load JPG ☒
33	20/11/19 10:28	General View		Load JPG ☒
34	20/11/19 10:28	General View		Load JPG ☒
35	20/11/19 10:28	General View		Load JPG ☒
36	20/11/19 10:28	General View		Load JPG ☒
37	20/11/19 10:28	General View		Load JPG ☒
38	20/11/19 10:28	General View		Load JPG ☒
Documentation			1 per page v ☒	

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	04/04/19 20:42	ACKNOWLEDGEMENT EMAIL TO AIG DD 04.04.2019		Load PDF	
2	04/04/19 20:42	EMAIL FROM AIG DD 04.4.19		Load PDF	
3	08/04/19 19:39	TP GIA REPORT		Load PDF	
4	08/04/19 19:48	TP GIA REPORT		Load PDF	
5	10/04/19 11:39	LETTER TO OI		Load PDF	
6	27/11/19 07:58	WORKSHOP INVOICE		Load PDF	
7	27/11/19 07:58	AUTHORISATION TO ACT FORM		Load PDF	
8	27/11/19 07:58	Release Voucher		Load PDF	
9	27/11/19 07:58	LOD		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	05/04/19 09:31	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SCN66B (Insd veh)	Model:	TOYOTA HIACE 3.0 D
	PC7096Y (TP veh)		COMMUTER (M)
Date of Accident:	02/04/2019		

Global Sum Settlement	☐ Yes	☒ No	
Repair Estimate	\$	8,938.41	
Final Repair Cost	\$	6,420.00	
Loss of Use	\$	900.00	9.00 days at \$100.00 per day
Rental (if any)	\$	0.00	days
LTA / GIA Search Fee	\$	0.00	
Others:	\$	0.00	
	\$		
Final Settlement Sum	\$	7,320.00	
Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)			
A) For <u>Non GIA Registered Workshop</u> :		Agreed Liability _____ (%)	
B) For <u>GIA Registered Workshop</u> :		BOLA Applicable: Yes/ No —BOLA Scenario No: _____	
BOLA Liability: _____ 100 _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Cheng Hoe Motor Pte Ltd	\$	7,320.00
2)		\$	

JOANNE LEE KHANG MIN

27 Nov
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19006030/KKA3Q2

Date: 27/11/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800136465
Claimant
Vehicle No : PC7096Y **Insured Vehicle No :** SCN66B
Date of Loss: 02/04/2019 **Nature of Claim:** TP **Claim No:** 1120169366SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **PC7096Y**
 Make & Model: TOYOTA HIACE, 3.0 D Commuter (M) Engine No: 1KD1969940
 Reg. Date: 23/02/2010 (Man. Year: 2009) Chassis No: JTFJT02P600001294
 Colour: White Odometer: 164218 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15X8 Rear Tyre Size: 195 R15X8
 Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm
 Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,773.65	4,320.80	1,452.85	25.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,580.00	2,230.00	350.00	13.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,353.65	6,550.80	1,802.85	21.58
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	8,353.65	6,000.00	2,353.65	28.18
+ GST 7.00/7.00% (S\$)	584.76	420.00	164.76	28.18
Nett Amount (S\$)	8,938.41	6,420.00	2,518.41	28.18
+ Loss of Use (9.0 x S\$100.00/day) (S\$)		900.00		
Nett Liability (S\$)		7,320.00		

INSPECTION

Date of Assignment: 04/04/2019
 Date Inspected: 04/04/2019 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun
 Industrial Park A
 Singapore 768761

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	396.10 FL	*396.10 FL
2	6		*REAR BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
3	2		*REAR BUMPER SIDE RETAINERS	Distorted	98.30 FL	*98.30 FL
4	1		*REAR TAILGATE	Bent	1,950.90 FL	*1,950.90 FL
5	1		*TAILGATE LOGO	Necessary	59.60 FL	*59.60 FL
6	1		*TAILGATE STICKER (TOYOTA HIACE)	Necessary	49.90 FL	*49.90 FL
7	1		*TAILGATE OUTER GARNISH	Warped	198.10 FL	*198.10 FL
8	1		*TAILGATE INNER LOCK	Dented	299.80 FL	*299.80 FL
9	1		*TAILGATE INNER RUBBER (50%)	Dented / Cut	293.40 FS	*195.60 FS
10	1		*TAILGATE INNER BOARD	Cracked	240.95 FL	*240.95 FL
11	2		*TAILGATE DAMPERS	Not Necessary	488.72 FL	*- FL
12	2		*TAILLAMPS	Cracked	555.24 FL	*555.24 FL
13	1		*REAR END PANEL OUTER	Bent	325.50 FL	*325.50 FL
14	1		*REAR END PANEL INNER	Bent	742.85 FL	*742.85 FL
15	1		*REAR END PANEL INNER TOP BEAM	Distorted / Dented	188.70 FL	*188.70 FL
16	1		*REAR VIEW MIRROR	Not Necessary	473.68 FL	*- FL
17	1		*REAR SPARE TYRE TRAY HOLDER	Not Necessary	264.13 FL	*- FL
18	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
19	1		*ROLL REAR WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS
20	1		*STICKER -60KM/H	Necessary	10.00 FS	*10.00 FS
21	1		*STICKER -EMERGENCY	Necessary	30.00 FS	*30.00 FS
22	2		*TAILLAMP PANEL	Not Necessary	580.20 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,507.07	5,602.54
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,733.42	1,281.74
Total Parts (\$\$)	5,773.65	4,320.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER ASSY ,TAILLAMPS ,TAILGATE & ATTACHMENT ,LOCK ASSY,TO STRAIGHTEN ,KNOCK & REPAIR REAR FLOOR BOARD PANEL,CUT ,WELD & RENEW REAR END PANEL & INNER AND REALIGN THE SAME	New	1,200.00	1,000.00
3	REMOVE & REFIX REAR FIX WHEEL CHAIR REAR CARPET ,ETC	New	200.00	150.00
4	PUTTY & RESPRAY ON REAR FLOOR BOARD PANEL ,REAR END PANEL OUTER & INNER,TAILGATE ,REAR BUMPER	New	1,000.00	900.00
5	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (S\$)			<u>2,580.00</u>	<u>2,230.00</u>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >