

ASS. REC. BY:

REF: CS/smo 19006031/T1+d3

Special Instruction:

Surveyor: Tau SKH

ASSIGNMENT (Office)

Minion

From (Person): Ruth Chua Gek Tiang of SMD

Date/Time: 5.4.19 8.59 a.m

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJS 4601 X

Insured:

PA9472 S

at Workshop m/s: Auto wheels motorworks

Tel:

97684247

of NO1. Bukit Batok Crescent, # 02-40

Policy No: D18MTSCBU 000367

Claim No:

CMTD 1901610

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 30.3.2019

(10:30am owner waiting) 8.4.19

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 5.5.19 9.28 a.m

Person Contacted:

Louis

Vehicle-IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SJS 4601 X - X ✓
	PA 9472 S - NS/INC 12007664/HIN D.O.A - 15/04/2012
11/4	Revised via merimen prei advise.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sampo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06, Singapore Land Tower
Singapore 048623

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ruth Chua Gek Tiang

Date: 11 Apr 2019

Preliminary Advice

Insured Vehicle No	: PA9472S	Accident Date	: 30/03/2019
TP Vehicle No	: SJS4601X	Assignment Date	: 05/04/2019
Make	: TOYOTA VIOS	Est. Duration of Repair	: 6.00
Date of Inspection	: 09/04/2019		
Inspection At	: AUTO WHEELS MOTORWORKS PTE LTD (HQ) NO.1 BUKIT BATOK CRESCENT, #02-40 WCEGA PLAZA SINGAPORE 658064		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,738.95
Revised Amount	:S\$	4,419.38
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,419.38

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Survey on "WP"

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 Apr 2019		05 Apr 2019 08:59 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by insurer]					
Insured:	HUI LEONG TRANSPORT(2010)PTE.LTD., Co. Reg. No.: 201010850C								
Main Claimant:	DS MOTOR & LEASING PTE. LTD., Co. Reg. No.: 201628527G								
Vehicle Reg. No.:	SJS4601X	Date of Loss:	30/03/2019 06:00 - :59 [115 Months and 12 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / CMTD1901610	Policy/Cover Note No.:	D18MTSCBU000367 (Comprehensive)						
Vehicle Reg. No. (Insured):	PA9472S	Policy No. (Claimant):							
		Excess:							
Repairer:	Auto Wheels Motorworks Pte Ltd (HQ) No.1 Bukit Batok Crescent, #02-40 WCEGA PLAZA, 658064 Bukit Batok - Tel: 97684247								
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Ruth Chua Gek Tiang - 6329 5153]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 16/04/2019]								
Adj Asg. Remarks:	WS: LOUIS 91928963/ VEH CMG MON 8/4 -PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Friday, 5 April 2019 8:56 AM
To: louisongautowheels@yahoo.com; 'admin-d@lkkauto.com';
'assignments@lkkauto.com'
Cc: Chua, Gek Tiang Ruth; Henry, Irene James
Subject: CMTD1901610/RUC - LKK/ PA9472S(nr) & SJS4601X ACC ON 30/03/2019 along Mandai Road toward SLE. - SUV ON MON 8/4 @10AM

Without Prejudice

Our Reference: CMTD1901610/RUC
Your Reference: SJS4601X

Hi Louis,


As spoken, we will appoint **LKK AUTO** to survey the above vehicle.

Aside to **LKK AUTO**,

Please make arrangement to conduct the survey for SJS4601X on a without Prejudice and any admission of liability basis.

Please submit with your report via Merimen upon completion of survey.

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623
Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Louis Ong [mailto:louisongautowheels@yahoo.com]

Sent: Friday, April 05, 2019 8:31 AM

To: Teo, Grace

Cc: Chua, Gek Tiang Ruth; Henry, Irene James

Subject: Re: CMTD1901610/RUC - SUV(NR)/ PA9472S & SJS4601X ACC ON 30/03/2019 along Mandai Road toward SLE.

Hi Grace,

Can help to arrange for survey on Monday 8/4/2019 @ 10am.

Customer waiting.

Survey at No1 Bukit Batok Crescent
#02-40 WCEGA PLAZA.

Thanks

Auto Wheels Motorworks PTE LTD
Louis Ong
91928963

On Tue, 2 Apr 2019 at 10:37, Teo, Grace
<grace.teo@sompo.com.sg> wrote:

Without Prejudice

Our Reference: CMTD1901610/RUC

Your Reference: SJS4601X

Hi Louis,

We acknowledged receipt of your claim documents and our in-house, Mr. Teo(98563133) will conduct the survey today.

Please be informed that **Ms. Ruth Chua** is the handler of this case.

We regret to inform that we are unable to revert on liability as we have yet to receive our insured's accident report.

Aside to Ruth,


For your update.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Louis Ong [mailto:louisongautowheels@yahoo.com]

Sent: Tuesday, April 02, 2019 8:38 AM

To: Claims - Motor Survey

Cc: Teo, Grace

Subject: Accident involved with vehicle SJS4601X and PA9472S(TP) on 30/03/2019 along Mandai Road toward SLE.

Hi,

We would like to do a Direct Settlement with you if our liability is 100%.

Can advise us on the liability and arrange for survey.

Vehicle is in.

Thanks

Auto Wheels Motorworks PTE LTD

No1 Bukit Batok Crescent

#02-40 WCEGA PLAZA

Louis Ong

91928963

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 3 May 2019 3:57 PM
To: louisongautowheels@yahoo.com; Taufikh (LKKAuto)
Cc: SUR
Subject: RE: Finalize for vehicle SJS4601X lumpsum \$3,500/- with 6 repair days

Dear Louis,

Confirm lump sum \$3500, 6days.

Please submit all relevant documents to Sompo insurance

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Louis Ong <louisongautowheels@yahoo.com>
Sent: Wednesday, 1 May 2019 9:18 AM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: Re: Finalize for vehicle SJS4601X lumpsum \$3,500/- with 6 repair days

Hi Taufikh,

The above attachment is the finalize and after paint.

Can help to finalize vehicle SJS4601X lumpsum \$3,500/- with 6 repair days.

No Supplementary.

Thanks

Auto Wheels Motorworks PTE LTD
Louis Ong
91928963

On Mon, 22 Apr 2019 at 17:47, Louis Ong
<louisongautowheels@yahoo.com> wrote:

Hi Taufikh,

The above attachment is the finalize and after paint.

Can help to finalize vehicle SJS4601X lumpsum \$3,500/- with 6 repair days.

No Supplementary.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/04/2019 15:47
Date Of Accident	30/03/2019 06:45
Exact Location Of Accident	ALONG MANDAI TOWARDS SLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJS4601X
Insured/Policyholder	
Name Of Registered Owner	DS MOTOR & LEASING PTE. LTD.
Co Reg No	201628527G
Email Address	DICKMOND@DSMOTOR.SG
Mobile Phone No	(LOCAL) +65-83021877
Alternative Phone No	OFFICE-97605007
Vehicle Particulars	
Manufacturer	TOYOTA
Model	VIOS EA-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
Insurance Company	
Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	18-MH001911-R02
Cover Note Number	
Driver	
Name of Driver	LEE TUAN YONG
NRIC No	S1773716C
Date Of Birth	19/02/1966
Occupation	OUTDOOR
Date Of Driving Pass	06/05/1987
Driving Experience	31 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-83021877
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 16 EUNOS CRESCENT #05-2855
Postcode	400016
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 30/03/2019 at 0645 hrs, I was travelling along Mandai towards SLE. As the traffic on the left lane was heavy, I was travelling straight on the centre lane. Suddenly a vehicle on the left lane abruptly filtered into my lane and I stopped. I then felt an impact from the rear of my vehicle. As I came down to check, Vehicle B (PA9472S) has collided onto the rear on my vehicle. After the impact, I felt discomfort in my neck and I went to visit the doctor.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PA9472S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	LEE TUAN YONG
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SJS4601X
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claim process.
2. This form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the GIA Records Management Group established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will be made available upon application by interested parties.
7. By the judgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available abroad.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have insured vehicles involved in this accident (a insurer(s) who have insured vehicles) involved in this accident shall be collectively referred to as the "Insurers", the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claim;
 - (ii) investigating the accident and/or faults;
 - (iii) administering my claims including the issuing of correspondence, workbooks, invoices, reports or notices to me, which could involve disclosure of certain personal data about me relating to the delivery of the same as well as on the external cases of knowledge that pass ages, and/or;
 - (iv) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) all insurer(s) who have insured vehicles) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/are be disclosed by any of the Insurers and/or GAFA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (b) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in valuing, investigating, settling or managing fraud, regulations, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulatory laws or court orders;

 Policyholder's Signature Date & Time	 Insurer's Signature (Insurer or the authorised agent) Name & Time	 Insurer's Signature Name Date & Time
--	--	---

I am fully aware that my insurer may have a 14-day period for me to decide on My Own Damage Claims.

Accident Sketch Plan

Date of Accident: 30/03/2019

SKETCH PLAN

Mandalai towards SLE



A : SJS4601X
B : PA9472S

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 30/03/2019 at 0645 hrs. I was travelling along Mandalai towards SLE. As the traffic on the left lane was heavy, I was travelling straight on the centre lane. Suddenly a vehicle on the left lane abruptly filtered into my lane and I stopped. I then felt an impact from the rear of my vehicle. As I came down to check, Vehicle B (PA9472S) has collided onto the rear on my vehicle.

After the impact, I felt discomfort in my neck and I went to visit the doctor.

- New Damage Claim
- Road Works Claim
- I am not involved in this report
- Reporting Only

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Injured Party's Signature
Date & Time



Driver's Signature
(If driver is not the policyholder)
Date & Time



Reporting Officer's Name
M/C/ID No.

AUTO WHEELS

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

ATTN: SOMPO INSURANCE

DATE: 1/4/2019
 VEHICLE NO: SJS4601X
 MODEL: TOYOTA VIOS
 YEAR: 2009
 ACCIDENT DATE: 30/03/2019
 TYPE OF CLAIM: TP CLAIM
 CLAIM ADVISOR: LOUIS ONG (91928963)
 EMAIL: louisongautowheels@yahoo.com

ESTIMATION

DESCRIPTION	QTY	LIST PRICE
PARTS		
BOOTLID	1	\$ 996.10 <i>bt -</i>
BOOTLID HINGE	2	\$ 240.60 <i>RY</i>
BOOTLID LOCK	1	\$ 195.40 <i>bt -</i>
REAR EMBLEM	1	\$ 55.40 <i>ne -</i>
REAR LOGO - VIOS	1	\$ 43.30 <i>ne -</i>
REAR LOGO E	1	\$ 39.20 <i>ne -</i>
BOOTLID OUTER GARNISH	1	\$ 211.50 <i>X AM</i>
REAR BUMPER	1	\$ 719.30 <i>de -</i>
REAR BUMPER CLIPS	10	\$ 30.00 <i>ne -</i>
REAR BUMPER RETAINER - OUTER	2	\$ 42.40 <i>LH-X^{ny} RH ne</i>
REAR BUMPER RETAINER - INNER	2	\$ 33.40 <i>LH-X^{ny} RH ne</i>
TAILLAMP	2	\$ 842.40 <i>LH-X^{ny} RH-Lens</i>
TAILLAMP PANEL	2	\$ 426.20 <i>LH-RH-RY</i>
REAR BUMPER REFLECTOR	2	\$ 280.80 <i>LH-RH-X^{ny}</i>
REAR WEATHER STRIP	1	\$ 156.70 <i>cut -</i>
END PANEL TOP GARNISH	1	\$ 178.90 <i>ea -</i>
END PANEL	1	\$ 695.70 <i>RY</i>

Signature
 1/4/19
 Taylor 9245769
 6 days
 Repair after repair
 surellhants.com
 9/4/19 2:45pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

AUTO WHEELS

MOTORWORKS PTE LTD

WCEGA PLAZA NO 1 BUKIT BATOK CRESCENT

#02-40 SINGAPORE 658064

SPARE TYRE PANEL <i>R</i>	1		RESTORE
SPARE TYRE BOARD	1	\$	415.50 <i>X NH</i>
RH REAR FENDER <i>R</i>	1		RESTORE

TOTAL:	\$	5,678.60
DISCOUNT 25%:	\$	1,419.65
	\$	<u>4,258.95</u>

S/NET

REAR NUMBER PLATE	1	\$	50.00 <i>X NH</i>
REVERSE SENSOR	1	\$	250.00 <i>200 nm ✓</i>
END PANEL SEALANT	1	\$	100.00 <i>X NH</i>
		\$	<u>400.00</u>

LABOUR

LABOUR FOR FACILITATE REPAIR - REAR		\$	1,800.00 <i>700</i>
TO RESRAY AFFECTED AREAS - BOOTLID		\$	300.00 <i>200</i>
TO RESPRAY AFFECTED AREAS - REAR BUMPER		\$	300.00 <i>200</i>
TO RESPRAY AFFECTED AREAS - END PANEL		\$	300.00 <i>200</i>
TO RESRAY AFFECTED AREAS - SPARE TYRE PANEL		\$	300.00 <i>X NH</i>
TO RESPRAY AFFECTED AREAS - RH REAR FENDER		\$	300.00 <i>200</i>
TO REMOVE AND REFIT BOOTLID COMPONENT FOR FACILITATE REPAIR		\$	250.00 <i>60</i>
RUST PROOFING		\$	80.00 <i>30</i>
SUNDARIES <i>NH</i>		\$	50.00 <i>20</i>
TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR		\$	250.00 <i>50</i>
TO REMOVE AND REFIT REVERSE SENSOR		\$	100.00 <i>30</i>
TO CHECK AND RECONNECT ALL NECESSARY WIRING		\$	50.00 <i>30</i>

TOTAL: \$ 4,080.00

TOTAL:	\$	8,738.95
7% GST:	\$	611.73
	\$	<u>9,350.68</u>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO19006031/T1TD3N2

Date: 07/05/2019

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D18MTSCBU000367
Claimant Vehicle No :	SJS4601X	Insured Vehicle No :	PA9472S
Date of Loss:	30/03/2019	Nature of Claim:	TP
		Claim No:	CMTD1901610

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJS4601X	Engine No:	1NZX953966
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY9305125615
Reg. Date:	18/08/2009 (Man. Year: 2009)	Odometer:	261119 km
Colour:	Silver		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,708.95	2,719.37	1,989.58	42.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,030.00	1,700.00	2,330.00	57.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,738.95	4,419.37	4,319.58	49.43
Approved Total (Overridden) (\$\$)		3,500.00		
	(\$\$)	8,738.95	3,500.00	5,238.95
	+ GST 7.00/7.00% (\$\$)	611.73	245.00	366.73
	Nett Amount (\$\$)	9,350.68	3,745.00	5,605.68

INSPECTION

Date of Assignment:	05/04/2019	
Date Inspected:	09/04/2019	Inspected At: Auto Wheels Motorworks Pte Ltd (HQ) No.1 Bukit Batok Crescent, #02-40 WCEGA PLAZA Singapore 658064
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 May 2019)
Parts: 143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS4601X)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BOOTLID	Bent	996.10 FL	*996.10 FL
2	2	*BOOTLID HINGE	Repair	240.60 FL	*- FL
3	1	*BOOTLID LOCK	Bent	195.40 FL	*195.40 FL
4	1	*REAR EMBLEM	Necessary	55.40 FL	*55.40 FL
5	1	*REAR LOGO-VIOS	Necessary	43.30 FL	*43.30 FL
6	1	*REAR LOGO E	Necessary	39.20 FL	*39.20 FL
7	1	*BOOTLID OUTER GARNISH	Not Necessary	211.50 FL	*- FL
8	1	*REAR BUMPER	Deformed	719.30 FL	*719.30 FL
9	10	*REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
10	1	*REAR BUMPER RETAINER -OUTER	Ns Not Necessary/Os Necessary	84.80 FL	*42.40 FL
11	1	*REAR BUMPER RETAINER -INNER	Ns Not Necessary/Os Necessary	66.80 FL	*33.40 FL
12	2	*TAILLAMP	Cracked	842.40 FL	*842.40 FL
13	2	*TAILLAMP PANEL	Repair	426.20 FL	*- FL
14	2	*REAR BUMPER REFLECTOR	Not Necessary	280.80 FL	*- FL
15	1	*REAR WEATHER STRIP	Cut	156.70 FL	*156.70 FL
16	1	*END PANEL TOP GARNISH	Cracked	178.90 FL	*178.90 FL
17	1	*END PANEL	Repair	695.70 FL	*- FL
18	1	*SPARE TYRE PANEL (NPA)	Repair	0.00 FL	*- FL
19	1	*SPARE TYRE BOARD	Not Necessary	415.50 FL	*- FL
20	1	*RH REAR FENDER (NPA)	Repair	0.00 FL	*- FL
21	1	*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
22	1	*REVERSE SENSOR	Not Working	250.00 FS	*200.00 FS
23	1	*END PANEL SEALANT	Not Necessary	100.00 FS	*- FS
24	1	*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	6,128.60	3,552.50
- List Item Discount on L Items 25.00/25.00% (S\$)	1,419.65	833.13
Total Parts (S\$)	4,708.95	2,719.37

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR FACILITATE REPAIR -REAR	New	1,800.00	700.00
2	TO RESPRAY AFFECTED AREAS -BOOTLID	New	300.00	200.00
3	TO RESPRAY AFFECTED AREAS -REAR BUMPER	New	300.00	200.00
4	TO RESPRAY AFFECTED AREAS -END PANEL	New	300.00	200.00
5	TO RESPRAY AFFECTED AREAS -SPARE TYRE PANEL	New	300.00	0.00
6	TO RESPRAY AFFECTED AREAS -RH REAR FENDER	New	300.00	200.00
7	TO REMOVE AND REFIT BOOTLID COMPONENT FOR FACILITATE REPAIR	New	250.00	60.00
8	RUST PROOFING	New	80.00	30.00
9	TO REMOVE AND REFIT REAR TRIM FOR FACILITATE REPAIR	New	250.00	50.00
10	TO REMOVE AND REFIT REVERSE SENSOR	New	100.00	30.00
11	TO CHECK AND RECONNECT ALL NECESSARY WIRING	New	50.00	30.00
Gross Labour Cost (S\$)			4,030.00	1,700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >