

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

Our Ref : MC1900281
Your Ref : SHA7384X
Date : 16/09/2019

INDIA INTERNATIONAL INSURANCE P/L
64 CECIL STREET #04/#05
IOB BUILDING
SINGAPORE 049711

Dear Sir/Madam,

Request for Direct Settlement for Accident involving our client's vehicle SKB362P and your Insured SHA7384X ON 27/03/2019 00:00 ALONG BLK 83 WHAMPOA DR MSCP LEVEL E

We refer to the above matter.

Please assess through your Insured's (SHA7384X) report and our Client (SKB362P) – LOW SAUW KHIE's report as attached and advise whether there are possibilities of direct settlement.

Please find attached the following :

- 1) Final Bill
- 2) GIA Motor Accident Report form
- 3) Certificate of Insurance, IC and Driving Licence
- 4) LTA Search

The above vehicle was surveyed by Mr Kenneth from LKK as appointed by INDIA on 29/04/2019.

We would quantify our claim as below:-

Cost of Repair	: \$775.75
Rental	: \$300.00(3 Day X \$100) Survyeor recommend 3 days. We had rented for 5 days
LTA Search	: \$7.45
=====	
Total	: \$1,083.20

Kindly acknowledge and revert on the possibility of direct settlement within 14 days.

Thank You.

Yours faithfully,

AH LIM MOTOR COMPANY
No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

Kee Mui Hong

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

M/S : INDIA INTERNATIONAL INSURANCE P/L
64 CECIL STREET #04/#05
IOB BUILDING
SINGAPORE 049711
TEL: 62238122 FAX: 62244174
ATTN: Motor Claim Department
Your Ref No: SKB362P
Claim Type: Third Party
Accident Date: 27/03/2019

Claim No: MC1900281
Final No: AL1901744
Date: 16 Sep 2019
Policy No: D18MTPV01007338
Veh Reg No: SKB362P
Make/Model: BMW 320I AT ABS D/AB
Chassis No:
TP Ins Co: INDIA

Tax Invoice-Final Repair Cost to Vehicle No :SKB362P

Description	Quantity	List Price	Amount
		SS	SS
LABOUR			
1 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	15.00	
2 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD. TO KNOCK & REPAIR REAR BUMPER,REAR FENDER LH, REAR DOOR LH,ROCKER PANEL SIDE SKIRT LH,FRT FENDER LH,FRONT SIDE MIRROR COVER LH INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	300.00	
3 TO SPRAY REAR BUMPER,REAR FENDER LH,REAR DOOR LH,ROCKER PANEL SIDE SKIRT LH,FRT FENDER LH,FRONT SIDE MIRROR COVER LH.	1 PC	400.00	
		715.00	715.00
INSURANCE			
4 MERIMEN CHARGES	1 EA	10.00	
		10.00	10.00
		Total	SS 725.00
		Add GST @ 7%	50.75
		Total Amount Payable	SS 775.75

TOTAL: SINGAPORE DOLLAR SEVEN HUNDRED SEVENTY FIVE AND CENTS SEVENTY FIVE ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 29/04/2019

For AH LIM MOTOR COMPANY

AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Industrial Park 2A
#01-09 AMK Autopoint Singapore 568047
Tel: 6483 1244 Fax: 6483 6170

E. & O. E.

AUTHORISED SIGNATURE