

AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A
 #01-09 AMK AUTOPOINT Singapore 568047
 Tel: 6483 1244 Fax: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST Reg No: M9-0009639-E

TP INSURER: India International Insurance Pte Ltd (HQ)

SURVEYOR COPY

Singapore

*LRC
10-30*

Claimant Insurer: Sompo Insurance Singapore Pte. Ltd.

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	29/03/2019
Vehicle Reg. No.:	SKB362P	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LOW SAUW KHIE		
Make/Model:	BMW 320I, 2.0 ABS D/AB 2WD 2DR GAS/D (A)	Vehicle Reg. Date:	25/04/2011
Vehicle Colour:	BLACK		
Engine No:	B250I818N46B20BD	Chassis No:	WBAPG56090NM26512
Odometer:	0 KM		
Paint Type:			
List Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	<i>3 days</i>		
Description of Accident/Loss	REFER TO THE POLICE REPORT & SKETCH PLAN BY DRIVER		
Remarks:	CAR NOT IN - TO BE ARRANGE		
Present Location:	AH LIM MOTOR COMPANY (AMK)		

*Not suitable
 Repair after paint
 Will check on consistency first
 Paying repair to old rec
 portion only*

COST OF CLAIMS	Amount
Parts	0.00
Miscellaneous Items	10.00
Labour	2,360.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	2,370.00
+ GST 7.00% (\$\$)	165.90
Nett Amount (\$\$)	2,535.90

This claim is handled by: ZILA

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 04 Apr 2019)**Parts:** M1-COUPE BMW 320I 2.0 ABS D/AB 2WD 2DR GAS/D (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Ah Lim Motor Company/SKB362P/04/04/2019 17:13**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

There are no new parts selected.

Ah Lim Motor Company/SKB362P/04/04/2019 17:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00 <i>15/</i>
2	LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	New	<i>un</i> 180.00 <i>X</i>
3	TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	New	<i>un</i> 80.00 <i>X</i>
4	TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD. TO KNOCK & REPAIR REAR BUMPER;RER FENDER LH; REAR DOOR LH;ROCKER PANEL SIDE SKIRT LH;FRT FENDER LH;FRONT SIDE MIRROR COVER LH INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	960.00 <i>300/</i>
5	TO SPRAY REAR BUMPER;REAR FENDER LH; REAR DOOR LH;ROCKER PANEL SIDE SKIRT LH;FRT FENDER LH;FRONT SIDE MIRROR COVER LH.	New	1,100.00 <i>400</i>
Gross Labour Cost (S\$)			2,360.00

Ah Lim Motor Company/SKB362P/04/04/2019 17:13. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: