

# AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047  
TEL: 6483 1244 ( 4 lines ) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg  
GST:M9-0009639-E RCB NO:06470300B

**M/S :** INDIA INTERNATIONAL INSURANCE P/L  
64 CECIL STREET #04/#05  
IOB BUILDING  
SINGAPORE 049711  
**TEL:** 62238122 **FAX:** 62244174  
**ATTN:** Motor Claim Department  
**Your Ref No:** SKB362P  
**Claim Type:** Third Party  
**Accident Date:** 27/03/2019

**Claim No:** MC1900281  
**Final No:** AL1901744  
**Date:** 16 Sep 2019  
**Policy No:** D18MTPV01007338  
**Veh Reg No:** SKB362P  
**Make/Model:** BMW 320I AT ABS D/AB  
**Chassis No:**  
**TP Ins Co:** INDIA

## Tax Invoice-Final Repair Cost to Vehicle No :SKB362P

<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Amount</u>
		<u>S\$</u>	<u>S\$</u>
<b>LABOUR</b>			
1 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	15.00	
2 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD. TO KNOCK & REPAIR REAR BUMPER,REAR FENDER LH, REAR DOOR LH,ROCKER PANEL SIDE SKIRT LH,FRT FENDER LH,FRONT SIDE MIRROR COVER LH INNER PANELS & AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	1 PC	300.00	
3 TO SPRAY REAR BUMPER,REAR FENDER LH,REAR DOOR LH,ROCKER PANEL SIDE SKIRT LH,FRT FENDER LH,FRONT SIDE MIRROR COVER LH.	1 PC	400.00	
		715.00	715.00
<b>INSURANCE</b>			
4 MERIMEN CHARGES	1 EA	10.00	
		10.00	10.00
		<b>Total</b>	<b>S\$ 725.00</b>
		<b>Add GST @ 7%</b>	<b>50.75</b>
		<b>Total Amount Payable</b>	<b>S\$ 775.75</b>

TOTAL: SINGAPORE DOLLAR SEVEN HUNDRED SEVENTY FIVE AND CENTS SEVENTY FIVE ONLY

The above vehicle was surveyed by KENNETH KONG -LKK on 29/04/2019

**For AH LIM MOTOR COMPANY**

**AH LIM MOTOR COMPANY**

No. 10 Ang Mo Kio Industrial Park 2A  
#01-09 AMK Autopoint Singapore 568047  
Tel: 6483 1244 Fax: 6483 6170

E. & O. E.

AUTHORISED SIGNATURE