COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHA 4519U

DATE 3/4/2019 17:13

MAKE :

New .	: HYUNDAI i40 Parts Description/ Labour	Type	Unit Price	A	mount	
)ty		- 7 1		\$	544.50	
	/- /			\$	22.40	
	Front Bumper Bracket Top (LH)			\$	24.60	
	Front Bumper Bracket (LH) X			\$	670.00	
	Front Door Mirror Assy (LH)			\$	107.10	
	Front Wheel Hub Cap (LH)			٥	107.10	
	SUB TOTAL			\$	1,368.60	
	Front CH Pour X regard SUB TOTAL LESS 20%			\$	273.72	
	DISCOUNTED TOTAL			\$	1,094.88	
	DISCOUNTED TOTAL					
					== 00	
	Front Door Comfort Logo (LH)			\$	75.00	N
	Service Committee Co					
	Labour Charge				200	ł
	Panel Beating			\$	400.00	
	Spray Painting Charge			\$	800.00	1
	Wiring Charge			\$	30.00	2
	Tuff Kote			\$	50.00	1
	FRT Wheel Alignment			\$	80.00	1
	TOTAL LABOUR			\$	1,360.00	
	DOTTINA TO TOTAL	8		\$	2,529.88	-
	ESTIMATE TOTAL			3	2,529.00	1
	Kahi 1 duy					
	1 4/4/19 1045hs. \\ 2 logs		honce notif	У		
	1 11 15	KK Auto C	onsuitants hence notifier of the following: before/after spray painting		1	
	11 4/4/19 1045hrs.	the Repair	Laforelatter spray	Yavru		
		. To resurve	damaged part(s) during too damaged part(s) during too as are subject to confirmation as survey is on a 1%, the	no.	basis	
	2 /21	. Parts and	damaged pants) do as are subject to confirmation by survey is on a ry, the amode assented to the re-	(Elunico	1	
	20/3	• Third pol	y survey is on a transfer of immediate them is must be re- nentary item is must be re- act to final approval from ins	anayed a	and omnany	
	P 10	• No illed	nentary item 5) must be ins	ura lice C	Olliba	
	17	is subj	nentary item 3) must be re- nentary item 3) must be re- act to final approval from ins			
	Before from pho	Lucia	Nedged by Repairer			
	Refore found Pho	Signat	re:	_		
	000	Date:				

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.