

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Nor Azian Binte Noordin

Date: 05 Apr 2019

Preliminary Advice

Vehicle No	: SBG938J	Accident Date	: 28/03/2019
Make	: MERCEDES-BENZ C180	Policy No.	: 1000913596
Assignment Date	: 05/04/2019	Excess	: S\$500.00
Date of Inspection	: 05/04/2019	Est. Duration of Repair	: 4.00
Inspection At	: RC AUTO-160 SIN MING (HQ) 160 SIN MING DRIVE, #06-20 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,514.30
Revised Amount	:S\$	7,023.50
Check Items (Estimated)	:S\$	370.80
Total	:S\$	7,394.30

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	123,000.00
COE / PARF Rebate	:S\$	69,030.00
Salvage Value	:S\$	
Margin for Repair	:S\$	53,970.00

Remarks

(X) The vehicle is economical for repair.

(X) Pending cost price from repairer