



CO. REG. NO: 199402370D

GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhinh.com.sg

Vehicle Insured : YM 8605 G
Accident Date : 31 -Mar- 2019

Date : 12-April-2019

Our Ref : 190175 (CHINA) / Simon

NIKKIE TEH (MS)
Singapore

SUPPLEMENTARY ITEMS FOR TOYOTA CHR HYBRID 1.8G CVT SLU 8181 E

4 pcs Reverse Sensor Retainer @\$35.00
1 pc Blind Spot Monitor Sensor LH
1 pc Blind Spot Monitor Sensor Bracket LH

<i>Mr</i>	\$ 140.00	✓
<i>Shen</i>	\$1615.00	✓
<i>Dir</i>	\$ 65.00	✓

	\$ 1820.00	
Less 25% -	\$ 455.00	

	\$ 1365.00	

1 pc Roof Top Black Sticker
1 pc Rear Top Spoiler Black Sticker
1 pc Rear Windscreen Solar Film

	\$750.00	SN	} <i>500JN</i> <i>\$450JN</i>
<i>Mr</i>	\$250.00	SN	
<i>Mr</i>	\$180.00	SN	<i>150JN</i>

Note: Amount quoted above is subjected to prevailing GST at time of tax invoice.



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Vehicle Insured : YM 8605 G
Accident Date : 31 -Mar- 2019

Date : 12-April-2019

Our Ref : 190175 (CHINA) / Simon

NIKKIE TEH (MS)
Singapore

ADDITIONAL LABOUR CHARGES FOR TOYOTA CHR HYBRID SLU 8181 E

To remove, re-align, re-calibrate and reprogram
Blind spot module software

B71 \$380.00 ✓

Towing charges from accident scene to workshop

\$ 60.00 501