

Vehicle No.SMH 7081 Z

MODEL:HONDA SHUTTLE HYBRID

QTY	DESCRIPTION	REPAIRER'S ESTIMATE(\$\$)	SURVEYORS ADJUSTMENT
PARTS (LIST ITEMS)			
1	REAR BUMPER	1200.00	✓
2	REAR BUMPER SIDE RETAINER	80.00	X
2	REAR BUMPER LHS & RHS BUMPER REFLECTOR	140.00	X
2	REAR BUMPER LHS & RHS REFLECTOR GARNISH	156.00	X
1	TAILGATE	1180.50	✓
2	REAR TAILGATE ABSORBER	250.00	X
1	TAILGATE CENTRE GARNISH	395.00	X
1	TAILGATE INNER TRIM BOARD	245.00	X
1	TAILGATE LOCK	105.00	X
1	TAILGATE HOLDER	65.00	X
2	TAILGATE RHS & LHS TAILLAMP	890.00	X
1	REAR END PANEL	510.00	?
1	REAR END PANEL TOP GARNISH	125.00	X
1	SMART BUZZER	125.00	?
1	REAR BUMPER TOWING CAP	28.00	X
1	REAR WINDSCREEN MOULDING	145.00	✓
1	REAR TAILGATE WEATHER STRIP	135.00	X
1	REAR END PANEL ANTENNA	85.00	?
1	REAR RHS & LHS BUMPER SPONGE	155.00	?
1	HONDA LOGO	32.00	✓
1	HYBRID LOGO	65.00	✓
1	SHUTTLE WORDING	62.00	✓
1	REAR SPARE TYRE PANEL	950.00	X
1	REAR SPARE TYRE TOP BOARD	585.00	X
		7708.50	0.00
		20% 1541.70	20%
		6166.80	
SPECIAL NETT ITEMS			
1 SETS	REAR BUMPER CLIPS	60.00	✓
1	REAR WINDSCREEN SEALANT	80.00	4000
1	REAR REVERSE CAMERA	450.00	X
1	REAR REVERSE SENSOR	280.00	2000
1	REAR INNER TRIM BOARD CLIPS	40.00	X
SPECIAL NETT		910.00	
TOTAL PARTS		7076.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not withstanding
Resurvey Bleepaint
4 days



PG.2

Vehicle No.SMH 7081 Z

MODEL:HONDA SHUTTLE HYBRID

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEY OF ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	1000.00 4501	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	800.00 501	
3	To remove and refix wiring and check all electrical components at damaged areas for proper functions	120.00 201	
4	To remove & replace reverse sensor and check for proper function.	150.00 501	
5	To remove & refit rear tailgate windscreen	150.00 1201	
6	To provide anti-rust treatment on affected areas	150.00 301	
7	Redo sealant	~ 120.00 X	
	Labour Total :	2490.00	
	TOTAL (PARTS & LABOUR):	9566.80	