



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2007658
INV Date 13/11/2020
Reference CC4/LPC19006052/Eba3q2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. GBG 2332T
Insured Veh. YN 1497Z
Claim No. 18/19/19/VC00/021598
Policy No. Z/18/VC00/102350
Accident Date 27/03/2019
Inspection Date 24/06/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CC4/LPC19006052/Eba3q2		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 13-11-2020		
		Code : LPC2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 1497Z	Veh. Inspected	GBG 2332T	
Policy No.	Z/18/VC00/102350	Coverage (\$)	0.00	
Claim No.	18/19/19/VC00/021598	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	05/04/2019	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA 150	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTFAT35Y70K208092	Colour	SILVER	
Odometer	61101	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/70 R15C	YOKOHAMA	7 mm	
L/H Front Tyre	195/70 R15C	YOKOHAMA	7 mm	
R/H Rear Tyre	155 R12C	YOKOHAMA	7 mm	
L/H Rear Tyre	155 R12C	YOKOHAMA	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/03/2019	Inspection Date	24/06/2019	
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 2332T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SUNDRY (SN)	NECESSARY	100.00	50.00
1	R/FRONT DOOR PANEL (SN)	DENTED	1,752.50	1,752.50
1	FRONT DOOR CHECK ASSY (SN)	NOT NECESSARY	156.00	-
1	FRONT DOOR LOW HINGE (SN)	NOT NECESSARY	93.50	-
1	FRONT DOOR TOP HINGE (SN)	NOT NECESSARY	93.50	-
1	R/FRT OUTER MIRROR (SN)	CUT	322.10	322.10
1	HEADLAMP ASSY, RH (SN)	CUT	1,165.00	1,165.00
1	PANEL, FR SIDE, RH (SN)	TO REPAIR SEE LABOUR	322.10	-
			4,004.70	3,289.60
	<u>LABOUR</u>			
	SUPPLY SEALANT.		100.00	100.00
	CHECK WIRING AND CONDUCT WATER TEST.		122.40	122.40
	REMOVE AND TRANSFER DOOR COMPONENTS ONTO NEW DOOR.		360.00	360.00
	TO RESET ECU AND REPROGRAMME		180.00	180.00
	SUPPLY COMPANY DOOR BLACK STICKER.		50.00	50.00
	REPLACE ACC DAMAGED PARTS AND STRAIGHTEN / REALIGN ACC AFFECTED AREAS. INCLUSIVE OF THE REPAIR OF PANEL, FR SIDE, RH.		2,160.00	720.00
	RESPRAY ACC AFFECTED AREAS.		2,360.00	1,475.00
	COMPANY LOGO, CONTACT AND EMAIL STICKER.		85.00	85.00
			5,417.40	3,092.40
GRAND TOTAL			9,422.10	6,382.00
RECOMMENDED COST OF REPAIRS				6,382.00

Report Ref No. CC4/LPC19006052/Eba3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBG 2332T

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBG 2332T

RE-INSPECTION

