

INS. REC. BY

REF: CS/CT119006056/ J+d3e2 Special Instruction:

Surveyor: Hwee Jie ASSIGNMENT (Office)From (Person): Chong Boon Sen of CTI Date/Time: 5/4/19 @ 12:53pm

Estimated Cost: _____ Bill to: _____

OD TP WS/TP RES / OD RES / EVA / INV / MV / CSTo inspect Vehicle No: SKZ 814B Insured: GBF 3846Bat Workshop m/s: Kah motor Tel: 8288 6302of 6A Mendai EstatePolicy No: Dm CVSN 30745613011 Claim No: SNM19D 201119C02

Sum Insured: _____ Excess: _____

Make of Vch: _____ D.O.A. 08/03/2019

(Client's Record)

CA / REV / REP. / REV 24 HRS

9/4/19 @ after 2pm
H.O.D. EndorsementDate/Time: 2:17pm @ 5/4/19 Person Contacted: Anikka Vehicle IN OUT

Date/Time Action/Instruction (✓) Estimate

Anikka say can arrange any surveyor to come for survey.SKZ 814B - XGBF 3846B - XPart by part \$4392.81 (Red: 6919.74: 61%)

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 5 April 2019 12:53 PM
To: Anikka Lai
Cc: assignments
Subject: RE: SKZ814B - TP CLAIMS AGAINST GBF3846B DOA: 08/03/2019 / our ref: SNM19D201119

Without Prejudice

Dear Anikka,

We appoint LKK.

Dear LKK,

Pls pri.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平狮城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Anikka Lai [mailto:anikkalai@honda.com.sg]
Sent: Friday, 5 April, 2019 12:02 PM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: RE: SKZ814B - TP CLAIMS AGAINST GBF3846B DOA: 08/03/2019 / our ref: SNM19D201119
Importance: High

Dear Boon Sen,

Pls arrange **Mr Adrian Ling** (LKK) to survey the vehicle next Tuesday (09/04/2019) after 2pm.

Thank you

Warmest Regards

Anikka Lai
Kah Motor Co. Sdn Bhd
6A Mandai Estate
Singapore 729903
DID : 6514 5248 HP : 8288 6302
Email: anikkalai@honda.com.sg

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Friday, 5 April, 2019 11:53 AM
To: Anikka Lai <anikkalai@honda.com.sg>
Subject: RE: SKZ814B - TP CLAIMS AGAINST GBF3846B DOA: 08/03/2019 / our ref: SNM19D201119

Dear Sirs

We refer to the above matter.

Liability is in favor of your client and we agree to go for Direct Settlement, subject to consistency of damages, based on our appointed surveyor's findings, with supporting documents.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Anikka Lai [<mailto:anikkalai@honda.com.sg>]
Sent: Friday, 5 April, 2019 11:49 AM
To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: FW: SKZ814B - TP CLAIMS AGAINST GBF3846B DOA: 08/03/2019
Importance: High

Dear Boon Sen,

As spoke, kindly advise the liability of direct settlement.

Thank you

Warmest Regards

Anikka Lai
Kah Motor Co. Sdn Bhd
6A Mandai Estate
Singapore 729903
DID : 6514 5248 HP : 8288 6302
Email: anikkalai@honda.com.sg

From: Anikka Lai
Sent: Thursday, 14 March, 2019 4:26 PM
To: 'irene.tay@sg.cntaiping.com' <irene.tay@sg.cntaiping.com>
Subject: SKZ814B - TP CLAIMS AGAINST GBF3846B DOA: 08/03/2019

Dear Irene,

Attached pls find the claims document for your necessary action. Kindly advise the liability of direct settlement.

Thank you

Warmest Regards

Anikka Lai
Kah Motor Co. Sdn Bhd
6A Mandai Estate
Singapore 729903
DID : 6514 5248 HP : 8288 6302
Email: anikkalai@honda.com.sg

From: Printer Service <printservice@honda.com.sg>
Sent: Thursday, 14 March, 2019 4:21 PM
To: Anikka Lai <anikkalai@honda.com.sg>
Subject: Attached Image



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/03/2019 14:48
Date Of Accident	08/03/2019 07:50
Exact Location Of Accident	PIE (CHANGI) B4 LORNIE RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ814B
Insured/Policyholder	
Name Of Registered Owner	CHUA KOK YEOW
NRIC No	S7513570Z
Email Address	CHUAKOKYEOW@GMAIL.COM
Mobile Phone No	(LOCAL) +65-94358577
Alternative Phone No	OFFICE-94358577

Vehicle Particulars

Manufacturer	HONDA
Model	JAZZ-1.5 VTIR (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	

Driver

Name of Driver	CHUA KOK YEOW
NRIC No	S7513570Z
Date Of Birth	06/05/1975
Occupation	INDOOR
Date Of Driving Pass	07/07/1999
Driving Experience	19 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94358577
Fax Number	
Contact Number	OFFICE-94358577
EEmail Address	CHUAKOKYEOW@GMAIL.COM

Address	-
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS ANNEX D&E

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF3846B
Vehicle Make/Model/Colour	TOYOTA VAN / SILVER
Details Of Properties	
Vehicle Category	GOODS VEHICLE
Name of Driver	TOH WAH KEONG
NRIC/Passport Number	S1729459H
Contact Number	97332655
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan Pg. 1

Vehicle Number: _____

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 9/3/19 10am

Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	3570Z
Vehicle Details	
Vehicle No.:	SKZ814B
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD
Primary Colour:	Purple
Manufacturing Year:	2015
Engine No.:	L15B31020460
Chassis No.:	JHMGK5850GX201372
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$15,377.00
Original Registration Date:	08 Jan 2016
First Registration Date:	08 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$10,377.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Jan 2026
PARF Rebate Amount:	\$7,782.00
Intended COE Rebate Details	
COE Expiry Date:	07 Jan 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,989.00
COE Rebate Amount:	\$38,421.00
Total Rebate Amount:	\$46,203.00

The information contained herein is correct as at 10 Apr 2019

OK



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

2pm - 9/4.
QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	Document No.	: SQT19001187	Page	1
Registration No	: SKZ814B	Date	: 13. Mar 2019	Customer No.	: WZC008
Chassis No	: JHMGK5850GX201372	Svc Advisor	: ANIKKA LAI SWEE KAM	Engine No	: L15B31020460
Model	: JAZZ 1.5VTIR CVT 16YM	Date Time	: 13. Mar 2019 8:42:00 PM	Surveyor Name	:
Owner's Name	: CHUA KOK YEOW	Survey Date	:	Authorisation Date	:
Ins Policy No.	:				
Date of Accident	: 8/3/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: CHUA KOK YEOW OWNER INSURER: LIBERTY ACC DATE: 08/03/2019 SURVEYED BY: DATE: REF NO: TP INSURER: CHINA TAIPING TP VEH: GBF3846B						
68100-TAS-Z50ZZ	TAILGATE COMP <i>BUC / ? X NN</i>	1	730.60	25	<i>621.01</i> 547.95	38.36	586.31
68210-T5A-013ZZ	HINGE COMPTAILGATE	2	33.20	25	49.80	3.49	53.29
74440-T5A-003	WEATHERSTRIPTAILGATE <i>nn x</i>	1	92.30	25	69.22	4.85	74.07
74800-T5A-J01	LOCK ASSYTAILGATE <i>nn x</i>	1	78.90	25	59.17	4.14	63.31
75722-T5L-T01	EMBLEMRR. <i>ncc / ✓</i>	1	10.90	25	8.17	0.57	8.74
73127-TY0-000	RUBBER CWINDSHIELD DAMPER <i>ncc / ✓</i>	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBERWINDSHIELD DAMPER <i>ncc / ✓</i>	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPERSTD 5X5 <i>ncc / ✓</i>	1	8.50	25	6.37	0.45	6.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>ncc / X NN</i>	2	60.00		120.00	8.40	128.40
04715-T5B-000ZZ	FACERR.BUMPER <i>Repair X</i>	1	502.50	25	376.87	26.38	403.25
71593-T5A-000	SPACERR.RR.BUMPER <i>ncc / ✓</i>	1	11.50	25	8.62	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER <i>ncc / ✓</i>	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER <i>ncc / ✓</i>	1	2.30	25	1.72	0.12	1.84
71502-T5A-000	GARNISHR.RR.BUMPER <i>nn x</i>	1	14.30	25	10.72	0.75	11.47
71507-T5A-000	GARNISHL.RR.BUMPER <i>nn x</i>	1	14.30	25	10.72	0.75	11.47
66100-TAR-T10ZZ	PANEL COMPRR. <i>? X NN</i>	1	320.40	25	240.30	16.82	257.12
					Sum Item	1536.55	107.56
							1,644.11
BOSUN	SUNDRIES	1	100.00		<i>30</i> 100.00	7.00	107.00

Printed on 14/3/2019 4:19:54 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
 3 ANSON ROAD #16-00
 SPRINGLEAF TOWER
 SINGAPORE 079909

Registration No : SKZ814B

Chassis No : JHMGK5850GX201372

Model : JAZZ 1.5VTIR CVT 16YM

Owner's Name : CHUA KOK YEOW

Ins Policy No. :

Date of Accident : 8/3/2019

Document No. : SQT19001187 Page 2

Date : 13. Mar 2019

Customer No. : WZC008

Svc Advisor : ANIKKA LAI SWEE KAM

Engine No : L15B31020460

Date | Time : 13. Mar 2019 8:42:00 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BG02R	REPLACE RR. WINDSCREEN.(N)	2	560.00		1120.00	101.92	1557.92
BOMISC1	RESET & CALLIBRATE SMART ENTRY SYSTEM (N)	1	200.00		200.00	14.00	214.00
BOMISC1	REMOVE & INSTALL REAR VIEW CAMERA (N)	1	600.00		600.00	42.00	642.00
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	120.00		120.00	8.40	128.40
BOJSE	BODY JOINT SEALANT TAILGATE	1	100.00		100.00	7.00	107.00
BODAMKIT	WINDSCREEN DAM KIT.	1	100.00		100.00	7.00	107.00
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	600.00		600.00	42.00	642.00
BKRP02M	CUT OFF & RENEW RR PANEL & DAMAGE PARTS.	1	3500.00		3500.00	245.00	3745.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	3000.00		3000.00	210.00	3210.00
Sum Labor					9776.00	684.32	10,460.32

Survey By: Hwee Jie - CLK

Date & Time: 9/4/19

Excess: -

Status: P/P 4 days.

Signature: [Signature]

[Handwritten Signature]
 11/4/19

Total Amount 11,312.55 791.88 12,104.43

Total (Inclusive of GST) 12,104.43

11385.61

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Printed on 14/3/2019 4:19:54 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	WZC008 / CHINA TAIPING	Document No:	SVO19022671
Chassis No:	JHMGK5850GX201372	Printed By:	ANIKKALAI
License No:	SKZ814B	Order Date:	9. April 2019
Mileage:	56719	Order Time:	3:32:03 PM
Engine No:	L15B31020460	Service Advisor:	ANIKKA LAI SWEE KAM

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount Includ GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: CHUA KOK YEOW OWNER INSURER: LIBERTY ACC DATE: 08/03/2019 SURVEYED BY: DATE: REF NO: TP INSURER: CHINA TAIPING TP VEH: GBF3846B						
68100-T5B-Z50ZZ	TAILGATE COMP	1	730.60	15	621.01	43.47	664.48
75722-T5L-T01	EMBLEMRR.	1	10.90	25	8.17	0.57	8.74
73127-TY0-000	RUBBER CWINDSHIELD DAMPER	1	11.40	25	8.55	0.60	9.15
73214-T5A-013	RUBBERWINDSHIELD DAMPER	2	6.50	25	9.75	0.68	10.43
73226-SZW-000	DAMPERSTD 5X5	1	8.50	25	6.37	0.45	6.82
71593-T5A-000	SPACERR.RR.BUMPER	1	11.50	25	8.62	0.60	9.22
71598-T5A-000	SPACERL.RR.BUMPER	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER	1	2.30	25	1.72	0.12	1.84
	SUM PARTS:				672.81	47.09	719.90
BOSUN	SUNDRIES	1	30.00		30.00	2.10	32.10
BG02R	1438 REPLACE RR. WINDSCREEN.(N)	1	560.00		560.00	39.20	599.20
BOMISC1	RESET & CALLIBRATE SMART ENTRY SYSTEM (N)	1	200.00		200.00	14.00	214.00
BOMISC1	1438 REMOVE & INSTALL REAR VIEW CAMERA (N)	1	280.00		280.00	19.60	299.60
BA02R	1729 REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	120.00		120.00	8.40	128.40
BOJSE	1718 BODY JOINT SEALANT TAILGATE	1	80.00		80.00	5.60	85.60
BODAMKIT	WINDSCREEN DAM KIT.	1	80.00		80.00	5.60	85.60
BKTG02R	1729 REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	350.00		350.00	24.50	374.50
BKRP02M	1729 CUT OFF & RENEW RR PANEL & DAMAGE PARTS. ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS.	1	1,120.00		1,120.00	78.40	1,198.40
BP05R	1718 SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)	1	900.00		900.00	63.00	963.00
	SUM LABOUR:				3,720.00	260.40	3,980.40
	TOTAL SGD				4,392.81	307.49	4,700.30

Total Payable (SGD)

4,700.30

P/P \$4392.81 4 days.

**HONDA****SERVICE PRE-INVOICE****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G**Customer:** WZC008 / CHINA TAIPING
Chassis No: JHMGK5850GX201372
License No: SKZ814B
Mileage: 56719
Engine No: L15B31020460**Document No:** SVO19022671
Printed By: ANIKKALAI
Order Date: 9. April 2019
Order Time: 3:32:03 PM
Service Advisor: ANIKKA LAI SWEE KAM

GST Amount is calculated from individual line(s)

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	05 Apr 2019		05 Apr 2019 17:24 Edit Adj Rpt	S\$4,392.81 Edit Estimates	S\$4,392.81 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	0, Co. Reg. No.: 0								
Main Claimant:	CHUA KOK YEOW, ID: S7513570Z								
Vehicle Reg. No.:	SKZ814B	Date of Loss:	08/03/2019 07:00 - :59 [38 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM19D201119C02	Policy/Cover Note No.:	DMCVSN30745618011						
Vehicle Reg. No. (Insured):	GBF3846B	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Kah Motor Co Sdn Bhd (Mandai) 8 Mandai Estate, CBODY REPAIR AND PAINT CENTRE, 729905 Mandai - Tel: 90721767								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ONG HWEE JIE] ... [Final Rpt due 16/04/2019]								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS			View All	Search Tasks					
			Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKZ814B (SNM19D201119C02)
 [GBF3846B]
 TP
CHUA KOK YEOW
 Mar 8 2019 7:00AM
 [0]
 Kah Motor Co Sdn Bhd

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
Assessment Reports									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print					
1	09/03/19 14:53	Accident Statement		Load HTM						
Photos/Images									3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print					
1	09/03/19 14:53	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
2	09/03/19 14:53	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
3	09/03/19 14:53	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
4	09/03/19 14:53	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
5	09/03/19 14:53	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
6	09/03/19 14:53	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
7	09/03/19 14:53	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	11/04/19 09:28	General View		Load JPG	<input checked="" type="checkbox"/>					
2	11/04/19 09:28	General View		Load JPG	<input checked="" type="checkbox"/>					
3	11/04/19 09:28	General View		Load JPG	<input checked="" type="checkbox"/>					
4	11/04/19 09:28	General View		Load JPG	<input checked="" type="checkbox"/>					
5	11/04/19 09:28	General View		Load JPG	<input checked="" type="checkbox"/>					
6	11/04/19 09:28	General View		Load JPG	<input checked="" type="checkbox"/>					
7	11/04/19 09:28	General View		Load JPG	<input checked="" type="checkbox"/>					
8	11/04/19 09:28	General View		Load JPG	<input checked="" type="checkbox"/>					
9	11/04/19 09:28	General View		Load JPG	<input checked="" type="checkbox"/>					
10	11/04/19 09:28	General View		Load JPG	<input checked="" type="checkbox"/>					
11	11/04/19 09:28	General View		Load JPG	<input checked="" type="checkbox"/>					
12	11/04/19 09:28	General View		Load JPG	<input checked="" type="checkbox"/>					
13	11/04/19 09:28	General View		Load JPG	<input checked="" type="checkbox"/>					
14	17/04/19 10:44	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>					
15	17/04/19 10:44	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>					
16	17/04/19 10:44	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>					
17	17/04/19 10:44	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>					
18	17/04/19 10:44	Replacement Part Photo		Load JPG	<input checked="" type="checkbox"/>					
Documentation									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print					
1	05/04/19 17:25	pri contact		Load PDF						
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print					
1	09/03/19 14:52	Sketch Plan [Linked Accident Report Documents]		Load TIF						

Linked Accident Report Documents

			View	View in Browser	
Assessment Reports			1 per page	[v]	[x]
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
1	09/03/19 14:53	Accident Statement	1	Load HTM	[x]
Photos/Images					
			3 per page	[v]	[x]
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
1	09/03/19 14:53	Accident Photo	1	Load JPG	[x]
2	09/03/19 14:53	Accident Photo	1	Load JPG	[x]
3	09/03/19 14:53	Accident Photo	1	Load JPG	[x]
4	09/03/19 14:53	Accident Photo	1	Load JPG	[x]
5	09/03/19 14:53	Accident Photo	1	Load JPG	[x]
6	09/03/19 14:53	Accident Photo	1	Load JPG	[x]
7	09/03/19 14:53	Accident Photo	1	Load JPG	[x]
Documentation					
			1 per page	[v]	[x]
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print
1	09/03/19 14:52	Sketch Plan	1	Load TIF	[x]

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div style="border: 1px solid black; width: 100%; height: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19006056/JTD3E2

Date: 24/04/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSN30745618011	
Claimant Vehicle No: SKZ814B	Insured Vehicle No: GBF3846B	
Date of Loss: 08/03/2019	Nature of Claim: TP	Claim No: SNM19D201119C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKZ814B	Engine No: L15B31020460
Make & Model: HONDA JAZZ, 1.5 VTIR (A)	Chassis No: JHMGK5850GX201372
Reg. Date: 08/01/2016 (Man. Year: 2015)	Odometer: 60108 km
Colour: Purple	
Engine Capacity: 1498 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55R16	Rear Tyre Size: 185/55R16
Front Left Side: Dunlop 6 mm	Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm	Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,709.61	702.81	1,006.80	58.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,676.00	3,690.00	5,986.00	61.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,385.61	4,392.81	6,992.80	61.42
+ GST 7.00/7.00% (S\$)	796.99	307.50	489.49	61.42
Nett Amount (S\$)	12,182.60	4,700.31	7,482.29	61.42

INSPECTION

Date of Assignment: 05/04/2019		
Date Inspected: 09/04/2019	Inspected At:	Kah Motor Co Sdn Bhd (Mandai) 6A MANDAI ESTATE SINGAPORE 729903
Estimated Period of Repair: 4.0 days		

Adjuster: ONG HWEE JIE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 24 Apr 2019)
Parts: 144	HONDA JAZZ 1.5 VTIR (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKZ814B)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE COMP	Buckled	621.01 FS	*621.01 FS
2	2		*HINGE COMP TAILGATE	Not Necessary	49.80 FS	*- FS
3	1		*WEATHERSTRIP TAILGATE	Not Necessary	69.22 FS	*- FS
4	1		*LOCK ASSY TAILGATE	Not Necessary	59.17 FS	*- FS
5	1		*EMBLEMRR	Necessary	8.17 FS	*8.17 FS
6	1		*RUBBER CWINDSHIELD DAMPER	Necessary	8.55 FS	*8.55 FS
7	1		*RUBBER WINDSHIELD DAMPER (2 Pcs)	Necessary	9.75 FS	*9.75 FS
8	1		*DAMPERSTD 5X5	Necessary	6.37 FS	*6.37 FS
9	2		*WINDSCREEN SEALANT	Not Necessary	120.00 FS	*- FS
10	1		*FACERR BUMPER	Repair	376.87 FS	*- FS
11	1		*SPACERR RR BUMPER	Necessary	8.62 FS	*8.62 FS
12	1		*SPACERL RR BUMPER	Necessary	8.62 FS	*8.62 FS
13	1		*CLIP,BUMPER	Necessary	1.72 FS	*1.72 FS
14	1		*GARNISHR RR BUMPER	Not Necessary	10.72 FS	*- FS
15	1		*GARNISHL RR BUMPER	Not Necessary	10.72 FS	*- FS
16	1		*PANEL COMPRR	Not Necessary	240.30 FS	*- FS
17	1		*SUNDRIES	Necessary	100.00 FS	*30.00 FS
Total Parts (S\$)					1,709.61	702.81

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACE RR WINDSCREEN	New	1,456.00	560.00
2	RESET & CALLIBRATE SMART ENTRY SYSTEM	New	200.00	200.00
3	REMOVE & INSTALL REAR VIEW CAMERA	New	600.00	280.00
4	REMOVE & INSTALL REVERSE SENSORS-4 PCS	New	120.00	120.00
5	BODY JOINT SEALANT TAILGATE	New	100.00	80.00
6	WINDSCREEN DAM KIT	New	100.00	80.00
7	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST	New	600.00	350.00
8	CUT OFF & RENEW RR PANEL & DAMAGE PARTS	New	3,500.00	1,120.00
9	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (5P)	New	3,000.00	900.00
Gross Labour Cost (S\$)			9,676.00	3,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >