



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

DATE : 05-04-2019

*not authorized
mercus
Take photo before rectify.
1 day.*

VEHICLE NO. : SLE3435R
ACCIDENT DATE : 03-04-2019 20:30
THIRD PARTY REF. : SHF754G

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE SLE3435R HONDA VEZEL

QTY PARTS DESCRIPTION

AMOUNT (SG\$)

1 1 REAR BUMPER SIDE RH
2 1 REAR BUMPER
3 10 REAR BUMPER CLIP@\$4.90

cu 195.00 ✓
su 463.70 X
nu 49.00 ✓

707.70

LESS 20 %

141.54

TOTAL (A)

566.16

LABOUR CHARGES

1 1 TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS

300.00 *200*

2 1 SPRAYPAINTING CHARGES

250.00 *150*

TOTAL (D)

550.00

ESTIMATE TOTAL

1,116.16

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No major modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: