| - Surveyor                    |                                      |                       | 19006065/E |             |                   |        |
|-------------------------------|--------------------------------------|-----------------------|------------|-------------|-------------------|--------|
| Estimated C                   |                                      | of                    | INC        | Date/Time   | 5/4/19/8          | 9.18cm |
| To Juspect \ at Workshop of   | 111/11                               | FBM 3818<br>eong Seng | 3×         | Tel 622     | K 4888D<br>737469 |        |
| Policy No<br>Sum Insured      |                                      |                       | Claim No   | MT/1038     | 231-002           |        |
| Make of Vel<br>(Client's Reco |                                      |                       | 9          |             | 1/4/2019          |        |
|                               | 1 REP. 1 REV 24 11<br>0-2000/05/4/10 |                       | ded Mr.7e0 | 11.O.D. Enc | 8/4/2019<br>OHT   | )      |
| Date/Time                     |                                      | (~) Esting            |            |             |                   |        |

26/4/19 @239pm Mr Teo Said vehicle waiting for spare parts

200 TATES

### Nivitha (LKK Auto)

From:

Annie Koh <annie.koh@income.com.sg>

Sent:

Friday, 5 April 2019 10:14 AM 'assignments@lkkauto.com'

To: Subject:

RE: TP CASES FARMED OUT TO LKK ON 05/04/2019

Re-send

Warmest Regards

Annie Koh Senior Admin, Motor Insurance T+65 64307899 www.income.com.sg











From: Annie Koh

Sent: Friday, 5 April 2019 9:18 AM

To: 'assignments@lkkauto.com' <assignments@lkkauto.com>

Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>

Subject: RE: TP CASES FARMED OUT TO LKK ON 05/04/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

| SN | OIC             | Claim No.          | Vehicle  | WorkShop<br>Name                             | WorkShop Address   | WorkShop<br>Contact          | OIVEH    | DOA    | Additional<br>Remarks |
|----|-----------------|--------------------|----------|--|--|------------------------------|----------|--------|-----------------------|
| 1  | CYNDIIE<br>YONG | MT/1038760-<br>001 | SHA9982G | DING<br>AUTOMOTIVE<br>PTE LTD                | 31 CORPORATION<br>ROAD SINGAPORE<br>649825                   | Nelson<br>Wong /<br>98912489 | FBM6655D | 3/4/19 |                       |
| 2  | AZHARI          | MT/1038231-<br>002 | FBM3818X | LEONG SENG<br>MOTOR PTE<br>LTD               | BLK 1006 #01-08<br>BUKIT MERAH<br>LANE 2 SINGAPORE<br>159762 | c s teo /<br>62737469        | SLK4888D | 1/4/19 |                       |
| 3  | JULIANA<br>LEE  | MT/1038813-<br>002 | SLE466X  | VERMOGEN<br>ACE PTE LTD                      | 6 BENOI ROAD,<br>SINGAPORE<br>629904                         | Pila /<br>6358<br>3031       | SJD5299H | 3/4/19 |                       |
| 4  | JARED<br>LIU    | MT/1038592-<br>002 | PC5282P  | WOODLANDS<br>TRANSPORT<br>SERVICE PTE<br>LTD | 8 GUL<br>CIRCLE SINGAPORE<br>629564                          | Mr<br>Chan /<br>9299<br>4122 | PA5960B  | 1/4/19 | 6559<br>8984          |

#### Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh Senior Admin Assistant, Motor Insurance T+65 6430 7899

www.income.com.sg











# Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

410121114

# Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars                          | tered verificie      |  |
|--|----------------------|--|
| Owner ID Type:                                     | Singapore NRIC       |  |
| Owner ID:<br>Vehicle Details                       | 2896J                |  |
| Vehicle No.:                                       | FBM3818X             |  |
| Vehicle to be Exported:                            | No                   |  |
| Intended Deregistration Date:                      | 08 Apr 2019          |  |
| Vehicle Make:                                      | YAMAHA               |  |
| Vehicle Model:                                     | YZF-R3 ABS           |  |
| Primary Colour:                                    | Black                |  |
| Manufacturing Year:                                | 2017                 |  |
| Engine No.:  | H405E0004645         |  |
| Chassis No.:                                       | MH3RH121000002554    |  |
| Maximum Power Output:                              | -                    |  |
| Open Market Value:                                 | \$5,111.00           |  |
| Original Registration Date:                        | 17 Oct 2017          |  |
| First Registration Date:                           | 17 Oct 2017          |  |
| Transfer Count:                                    | 1                    |  |
| Actual ARF Paid:<br>Intended PARF Rebate Details   | \$806.00             |  |
| PARF Eligibility:                                  | No                   |  |
| PARF Eligibility Expiry Date:                      | •                    |  |
| PARF Rebate Amount:<br>Intended COE Rebate Details | \$0.00               |  |
| COE Expiry Date:                                   | 16 Oct 2027          |  |
| COE Category:                                      | D - Motorcycle       |  |
| COE Period(Years):                                 | 10                   |  |
| QP Paid:   | \$5,501.00           |  |
| COE Rebate Amount:                                 | \$4,687.00           |  |
| Total Rebate Amount:                               | \$4,687.00           |  |
|  | W. Supplied Property |  |

The information contained herein is correct as at 08 Apr 2019

OK

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

|                            | ACCIDENT STATEMENT     |  |
|----------------------------|------------------------|--|
| Date Of Report             | 02/04/2019 12:14       |  |
| Date Of Accident           | 01/04/2019 07:30       |  |
| Exact Location Of Accident | GOMBAK DRIVE           |  |
| Country/State of Loss      | SINGAPORE              |  |
|                            | DETAILS OF OWN VEHICLE |  |

| DETAIL | LS OF | OWN | VEHI | CLE |
|--------|-------|-----|------|-----|
|--------|-------|-----|------|-----|

Vehicle Registration Number FBM3818X

Insured/Policyholder

Name Of Registered Owner SOH JIAYU NRIC No S9002896J

Email Address SOHJIAYU@GMAIL.COM Mobile Phone No (LOCAL) +65-82989810 Alternative Phone No OTHERS-82989810

Vehicle Particulars

Manufacturer YAMAHA Model YZF R3 ABS Exact Purpose for which vehicle was being used at PRIVATE USE

time of accident

NO

Are you claiming under your own insurance policy for repair to your vehicle?

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

MOTORCYCLE

Insurance Company

Name of Insurance Company SOMPO INSURANCE SINGAPORE PTE. LTD.

Type Of Coverage THIRD PARTY FIRE AND/OR THEFT

Fleet Policy NO

D18MTMC01005677 Policy Number

Cover Note Number NA

Driver

Name of Driver SOH JIAYU NRIC No S9002896J Date Of Birth 25/01/1990 Occupation OUTDOOR Date Of Driving Pass 18/09/2013

5 YEARS AND 6 MONTHS **Driving Experience** 

Gender MALE

Mobile Number (LOCAL) +65-82989810

Fax Number

Contact Number OTHERS-82989810

EMail Address SOHJIAYU@GMAIL.COM Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

100

Insurance Company of Driver's Own Vehicle

•

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE

Weather Conditions CLEAR
Road Surface WET

Other Information

ambulance?

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle)

involved in the accident

2

Was any body injured in the Accident? YES

Was any injured conveyed to hospital by

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

NAME OF

**Details of Police Action** 

Was the accident reported to the police?

YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER]

JURONG WEST N P C

Was notice of intended Prosecution given?

NO

If Yes, against whom?

#### Circumstances of Accident

REFER TO POLICE REPORT NO:1/20190401/2110 LODGED AT JURONG WEST N P C. ON 01/04/2019 AT ABOUT 0732 HRS, I WAS RIDING MY MOTORCYCLE, V1 (PLATE FBM3818X) ALONG GOMBAK DRIVE INSIDE GOMBAK CAMP. THEE WAS A CAR, V2 (PLATE NO: SLK4888D) INFRONT OF ME STOPPED AS THERE WA ANOTHER CAR, V3 WAS TURNING LEFT. AS THE ONCOMING TRAFFIC WAS CLEAR, I PROCEED TO OVERTAKE V2. HOWEVER, AS SOON AS I OVERTAKE, V2 MADE A LEFT TURN COLLIDING ON MY REAR PORTION OF MY BIKE. I LOST CONTROL AND FELL DOWN WITH MY BIKE. THERE WERE ABRASION AND BRUISE ON MY ARM. WE EXCHANGE PARTICULARS AND SUBSEQUENTLY LEFT. I WENT TO MINDEF MEDICAL CENTRE AND RECEIVED 03 DAYS OF MC. THERE IS AN IN-VEHICLE CAMERA, HOWEVER I AM UNSURE WHETHER IT HAVE RECORDED THE INCIDENT.

#### Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

#### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SLK4888D

Vehicle Make/Model/Colour LEXUS RX450H

Details Of Properties NA

Vehicle Category PRIVATE CAR

Name of Driver MEHAR MUKESH MUNI

NRIC/Passport Number S6926267H Contact Number 97578365

Address Postcode





Police Station Of Origin: Jurong West N.P.C 700 Corporation Road SINGAPORE 649818 Tel No: 1800-2689999

1 of 3 Report No. T/20190401/2110

# REPORT OF A TRAFFIC ACCIDENT

| 01/04/20                                     | e Report I<br>19 14:58            | Made:                     | Vide Report No.:                                       | Station Diary No.:         |  |  |
|--|-----------------------------------|---------------------------|--|----------------------------|--|--|
| Informar                                     | it's Partic                       | ulars                     |  |                            |  |  |
|  | Informant:                        |                           | Address:<br>APT BLK 433 JURONG WES<br>SINGAPORE 640433 | ST STREET 42 #06-510       |  |  |
| ID Type / ID No.:<br>NRIC NO / S9002896J     |                                   |                           | Contact No.:<br>Home/Office:                           | Mobile: 82989810           |  |  |
|  | Nationality:<br>SINGAPORE CITIZEN |                           | Email:   | Widdlie, 52363610          |  |  |
| Sex:<br>Female                               | Age:<br>29                        | Date of Birth: 25/01/1990 | Type of Informant:<br>Rider                            |                            |  |  |
| Race:<br>Chinese                             |                                   |                           | Language:  | Institution / School Name: |  |  |
| Occupation: Singapore Armed Forces personnel |                                   | orces personnel           | Driving Licence Information:<br>Class:                 | Date of Expiry:            |  |  |

| Type of Accident:                      | Non-Injury<br>Others | Drink<br>Drive:<br>No              | Date/Time of<br>Accident:<br>01/04/2019 07:30 | Type of Location<br>Straight Road |  |
|--|----------------------|------------------------------------|---|-----------------------------------|--|
| Location:<br>Along Road 1<br>GOMBAK DR | IVE                  |                                    | 9.13 123 13 07.30                             |                                   |  |
| Weather:                               |                      | Road Surface:                      | R   | oad Speed Limit:                  |  |
|  |                      |                                    |   |                                   |  |
| Traffic Flow:<br>Two Way               |                      | Traffic Control:<br>Not Controlled | Tı  | raffic Volume;                    |  |

| Details of V | I I I I I I I I I I I I I I I I I I I |        |            |       |                     |                 |
|--------------|---------------------------------------|--------|------------|-------|---------------------|-----------------|
| Vehicle No.  | Туре                                  | Make   | Model      | Color | Condition           | No of Passenger |
| FBM3818X     |                                       | YAMAHA | YZF-R3 ABS | Black | Slightly<br>Damaged | 0               |
| SLK4888D     | Car                                   |        |            |       | Slightly<br>Damaged | 0               |

| COLUMN THE REPORT OF PERSONS ASSESSED. | ehicle Insurance                   |                | ALL STREET, 12-12-12-12-12-12-12-12-12-12-12-12-12-1   | TRANSPORTED IN |
|--|------------------------------------|----------------|--|----------------|
|  | Insurance Company                  | Insurance No   | Effective  | Expiry Date    |
| FBM3818X                               | TENET SOMPO INSURANCE PTE.<br>LTD. | D18MTMC0100567 | the control of the co | 18/10/2019     |





Report No. T/20190401/2110

Police Station Of Origin: Jurona West N.P.C 700 Corporation Road SINGAPORE 649818

Tel No: 1800-2689999 CONTINUATION OF REPORT

| Details of Perso<br>Any Pedestrian Ir |                       |                   |   |           |                                   |
|---------------------------------------|-----------------------|-------------------|---|-----------|-----------------------------------|
| No. of Pedestrian                     |                       | Use of Ped        | lestrian  | Cross     | ing: NA                           |
| Rider                                 |                       |                   | and the second                                  |           |                                   |
| Name                                  | SOH JIAYU             |                   | ID No.  |           | S9002896J                         |
| Related Vehicle                       | FBM3818X (Motorcycle) |                   | Conta   | ct No.    | 82989810                          |
| Hospital/Clinic                       | NIL                   |                   | Class<br>Driving<br>Licence<br>Expiry           | g<br>ce & | Class: NIL<br>Date of Expiry: NIL |
| Date Treatment                        | NIL                   | Date Disch        | narge   | NIL       |                                   |
| No. of Days gran                      | ted Medical Leave 03  | Degree of         | Injury  | Slight    | 1                                 |
| Driver                                |                       | The Property last | A CAMPA   |           | NOT TRACE LESS !                  |
| Name                                  | MEHAR MUKESH MUNI     |                   | ID No.  |           | S6926267H                         |
| Related Vehicle                       | SLK4888D (Car)        |                   | Contact No.                                     |           | 97578635                          |
| Hospital/Clinic                       | NIL                   |                   | Class of<br>Driving<br>Licence &<br>Expiry Date |           | Class: NIL<br>Date of Expiry: NIL |
| Date Treatment                        | NIL                   | Date Disch        | narge   | NIL       |                                   |
| No. of Days gran                      | ted Medical Leave NIL | Degree of         | Injury  | NIL       |                                   |

#### Brief Details.

On 01/04/2019 at about 0732hrs I was riding my motorcycle, V1 (plate no: FBM3818X) along Gombak Drive inside Gombak Camp. There was a car, V2(plate no: SLK4888D) in front of me stopped as there was another car, V3 was turning left. As the oncoming traffic was clear, I proceed to overtake V2. However, as soon as I overtook, V2 made a left turn colliding on my rear portion of my bike. I lost control and fell down with my bike. There were abrasion and bruise on my arm. We exchanged particulars and subsequently left. I went to MINDEF medical centre and received 03 days of MC. There is an in-vehicle camera however I am unsure whether it have recorded the incident.

Steve (LKK)

Leong Seng Motor Pte Ltd
Blk 1006 Bukit Merah Lane 2

#01-08 Singapore 159762

Tel: 62737469 Fax: 62727669

Why pain 2 8/4/19 4.00 pm

3 4 L/S Ry Al Spy Veh No:

Model:

FBM3818X

R3

| 5/No | Parts Description  | ОТУ | List | t Price  | Net      | t Price | Remark |
|------|--|-----|------|----------|----------|---------|--------|
|      | Front wheel rim / UT   | QII | \$   | 885.00   | 1.46     |         | Hemaik |
| 2    | Front wheel bearing / NE(  |     | \$   | 50.00    | $\vdash$ |         |        |
|      | Front wheel axle / BT  |     | -    | 125.00   | $\vdash$ |         |        |
|      | CONTRACTOR OF THE CONTRACTOR O |     | \$   |          | -        |         |        |
|      | Front fork assy  |     | \$   | 1,750.00 | $\vdash$ |         |        |
|      | Fork under bracket ?   |     | \$   | 350.00   | $\vdash$ |         |        |
|      | Front signal lamp (RH) (UT   |     | \$   | 85.00    | _        |         |        |
| 7    | Brake lever (RH) CVT   |     | \$   | 50.00    | _        |         |        |
| _    | Handle bar X   |     | \$   | 145.00   |          |         |        |
| 9    | Mirror / (41   |     | \$   | 98.00    |          |         |        |
| 10   | Side cover (R) / (M)   |     | \$   | 275.00   |          |         |        |
| 11   | Brake pedal / (4)  |     | \$   | 130.00   |          |         |        |
| 12   | Front foot rest  |     | \$   | 65.00    |          |         |        |
| 13   | Front foot rest bracket <  |     | \$   | 170.00   | $\vdash$ |         |        |
|      | Rear foot rest   |     | \$   | 45.00    |          |         |        |
|      | Exhaust muffler / 647 01)  |     | \$   | 740.00   | $\vdash$ |         |        |
| _    | Exhaust muffler protector / (47  |     | \$   | 125.00   | -        |         |        |
|      | Tail cover / (M)   |     | \$   | 320.00   | $\vdash$ |         |        |
|      | Rear signal lamp X   |     | \$   | 85.00    | $\vdash$ |         |        |
|      | Frame slider (fH) and  |     | Ş    | 65.00    | ć        | 180.00  |        |
|      |  |     | -    |          | \$       |         |        |
|      |  |     | _    |          | \$       | 175.00  | 100    |
|      | Front tyre ?   |     | _    |          | \$       | 170.00  |        |
|      | Repair alignment   |     | _    |          | \$       | 320.00  | V 10   |
| _    | Towing 2 way   |     |      |          | \$       | 120.00  | 60     |
|      | Labour   |     |      |          | \$       | 350.00  | 250    |
| 25   |  |     |      |          |          |         |        |
| 26   |  |     |      |          |          |         |        |
| 27   |  |     |      |          |          |         |        |
| 28   |  |     |      |          |          |         |        |
| 29   |  |     |      |          |          |         |        |
| 30   |  |     |      |          |          |         |        |
| 31   |  |     |      |          |          |         |        |
| 32   |  |     |      |          |          |         |        |
| 33   |  |     |      |          |          |         |        |
| 34   |  |     |      |          | _        |         |        |
| 35   | LIVE A CONTRACT OF THE CONTRAC |     |      |          | -        |         |        |
| 36   | LKK Auto Consultants hence notify the Repairer of the following:   |     |      |          | $\vdash$ |         |        |
| 37   | To resurvey before/after spray painting  |     |      |          | -        |         |        |
| _    | To display damaged part(s) during resurvey   |     | _    |          | -        |         |        |
| 38   | Parts prices are subject to confirmation   |     |      |          | -        |         |        |
| 39   | <ul> <li>Third party survey is on a "Without Prejudice" basis</li> <li>No illegal modification(s) is allowed</li> </ul>  |     |      | 5 402 00 | L        |         |        |

Supplementary item(s) must be resurveyed and is subject to final approval from Instances 100 pany

Acknowledged by Repairer

Signature:

Date:

\$ 5,493.00 \$ 1,315.00

\$ 549.30

\$ 4,943.70

# Leong Seng Motor Pte Ltd

Steve (LKK)

Blk 1006 Bukit Merah Lane 2 #01-08 Singapore 159762

Tel: 62737469 Fax: 62727669
WL PRIM L 8/4/19 4.00 PM
3 Ly L/S Ry AL Spy Veh No:
Model:

FBM3818X

| 5/Nd | Parts Description                | QTY | List Price                                       | Nett Price | Remark     |
|------|----------------------------------|-----|--|------------|------------|
| _    | Front wheel rim / BT             |     | \$ 885.00  | 850/       |            |
| 2    | Front wheel bearing / NE(        |     | \$ 50.00   | /          |            |
| 3    | Front wheel axle / DT            |     | \$ 125.00  | 68/        |            |
| 4    | Front fork assy ?                |     | \$ 1,750.00                                      | 1680/      |            |
| 5    | Fork under bracket ? X N/M       |     | \$ 350.00  | X          |            |
| 6    | Front signal lamp (RH) (UT)      |     | \$ 85.00   | 601        |            |
| 7    | Brake lever (RH) (VI             |     | \$ 50.00   | /          |            |
| 8    | Handle bar X N/II                |     | \$ 145.00  | X          |            |
| 9    | Mirror / (4T                     |     | \$ 98.00   | 90/        |            |
| 10   | Side cover (R) / (N)             |     | \$ 275.00  | /          |            |
| _    | Brake pedal / (VT                |     | \$ 130.00  | 85/        |            |
|      | Front foot rest                  |     | \$ 65.00   | ×          |            |
| _    | Front foot rest bracket <        |     | \$ 170.00  | X          |            |
|      | Rear foot rest X /////           |     | \$ 45.00   | ×          |            |
|      | Exhaust muffler / 64 00          |     | \$ 740.00  | /          |            |
| -    | Exhaust muffler protector / (Vi7 |     | \$ 125.00  | /          |            |
|      | Tail cover / (V)                 |     | \$ 320.00  | /          |            |
|      | Rear signal lamp X N/N           |     | \$ 85.00   | X          |            |
|      | Frame slider (fH) CVT            |     | 11797  | \$ 180.00  | /          |
|      | Engine slider (PM) (MT           |     | 4595   | \$ 175.00  | /          |
|      | Front tyre ? × MM                |     | 10%  | \$ 170.00  | 100×       |
| _    | Repair alignment                 |     | 3953-70  | \$ 320.00  | ER 180 700 |
| 23   | Towing 2 way                     |     | 0.19   | \$ 120.00  | 60         |
| 24   | Labour                           |     |  | \$ 350.00  | 250 300    |
| 25   |                                  |     |  |            | 70 0       |
| 26   | l har I -                        |     |  | 915        |            |
| 27   | M (1)5                           |     |  |            |            |
| 28   |                                  |     |  |            |            |
| 29   |                                  |     | 1  |            |            |
| 30   |                                  |     |  |            |            |
| 31   |                                  | _   | -  |            |            |
| 32   |                                  |     |  |            |            |
| 33   |                                  |     |  |            |            |
| 34   |                                  | _   | 1  |            |            |
| 35   |                                  | -   | <del> </del>                                     |            |            |
| 36   |                                  | +   | <del>                                     </del> |            |            |
| 37   |                                  |     |  |            |            |
| 38   |                                  | -   | 1  | -          |            |
| 39   |                                  |     | <del> </del>                                     |            |            |
| 33   | 0 2957.70                        |     | \$ 5,493.00                                      | Ć 1 21F 00 |            |

P- 3953.70 \$

N+L-915
4868.70 \$

LIS-3894.96 = 3909 Less 10%

\$ 5,493.00 \$ 1,315.00

\$ 549.30 \$ 4,943.70

6258.70

## Veron Chen (LKKAuto)

From:

leongseng <leongsen@singnet.com.sg>

Sent:

Saturday, 11 May 2019 10:12 AM

To:

SUR

Subject:

FBM3818 marked estimate

Attachments:

IMG\_20190511\_0002.pdf

Dear Steve

Pls find enclosed FBM3818X marked estimate

Kindly check and advice us on your recommended COR

Pls find below are our working on COR

parts

\$4698.00

less 10%

(\$469.80)

\$4228.20

net item & labour \$915.00

sub total

\$5143.20

less 20%

(\$1028.64)

total

\$4114.58

Based on our above working, we will like to request for Lump Sum \$4100.00

Kindly consider and keep us posted of your recommended COR.

Thanks

c s teo



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

|      |  | DAMAGE ASSES                | SMENT REPORT         |                         |  |  |  |
|------|--|-----------------------------|----------------------|-------------------------|--|--|--|
| NITL | IC INCOME INSUE  | RANCE CO-OPERATIVE LTD      |                      | 85/Fvd3e2               |  |  |  |
| 73 B | BRAS BASAH ROA<br>-01 NTUC TRADE I   |                             | Date: 15-05-2019     |                         |  |  |  |
| ATT  | N : AZHARI   |                             | Code: INC            |                         |  |  |  |
| 1.   | 一般質量了  | Policy Particulars          | :- THIRD PARTY CLAIM |                         |  |  |  |
|      | Insured Veh.   | SLK 4888D                   | Veh. Inspected       | FBM 3818X               |  |  |  |
|      | Policy No.   |                             | Coverage (\$)        | 0.00                    |  |  |  |
|      | Claim No.  | MT/1038231-002              | Excess (\$)          | 0.00                    |  |  |  |
|      | Assign From  | ANNIE KOH                   | Assign Date          | 05/04/2019              |  |  |  |
| 2.   |  | Vehicle Parti               | culars & Condition   |                         |  |  |  |
|      | Make & Model   | YAMAHA R3                   | c.c                  | 321                     |  |  |  |
|      | Engine No.   | HIDDEN                      | Year of Reg.         | 2017                    |  |  |  |
|      | Chassis No.  | MH3RH121000002554           | Colour               | BLACK                   |  |  |  |
|      | Odometer   | 11669 KM                    | Steering             | IN ORDER                |  |  |  |
|      | Brakes   | IN ORDER                    | Modification         | SPORTS RIM              |  |  |  |
|      | General  | GOOD                        |                      |                         |  |  |  |
| 3.   |  | Conditi                     | ions of Tyres        |                         |  |  |  |
|      |  | Size                        | Make                 | Balance                 |  |  |  |
|      | R/H Front Tyre   | 110/70-17                   | MICHELIN             | 6 mm                    |  |  |  |
|      | L/H Front Tyre   |                             |                      | mm                      |  |  |  |
|      | R/H Rear Tyre  | 140/70-17                   | MICHELIN             | 6 mm                    |  |  |  |
|      | L/H Rear Tyre  |                             |                      | mm                      |  |  |  |
| 4.   | Description of Damages   |                             |                      |                         |  |  |  |
|      | AR   |                             |                      |                         |  |  |  |
|      | DAMAGES SEE DI   | ETAILS.                     |                      |                         |  |  |  |
| 5.   |  | General Information         |                      |                         |  |  |  |
|      | Accident Date  | 01/04/2019                  | Inspect Date / Time  | 08/04/2019 ( 03:32 PM ) |  |  |  |
|      | Survey held at   | LEONG SENG MOTOR PTE LT     | D                    |                         |  |  |  |
|      | BLK 1006, BUKIT MERAH LANE 2<br>#01-08<br>ALEXANDRA VILLAGE<br>SINGAPORE 159762.   |                             |                      |                         |  |  |  |
| 5a.  |  | Remarks                     |                      |                         |  |  |  |
|      | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                             |                      |                         |  |  |  |
|      | B)IN ACCORDANG   | JE TO TOUR INSTRUCTIONS, VI | VE HAVE NOT AUTHORIS | ED KEI AIKO.            |  |  |  |

ESTIMATED NORMAL PERIOD FOR REPAIR:

3 Working Days



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

# ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBM 3818X

| ty | Description of Parts      | Condition     | Estimate By<br>Workshop (\$)) | Our Adjusted (\$) |
|----|---------------------------|---------------|-------------------------------|-------------------|
|    | REPLACEMENT OF PARTS      |               |                               |                   |
| 1  | FRONT WHEEL RIM           | BENT          | 885.00                        | 850.00            |
| 1  | FRONT WHEEL BEARING       | NECESSARY     | 50.00                         | 50.00             |
| 1  | FRONT WHEEL AXLE          | BENT          | 125.00                        | 68.00             |
| 1  | FRONT FORK ASSY           | BENT          | 1,750.00                      | 1,680.00          |
| 1  | FORK UNDER BRACKET        | NOT NECESSARY | 350.00                        | -                 |
| 1  | FRONT SIGNAL LAMP (RH)    | сит           | 85.00                         | 60.00             |
| 1  | BRAKE LEVER (RH)          | сит           | 50.00                         | 50.00             |
| 1  | HANDLE BAR                | NOT NECESSARY | 145.00                        |                   |
| 1  | MIRROR                    | CUT           | 98.00                         | 90.00             |
| 1  | SIDE COVER (R)            | сит           | 275.00                        | 275.00            |
| 1  | BRAKE PEDAL               | сит           | 130.00                        | 85.00             |
| 1  | FRONT FOOT REST           | NOT NECESSARY | 65.00                         |                   |
| 1  | FRONT FOOT REST BRACKET   | NOT NECESSARY | 170.00                        | ,                 |
| 1  | REAR FOOT REST            | NOT NECESSARY | 45.00                         |                   |
| 1  | EXHAUST MUFFLER           | DENTED        | 740.00                        | 740.00            |
| 1  | EXHAUST MUFFLER PROTECTOR | сит           | 125.00                        | 125.00            |
| 1  | TAIL COVER                | сит           | 320.00                        | 320.00            |
| 1  | REAR SIGNAL LAMP          | NOT NECESSARY | 85.00                         |                   |
|    | LESS 10% DISCOUNT         |               | -549.30                       | -439.30           |
|    |                           |               | 4,943.70                      | 3,953.70          |
|    | SPECIAL NETT ITEMS        |               |                               |                   |
| 1  | FRAME SLIDER (RH) (SN)    | сит           | 180.00                        | 180.00            |
| 1  | ENGINE SLIDER (RH) (SN)   | сит           | 175.00                        | 175.00            |
| 1  | FRONT TYRE (SN)           | NOT NECESSARY | 170.00                        |                   |
|    | 41                        |               | 525.00                        | 355.00            |
|    | LABOUR                    |               |                               |                   |
|    | REPAIR ALIGNMENT.         |               | 320.00                        | 200.00            |
|    | TOWING 2 WAY.             |               | 120.00                        | 60.00             |
|    | LABOUR.                   |               | 350.00                        | 300.00            |
|    |                           |               | 790.00                        | 560.00            |

Report Ref No. CS/INC19006065/Evd3e2



Page No.:2 of 2

| GRAND TOTAL  | 6,258.70 | 4,868.70 |  |
|--|----------|----------|--|
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED) |          | 3,900.00 |  |

Report Ref No. CS/INC19006065/Evd3e2

**CHEN TSUE YEE** 

**Automotive Assessor** 

h

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.