

ASSIGNMENT

REF CS/INC 19006070/T19d3

Special Instruction

Surveyor

Taufik

ASSIGNMENT (Office)

From (Person)

Annie Koh

of

INC

Date/Time

5/4/19 @ 10:14am

Estimated Cost

Fill by

OD (TP) WS/TP RES/OD RES/EVA/INV/MT/CS

To Inspect Vehicle No

STE 466X

Insured

SID 5299H

at Workshop no

vermogen

Tel

6358 3031

of

G Benoi place

Policy No

Claim No

MT/1038813-002

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A

03/04/2019

CA / REV / REP / REV 24 HRS

up

H.O.D. Endorsement

Date/Time

10:20am @ 5/4/19

Person Contacted

pila

Vehicle

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SE 466X -X

SID 5299H - MBA/INC 15013254/21

D.O.A - 4/8/2015

16/4/19 @ 3:05pm confirmed with ER1 LS @ 440, 7 days by email.

CRN @ 14019.20, 76%)

Surrey

Taylor

REF: INC

ASSIGNMENT

From

Date: 5/4/2019

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLE 466X

at Workshop n/s

Vermogen
6 Benoiplace

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

7

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLE 466X.

Yr Regn:

206

July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Siata

C.C.

1496

Colour

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

F 182/06

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NSP1707028471

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Fireng.

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

5/4/17 0320pm

Survey held at

Vermogen

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 16 APR 2019

Date/Time, File Pass to?

☐

Preli. Report

1) 16/4 14:15

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

7

Resurvey No. of Trip:

1

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation.

S + RS. \$

Photos

Others

TOTAL

Report Format :

7P

Lump Sum / L.P. (\$)

4400

Nivitha (LKK Auto)

From: Annie Koh <annie.koh@income.com.sg>
Sent: Friday, 5 April 2019 10:14 AM
To: 'assignments@lkkauto.com'
Subject: RE: TP CASES FARMED OUT TO LKK ON 05/04/2019

Re-send

Warmest Regards

Annie Koh
Senior Admin,
Motor Insurance
T +65 64307899
www.income.com.sg



From: Annie Koh
Sent: Friday, 5 April 2019 9:18 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 05/04/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	OI VEH	DOA	Additional Remarks
1	CYNDIE YONG	MT/1038760-001	SHA9982G	DING AUTOMOTIVE PTE LTD	31 CORPORATION ROAD SINGAPORE 649825	Nelson Wong / 98912489	FBM6655D	3/4/19	
2	AZHARI	MT/1038231-002	FBM3818X	LEONG SENG MOTOR PTE LTD	BLK 1006 #01-08 BUKIT MERAH LANE 2 SINGAPORE 159762	c s teo / 62737469	SLK4888D	1/4/19	
3	JULIANA LEE	MT/1038813-002	SLE466X	VERMOGEN ACE PTE LTD	6 BENOI ROAD, SINGAPORE 629904	Pila / 6358 3031	SJD5299H	3/4/19	
4	JARED LIU	MT/1038592-002	PC5282P	WOODLANDS TRANSPORT SERVICE PTE LTD	8 GUL CIRCLE SINGAPORE 629564	Mr Chan / 9299 4122	PA5960B	1/4/19	6559 8984

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh

Senior Admin Assistant, Motor Insurance

T +65 6430 7899

www.income.com.sg



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

Shiau Chan (LKKAUTO)

From: ezel.t@vermogen-group.com
Sent: Tuesday, 16 April 2019 3:05 PM
To: Shiau Chan (LKKAUTO); Taufikh (LKKAUTO)
Cc: 'Glorioso Eric Paul Patambang'; 'Baldoz Juan Paulo Bongon'; SUR
Subject: RE: TP FINALISE SLE466X DOA: 03/04/2019

Dear Shiau Chan,

COR & DOR confirmed.

Thanks & Regards,
Ezel Tejano

-----Original Message-----

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Tuesday, April 16, 2019 2:58 PM
To: ezel.t@vermogen-group.com; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>
Cc: 'Glorioso Eric Paul Patambang' <eric.g@vermogen-group.com>; 'Baldoz Juan Paulo Bongon' <paulo.b@vermogen-group.com>; SUR <sur@lkkauto.com>
Subject: RE: TP FINALISE SLE466X DOA: 03/04/2019

Dear Ezel,

WITHOUT PREJUDICE

Offer Lump Sum \$4,400.00 before GST and 7 repair days.

Kindly confirm.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: ezel.t@vermogen-group.com <ezel.t@vermogen-group.com>
Sent: Monday, 15 April 2019 3:39 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Cc: 'Glorioso Eric Paul Patambang' <eric.g@vermogen-group.com>; 'Baldoz Juan Paulo Bongon' <paulo.b@vermogen-group.com>
Subject: TP FINALISE SLE466X DOA: 03/04/2019

Dear Taufikh,

Please check and confirm finalise COR L/S \$4,500.00 before GST in 7 working days (excluding PRS/RS/Weekend & PH).

Thank you.
Best Regards,

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/04/2019 16:46
Date Of Accident	03/04/2019 17:30
Exact Location Of Accident	SLE TOWARDS WOODLANDS AVE 2 EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE466X
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66944919

Vehicle Particulars

Manufacturer	TOYOTA
Model	SIENTA
Exact Purpose for which vehicle was being used at time of accident	HIRER

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	19-MK000194-R00
Cover Note Number	

Driver

Name of Driver	MOHAMMAD AZMAN BIN SAFAR WAN
NRIC No	S8024239E
Date Of Birth	25/08/1980
Occupation	OUTDOOR
Date Of Driving Pass	08/03/2008
Driving Experience	11 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90106639
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address 44 BENOI ROAD BLOCK B, SINGAPORE 629904
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 3
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 4
 Passenger 1
 NAME: : WIFE
 GENDER: : FEMALE
 Passenger 2
 NAME: : DAUGHTER
 GENDER: : FEMALE
 Passenger 3
 NAME: : DAUGHTER
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO PHOTOS AS ATTACHED, THANK YOU!

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJD5299H
 Vehicle Make/Model/Colour
 Details Of Properties VEH. B
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SDP63L
Vehicle Make/Model/Colour
Details Of Properties VEH. C
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name MOHAMMAD AZMAN BIN SAFAR WAN
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLE466X
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 2

Name WIFE
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLE466X
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 3

Name DAUGHTER
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLE466X
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 4

Name DAUGHTER

Approximate Age

Injuries Sustain

Injured person in which vehicle?

SLE466X

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

Accident Sketch Plan

04/2019

SLE - Google Maps

Google Maps SLE




Image capture: Apr 2018 © 2019 Google

Singapore

Google

Street View - Apr 2018

Paro Rosewood
LE

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/IN No.:

Accident Sketch Plan Pg. 2

SLE TOWARDS WOODLANDS AVE 2 EXIT

SKETCH PLAN

- (A) SLE466X
- (B) SJD5299H
- (C) SDP63L



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along SLE towards Woodlands Ave 2 exit. The traffic was heavy and the movement was very slow where I would move a few metres and stop again repeatedly. While my car was stationary, when suddenly I felt a strong impact coming from the rear of my car. I went out to check. I realised I was involved in chain collision. I am the 1st car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

YARA RAHMAN

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	4597K
Vehicle No.:	SLE466X
Vehicle to be Exported:	Yes
Intended Deregistration Date:	04 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA 1.5G CVT ABS D/AIRBAG 2WD 5DR
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	2NR8605473
Chassis No.:	NSP1707028471
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$19,449.00
Original Registration Date:	04 Jul 2016
First Registration Date:	04 Jul 2016
Transfer Count:	1
Actual ARF Paid:	\$9,449.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Jul 2026
PARF Rebate Amount:	\$7,086.00
COE Expiry Date:	03 Jul 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$53,694.00
COE Rebate Amount:	\$38,911.00
Total Rebate Amount:	\$45,997.00

The information contained herein is correct as at 04 Apr 2019

OK



SLE466X

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : NTUC
OWN INSURER : TMIS
CLAIM TYPE : TP
Date of Accident : 3-Apr-2019

Vehicle Reg. No. : SLE466X
Vehicle Reg. Date: 4-Jul-2016
Make / Model : T. SIENTA 1.5G CVT ABS
Engine No. : 2NR8605473
Chassis No. : NSP1707028471

COST OF CLAIMS

Parts Cost / List Items : \$ 18,085.60
Plus/Less 25% \$ 4,521.40
Total Cost / List : \$ 13,564.20
Special Nett Items : \$ 375.00
Total Parts Amount : \$ 13,939.20
Total Labour Amount : \$ 4,480.00
Gross Total : \$ 18,419.20
GST % : 7% \$ 1,289.34
Nett Amount : \$ 19,708.54

Signature
10/4/19

Surveyor Name and Company :

Tay Jia 97495749

Date of survey : 5/4/19 @ 320pm

Part by Part / Lump Sum : For 6-7 days

Resurvey Before Paint / After Paint After Paint

Authorize/Not Authorize/Without Prejudice Without Prejudice

Email : suvo@lkkauto.com

Fax No : _____

HP No : _____

This claim is handled by : EZEL

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts to be replaced to confirmation
- To display damaged part(s) during resurvey
- To display damaged part(s) during resurvey
- To display damaged part(s) during resurvey

Acknowledged by Repairer

Signature:

Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLE466X**
 Vehicle Reg. Date: **7/4/2016**
 Make / Model : **T. SIENTA 1.5G CVT ABS D/AIRBAG 2WD 5DR**
 Engine No. : **2NR8605473**
 Chassis No. : **NSP1707028471**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Rear windscreen moulding	rel ✓	\$ 168.40	✓	
2	1	Rear number plate lamp assy	x un	\$ 158.00		
3	1	Rear bumper	de ✓	\$ 534.00	497-60	
4	1	Rear bumper cover center	de ✓	\$ 183.00		
5	2	Rear bumper cover LH/RH	124 LH-de ✓, RH-x	\$ 248.00		
6	1set	Rear bumper clips	rel ✓ 30	\$ 50.00		
7	2	Rear bumper side retainer LH/RH	82 LH-rel ✓, RH-x	\$ 164.00		
8	2	Rear bumper bracket LH/RH	82 LH-rel ✓, RH-x	\$ 164.00		
9	1	Rear bumper sponge	rel ✓	\$ 54.00	x un.	
10	2	Rear bumper reflector LH/RH	LH-x un, RH-x un	\$ 216.00	x un	
11	2	Rear bumper splash shield LH/RH	x un	\$ 156.00		
12	1	Tail gate	bt ✓	\$ 1,086.00	991-58	
13	1	Tail gate lock	bt ✓	\$ 448.00		
14	1	Tail gate striker	bt ✓	\$ 48.00		
15	2	Tail gate stay LH/RH	x un	\$ 454.00		
16	1	Tail gate logo	rel ✓	\$ 57.00		
17	1	Tail gate emblem RH	rel ✓	\$ 63.00		
18	1	Tail gate outer garnish	x un	\$ 278.00	x	
19	1	Tail gate weatherstrip	twi ✓	\$ 357.00		
20	2	Tail gate lamp LH/RH	x x un	\$ 294.00	x	
21	1	Tailgate trimboard	x un	\$ 280.00		
22	2	Tail gate inner side trim LH/RH	x un	\$ 1,214.00		
23	2	Tail lamp LH/RH	A x un	\$ 780.00		
24	2	Tail lamp clips LH/RH	x un	\$ 40.00		
25	1	Tail gate inner handle	de ✓	\$ 90.00		
26	1	Antenna sensor	x ✓	\$ 190.00	x	
27	1	Rear wiper motor	x } x	\$ 400.00		
28	1	Rear wiper motor link	x } x	\$ 240.00		
29	1	Rear wiper arm	x } x	\$ 200.00		
30	1	Rear wiper blade	x } x	\$ 400.00		
31	1	Rear end panel outer	bt ✓	\$ 498.20		
32	1	Rear end panel inner	un Rel x	\$ 498.20	x	
33	1	Rear end panel garnish	rel ✓	\$ 195.20		
34	1	Spare tyre well panel	R x	\$ 822.60		
35	1	Spare tyre board	x } x	\$ 487.00		
36	1	Spare tyre bracket	x } x	\$ 60.00		
37	1	Spare tyre tool cover	x } x	\$ 280.00		
38	1	Spare tyre tool tray	1 de ✓	\$ 419.00		
39	1	Exhaust muffler	x un	\$ 673.00		
40	1	Exhaust muffler mounting	x un	\$ 70.00		

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLE466X**
 Vehicle Reg. Date: **7/4/2016**
 Make / Model : **T. SIENTA 1.5G CVT ABS D/AIRBAG 2WD 5DR**
 Engine No. : **2NR8605473**
 Chassis No. : **NSP1707028471**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Exhaust heat shield	X	\$ 90.00		
42	2	Rear fender LH/RH	X	\$ 3,352.00		
43	2	Rear fender garnish lower LH/RH	X	\$ 142.00		
44	2	Rear fender garnish upper LH/RH	X	\$ 1,214.00		
45	2	Rear fender air duct LH/RH	X	\$ 150.00		
46	1set	Tailgate trimboard clips	X	\$ 40.00		
47	2set	Tail gate inner side trim LH/RH clips	X	\$ 80.00		
48	1	Rear end panel sealant	new → 9		\$ 40.00	✓
49	1	Sundries	new 20		\$ 50.00	✓
50	1	Reverse sensor	new ✓		\$ 200.00	✓
51	1	Rear number plate with frame	new - X		\$ 45.00	✓
52	1	Rear windscreen sealant	new ✓		\$ 40.00	✓
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]



SLE466X

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : NTUC
OWN INSURER : TMIS
CLAIM TYPE : TP
Date of Accident : 3-Apr-2019

Vehicle Reg. No. : SLE466X
Vehicle Reg. Date: 4-Jul-2016
Make / Model : T. SIENTA 1.5G CVT ABS
Engine No. : 2NR8605473
Chassis No. : NSP1707028471

COST OF CLAIMS

Parts Cost / List Items : \$ 18,085.60
Plus/Less 25% \$ 4,521.40
Total Cost / List : \$ 13,564.20
Special Nett Items : \$ 375.00
Total Parts Amount : \$ 13,939.20
Total Labour Amount : \$ 4,480.00
Gross Total : \$ 18,419.20
GST % : 7% \$ 1,289.34
Nett Amount : \$ 19,708.54

Surveyor Name and Company :

Tayfik 97495749
Date of survey : 5/4/19 3:20 pm
Part by Part / Lump Sum : For 6-7 days
Resurvey Before Paint / After Paint
Authorize/Not Authorize/Without Prejudice
Email : suvo@kwafo.com
Fax No : _____
HP No : _____

This claim is handled by : EZEL

6 Benoi Sector, Singapore (629904)
Tel : 6358 3031 | Fax No : 6694 4929

PAGE 1

[illegible]

P - 3648.60
L - 2020
T - 5668.60
- 20%
4534.88

$$\underline{218 = \$4500/-}$$

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLE466X**
 Vehicle Reg. Date: **7/4/2016**
 Make / Model : **T. SIENTA 1.5G CVT ABS D/AIRBAG 2WD 5DR**
 Engine No. : **2NR8605473**
 Chassis No. : **NSP1707028471**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Rear windscreen moulding	nd ✓	\$ 168.40		
2	1	Rear number plate lamp assy	X	\$ 158.00		
3	1	Rear bumper	de ✓	\$ 534.00		
4	1	Rear bumper cover center	de ✓	\$ 183.00		
5	2	Rear bumper cover LH/RH	LH-de ✓, RH-X	\$ 248.00	124	
6	1set	Rear bumper clips	nd ✓ 30	\$ 50.00		
7	2	Rear bumper side retainer LH/RH	LH-nd ✓, RH-X	\$ 154.00	82	
8	2	Rear bumper bracket LH/RH	LH-nd ✓, RH-X	\$ 154.00	82	
9	1	Rear bumper sponge	?	\$ 54.00		
10	2	Rear bumper reflector LH/RH	LH-?, RH-X	\$ 216.00		
11	2	Rear bumper splash shield LH/RH	X	\$ 156.00		
12	1	Tail gate	bt ✓	\$ 1,086.00		
13	1	Tail gate lock	bt ✓	\$ 448.00		
14	1	Tail gate striker	bt ✓	\$ 48.00		
15	2	Tail gate stay LH/RH	X	\$ 454.00		
16	1	Tail gate logo	nd ✓	\$ 57.00		
17	1	Tail gate emblem RH	nd ✓	\$ 63.00		
18	1	Tail gate outer garnish	?	\$ 278.00		
19	1	Tail gate weatherstrip	fw ✓	\$ 357.00		
20	2	Tail gate lamp LH/RH	X	\$ 294.00		
21	1	Tailgate trimboard	X	\$ 280.00		
22	2	Tail gate inner side trim LH/RH	X	\$ 1,214.00		
23	2	Tail lamp LH/RH	A X	\$ 780.00		
24	2	Tail lamp clips LH/RH	X	\$ 40.00		
25	1	Tail gate inner handle	de ✓	\$ 90.00		
26	1	Antenna sensor	?	\$ 190.00		
27	1	Rear wiper motor	X	\$ 400.00		
28	1	Rear wiper motor link	X	\$ 240.00		
29	1	Rear wiper arm	X	\$ 200.00		
30	1	Rear wiper blade	X	\$ 400.00		
31	1	Rear end panel outer	bt ✓	\$ 498.20		
32	1	Rear end panel inner	Ref ?	\$ 498.20		
33	1	Rear end panel garnish	de ✓	\$ 195.20		
34	1	Spare tyre well panel	R X	\$ 822.60		
35	1	Spare tyre board	X	\$ 487.00		
36	1	Spare tyre bracket	X	\$ 60.00		
37	1	Spare tyre tool cover	X	\$ 280.00		
38	1	Spare tyre tool tray	1 de ✓	\$ 419.00		
39	1	Exhaust muffler	X	\$ 673.00		
40	1	Exhaust muffler mounting	X	\$ 70.00		

P - 4464.80 - 25% = 3348.60

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6358 3031 | Fax No : 6694 4929

Vehicle Reg. No. : **SLE466X**
 Vehicle Reg. Date: **7/4/2016**
 Make / Model : **T. SIENTA 1.5G CVT ABS D/AIRBAG 2WD 5DR**
 Engine No. : **2NR8605473**
 Chassis No. : **NSP1707028471**

PAGE 2

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
41	1	Exhaust heat shield	X	\$ 90.00		
42	2	Rear fender LH/RH	X	\$ 3,352.00		
43	2	Rear fender garnish lower LH/RH	✓	\$ 142.00		
44	2	Rear fender garnish upper LH/RH	✓	\$ 1,214.00		
45	2	Rear fender air duct LH/RH	X	\$ 150.00		
46	1set	Tailgate trimboard clips	X	\$ 40.00		
47	2set	Tail gate inner side trim LH/RH clips	X	\$ 80.00		
48	1	Rear end panel sealant	me ✓ 9		\$ 40.00	
49	1	Sundries	20		\$ 50.00	
50	1	Reverse sensor	me ✓		\$ 200.00	
51	1	Rear number plate with frame	X		\$ 45.00	
52	1	Rear windscreen sealant	me ✓		\$ 40.00	
53	0	0				
54	0	0				
55	0	0				
56	0	0				
57	0	0				
58	0	0				
59	0	0				
60	0	0				
61	0	0				
62	0	0				
63	0	0				
64	0	0				
65	0	0				
66	0	0				
67	0	0				
68	0	0				
69	0	0				
70	0	0				
71	0	0				
72	0	0				
73	0	0				
74	0	0				
75	0	0				
76	0	0				
77	0	0				
78	0	0				
79	0	0				
80	0	0				

DN - 300



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19006070/T1qd3s2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 24-04-2019



ATTN: JULIANA LEE

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJD 5299H	Veh. Inspected	SLE 466X
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1038813-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	05/04/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA SIENTA	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	NSP1707028471	Colour	BLUE
Odometer	182106 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60R15	FIRENZA	6 mm
L/H Front Tyre	185/60R15	FIRENZA	6 mm
R/H Rear Tyre	185/60R15	FIRENZA	6 mm
L/H Rear Tyre	185/60R15	FIRENZA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/04/2019	Inspect Date / Time	05/04/2019 (03:20 PM)
Survey held at	6 BENOI PLACE		
Repairer	VERMOGEN ACE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 466X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR WINDSCREEN MOULDING	NECESSARY	168.40	168.40
1	REAR NUMBER PLATE LAMP ASSY	NOT NECESSARY	158.00	-
1	REAR BUMPER	DEFORMED	534.00	497.60
1	REAR BUMPER COVER CENTER	DEFORMED	183.00	183.00
2	REAR BUMPER COVER LH/RH	N/S DEFORMED / O/S NOT NECESSARY	248.00	124.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	30.00
2	REAR BUMPER SIDE RETAINER LH/RH	N/S NECESSARY / O/S NOT NECESSARY	164.00	82.00
2	REAR BUMPER BRACKET LH/RH	N/S NECESSARY / O/S NOT NECESSARY	164.00	82.00
1	REAR BUMPER SPONGE	NOT NECESSARY	54.00	-
2	REAR BUMPER REFLECTOR LH/RH	NOT NECESSARY	216.00	-
2	REAR BUMPER SPLASH SHIELD LH/RH	NOT NECESSARY	156.00	-
1	TAIL GATE	BENT	1,086.00	991.58
1	TAIL GATE LOCK	BENT	448.00	448.00
1	TAIL GATE STRIKER	BENT	48.00	48.00
2	TAIL GATE STAY LH/RH	NOT NECESSARY	454.00	-
1	TAIL GATE LOGO	NECESSARY	57.00	57.00
1	TAIL GATE EMBLEM RH	NECESSARY	63.00	63.00
1	TAIL GATE OUTER GARNISH	NOT NECESSARY	278.00	-
1	TAIL GATE WEATHERSTRIP	TWISTED	357.00	357.00
2	TAIL GATE LAMP LH/RH	NOT NECESSARY	294.00	-
1	TAILGATE TRIMBOARD	NOT NECESSARY	280.00	-
2	TAIL GATE INNER SIDE TRIM LH/RH	NOT NECESSARY	1,214.00	-
2	TAIL LAMP LH/RH	NOT NECESSARY	780.00	-
2	TAIL LAMP CLIPS LH/RH	NOT NECESSARY	40.00	-
1	TAIL GATE INNER HANDLE	DEFORMED	90.00	90.00
1	ANTENNA SENSOR	NOT NECESSARY	190.00	-
1	REAR WIPER MOTOR	NOT NECESSARY	400.00	-

Report Ref No. CS/INC19006070/T1qd3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR WIPER MOTOR LINK	NOT NECESSARY	240.00	-
1	REAR WIPER ARM	NOT NECESSARY	200.00	-
1	REAR WIPER BLADE	NOT NECESSARY	400.00	-
1	REAR END PANEL OUTER	BENT	498.20	498.20
1	REAR END PANEL INNER	NOT NECESSARY	498.20	-
1	REAR END PANEL GARNISH	DEFORMED	195.20	195.20
1	SPARE TYRE WELL PANEL	TO REPAIR SEE LABOUR	822.60	-
1	SPARE TYRE BOARD	NOT NECESSARY	487.00	-
1	SPARE TYRE BOARD	NOT NECESSARY	60.00	-
1	SPARE TYRE TOOL COVER	NOT NECESSARY	280.00	-
1	SPARE TYRE TOOL TRAY	DEFORMED	419.00	419.00
1	EXHAUST MUFFLER	NOT NECESSARY	673.00	-
1	EXHAUST MUFFLER MOUNTING	NOT NECESSARY	70.00	-
1	EXHAUST HEAT SHIELD	NOT NECESSARY	90.00	-
2	REAR FENDER LH/RH	NOT NECESSARY	3,352.00	-
2	REAR FENDER GARNISH LOWER LH/RH	NOT NECESSARY	142.00	-
2	REAR FENDER GARNISH UPPER LH/RH	NOT NECESSARY	1,214.00	-
2	REAR FENDER AIR DUCT LH/RH	NOT NECESSARY	150.00	-
1	SET TALGATE TRIMBOARD CLIPS	NOT NECESSARY	40.00	-
2	SET TAIL GATE INNER SIDE TRIM LH/RH CLIPS	NOT NECESSARY	80.00	-
	LESS 25% DISCOUNT		-4,521.40	-1,083.49
			13,564.20	3,250.49
	<u>SPECIAL NETT ITEMS</u>			
1	REAR END PANEL SEALANT (SN)	NECESSARY	40.00	40.00
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	REVERSE SENSOR (SN)	NOT WORKING	200.00	200.00
1	REAR NUMBER PLATE WITH FRAME (SN)	NOT NECESSARY	45.00	-
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	40.00	40.00
			375.00	300.00

Report Ref No. CS/INC19006070/T1qd3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE AND REPLACE DAMAGED PARTS AND TO PANEL BEATING ACCIDENT AREA. INCLUSIVE OF THE REPAIR OF SPARE TYRE WELL PANEL.		2,000.00	800.00
	TO REMOVE AND REPLACE REVERSE SENSOR.		100.00	30.00
	TO REMOVE AND REFIT INNER TRIM, INNER SEAT, TRIM BOARD, TO ASSIST REPAIR.		150.00	50.00
	TO RUSTPROOF ACCIDENT REPAIR AREA.		200.00	30.00
	TO TRANSFER TAILGATE MECHANISM TO NEW TAILGATE.		150.00	60.00
	TO CHECK AND RECTIFY WIRING AFTER DISCONNECT AND CONNECT.		50.00	30.00
	TO PUTTY AND RESPRAY REPLACED PARTS AND ACCIDENT REPAIR AREA.		1,500.00	900.00
	TO REMOVE & REFIT REAR WINDSCREEN.		180.00	120.00
	TO REMOVE AND REPLACE AND ALIGN EXHAUST PIPE.	NOT NECESSARY	150.00	-
			4,480.00	2,020.00
	GRAND TOTAL		18,419.20	5,570.49
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			4,400.00

Report Ref No. CS/INC19006070/T1qd3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.