



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SJR6556K

Cheong Chee Keat

Blk 75C Redhill Road
#12-84
Singapore 153075

Mobile: 97315005

Vehicle & Document Information

WIP No 32334
Reg No/Reg Date SJR6556K / 31/05/2018
Date In/Mileage / 0
Chassis No WDD2050402R383851
Engine No 27491031335181
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim 027 775 Iridium sil/ 041 101 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator			
CSI00001	Cash	31/05/2019/ 18:14	VS	356 / Vincent Seah			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

<p>M BPNSUN POLICY NO/ACC DATE : 1800053154 // 04.04.19 DRIVE IN/EXCESS : 05.04.19 // TP CAR NO.: SKA812M-AXA INS DATE IN/DATE SURVEY: 10.06.19 // DIRECT SETTLEMENT : VIC AIPEH-LKK</p>					
A BPILAB	"USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT"			0.10	380.00
A BPILAB	REMOVE & REPLACE ON REAR BUMPER, REAR BOOT				960 2480.00
A BPIRES	RESPRAY ON REAR BUMPER, REAR BOOT				600 1880.00
M REAR BUMPER	repair	1.00	1590.64	00.00	1590.64
M MOULDING		1.00	131.28	00.00	131.28
M MERCEDES STAR		1.00	48.25	00.00	48.25
M SEALING GROMMET		3.00	1.88	00.00	5.64
M C180 MODEL PLATE		1.00	84.56	00.00	84.56
M TRUNK LID		1.00	2110.79	00.00	2110.79

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirmed & accepted by

7% GST on 8551.16

Total Payable 9,149.74

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SJR6556K

Cheong Chee Keat

Blk 75C Redhill Road
#12-84
Singapore 153075

Vehicle & Document Information

WIP No	32334
Reg No/Reg Date	SJR6556K / 31/05/2018
Date In/Mileage	10/06/2019 / 17419
Chassis No	WDD2060402R38385
Engine No	27491031335181
Make/Model	MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim	027 775 Iridium sil/ 041 101 Leather Bla

Account No	Terms	Date/Time Printed	CSE	Operator
CSI00001	Cash	08/08/2019/ 17:34	VS	356 / Vincent Seah
Description of Goods / Services				
Qty	Unit Price	Disc%	Amount	

M BPNSUN

POLICY NO/ACC DATE : 1800053154 / 04/06/19
DRIVE IN/EXCESS : 405/04/19 // TP CAR NO. : SKA812M-AXA INS
DATE IN/DATE SURVEY: 10.06.19 // 10.06.19 RASUL-LKK 14:40PM
DIRECT SETTLEMENT : VIC AIPEH-LKK

A BPILAB

"USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO
STANDARD SETTINGS.NETT"

A BPILAB

REMOVE & REPLACE ON REAR BUMPER

A BPIRES

RESpray ON REAR BUMPER

0.10 380.00

960.00

600.00

ESTIMATE

Finalization

3 days

Confirmed & accepted by

	Nett	1,940.00
7% GST on	1940.00	135.80
Total Payable		2,075.80

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany