



**ESTEM
PERFORMANCE**

ESTEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLH 4260 E

Finalised

Parts (a) Cost / List Price Items

\$ 577.90 2,659.80

Plus/Less 25%

\$ 144.48 664.95

Total of Cost / List

\$ 433.42 1,994.85

(b) Nett Price Items

Less

Total of Nett Item

(c) Special Nett Items

Total Parts Cost

433.42

Labour

\$ 440.00 1,100.00

Total

\$ 873.42 *✓dk* 3,094.85

*Not Authorized
Resurvey Required*

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Kennerth

Company

LKK

Survey conducted on

8/4/19 at *12:45*

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : *02* day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor

Lc

Date:

8/4/19



**ESTEEM
PERFORMANCE**

ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Prepare Parts

Vehicle No. :
Make & Model :
Chassis No. :

SLH 4260 E

TOYOTA PRIUS

JTDKB3FUX03536578

Submit By :
Year Manufacture :
Engine No. :

Carmen Lim
2016

Cost / List

i/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front bumper <i>Bu</i>	1	\$450.80		<i>✓</i>
2	Front bumper clip <i>nc</i>	10	\$40.00		<i>✓</i>
3	Front bumper reinforcement - upper <i>nc</i>	1	\$711.50		<i>X</i>
4	Front bumper reinforcement - lower <i>nc</i>	1	\$245.30		<i>X</i>
5	Front bumper side retainer RH <i>nc</i>	1	\$107.20		<i>X</i>
6	Front bumper side retainer LH <i>nc</i>	1	\$107.20		<i>X</i> <i>x</i>
7	Front bumper emblem <i>nc</i>	1	\$87.10		<i>✓</i>
8	Fog lamp LH <i>nc</i>	1	\$910.70		<i>X</i> <i>x</i>
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

577.90



Blok 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 6695336.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemparf.com.sg

Vehicle No. : SLH 4260 E
Make & Model : TOYOTA PRIUS

Submit By : Carmen Lim
Year of Manufacture : 2016

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.