

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0441/2019/DY
Date : 5-Apr-19

Vehicle IN workshop.

Your insured vehicle no : **SLT 2015 Y**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Michael Wong Wing Kwong
Address : 3B Lengkong Satu
Singapore 417478
Telephone : 91769996
Type of Claim : Third Party Claim
Policy No. : 2100380684-04
Vehicle No : **SJE 800 M**
Model Code : A4 1.4 TFSI MU
Model / Year : 30/6/2014
Engine No : CJE076408
Chassis No : WAUZZZ8K9EA114858
Mileage :
Date In : 5-Apr-19
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Apr-19
Place of Accident : Carpark of Tan Boon Liat Building

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SJE 800 M

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	s/n \$ 360.00	✓
2	To dismantle and renew front bumper, lhs front fender, bonnet and lhs headlight. To inspect lock carrier for further damages. Reorganize crash management components. Reinstall all parts removed.	\$ 2,700.00	1750 .
3	✓ To respray front bumper, bonnet and lhs front fender. ✓	\$ 2,700.00	1650 .
4	✓ To renew lhs front rim and carry out wheel alignment.	s/n \$ 280.00	✓
5	To carry out diagnostic check.	s/n \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>6,232.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SJE 800 M**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	FRONT BUMPER <i>Distorted</i>	\$ 2,100.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 234.00	✓
3	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE <i>new</i>	\$ 207.00	✓
4	FRONT BUMPER AIR GUDIE GRILLE-LH <i>new</i>	\$ 123.00	✓
5	FRONT WHEEL SPOILER- LH <i>new</i>	\$ 45.00	✓
6	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	\$ 113.00	✓
7	FRONT BUMPER REINFORCEMENT BEAM <i>new</i>	\$ 802.00	✓
8	FRONT BUMPER COVER <i>new</i>	\$ 116.00	✓
9	FRONT BUMPER GUIDE SECTION-LH <i>2nd</i>	\$ 33.00	✓
10	SIGN "CAUTION" <i>3 new</i>	\$ 13.00	✓
11	AIR CONDITIONER STICKER	\$ 22.00	✓
12	FRONT FENDER-LH <i>Distorted</i>	\$ 904.00	✓
13	FRONT FENDER ATTACHMENT PARTS-LH <i>?</i>	\$ 52.00	?
14	FRONT FENDER BRACKET - LH <i>But</i>	\$ 48.00	✓
15	FRONT FENDER BRACKET DEFORMATION-LH <i>new</i>	\$ 45.00	✓
16	FRONT FENDER BRACE-LH <i>But</i>	\$ 107.00	✓
17	FRONT STONE CHIP GUARD -LH <i>new</i>	\$ 67.00	✓
18	ADHESIVE TAPE <i>?</i>	\$ 50.00	?
19	FRONT WHEEL HOUSING-LH <i>tor</i>	\$ 223.00	✓
20	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS-LH <i>?</i>	\$ 41.00	?
SUB TOTAL SPARE PARTS		\$ 5,345.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SJE 800 M**

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	BONNET <i>Revised</i>	\$ 2,549.00	✓
22	BONNET PROTECTIVE FILM <i>new</i>	\$ 42.00	✓
23	BONNET ATTACHMENT PARTS ?	\$ 152.00	?
24	BONNET GAS FILLED STRUT <i>new</i>	\$ 109.00	✓
25	BONNET FRONT EDGE PROTECTION <i>new</i>	\$ 25.00	✓
26	BONNET LID HINGE-LH/RH <i>new</i>	2 \$ 136.00	+
27	BONNET CATCH HOOK <i>new</i>	\$ 127.00	+
28	HEALDIGHT-LH <i>cracked</i>	\$ 2,152.00	✓
29	HEADLIGHT FOR POWER MODULE-LH <i>new</i>	\$ 520.00	+
30	HEADLIGHT CONTROL UNIT-LH <i>new</i>	\$ 1,051.00	+
31	HEADLIGHT BRACKET-LH ?	\$ 96.00	?
32	HEADLIGHT MOUNTING-LH ?	\$ 107.00	?
33	HEALDIGHT LIFT CYLINDER-LH ?	\$ 192.00	?
34	WASH WATER RESERVOIR ?	\$ 200.00	?
35	FRONT LHS RIM <i>4t</i>	TBC	✓
35	SUNDRIES ?	\$ 800.00	?
TOTAL SPARE PARTS		\$ 13,603.00	
TOTAL LABOUR CHARGES		\$ 6,232.00	
GRAND TOTAL		\$ 19,835.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 08/04/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 06 days

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant