



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2007459
INV Date 09/11/2020
Reference CC4/LPC19006093/Eba3q2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SKL 5020R
Insured Veh. SJU 5313K
Claim No. 18/19/19/VP05/021628
Policy No. Z18VP05018971
Accident Date 03/04/2019
Inspection Date 08/04/2019

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC19006093/Eba3q2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 09-11-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJU 5313K	Veh. Inspected	SKL 5020R
Policy No.	Z18VP05018971	Coverage (\$)	0.00
Claim No.	18/19/19/VP05/021628	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	05/04/2019

2. Vehicle Particulars & Condition

Make & Model	NISSAN TEANA	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	MNTBBAL33Z0000024	Colour	GREY
Odometer	156353	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	BRIDGESTONE	7 mm
L/H Front Tyre	215/55 R17	BRIDGESTONE	7 mm
R/H Rear Tyre	215/55 R17	BRIDGESTONE	7 mm
L/H Rear Tyre	215/55 R17	BRIDGESTONE	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/04/2019	Inspection Date	08/04/2019
Survey held at	CHARN'S CUSTOMCRAFT BLK 1010 BUKIT MERAH LANE 3 #01-105 SINGAPORE 159724		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKL 5020R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BOOT LOGO (N)	NOT NECESSARY	60.00	-
1	REAR BOOT EMBLEM 'TEANA' (N)	NOT NECESSARY	87.00	-
1	REAR BOOT EMBLEM '2.0 XL' (N)	NOT NECESSARY	73.00	-
1	REAR BUMPER (N)	DENTED	848.10	848.10
1	REAR BUMPER REINFORCEMENT (N)	NOT NECESSARY	533.80	-
1	REAR BUMPER SPONGE (N)	NOT NECESSARY	244.30	-
	LESS 10% DISCOUNT		-184.62	-84.81
			1,661.58	763.29
	<u>SPECIAL NETT ITEMS</u>			
1	SET REVERSE SENSOR (SN)	SHORTED	200.00	200.00
			200.00	200.00
	<u>LABOUR</u>			
	REMOVE NECESSARY PARTS :JACKING ,PANEL BEATING ,REPAIR AND STRAIGHTEN REAR INNER PANEL ,REAR END PANEL,REAR BOOT AND REAR BUMPER .		380.00	200.00
	PUTTY AND RESPRAY REAR INNER PANEL,REAR END PANEL,REAR BOOT AND REAR BUMPER .		450.00	400.00
			830.00	600.00
	GRAND TOTAL		2,691.58	1,563.29
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,250.00

Report Ref No. CC4/LPC19006093/Eba3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKL 5020R

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKL 5020R

RE-INSPECTION

