



# CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,  
Spray-Painting, Mechanical Repair And Customizing of Cars  
BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724  
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723  
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg  
Bus. Reg. No. 251513/00M

AXA/LONPAC(SJU5313K)  
DOA: 03/104/2019@1955

LONPAC INSURANCE BHD

ATTN: THE MOTOR CLAIMS DEPT

Steve  
83778813

Wl pain c 8/4/19 3.00 pm  
3 days  
L/S

AL SPY

5/4/2019

## THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

SKL 5020 R - NISSAN TEANA 2.0L CVT

CHASSIS: MNTBBAL33Z0000024 (2013)

1 pc	Rear boot logo	<del>MEC</del>	X	NN	(NETT)	\$ 60.00	X
1 pc	Rear boot emblem 'TEANA'	<del>MEC</del>	X	NN	(NETT)	\$ 87.00	X
1 pc	Rear boot emblem '2.0XL'	<del>MEC</del>	X	NN	(NETT)	\$ 73.00	X
1 pc	Rear bumper	<del>DD</del>			(NETT)	\$ 848.10	✓
1 pc	Rear bumper reinforcement	?	X	NN	(NETT)	\$ 533.80	X
1 pc	Rear bumper sponge	?	X	NN	(NETT)	\$ 244.30	X
						\$ 1,846.20	
LESS 10%						\$ 184.62	
						\$ 1,661.58	
						848.10	
						-10%	
						763.19	
1 set	Reverse sensor (S/NETT)					\$ 200.00	✓ SHORTED
Remove necessary parts: jacking, panel beating, repair and straighten rear inner panel, rear end panel, rear boot and rear bumper.						\$ 380.00	200
Putty and respray rear inner panel, rear end panel, rear boot and rear bumper.						\$ 450.00	400
						\$ 2,691.58	
ADD 7% GST						\$ 188.41	
						\$ 2,879.99	

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P - 763.19  
N - 200  
L - 600  
1563.19

L/S - 1250.55  
= 1250