



Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sgToyota Bodycare Centre
17 Ubi Road #
Singapore 409611
Tel no.: 6631 1188Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Account Detail				Account No		Customer Detail			
Lonpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia <i>30/4/19</i>				<i>not valid</i> S1000007/ICLPI1 Document No Document Date 05/04/2019		Ms Lee Li Wen Catherine 23 Tampines Central 7 #04-28 The Tampines Trilliant Singapore 526609 Mobile: 85885048			
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks		
18	AHXVB	E5	29/06/2018	SMC4352M	0	18108	67/DS/SMC4352M		
Chassis No		Engine No		Terms	Service Engineer	Vehicle In	Collected On		
JTDKDD3B3001615292		1N28575640		60	Sam San Joi	04/04/2019 13.30	--/--/---- 0.00		
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-SGE2009D ACC DATE:04/04/2019 DRIVE IN:04/04/2019 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:							30.00 ✓
2	S	PSP PER PANE LABOUR FOR PLATINUM SHINEPRO & SHINE						91.59	183.18
3	C	BP-ECU2 TO RESET ECU AND REPROGRAMME							164.00 ✓
4	S	BP-SUBLET DRILL HOLE & INSTALL REAR REVERSE SENSOR							164.00 ✓
5	S	BP-SUBLET CHECK LIGHTING & CONDUCT WATER LEAK TEST							164.00 ✓
6	S	BP-SUBLET REMOVE & INSTALL REAR COMPARTMENT CARPE							328.00 ✓
7	S	T, GARNISH AND TRIMMING TO ASSIST REPAIR							
8	S	BP-SUBLET REPLACE REAR ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS RESPRAY JOB ON REAR ACCIDENT AFFECTED AR EAS				618	1312		2624.00
9	1	T52159-52984 COVER, RR BUMPER				1.00	460.70		460.70
10	2	T52563-52031 RETAINER, BUMPER LH				1.00	48.70	X	48.70
11	3	T52576-52160 RETAINER, RR BUMPER				1.00	67.90	X	67.90
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.									
For & on behalf of Borneo Motors		Customer's Signature		Change Summary		Total			
		Please acknowledge receipt of vehicle 		Parts Labour Materials Lubrication/Fluid Others		Amount Due			

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 05/04/2019
TIME 08:51Acknowledged by Repaire
Signature
Date

3917918

3917918

VEHICLE NO SMC4352M

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Download "My Toyota SG" app on Playstore or Appstore to access your Toyota ME account & more!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking:
www.toyota.com.sg
Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
Longpac Insurance Berhad 100 Beach Road #19-00 Shaw Tower Singapore 189702 Attn: Ms Lily Koh/Mr Chia	S1000007/ICLPI1	Ms Lee Li Wen Catherine 23 Tampines Central 7 #04-28 The Tampines Trilliant Singapore 528609 Mobile: 85885048
	Document No 0	
	Document Date 05/04/2019	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
18	AXXVB	E5	NHP10R	29/06/2018	SMC4352M	0	18108 67/DS/SMC4352M
Chassis No	Engine No	Terms	Service Engineer	Vehicle In	Collected On		
UTDKD3B3001615292	1N28575640	60	Sam San Jol	04/04/2019 13.30	--/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
12	4	T52562-52061 RETAINER, RR BUMPER R	1.00	48.70		48.70
13	5	T52575-52180 RETAINER, RR BUMPER R	1.00	67.90		67.90
14	6	S52161-0K040 CLIPS	10.00	4.00		40.00
15	7	T52171-52180 REINFORCEMENT, RR	1.00	582.60		582.60
16	8	T52016-52140 ARM SUB-ASSY, LH	1.00	116.70		116.70
17	9	T52015-52130 ARM SUB-ASSY, RH	1.00	116.70		116.70
18	0	T58307-52700 PANEL SUB-ASSY, BODY	1.00	0.00		
19	1	T58399-52010 COVER, FLOOR UNDER	1.00	86.90		86.90
20	2	T67005-52D10 PANEL ASSY, BACK DOOR	1.00	930.60		930.60
21	3	T75403-48010 PLATE, LUGGAGE	1.00	47.20		47.20
22	4	T75441-52140 PLATE, BACK DOOR	1.00	45.00		45.00
23	5	T75442-52460 PLATE, LUGGAGE	1.00	52.60		52.60
24	6	T75441-52130 PLATE, LUGGAGE	1.00	60.70		60.70
25	7	SPC507-52001 88 YELLOW 5A3 REV SENSOR	1.00	169.60		169.60

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary		Total	8,751.68
	Please acknowledge receipt of vehicle	Parts	2,942.50	GST 7.00%	612.62
		Labour	194.00	Less	0.00
		Materials	5,615.18		
		Lubrication/Fluid	0.00		
		Others	0.00		
				Amount Due	9,364.30

PLEASE TEAR ALONG PERFORATED LINE

3917919

TO SECURITY GUARD

3917919

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 05/04/2019
TIME 08:51

VEHICLE NO SMC4352M

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors